



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 636894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No: 196003963G

Page 2 / 2

ESTIMATE

Date	: 26/06/2018	Reg No	: YP2373E
To	: AXA INSURANCE SINGAPORE PTE LTD	Model	: FEB21ER4SDEB C/C MT
Attn.	:	Chassis No	: FEB21EA20464
Office / Mobile	:	Engine No	: 4P10C13278
Email Address	:	Quotation No.	: 64937
		Ref. No.	: GBE/SVC/SALES-4653/180626
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/06/2018
Attn.	: LILEWEI	Policy No.	: D18MTPCVE001567
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - AXA
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

PREPARED BY : LILEWEI

DATE / TIME :

06/07/18 @ 11am

SURVEYOR :

Tanph

MOBILE NO :

97445749

OFFICE FAX NO :

EMAIL ADDRESS :

sur@lkkauto.com

EXCESS AMOUNT :

REPAIR TYPE :

PART-BY-PART / LUMP SUM

AUTHORISATION :

AUTHORISED / NOT AUTHORISED

RE-SURVEY :

BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

6-8 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bisSAFE
S T A R

AIA

SAC
Contributor No: AIA-335121243

AIA

SAAS
Contributor No: AIA-335121243



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
10 Tuas Avenue 18 Singapore 638894
Tel: +65 6881 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6883 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 196303663G

Page 1 / 2

ESTIMATE

Date	: 26/06/2018	Reg No	: YP2373E
To	: AXA INSURANCE SINGAPORE PTE LTD	Model	: FEB21ER4SDEB C/C MT
Attn.	:	Chassis No	: FEB21EA20464
Office / Mobile	:	Engine No	: 4P10C13278
Email Address	:	Quotation No.	: 64937
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4653/180626
Attn.	: LILEWEI	D.O.A.	: 14/06/2018
Office / Mobile	: +65 6864 0637	Policy No.	: D18MTPCVC001567
Email / Fax No.	: LiLewei@goldbell.com.sg	Claim Type	: TP CLAIM - AXA
		Workshop	: 29 TANJONG PENJURU

SPECIAL NETT ITEMS

1	VERTICAL WOOD - photo	2	CR 4000.00
2	HORIZONTAL WOOD	8 2 cm - AGO	? 3300.00
3	REAR DECK LOWER RAIL	1	CR 550.00
4	FLOOR WOODEN PANEL	6	T 5100.00
5	REAR WOODEN STEP PANEL	1	CR 450.00
6	REAR BUMPER	1	X 850.00
7	REAR BUMPER BRACKET	2	X 360.00
8	I - STRIP	2	H 200.00
9	J - STRIP	2	ht 240.00
10	REAR NUMBER PLATE	1	? 20.00
11	"60 KM/H" STICKER	1	nei 20.00
12	REAR DECK PANEL	1	CR 950.00
13	REAR DECK SIDE PANEL	1	? 2000.00
14	U - BOLT	6	? 1080.00
15	BOLT AND NUT (SET)	8	A TB 280.00
16	TAIL LAMP TOP BRACKET LHS	1	X 150.00

PARTS TOTAL:

19550.00

3000

4000.00

LABOUR CHARGES

1	TO REMOVE, REFIX AND REALIGN REAR DECK ASSY, TO REPLACE ALL DAMAGED PARTS.	✓	180.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	So	80.00
3	SUNDRIES	200	450.00
4	TO CARRY OUT SPRAY PAINTING.		

LABOUR TOTAL :

4,710.00

SUB-TOTAL :

24,260.00

GST @ 7% for \$ 24,260.00

1,698.20

GRAND TOTAL (S\$) :

25,958.20

biSAFE
ST & R

