

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

1/eng.
(LKK)
09/07/18
Monday
Confirmed.

01/07/2018

Owner: MKM CAR LEASING PTE LTD

Not wither
11/07/18
Resurvey After Paint
4 days

ESTIMATE TO REPAIR TOYOTA ALITS -SKK5320E

1pc	front LH fender
1pc	front LH fender inner shield
1pc	front LH side skirt
1pc	front LH door protector
1pc	front LH door protector chrome
1pc	front LH absorber
1pc	front LH knuckle arm
1pc	front LH knuckle bearing

Bj	\$	281.45	—
D11	\$	181.50	—
n	\$	658.25	X
sur	\$	121.35	—
na	\$	121.10	—
	\$	381.52	7
	\$	458.50	7
	\$	218.25	7

less 25%

\$	2,421.92
\$	605.48
\$	1,816.44

1pc front LH sport rim

R s.nett \$ 580.00 X

remove & refix undercarriage
alignment
tuffkote
wiring
spray painting
labour charges
Total

\$	380.00	7
\$	80.00	601
\$	80.00	301
\$	60.00	201
\$	750.00	5501
\$	600.00	4001
\$	4,346.44	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: