

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 3862J

MAKE :

MODEL : HYUNDAI i40

China Taiping
CPLP)

DATE 6/30/2018

(Sat)

LKK -

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 250.00 206
	Wiring Charge			\$ 30.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 20
	NA 2 LKK 2/7/18 1740 LKK PIP 2 DAYS Before paint photo. After repair photo.			
	<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 750.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				