

REPAIR ESTIMATE*

VEHICLE NO : SHD 3210A

DATE 29/6/2018 14:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH)			\$ 980.50
	SUB TOTAL			\$ 980.50
	LESS 20%			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	Labour Charge			
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 150.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,234.40
<p>Tanpin 97495749</p> <p>01 day</p> <p>Resurvey before paint</p> <p>surv @ 1 hour</p> <p>29/6/18 @ 1730</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplemental claims must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				