

22/03/2018

ASS. REC. BY:

REF: CS/CT118012192/Atd3n2

Special Instruction:

Surveyor:

Munimen

Adrian

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 4/7/18 @ 2:47pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 4171T

Insured:

GBC 9157H

at Workshop in/s

Joo Huk Kee

Tel:

67431913

of

B1K 3007 Ubi Rd 1 # 01-406

Policy No:

DMCVSN3014751800

Claim No:

SNM18D03293C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement

Date/Time:

3:15pm @ 4/7/18

Person Contacted:

Nabilah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 4171T - X

lump sum \$7300+ (Red: 4088.53, 35%)

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

14/10/08.

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop in/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ4171T.

Yr Regn: 2008 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Allion.

c.c 1496.

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

162308

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NZT2603032962.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R17.

R: 225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

04/07/18.

Survey held at

JHK.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China.

Pending COE Renewal.

MV: 111C
TV: 7.8K
Nett: 3.2K

RECEIVED 23 OCT 2018

Date/Time, File Pass to?



Preli. Report

1) 23/10 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Office

TOTAL

220

Report Format:

Lump Sum / L.B.I. (\$)

TP
7300/-



LKK Auto Consultants Pte Ltd

5th Floor, #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 19960719R GST Reg. No. 19-9607198-R

Affiliated to F&T International Les Experts En Automobile	
CHINA TAIPING INSURANCE (S) PTE	CTI118012192/Atd3
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 07	Date: 04-07-2018 Case: CTI
	
1. PARTY CLAIM	
Insured: GBC 9157H	Vehicle: SLJ 4171T
Policy No: DMCVSN3014	Cash (\$): 0.00
Claim No: SNM16D	Cash (\$): 0.00
Assign From: MERIMEN (RE)	Claim Date: 04/07/2018
2. Description	
Make:	0
Engl: HIDDEN	Reg:
Chassis:	
Odor:	
Brake:	
Gen:	
3. Measurements	
Size	Balance
R/H	mm
L/H	mm
R/H	mm
L/H	mm
4. Notes	
5. Date: 04/07/2018	
Appr: 30/06/2018	
Supr: JOO H	
3007 U	
KAMPONG	
SINGAPORE	
5a. ON WAS	
CE TO YC	
" BASIS.	
THORISED REPAIRS.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2018		04 Jul 2018 14:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOULD 8 ENGINEERING & MARINE PTE LTD, Co. Reg. No.: 200701057Z		
Main Claimant:	GOH LIAK CHEE, ID: S1434111J		
Vehicle Reg. No.:	SLJ4171T	Date of Loss:	30/06/2018 19:00 - :59
Claim Type:	TP / SNM18D03293C02	Policy/Cover Note No.:	DMCVSN3014751800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC9157H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/07/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Lucas Lee

From: Nabilah Senin <nabilah@jhk.com.sg>
Sent: Monday, 2 July, 2018 6:09 PM
To: Claims Dept of CTI
Subject: New Third Party Claim - SLJ4171T / GBC9157H on 30/06/2018
Attachments: doc20180702180710.pdf

Our Ref : SLJ4171T
Your Ref : GBC9157H

Dear Sir/Mdm,

Kindly please arrange pre-repair survey for the above and if possible would like to do direct settlement.

Please provide us your list of surveyors for our selection.

Attached are the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you.

Best regards,
Nabilah Senin | Admin Clerk
Joo Hak Kee Auto Pte Ltd
3007 Ubi Road 1
#01-406 Singapore 408701
O: 6743 1913 | F: 6743 5234
E: nabilah@jhk.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years COE Renewal Toyota Wish 1.8A.



\$2800 Down Payment Monthly
From \$688 Onwards. Lowest
3.68% P.A. @ GV Cars Financing.
GV Credit Pte Ltd - StarAd



View our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

14 vehicles

Search

Allion

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Allion

Any

Any

2009

Any

Any

Any

Available



☐ Toyota Allion 1.5A (New 5-yr COE)

\$37,800

\$7,560 /yr

22-Jan-2009

1,496 cc

-

Sedan

Available

Luxury Edition, New 2K White Paintwork, Very Well Kept, Wear And Tear Parts Replace, No Repairs Needed, Spacious Compartment, Smooth And Comfort Drive, Welcome Test Drive, Low Fuel Consumption, New Fu...

Posted: 12-Jun-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



☐ Toyota Allion 1.5A (New 5-yr COE)

\$37,988

\$7,590 /yr

23-Feb-2009

1,496 cc

140,000 km

Sedan

Available

Very Very Good Condition! See To Believe! Option With 5 Years COE. Definitely Better Than Altis In Term Of Space And Fuel Consumption. Luxurious Toyota Allion With Great Driving Feel. New Paint! AL...

Posted: 02-Jul-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



☐ Toyota Allion 1.5A

\$16,800

\$11,880 /yr

04-Mar-2009

1,496 cc

-

Sedan

Available

Careful Owner, Luxurious Toyota Allion With Great Driving Feel. Reliable Classic Saloon! 6 Months Free Servicing By Reputable Workshop With 40 Years Experience In The Market For A Peace Of Mind, View ...

Posted: 01-Jul-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



☐ Toyota Allion 1.5A (New 5-yr COE)

\$34,800

\$6,960 /yr

12-Mar-2009

1,496 cc

120,000 km

Sedan

Available

Very Good Condition! See To Believe! Option With 5 Years COE. Definitely Better Than Altis In Term Of Space And Fuel Consumption. Luxurious Toyota Allion With Great Driving Feel. Bank/ In House Loa...

Posted: 05-Jun-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle



☐ Toyota Allion 1.5A

\$18,000

\$12,080 /yr

07-May-2009

1,469 cc

128,000 km

Sedan

Available

Immaculate Condition! Fuel Efficient Sedan With Luxurious Interior And Spacious Boot, Low Mileage, Well Taken Care Of. Just Done Servicing, Just Changed 4 New Tyres. Schedule A Test Drive Today. Viewing...

Carro
Posted: 05-Jun-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



☐ Toyota Allion 1.5A

\$16,888

\$8,840 /yr

26-May-2009

1,496 cc

166,025 km

Sedan

Available

Single Owner, Well Maintained Car. Only Used For City Driving, Reliable And Fuel Efficient Car. Selling Due To Upgrading.

Posted: 26-Jun-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota



☐ Toyota Allion 1.5A

\$17,000

\$8,370 /yr

28-May-2009

1,496 cc

140,000 km

Sedan

Available

Definitely Better Than Altis In Term Of Space And Fuel Consumption. Luxurious Toyota Allion With Great Driving Feel. Reliable Classic Saloon! View To Believe. Schedule A Test Drive Today. Viewing Is...

Carro
Posted: 03-Jul-2018 Tags: 2009 Toyota Allion, Toyota Allion, Toyota, Allion, Used Toyota

SHORTLISTED HISTORY

Compare

Transfer Fee Enquiry

[➤ Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.: SLJ4171T
 Vehicle Type: P10 - Passenger Motor Car
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: TOYOTA
 Vehicle Model: ALLION 1.5 A
 Chassis No.: NZT2603032962
 Propellant: Petrol
 Engine No.: 1NZD196874
 Engine Capacity: 1496 cc
 Maximum Power Output: 81.0 kW (108 bhp)
 Maximum Laden Weight: 1475 kg
 Unladen Weight: 1200 kg
 Year Of Manufacture: 2008
 Original Registration Date: 14 Oct 2008
 Lifespan Expiry Date: -
 COE Category: A - Car (1600cc & below)
 Quota Premium: \$13,801.00
 COE Expiry Date: 13 Oct 2018
 Road Tax Expiry Date: 13 Oct 2018
 PARF Eligibility Expiry Date: 13 Oct 2018
 Inspection Due Date: 13 Oct 2019
 Intended Transfer Date: 02 Jul 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -



Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLJ4171T		
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	ALLION 1.5 A		
Chassis No. :	NZT2603032962		
Propellant :	Petrol		
Engine No. :	1NZD196874		
Engine Capacity :	1496 cc		
Maximum Power Output :	81.0 kW (108 bhp)		
Maximum Laden Weight :	1475 kg		
Unladen Weight :	1200 kg		
Year Of Manufacture :	2008		
Original Registration Date :	14 Oct 2008		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
PQP Paid :	\$15,142.00		
COE Expiry Date :	13 Oct 2023		
Road Tax Expiry Date :	13 Oct 2018		
Inspection Due Date :	13 Oct 2019		
Intended Transfer Date :	16 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 14 Oct 2018 to 13 Apr 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	376.00	-	376.00
Total Amount Payable :			401.00
Amount Payable (From 14 Oct 2018 to 13 Oct 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	751.00	-	751.00
Total Amount Payable :			776.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

Enquire Transfer Fee

Vehicle No. :	SLJ4171T
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	ALLION 1.5 A
Chassis No. :	NZT2603032962
Propellant :	Petrol
Engine No. :	1NZD196874
Engine Capacity :	1496 cc
Maximum Power Output :	81.0 kW (108 bhp)
Maximum Laden Weight :	1475 kg
Unladen Weight :	1200 kg
Year Of Manufacture :	2008
Original Registration Date :	14 Oct 2008
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$13,801.00
COE Expiry Date :	13 Oct 2018
Road Tax Expiry Date :	13 Oct 2018
PARF Eligibility Expiry Date :	13 Oct 2018
Inspection Due Date :	13 Oct 2019
Intended Transfer Date :	02 Jul 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

OK Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3863B
Vehicle Details	
Vehicle No.:	SLJ4171T
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1N2D196874
Chassis No.:	NZT2603032962
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,881.00
Original Registration Date:	14 Oct 2008
First Registration Date:	14 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$14,881.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2018
PARF Rebate Amount:	\$7,440.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$13,801.00
COE Rebate Amount:	\$378.00
Total Rebate Amount:	\$7,818.00

The information contained herein is correct as at 04 Jul 2018

OK



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司
SINCE 1986

TP China

Denise

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER : GOH MING MING, KELVIN (WU MINGMING)
INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO.: 5087383930
REFERENCE: CHINA TAIPING DIRECT
DATE OF ACCIDENT: 30/06/2018

Est. No. : E18070001
Date : 04/07/2018
Vehicle Num. : SLJ4171T
Make/Model : Toyota ,Allion 1.5 A
Chassis/Eng# : NZT2603032962
Yr. of Manu : 2008

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	FRONT BUMPER <i>Distorted</i>	1.00	850.60	850.60 ✓
2	FRONT BUMPER CLIPS <i>n</i>	10.00	9.60	96.00 30
3	FRONT BUMPER SIDE RETAINER LH <i>Dist</i>	1.00	108.70	108.70 ✓
4	FRONT BUMPER SIDE RETAINER RH <i>Me n</i>	1.00	108.70	108.70 ✓
5	FRONT BUMPER REINFORCEMENT <i>Best Best</i>	1.00	368.60	368.60 ✓
6	FRONT BUMPER SPONGE <i>Broken</i>	1.00	214.70	214.70 ✓
7	GRILLE <i>Me n</i>	1.00	320.60	320.60 ✓
8	GRILL LOGO EMBLEM <i>Me n</i>	1.00	68.90	68.90 ✓
9	HEAD LAMP LH <i>Smashed</i>	1.00	560.50	560.50 ✓
10	HEAD LAMP RH <i>Me n</i>	1.00	560.50	560.50 ✓
11	HEAD LAMP BRACKET LH <i>Me n</i>	1.00	120.80	120.80 ✓
12	HEAD LAMP BRACKET RH <i>Me n</i>	1.00	120.80	120.80 ✓
13	BONNET <i>Distorted</i>	1.00	850.60	850.60 ✓
14	BONNET HINGE LH <i>Me n</i>	1.00	105.60	105.60 ✓
15	BONNET HINGE RH <i>Me n</i>	1.00	105.60	105.60 ✓
16	SUPPORT PANEL <i>Best</i>	1.00	780.60	780.60 ✓
17	AIR CON BLOWER PIPE <i>Me n</i>	1.00	360.50	360.50 ✓
18	CROSS MEMBER <i>Me n</i>	1.00	1,180.60	1,180.60 ✓
19	STEERING RACK & PINION <i>Me n</i>	1.00	1,480.60	1,480.60 ✓
20	FUSE BOX <i>Smashed</i>	1.00	214.80	214.80 ✓
21	BONNET LOCK <i>Me n</i>	1.00	150.60	150.60 ✓
22	FRONT FENDER LH <i>Distorted</i>	1.00	489.70	489.70 ✓

Continue on next page...



BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE₃



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER : GOH MING MING, KELVIN (WU MINGMING)
INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO.: 5087383930
REFERENCE: CHINA TAIPING DIRECT
DATE OF ACCIDENT: 30/06/2018

Est. No. : E18070001
Date : 04/07/2018
Vehicle Num. : SLJ4171T
Make/Model : Toyota ,Allion 1.5 A
Chassis/Eng# : NZT2603032962
Yr. of Manu : 2008

No	Description	Qty	U/P	Amt
23	FRONT FENDER INNER SHIELD LH <i>Missing</i>	1.00	310.50	310.50 ✓
24	FRONT FENDER INNER SHIELD CLIPS LH <i>New</i>	6.00	9.60	57.60 ✓
25	FRONT FENDER INNER TRIM/PANEL LH <i>Distorted</i>	1.00	780.40	780.40 ✓
26	FRONT DOOR LH <i>Repair</i>	1.00	980.60	980.60 ✓
27	FRONT SIDE MIRROR LH <i>Cracked</i>	1.00	580.60	580.60 ✓
28	FRONT SIDE MIRROR 1/4 GARNISH LH <i>Paint</i>	1.00	150.60	150.60 +
29	FRONT SHOCK ABSORBER LH <i>Best</i>	1.00	368.60	368.60 2
30	FRONT SHOCK ABSORBER RH <i>Best</i>	1.00	368.60	368.60 2
31	FRONT SHOCK ABSORBER BUSH LH <i>2 new</i>	1.00	60.80	60.80 2
32	FRONT SHOCK ABSORBER BUSH RH <i>2 new</i>	1.00	60.80	60.80 2
33	FRONT WHEEL BEARING LH <i>2 new</i>	1.00	136.60	136.60 2
34	FRONT WHEEL BEARING RH <i>2 new</i>	1.00	136.60	136.60 2
35	FRONT LOWER ARM LH <i>Best</i>	1.00	419.70	419.70 2
36	FRONT LOWER ARM RH <i>Best</i>	1.00	419.70	419.70 2
37	FRONT KNUCKLE ARM LH <i>Best</i>	1.00	438.60	438.60 2
38	FRONT KNUCKLE ARM RH <i>Best</i>	1.00	438.60	438.60 2
39	FRONT KNUCKLE ARM BEARING LH <i>2 new</i>	1.00	128.60	128.60 2
40	FRONT KNUCKLE ARM BEARING RH <i>2 new</i>	1.00	128.60	128.60 2

Amt S\$ 15,184.70
Discount (25.00%) S\$ 999.99
Subtotal S\$ 11,388.53

Section: LABOUR

Continue on next page...



BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER : GOH MING MING, KELVIN (WU MINGMING)
 INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO.: 5087383930
 REFERENCE: CHINA TAIPING DIRECT
 DATE OF ACCIDENT: 30/06/2018

REPAIR ESTIMATE

Est. No. : E18070001
 Date : 04/07/2018
 Vehicle Num. : SLJ4171T
 Make/Model : Toyota ,Allion 1.5 A
 Chassis/Eng# : NZT2603032962
 Yr. of Manu : 2008

No	Description	Qty	U/P	Amt
41	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	980.00	980.00 ✓
42	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	1,050.00	1,050.00 ✓
43	TO DISMANTLE & RE-FIT UNDERCARRIAGE	1.00	300.00	300.00 ✓
44	TO PERFORM 4 WHEEL ALIGNMENT	1.00	100.00	100.00 80 ✓
45	TO ALIGN HEAD LAMP	1.00	60.00	60.00 30 ✓
46	TO CHECK WIRING FUNCTION AND REFIT WIRING	1.00	80.00	80.00 30 ✓
47	TO ANTI-RUST	1.00	100.00	100.00 40 ✓

Amt S\$ 2,670.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 2,670.00

Adrian Lij
 1/5 07/07/18
 10 Days


total: 9141.67
 1/5: 7.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Surveyed by/Company : _____
 Contact Number : _____
 Date/Time : _____
 Licensed Automotive Surveyor's Sign: _____

Acknowledged by Repairer
 Signature: _____
 Date: _____



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 11,388.53
 LABOUR Subtotal S\$ 2,670.00
 Total S\$ 14,058.53

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE₃

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012192/ATD3N2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3014751800
Claimant Vehicle No :	SLJ4171T	Insured Vehicle No :	GBC9157H
Date of Loss:	30/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03293C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4171T	Engine No:	1NZD196874
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603032962
Reg. Date:	14/10/2008 (Man. Year: 2008)	Odometer:	162308 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,388.52	6,681.67	4,706.85	41.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	2,460.00	210.00	7.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,058.52	9,141.67	4,916.85	34.97
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	14,058.52	7,300.00	6,758.52	48.07
+ GST 7.00/7.00% (S\$)	984.10	511.00	473.10	48.07
Nett Amount (S\$)	15,042.62	7,811.00	7,231.62	48.07

INSPECTION

Date of Assignment:	04/07/2018		
Date Inspected:	04/07/2018	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts: 143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLJ4171T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	850.60 FL	*850.60 FL
2	10		*FRONT BUMPER CLIPS	Necessary	96.00 FL	*30.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	108.70 FL	*108.70 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	108.70 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	368.60 FL	*368.60 FL
6	1		*FRONT BUMPER SPONGE	Cracked	214.70 FL	*214.70 FL
7	1		*GRILLE	Not Necessary	320.60 FL	*- FL
8	1		*GRILLE LOGO EMBLEM	Not Necessary	68.90 FL	*- FL
9	1		*HEAD LAMP LH	Smashed	560.50 FL	*560.50 FL
10	1		*HEAD LAMP RH	Not Necessary	560.50 FL	*- FL
11	1		*HEAD LAMP BRACKET LH	Not Necessary	120.80 FL	*- FL
12	1		*HEAD LAMP BRACKET RH	Not Necessary	120.80 FL	*- FL
13	1		*BONNET	Distorted	850.60 FL	*850.60 FL
14	1		*BONNET HINGE LH	Not Necessary	105.60 FL	*- FL
15	1		*BONNET HINGE RH	Not Necessary	105.60 FL	*- FL
16	1		*SUPPORT PANEL	Bent	780.60 FL	*780.60 FL
17	1		*AIR CON BLOWER PIPE	Not Necessary	360.50 FL	*- FL
18	1		*CROSS MEMBER	Not Necessary	1,180.60 FL	*- FL
19	1		*STEERING RACK & PINION	Not Necessary	1,480.60 FL	*- FL
20	1		*FUSE BOX	Cracked	214.80 FL	*214.80 FL
21	1		*FRONT FENDER INNER SHIELD LH	Missing	310.50 FL	*310.50 FL
22	6		*FRONT FENDER INNER SHIELD CLIPS LH	Necessary	57.60 FL	*57.60 FL
23	1		*FRONT FENDER INNER TRIM/PANEL LH	Distorted	780.40 FL	*780.40 FL
24	1		*FRONT DOOR LH	Repair	980.60 FL	*- FL
25	1		*FRONT SIDE MIRROR LH	Cracked	580.60 FL	*580.60 FL
26	1		*FRONT SIDE MIRROR 1/4 GARNISH LH	Not Necessary	150.60 FL	*- FL
27	1		*FRONT SHOCK ABSORBER LH	Bent	368.60 FL	*368.60 FL
28	1		*FRONT SHOCK ABSORBER RH	Bent	368.60 FL	*368.60 FL
29	1		*FRONT SHOCK ABSORBER BUSH LH	Not Necessary	60.80 FL	*- FL
30	1		*FRONT SHOCK ABSORBER BUSH RH	Not Necessary	60.80 FL	*- FL
31	1		*FRONT WHEEL BEARING LH	Not Necessary	136.60 FL	*- FL
32	1		*FRONT WHEEL BEARING RH	Not Necessary	136.60 FL	*- FL
33	1		*FRONT LOWER ARM LH	Bent	419.70 FL	*419.70 FL
34	1		*FRONT LOWER ARM RH	Bent	419.70 FL	*419.70 FL
35	1		*FRONT KNUCKLE ARM LH	Bent	438.60 FL	*438.60 FL
36	1		*FRONT KNUCKLE ARM RH	Bent	438.60 FL	*438.60 FL
37	1		*FRONT KNUCKLE ARM BEARING LH	Necessary	128.60 FL	*128.60 FL
38	1		*FRONT KNUCKLE ARM BEARING RH	Necessary	128.60 FL	*128.60 FL
39	1		*BONNET LOCK	Not Necessary	150.60 FL	*- FL
40	1		*FRONT FENDER LH	Distorted	489.70 FL	*489.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 15,184.70 8,908.90
 - List Item Discount on L Items 25.00/25.00% (S\$) 3,796.18 2,227.23

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	11,388.52	6,681.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	New	980.00	980.00
2	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	New	1,050.00	1,000.00
3	TO DISMANTLE & RE-FIT UNDERCARRIAGE	New	300.00	300.00
4	TO PERFORM 4 WHEEL ALIGNMENT	New	100.00	80.00
5	TO ALIGN HEAD LAMP	New	60.00	30.00
6	TO CHECK WIRING FUNCTION AND REFIT WIRING	New	80.00	30.00
7	TO ANTI-RUST	New	100.00	40.00
Gross Labour Cost (S\$)			2,670.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >