

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

EQ
CLCC)
Tuesday
(10/07/18
Confirmation

Not Authored
Resurvey B&Pain
4-5 days

01/07/2018

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL - SLH1071D

1pc	rear tailgate
1pc	rear tailgate HONDA logo
1pc	rear tailgate VEZEL emble
1pc	rear tailgate RH reflector
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear tailgate windscreen glass moulding
1pc	rear RH taillamp
1pc	rear bumper
1pc	rear bumper side RH bumper
1pc	rear bumper side RH retainer
1pc	rear bumper RH reflecter
1pc	rear end panel
1pc	rear end panel inner garnish

B1	\$ 1,100.90	✓
nn	\$ 27.00	X
na	\$ 55.10	✓
SL	\$ 421.40	X
n	\$ 198.40	✓
SL	\$ 135.20	X
	\$ 252.70	?
nn	\$ 150.55	✓
	\$ 460.60	?
B1	\$ 986.30	✓
B1	\$ 195.20	✓
Dir	\$ 24.80	✓
	\$ 151.50	?
	\$ 530.90	?
	\$ 109.90	?
	\$ 4,800.45	
	\$ 960.09	
	\$ 3,840.36	

less 20%

1 set rear reverse sensor

shen s.nett \$ 280.00 *200.00*

remove & refix rear windscreen glass
wiring
tuffkote
sealant
spray painting
labour charges
Total

	\$ 120.00	✓
	\$ 100.00	201
	\$ 80.00	?
na	\$ 60.00	40.00
	\$ 850.00	5501
	\$ 800.00	?
	\$ 6,130.36	



Date: _____

Signature: _____

Acknowledged by Reparer

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company