

REPAIR ESTIMATE*

VEHICLE NO : SHB 4327B

DATE 29/6/2018 12:00

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			\$ 562.30	
	Front Bumper Sponge			\$ 142.20	
	Front Bumper Reinforcement			\$ 526.10	
	Front Bumper Centre Grille			\$ 176.90	
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	\$ 44.80	
	Front Bumper Retainer Mounting		\$ 9.20	\$ 18.40	
	SUB TOTAL			\$ 1,470.70	
	LESS 20%			\$ 294.14	
	DISCOUNTED TOTAL			\$ 1,176.56	
	Front Number Plate			\$ 25.00	Nett
	Front No Plate Trim Cover			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 350.00	
	Spray Painting Charge			\$ 250.00	
	TOTAL LABOUR			\$ 600.00	
	ESTIMATE TOTAL			\$ 1,831.56	
<p>Tan Jiah 97495744</p> <p>WP</p> <p>2 days</p> <p>Resurvey after repair</p> <p>sur @ lkh auto.com</p> <p>21/6/18 @ 1715</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

CHINA

JH.