

INSURER

INS. CASE OWNER:

CC

ATG1801

205

A^W 4639

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

4/3/18

Date / Time:

4/3/18

Registered in Merimen:

4/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 2983J

Claim No.:

04347246746

Name of Insured:

UR

Policy No.:

A0000070

Insured Tel No.:

HP:

4/3/18

Make / Model:

MITSUBISHI

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MIGUEL GIOVANNI MARTINEZ

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

Gx 87755

INSRS:
WSP:
Tel:
Liability:
RMKS:

modern

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

12/3/18
vrm

Gx 87755-K

SLN 2983J-K

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

13/7/18 email

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

15/4/19

Confirm with:

Ms Chin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 37.

If NO or B 28, Ass. Lia:

Repair Cost: +684

SS

4601.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

800.00 (5 100 x 8 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

5408.49

Global Sum SS: 5400.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5400.00

Name 1:

modern Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 6X8175 S.Yr Regn: 2004, Sept.Type: ☒ M.Cycle / Bus / ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota LiteaceC.C. 2184Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading 428167

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CR42509528Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 165R13CR: 165R13C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hifly

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 05/07/18Survey held at ModernDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/4/19

TP ALG.
Confirm US \$ 4300.00 with 7 working days
COE Expiry: 23/09/19.MV: 151C
PV: 5.81C
Nett: 9.21C(Pd) = \$ 3887.53
48.1)

Date/Time. File Pass to?

☐

Prel. Report

/

☐

Final Report

Date/Time. File Return to?

/

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: \$

Photos:

+ Spec:

TOTAL

Report Format

Lump Sum / L.B.I: \$

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18012205/Awb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 04-07-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 2983J	Veh. Inspected	GX 8175S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/07/2018	Inspection Date	05/07/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Vivian

Quotation
 DATE : 06.07.2018
 VEH NO : GX8175S
 MODEL : Toyota Liteace
 D O A : 02.07.2018
 YR REF : SLN2983J

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GX8175S (Toyota Liteace)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	381.10 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	1	90.00 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	1	85.00 ✗
5	Rear End Panel Outer <i>Distorted</i>	1	561.40 ✓
6	Rear End Panel Inner <i>Repair</i>	1	371.50 ✗
7	Rear End Panel Top Garnish <i>Cracked</i>	1	113.20 ✓
8	Tailgate <i>Distorted</i>	1	1,086.50 ✓
9	Tailgate Lock <i>Jammed</i>	1	220.40 ✓
10	Tailgate Weatherstripe <i>new</i>	1	281.70 ✓
11	Tailgate Inner Trim Board <i>new</i>	1	185.10 ✓
12	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
13	Tailgate Outer Garnish <i>new</i>	1	186.50 ✗
14	Tailgate Glass Moulding <i>new</i>	1	171.00 ✓
15	Toyota Logo <i>new</i>	1	31.60 ✓
16	Rear Exhaust Pipe <i>Repair</i>	1	775.20 ✗
17	Rear Exhaust Mounting <i>new</i>	1	36.50 ✗
			4,636.70
Less 25%			(1,159.18)
			\$ 3,477.53

S/NETT ITEMS

1	Reverse Sensor <i>Damaged</i>	4 pcs	350.00 <i>new</i>
2	Tailgate Glass Sealant <i>new</i>	1	60.00 ✓
3	Tailgate Advertisement Stickers <i>new</i>	1	450.00 <i>280</i>
4	7pax Sticker <i>new</i>	1	10.00 ✓
5	70km/h Sticker <i>new</i>	1	10.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GX8175S (Toyota Liteace)

6	Rear Camera	<i>N/A</i>	1		500.00 X
		<i>\$60</i>		Total Parts	\$ 4,857.53

LABOUR CHARGE

1	To knocking & pull ou rear portion & renew above parts	\$	1,200.00 1000
2	To putty & spray up paint works	\$	1,000.00 900
3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 60
5	To remove rear camera	\$	100.00 60
6	To remove rear video recorder	\$	100.00 50
7	To underseal	\$	150.00 50
8	To remove upholstery	\$	150.00 40
9	To remove tailgate glass	\$	180.00 120
10	To transfer tailgate fittings	\$	150.00 80
11	To remove exhaust pipe	\$	150.00 80
Total Labour		\$	3,330.00
Grand Total		\$	8,187.53

NOTE :

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 5416.50
L/S: 43K
7 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Director

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7919N
Vehicle Details	
Vehicle No.:	GX81755
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 2.2M
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	3C3995883
Chassis No.:	CR425009528
Maximum Power Output:	-
Open Market Value:	\$23,649.00
Original Registration Date:	24 Sep 2004
First Registration Date:	24 Sep 2004
Transfer Count:	1
Actual ARF Paid:	\$1,183.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE/COA Details	
COE Expiry Date:	23 Sep 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$23,901.00
COE Rebate Amount:	\$5,802.00
Total Rebate Amount:	\$5,802.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 06 Jul 2018

OK

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SLN2983J

Our Ref : GX8175S

Date : 14.08.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-3000 Fax : 6-415-3727

Attn : The Motor Claim Dept

**RE : ACCIDENT INVOLVING GX8175S & SLN2983J ON 02.07.2018
AT T-JUNCTION OF AMK AVE 1 & UPPER THOMSON RD**

We refer to the above matter.

We have been authorized by our client M/s ATT Systems (s) Pte Ltd to make claim against your insured vehicle No. SLN2983J in respect of the above accident for the following :

Repair Cost	\$ 4,601.00 (Incl GST)
Loss of use (\$150 x 8 days)	\$ 1,200.00
Search fee	\$ 7.49
Total :	\$ 5,808.49

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Friday, 13 July, 2018 10:25 AM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: ACCIDENT INVOLVING SLN 2983J AND GX 8175S ON 02/07/2018

Our Ref: CC6/LCR18012205/Awb3

13 July 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLN 2983J AND GX 8175S ON 02/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORIZATION

Date: 3 July 2018

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

Gx 8175 S / SLN 2983 J

ON 02/7/18 ALONG T-Junction of Ang Mo Kio
Ave 1 & Upper Thomson Road.

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully





Y

Signature of Owner

Susanna Wan / 88739658D

Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$5,400.00 (Global Sum) for vehicle no. GX 8175S that was damaged pursuant to the accident which occurred on 02/07/2018 (date) along JUNCTION OF UPPER THOMSON RD (location) involving vehicle no/s SLN 2983J this is pursuant to the inspection conducted on 05/07/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner ATT SYSTEMS (S) PTE LTD ("the third party claimant") of vehicle no. GX 8175S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GX 8175S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of April (month) 2019 (year)

LWP

Signed by appointed surveyor


Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120


Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001238

Date : 10/08/2018
Vehicle Num. : GX 8175S
Make/Model : TOYOTA LITEAGE-2004
Chassis/Eng# :
Accident Date : 02/07/2018
Claim No. :
Reference :
Policy No. : 5013050788-12

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		4,300.00
		Labour Total S\$:		4,300.00

Total S\$:	4,300.00
GST @ 7% S\$:	301.00
Amount Due S\$:	4,601.00
=====	


MODERN AUTOMOTIVE PTE LTD



53 - Modern

Thank you!

Minder Kaur has successfully logged out.

Your last login date and time was 04 Jul 2018, 11:08:59.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please CLEAR YOUR CACHE after each session.

GX81BS

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)	Log Date/Time
1	Vehicle	SLN2983J -		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	04 Jul 2018 / 11:10:06

Enquire Vehicle & Owner Information (Vehicle No. SLN2983J As At 02 Jul 2018 / 12:45:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MODERN AUTOMOTIVE

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLN2983J
Make Description/Model: MITSUBISHI / LANCER EX 1.6 AT LED TAIL LAMP
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2018 Edit Reg		05 Jul 2018 00:00 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: -		
Main Claimant:	ATT SYSTEMS (S) PTE LTD, Co. Reg. No.: 199407919N		
Vehicle Reg. No.:	GX8175S	Date of Loss:	02/07/2018 12:00 - :59 [165 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0434329467SG	Policy/Cover Note No.:	0999994796 (Comprehensive)
Vehicle Reg. No. (Insured):	SLN2983J	Policy No. (Claimant):	5013050788-12
		Excess:	
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/07/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.













































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GX8175S (0434329467SG)
[SLN2983J]
TP
ATT SYSTEMS (S) PTE LTD
Jul 2 2018 12:00PM
[LCRF PTE LTD]
Modern Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser																																																																																																																																																												
Letters/Correspondences																																																																																																																																																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Finalized On</th> <th></th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>(Draft)</td> <td>Third Party Express Settlement - Payment Breakdown</td> <td></td> <td>Edit</td> </tr> </tbody> </table>			No	Finalized On		Thumbnail	Print	1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	<div>1 per page</div> <div><input checked="" type="checkbox"/></div>																																																																																																																																																		
No	Finalized On		Thumbnail	Print																																																																																																																																																											
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit																																																																																																																																																											
Assessment Reports																																																																																																																																																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Finalized On</th> <th></th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12/07/18 16:39</td> <td> Accident Statement <small>From: SC + Reg. No: SLN2983J, Claimant: LCRF PTE LTD</small> </td> <td></td> <td>Load HTM</td> </tr> </tbody> </table>			No	Finalized On		Thumbnail	Print	1	12/07/18 16:39	Accident Statement <small>From: SC + Reg. No: SLN2983J, Claimant: LCRF PTE LTD</small>		Load HTM	<div>1 per page</div> <div><input checked="" type="checkbox"/></div>																																																																																																																																																		
No	Finalized On		Thumbnail	Print																																																																																																																																																											
1	12/07/18 16:39	Accident Statement <small>From: SC + Reg. No: SLN2983J, Claimant: LCRF PTE LTD</small>		Load HTM																																																																																																																																																											
Photos/Images																																																																																																																																																															
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>No</th> <th>Relabel/Reorder</th> <th></th> <th>Thumbnail</th> <th>Print</th> </tr> </thead> <tbody> <tr><td>1</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>2</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>3</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>4</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>5</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>6</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>7</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>8</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>9</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>10</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>11</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>12</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>13</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>14</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>15</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>16</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>17</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>18</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>19</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>20</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>21</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>22</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>23</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>24</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>25</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>26</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>27</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>28</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>29</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> <tr><td>30</td><td>02/08/18 18:39</td><td>General View</td><td></td><td>Load JPG</td></tr> </tbody> </table>			No	Relabel/Reorder		Thumbnail	Print	1	02/08/18 18:39	General View		Load JPG	2	02/08/18 18:39	General View		Load JPG	3	02/08/18 18:39	General View		Load JPG	4	02/08/18 18:39	General View		Load JPG	5	02/08/18 18:39	General View		Load JPG	6	02/08/18 18:39	General View		Load JPG	7	02/08/18 18:39	General View		Load JPG	8	02/08/18 18:39	General View		Load JPG	9	02/08/18 18:39	General View		Load JPG	10	02/08/18 18:39	General View		Load JPG	11	02/08/18 18:39	General View		Load JPG	12	02/08/18 18:39	General View		Load JPG	13	02/08/18 18:39	General View		Load JPG	14	02/08/18 18:39	General View		Load JPG	15	02/08/18 18:39	General View		Load JPG	16	02/08/18 18:39	General View		Load JPG	17	02/08/18 18:39	General View		Load JPG	18	02/08/18 18:39	General View		Load JPG	19	02/08/18 18:39	General View		Load JPG	20	02/08/18 18:39	General View		Load JPG	21	02/08/18 18:39	General View		Load JPG	22	02/08/18 18:39	General View		Load JPG	23	02/08/18 18:39	General View		Load JPG	24	02/08/18 18:39	General View		Load JPG	25	02/08/18 18:39	General View		Load JPG	26	02/08/18 18:39	General View		Load JPG	27	02/08/18 18:39	General View		Load JPG	28	02/08/18 18:39	General View		Load JPG	29	02/08/18 18:39	General View		Load JPG	30	02/08/18 18:39	General View		Load JPG	<div>3 per page</div> <div><input checked="" type="checkbox"/></div>	
No	Relabel/Reorder		Thumbnail	Print																																																																																																																																																											
1	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
2	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
3	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
4	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
5	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
6	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
7	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
8	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
9	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
10	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
11	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
12	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
13	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
14	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
15	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
16	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
17	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
18	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
19	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
20	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
21	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
22	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
23	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
24	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
25	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
26	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
27	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
28	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
29	02/08/18 18:39	General View		Load JPG																																																																																																																																																											
30	02/08/18 18:39	General View		Load JPG																																																																																																																																																											

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	02/08/18 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/18 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/18 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/18 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/18 18:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/18 18:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/18 18:40	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/18 18:01	TP GIA REPORT	 Load PDF	
2	13/07/18 10:27	Email letter to OI ACCIDENT INVOLVING SLN 2983J AND GX 8175S ON 02.07.2018	 Load PDF	
3	26/04/19 11:05	WORKSHOP INVOICE	 Load PDF	
4	26/04/19 11:05	AUTHORISATION TO ACT FORM	 Load PDF	
5	26/04/19 11:05	Release Voucher	 Load PDF	
6	26/04/19 11:05	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer.Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN2983J (Insd veh)	Model:	TOYOTA LITEACE 2.2 D (M)
	GX8175S (TP veh)		
Date of Accident:	02/07/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	8,760.65
Final Repair Cost	:	\$	5,400.00
Loss of Use	:	\$	8.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,400.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability 100 (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 5,400.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

26 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18012205/AWB3Q2

Date: 26/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994796

Claimant Vehicle No : GX8175S

Insured Vehicle No : SLN2983J

Date of Loss: 02/07/2018

Nature of Claim: TP

Claim No: 0434329467SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GX8175S

Make & Model: TOYOTA LITEACE, 2.2 D (M)

Engine No: 3C3995883

Reg. Date: 24/09/2004 (Man. Year: 2004)

Chassis No: CR425009528

Colour: Silver

Odometer: 428167 km

Engine Capacity: 2184 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165 R13C

Rear Tyre Size:

165 R13C

Front Left Side: HIFLY 6 mm

Rear Left Side:

HIFLY 6 mm

Front Right Side: HIFLY 6 mm

Rear Right Side:

HIFLY 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,857.52	2,946.50	1,911.02	39.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,470.00	860.00	25.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,187.52	5,416.50	2,771.02	33.84
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	8,187.52	4,300.00	3,887.52	47.48
+ GST 7.00/7.00% (S\$)	573.13	301.00	272.13	47.48
Nett Amount (S\$)	8,760.65	4,601.00	4,159.65	47.48
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,408.49		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 05/07/2018

Date Inspected: 05/07/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	381.10 FL	*381.10 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	90.00 FL	*90.00 FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	85.00 FL	*- FL
5	1		*REAR END PANEL OUTER	Dented	561.40 FL	*561.40 FL
6	1		*REAR END PANEL INNER	Repair	371.50 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Cracked	113.20 FL	*113.20 FL
8	1		*TAILGATE	Distorted	1,086.50 FL	*1,086.50 FL
9	1		*TAILGATE LOCK	Jammed	220.40 FL	*220.40 FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	281.70 FL	*281.70 FL
11	1		*TAILGATE INNER TRIM BOARD	Torn	185.10 FL	*185.10 FL
12	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*TAILGATE OUTER GARNISH	Not Necessary	186.50 FL	*- FL
14	1		*TAILGATE GLASS MOULDING	Necessary	171.00 FL	*171.00 FL
15	1		*TOYOTA LOGO	Necessary	31.60 FL	*31.60 FL
16	1		*REAR EXHAUST PIPE	Repair	775.20 FL	*- FL
17	1		*REAR EXHAUST MOUNTING	Not Necessary	36.50 FL	*- FL
18	4		*REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
19	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
20	1		*TAILGATE ADVERTISEMENT STICKERS	Necessary	450.00 FS	*280.00 FS
21	1		*7PAX STICKER	Necessary	10.00 FS	*10.00 FS
22	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
23	1		*REAR CAMERA	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	6,016.70	3,742.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,159.18	795.50
Total Parts (S\$)	4,857.52	2,946.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OU REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	1,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	900.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE REAR CAMERA	New	100.00	60.00
6	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
7	TO UNDERSEAL	New	150.00	50.00
8	TO REMOVE UPHOLSTERY	New	150.00	40.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
11	TO REMOVE EXHAUST PIPE	New	150.00	80.00
Gross Labour Cost (S\$)			3,330.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >