



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Adrian LK. ALG

LAM KOK MENG AARON

02/07/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 29/06/2018

Estimated repair cost for vehicle no: SJE2289B HONDA ACCORD 2.0 M '07

CHASSIS: CL71300417

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper <i>Paint</i>		\$950.00 <i>+</i>
2	1	Rear RH Bumper Side Retainer <i>new</i>		\$25.00 <i>+</i>
3	1	Rear Bumper Lower Spoiler <i>new</i>		\$878.20 <i>✓</i>
4	10	Rear Bumper Clips <i>new</i>	\$3.90	\$39.00 <i>+</i>
5	1	Rear RH Rim <i>lot</i>		<del>\$901.20</del> <i>450/s</i>
6	1	Rear RH Lower Arm		\$395.20 <i>+</i>
7	1	Rear RH Knuckle Arm <i>2 new</i>		\$380.00 <i>+</i>
8	1	Rear RH Shock Absorber		\$320.50 <i>+</i>
			<i>450 (su)</i>	Subtotal :- <u>\$3,889.10</u>

**Labour charges**

To remove & refit rear bumper reverse sensor	\$100.00 <i>+</i>
To remove & refit RH rear undercarriage	\$380.00 <i>+</i>
To check wheel alignment computer	\$150.00 <i>80</i>
To check wiring	<i>680</i> \$60.00 <del>70</del>
Tuff kote	\$150.00 <i>+</i>
Panel beating	<del>\$850.00</del> <i>200</i>
Spray painting	<del>\$750.00</del> <i>500</i>

Subtotal :- \$2,440.00

Total:- \$6,329.10

Adrian Lj  
04/07/18.

total : 1130

h/s : 900.

02 days