

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHD 8867Y

DATE 3/7/2018 11:30

MAKE :

MODEL : MERCEDES BENZ

DOA: 03.07.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 1,510.00
	Rear Bumper Reinforcement			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH)		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH)		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH)		\$ 115.00	\$ 230.00
	<b>SUB TOTAL</b>			<b>\$ 3,410.00</b>
	<b>LESS 20%</b>			<b>\$ 682.00</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,728.00</b>
	Rear Bumper Rubber Mat			\$ 50.00
	Reverse Sensor (not working)			
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 820.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,598.00</b>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Larry Ng

NA2 LKK  
4/7/18 1615  
L/S  
2D 883  
After repair photo

crack

?

Nett

200  
200  
20  
20