



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717

Tel : 67572622 Fax : 67411626

QUOTATION FOR REPAIR

TO	AXA INSURANCE	DATE	03.07.2018
ATTN	Claims Officer	PAGE	1 OF 1
MODEL	BMW 530I M SPORT	VEH NO	SJZ2031S
YEAR	2017	C/N0	WBAJA52010WA34585
ENGINE	1998	D.O.A	28.06.2018

3RD PARTY CLAIM (DIRECT SETTLEMENT)

S/NO	Part (List)	Qty	Price
1	Part (List)		
2	REAR BUMPER (UPPER) / Acc.	1	\$ 3,492.00
3	REAR BUMPER (LOWER) / Acc.	1	\$ 398.00
4	REAR BUMPER PARKING ALL ROUND SENSOR @\$840 / PC 2PC ?	6	\$ 5,040.00
5	REAR BUMPER REINFORCEMENT ?	1	\$ 1,760.00
6	REAR BUMPER LHS RETAINER X	1	\$ 123.00
7	REAR BUMPER RHS RETAINER X	1	\$ 123.00
8	REAR BUMPER CENTRE BRACKET ?	1	\$ 111.00
9	REAR BUMPER LHS REFLECTOR ?	1	\$ 80.00
10	REAR BUMPER RHS REFLECTOR ?	1	\$ 85.00
11	REAR BUMPER CLIP / Acc.	1 SET	\$ 130.00
12	TAILGATE repair X	1	\$ 3,757.00
13	TAILGATE WEATHER STRIP X	1	\$ 233.00
14	TAILGATE UPPER LOCK X	1	\$ 499.00
15	TAILGATE BMW LOGO / Acc.	1	\$ 155.00
16	TAILGATE 530I LOGO / Acc.	1	\$ 145.00
17	TAILGATE LHS TAILLAMP X	1	\$ 775.00
18	TAILGATE RHS TAILLAMP X	1	\$ 775.00
19	LHR FENDER TAILLAMP X	1	\$ 1,294.00
20	RHR FENDER TAILLAMP X	1	\$ 1,294.00
21	REAR END PANEL ?	1	\$ 1,879.00
22	REAR END PANEL TOP GARNISH ?	1	\$ 1,304.00
23	REAR END PANEL KEYLESS ENTRY SENSOR ?	1	\$ 650.00
24	REAR EXHAUST SILENCER ASSY repair X	1	\$ 1,900.00
25	LHR EXHAUST TAIL CHROME END PIPE X ?	1	\$ 420.00
26	RHR EXHAUST TAIL CHROME END PIPE X ?	1	\$ 420.00
	SUB-TOTAL		\$ 26,842.00
	DISCOUNT 10%		\$ 2,684.20
	SUB-TOTAL		\$ 24,157.80

	Part (S/Nett)			
1	REAR NO. PLATE WITH CASING X {NN	1	\$	75.00
2	TAILGATE REVERSE CAMERA X	1	\$	780.00
3	CERAMIC COATING APPLICATION ? - Need original	1	\$	950.00
	Invoice			
		SUB-TOT	\$	1,805.00
	Labour			
	TO REPAIR / REPLACE ACCIDENT DAMAGED 520	1	\$	3,120.00
	PART PLUS KNOCK & STRAIGHTEN ACCIDENT			
	RELATED PORTION			
	TO SPRAYING PAINT ACCIDENT AFFECTED PORTION 250	1	\$	2,100.00
	TO CONDUCT WIRING & HEADLAMP HARNESS CHECK		\$	150.00
	TO PERFORM FULL SYSTEM DIAGNOSIS	1	\$	850.00
	TO REPLACE REAR BUMPER PARKING SENSOR	1	\$	180.00
		SUB-TOT	\$	6,400.00
		SUB-TOTAL	\$	32,362.80
		GST 7%	\$	2,265.40
		TOTAL	\$	34,628.20

REMARK THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

4 Days.

before paint photos.

Quo Qi Ang - 82880282

11/7/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: