

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 06 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKF4311P		
TP Vehicle No	: SLW2599M	Accident Date	: 23/06/2018
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 05/07/2018
Date of Inspection	: 05/07/2018	Est. Duration of Repair	: 2.00
Inspection At	: WEI LEE MOTOR WORKS (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,272.58
Revised Amount	:S\$	1,218.05
Check Items (Estimated)	:S\$	254.78
Total	:S\$	1,472.83
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.