

SURVEYOR
MERIMEN

Kunth

ASSIGNMENT (Office)

From (Person):

Lionel fun

of

MSG

Date/Time:

5/7/18 @ 10:38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 2599M

Insured:

SKF 4311P

at Workshop no/:

Wei Lee Motors

Tel:

6456 9830

of

Blk 9 Sin Ming Ind. Est #01-32

Policy No:

29053410QMP

Claim No:

563297

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/06/2018

CA / REV / REP. / REV 24 HRS

lup?

H.O.D. Endorsement:

Date/Time: 1:47pm @ 5/7/18

Person Contacted:

Karen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 2599M-X

SKF 4311P-X

6/7/18

Send preli revised via merimen

10/8/18
@ 3:54pm

✓ 1 Lm 89501 confirmed with Karen (Ref 1333.58, 589)

ASS. REC. BY:

REF: *msc 1*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

6/7 File pass to Catherine

RECEIVED 13 AUG 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

10/8 - typist

Report Format:

Lump Sum / I.B.I. (\$) *merimen*

950/2

Days Of Repair: *2*Resurvey No. of Trip: *1*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Fuels

Others

TOTAL

150

10

160

Veh No:

SLW 259PM

Yr Regn:

*11, 08*Type: *M. Car* / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis CX c.c. *1598*

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

6723

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*NR0532EE 106120775*Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18012256/Kvd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 05-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 4311P	Veh. Inspected	SLW 2599M
Policy No.	29053410QMY	Coverage (\$)	0.00
Claim No.	563297	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/06/2018	Inspection Date
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 06 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKF4311P		
TP Vehicle No	: SLW2599M	Accident Date	: 23/06/2018
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 05/07/2018
Date of Inspection	: 05/07/2018	Est. Duration of Repair	: 2.00
Inspection At	: WEI LEE MOTOR WORKS (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,272.58
Revised Amount	:S\$	1,218.05
Check Items (Estimated)	:S\$	254.78
Total	:S\$	1,472.83

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jul 2018		05 Jul 2018 10:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LEE WERN WEI, ID: S8239241F, Tel: +6597607000		
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SLW2599M	Date of Loss:	23/06/2018 12:00 - :59 [115 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 563297	Policy/Cover Note No.:	29053410QMY (Third Party Only) Coverage: 30/11/2017 - 29/11/2018
Vehicle Reg. No. (Insured):	SKF4311P	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/07/2018]		
Driver/Custodian (Insured):	LEE WERN WEI (35 / Female), NRIC: S8239241F, Tel: +6597607000		
Adj Asg. Remarks:	ON WP. Car in at 1pm to 2.30pm. Liability : 100% Please contact Karen Seah @ 6456 9830 to arrange for survey.		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1813C
Vehicle Details	
Vehicle No.:	SLW2599M
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4802852
Chassis No.:	MR053ZEE106120775
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	10 Nov 2008
First Registration Date:	10 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Nov 2018
PARF Rebate Amount:	\$8,042.00
Intended COE Rebate Details	
COE Expiry Date:	09 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,455.00
COE Rebate Amount:	\$357.00
Total Rebate Amount:	\$8,399.00

The information contained herein is correct as at 06 Jul 2018.

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Notified
61 Sep 8?
Resurvey After Parts
2 days*

03, July 2018

MSIG Insurance (S) PL
4 Shenton Way #21-01 SGX Centre 2
S 068807

Attn: Motor claim dept-3rd party
Claiming against your insured vehicle No: SKF4311P
Accident involving vehicle No: SLW2599M/SKF4311P
DOA: 23/06/2018 AT Sentosa Gantry

Dear officer incharge
To supply--

Description	Qty	Amount
Front bumper <i>465</i>	1 <i>BU/CM</i>	423.60 ✓
Bumper retainer	1 <i>D.S</i>	51.90 ✓
Front bumper enforcement <i>395.50</i>	1 <i>R</i>	339.70 X
Bumper lower garnish	1 <i>SL</i>	93.00 X
Headlamp <i>560</i>	1 <i>CM</i>	481.90 ✓
	Parts	1,400.10
	Parts less 25%	350.02
		1,050.00

To remove damaged parts and attachments.
Repair/reshape dented areas.
Replace above parts.
To spray paint.

number plate

9/7/18

700.00 *250*
500.00 *220*

CM 3000 ✓
2272.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012256/KVD3N2

Date: 14/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29053410QMY
Claimant Vehicle No :	SLW2599M	Insured Vehicle No :	SKF4311P
Date of Loss:	23/06/2018	Nature of Claim:	TP
		Claim No:	563297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2599M	Engine No:	3ZZ4802852
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106120775
Reg. Date:	10/11/2008 (Man. Year: 2008)	Odometer:	67251 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,072.57	748.05	324.52	30.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	470.00	730.00	60.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,272.57	1,218.05	1,054.52	46.40
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	2,272.57	950.00	1,322.57	58.20

INSPECTION

Date of Assignment:	05/07/2018	
Date Inspected:	05/07/2018 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW2599M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Cracked	423.60 FL	*423.60 FL
2	1		*BUMPER RETAINER	Distorted	51.90 FL	*51.90 FL
3	1		*FRONT BUMPER ENFORCEMENT	Repair	339.70 FL	*- FL
4	1		*BUMPER LOWER GARNISH	Serviceable	93.00 FL	*- FL
5	1		*HEADLAMP	Cut	481.90 FL	*481.90 FL
6	1		*NUMBER PLATE	Cracked	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	1,420.10	987.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	347.53	239.35
Total Parts (\$\$)	1,072.57	748.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.REPAIR/RESHAPE DENTED AREAS.REPLACE ABOVE PARTS	New	700.00	250.00
2	TO SPRAY PAINT	New	500.00	220.00
Gross Labour Cost (\$\$)			1,200.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >