



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L		NAME : MS ELMIE LASTRI LINARDI		WIP : 19983	
4 SHENTON WAY #21-01		ADDRESS : 141 LENTOR STREET		EXCESS :	
SGX CENTRE 2		SINGAPORE 786838		DATE: 4-Jul-18	
SINGAPORE 068807					
ATTN : MOTOR CLAIMS		TEL : 98160110			
FAX :					
VEH NO :	SJG3688R	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWLN720302D97762	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGE CLAIM
MODEL :	MINI COOPER S CUBMAN F54	DATE REG.:	15-Jul-16	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES	
		QTY				
1	SHORT ENGINE	1	M11.00.2.455.332	OK ✓	\$ 19,967.55	✓
2	AUTOMATIC TRANSMISSION	1	B24.00.8.695.808	?	\$ 17,963.35	X
3	ATF 6	7	B83.22.2.355.599	new ✓	\$ 464.80	✓
4	BODY DOMAIN CONTROLLER UNIT	1	B61.35.8.715.964	shorted ✓	\$ 1,348.80	✓
5	AIRBAG CONTROL UNIT	1	B65.77.9.495.909	shorted ✓	\$ 1,024.75	✓
6	MAIN WIRING	1	M61.11.2.411.276	shorted ✓	\$ 7,886.75	✓
7	FRONT FLOOR TRIM COVER	1	M51.47.7.392.166	✓	\$ 575.05	✓
8	REAR FLOOR TRIM COVER	1	M51.47.7.392.158	✓	\$ 383.40	✓
9	ENGINE UNDER COVER	1	M51.75.7.357.974	fy ✓	\$ 226.95	✓
10	FRONT SOUND SPEAKER LH	1	B65.13.9.275.995	shorted ✓	\$ 409.45	✓
11	FRONT SOUND SPEAKER RH	1	B65.13.9.275.996	shorted ✓	\$ 409.45	✓
12	SPORT RIM	2	M36.11.6.856.056	cut ✓	\$ 3,994.38	✓
TOTAL PARTS					\$ 54,654.68	
					\$ -	
TOTAL PARTS COST					\$ 54,654.68	

Labour Description

1	TO REMOVE & REPLACE THE ENGINE BLOCK.	NETT	✓	\$ 4,200.00		✓
2	TO REMOVE & REPLACE THE AUTOMATIC TRANSMISSION.	NETT	✓	\$ 2,520.00		✓
3	TO REMOVE & REFIT THE FRONT UNDER CARRIAGE TO REPLACE THE ENGINE BLOCK.	NETT	✓	\$ 2,520.00		✓
4	TO REPLACE THE MAIN WIRE HARNESS SYSTEM	NETT	✓	\$ 4,200.00		✓
5	TO APPLY NEW ENGINE BLOCK NUMBER AT LTA REGISTRATION FEE.	NETT	✓	\$ 200.00		✓
6	TO SEND CAR TO INSPECTION CENTRE FOR ENGINE REPLACEMENT.	NETT	✓	\$ 500.00		✓
7	TO REPLACE 1 PC TYRE. 225/35 R19	NETT	80% cut ✓	\$ 580.00		
8	TO MOUNT 2 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT		\$ 200 240.00		✓

9	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT ✓	\$ 560.00	✓
10	TO REMOVE AND REPLACE FRONT & REAR FLOOR TRIM. 840	1260	\$ 1,680.00	✓
11	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	200	\$ 250.00	✓
12	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	300	\$ 350.00	✓
13	TO JACK UP & TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT ✓	\$ 400.00	✓
14	SUNDRIES.	NETT 50	\$ 100.00	✓
		TOTAL LABOUR	\$ -	\$ 18,300.00
		TOTAL PARTS	\$ -	\$ 54,654.68
		TOTAL	\$ -	\$ 72,954.68
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -

(S) 547.50 73,502.18

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Taufik 97495749

Revert

Not Authorised.

Ex: to be advise.

6/7/18 @ 1145

sur@lkhanto.com

taufik@lkhanto.com

20 days.

12/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: