

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6617R

DATE 3/7/2018 15:32

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Clips			\$ 22.00
	Tail Lamp (LH)			\$ 565.60
	Tail Lamp Panel Top (LH)			\$ 545.90
	Rear Fender (LH)			\$ 2,020.10
	Rear Fender Inner Lining (LH)			\$ 164.40
	Rear Fender Air-Duct			\$ 51.60
	Rear Windscreen Moulding			\$ 60.00
	Fuel Lid Cover			\$ 94.40

Lble

BQ

L/S

Chuang

XR

?

crack

?

DT

?

?

crack

Nett

Nett

Nett

400

200

20

X n n

50

50

20