

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5782H****AAD1807-023***Not Authored  
V/Smp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5782H**

VF1ABL15AUC279577

RENAULT

LATITUDE

2.7.2018

**III****PART****LIST**

|    |                               |    |                   |   |
|----|-------------------------------|----|-------------------|---|
| 1  | 1 BUMPER COVER REAR           | \$ | <i>B</i> 1,108.46 | — |
| 2  | 1 BUMPER LOWER REAR           | \$ | <i>CM</i> 768.84  | — |
| 3  | 1 BUMPER BRACKET CTR REAR     | \$ | <i>D</i> 113.47   | — |
| 4  | 1 BUMPER BRACKET SIDE RH REAR | \$ | <i>D</i> 135.97   | — |
| 5  | 1 BUMPER RETAINER RH REAR     | \$ | <i>CM</i> 44.99   | — |
| 6  | 1 BUMPER REFLECTOR RH         | \$ | <i>CM</i> 43.61   | — |
| 7  | 1 BUMPER BRACKET SIDE LH REAR | \$ | <i>SM</i> 135.97  | X |
| 8  | 1 BUMPER RETAINER LH REAR     | \$ | <i>SM</i> 44.99   | X |
| 9  | 1 BUMPER REFLECTOR LH         | \$ | <i>SM</i> 43.61   | X |
| 10 | 1 BUMPER BEAM REAR            | \$ | <i>B</i> 777.52   | — |
| 11 | 1 BUMPER BEAM BRACKET LH REAR | \$ | <i>B</i> 225.95   | — |
| 12 | 1 BUMPER BEAM BRACKET RH REAR | \$ | <i>B</i> 225.95   | — |
| 13 | 1 BOOT REAR                   | \$ | <i>B</i> 2,872.68 | — |
| 14 | 1 BOOT FINISHER               | \$ | <i>SM</i> 470.06  | X |
| 15 | 1 BOOT WHEATERSTRIP           | \$ | <i>D</i> 323.05   | — |
| 16 | 1 BOOT REFLECTOR LAMP LH      | \$ | <i>CM</i> 493.35  | — |
| 17 | 1 BOOT REFLECTOR LAMP RH      | \$ | <i>CM</i> 493.35  | — |
| 18 | 1 BOOT BADGE 'RENAULT'        | \$ | <i>NR</i> 225.36  | — |
| 19 | 1 BOOT BADGE                  | \$ | <i>NR</i> 225.36  | — |
| 20 | 1 BOOT STRUT LH               | \$ | <i>SM</i> 276.08  | X |
| 21 | 1 BOOT STRUT RH               | \$ | <i>SM</i> 276.08  | X |
| 22 | 1 BOOT HINGE LH               | \$ | <i>R</i> 367.84   | X |
| 23 | 1 BOOT HINGE RH               | \$ | <i>R</i> 367.84   | X |
| 24 | 1 BOOT INNER TRIM             | \$ | <i>SM</i> 586.45  | X |
| 25 | 1 BOOT SWITCH                 | \$ | <i>SM</i> 168.13  | X |
| 26 | 1 BOOT LOCK                   | \$ | <i>NR</i> 202.67  | — |
| 27 | 1 BOOT LOCK CATCH             | \$ | <i>R</i> 74.40    | X |
| 28 | 2 LICENCE PLATE LAMP          | \$ | <i>SM</i> 50.52   | X |
| 29 | 2 BOOT RUBBER PLUG            | \$ | <i>SM</i> 221.81  | X |

**Trans-cab Auto Services Pte Ltd****AAD1807-023**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5782H**

|              |                                           |           |              |                  |   |
|--------------|-------------------------------------------|-----------|--------------|------------------|---|
| 30           | 1 DOOR PANEL REAR LH                      | \$        | <i>R</i>     | 2,844.66         | X |
| 31           | 1 FENDER PANEL INNER TRIM REAR LH         | \$        | <i>Sm</i>    | 671.45           | X |
| 32           | 1 FENDER PANEL REAR LH                    | \$        | <i>R</i>     | 3,299.13         | X |
| 33           | 1 WHEELARCH REAR LH                       | \$        | <i>Sm</i>    | 543.47           | X |
| 34           | 1 FENDER PANEL INNER TRIM REAR RH         | \$        | <i>Sm</i>    | 671.45           | X |
| 35           | 1 FENDER PANEL REAR RH                    | \$        | <i>Bu</i>    | 3,299.13         | ✓ |
| 36           | 1 WHEELARCH REAR RH                       | \$        | <i>Sm</i>    | 543.47           | X |
| 37           | 1 TAILLAMP RH                             | \$        | <i>CM</i>    | 552.55           | ✓ |
| 38           | 1 TAILLAMP PANEL RH                       | \$        | <i>B</i>     | 986.70           | ✓ |
| 39           | 1 TAILLAMP LH                             | \$        | <i>ngcm</i>  | 552.55           | ✓ |
| 40           | 1 TAILLAMP PANEL LH                       | \$        | <i>R</i>     | 986.70           | X |
| 41           | 1 OUTER PANEL REAR (End Panel)            | \$        | <i>B</i>     | 1,471.77         | — |
| 42           | 1 OUTER PANEL REAR (End Panel)TRIM        | \$        | <i>nd</i>    | 404.56           | — |
| 43           | 1 SPARE WHEEL PANEL (Luggage Floor Panel) | \$        | <i>Bu/Bu</i> | 2,189.88         | ✓ |
| 44           | 1 SPARE WHEEL PANEL TRIM                  | \$        | <i>Sm</i>    | 612.21           | X |
| 45           | 1 EXHAUST REAR                            | \$        | <i>B</i>     | 7,489.05         | ✓ |
| 46           | 1 EXHAUST CAP REAR                        | \$        | <i>nd</i>    | 230.49           | ✓ |
| 47           | 1 FUEL FLAP L70Y                          | \$        | <i>Sm</i>    | 343.57           | X |
| 48           | 1 CHASSIS PANEL REAR RH                   | \$        | <i>R</i>     | 3,766.43         | X |
| 49           | 1 WHEEL HOUSING PANEL REAR RH             | \$        | <i>R</i>     | 4,682.09         | X |
| <b>TOTAL</b> |                                           | <b>\$</b> |              | <b>47,505.69</b> |   |
| <b>10%</b>   |                                           | <b>\$</b> |              | <b>4,750.57</b>  |   |
|              |                                           | <b>\$</b> |              | <b>42,755.12</b> |   |

**Specical Nett**

|    |                                     |    |              |        |             |
|----|-------------------------------------|----|--------------|--------|-------------|
| 1  | 1SET PARKING AID                    | \$ | <i>Short</i> | 700.00 | <i>Good</i> |
| 2  | 1SET REAR BUMPER CLIP               | \$ | <i>me</i>    | 66.00  | ✓           |
| 3  | 1SET BUMPER BRACKET CTR CLIP        | \$ | <i>me</i>    | 33.00  | ✓           |
| 4  | 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | <i>na</i>    | 10.00  | X           |
| 5  | 1SET BUMPR RETAINER RH CLIP RR      | \$ | <i>na</i>    | 20.00  | X           |
| 6  | 1SET BUMPR BRACKET SIDE CLIP LH RR  | \$ | <i>na</i>    | 10.00  | X           |
| 7  | 1SET BUMPR RETAINER CLIP LH RR      | \$ | <i>na</i>    | 20.00  | X           |
| 8  | 1SET BUMPER LOWER REAR RIVET        | \$ | <i>na</i>    | 22.00  | X           |
| 9  | 1SET BUMPER LOWER REAR CLIP         | \$ | <i>me</i>    | 66.00  | ✓           |
| 10 | 1 EXHAUST MOUNTING REAR             | \$ | <i>Sm</i>    | 17.82  | X           |
| 11 | 1SET BOOT FINISHER CLIP             | \$ | <i>na</i>    | 24.20  | X           |
| 12 | 1 BOOT STICKER "Trans-cab"          | \$ | <i>me</i>    | 30.00  | ✓           |

13 1 BOOT STICKER "6555-3333"

\$

30.00

**Trans-cab Auto Services Pte Ltd**

**AAD1807-023**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5782H**

14 1 BOOT INNER TRIM CLIP

\$

*na* 45.00 *X*

15 1SET FENDER WHEELARCH REAR RH CLIP

\$

*na* 35.00 *X*

16 1SET FENDER WHEELARCH REAR LH CLIP

\$

*na* 35.00 *X*

17 1 FENDER INNER TRIM CLIP LH

\$

*na* 28.00 *X*

18 1 FENDER INNER TRIM CLIP LH

\$

*na* 28.00 *1*

19 1 TAILLAMP CLIP RH

\$

*na* 5.00 *—*

20 1 TAILLAMP CLIP LH

\$

*na* 5.00 *—*

21 2 REAR WINDSCREEN SELANT

\$

*na* 80.00 *6000*

22 1 WINDSCREEN MOULDING

\$

*na* 100.00 *—*

23 1 REAR WINDSCREEN INNER SPONGE SEAL

\$

*na* 100.00 *3000*

24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)

\$

*na* 385.00 *X*

25 1 SPARE TYRE

\$

*na* 330.00 *X*

**TOTAL \$**

**2,225.02**

**TOTAL PARTS \$**

**44,980.14**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$

6,000.00 *11000*

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of Parts,  
Adjust And Realign The Same

\$

4,200.00 *20000*

To Rust-Proofing Of The Affected Areas.

\$

170.00 *1200*

To reinstall rear bumper parking sensor.

\$

170.00 *600*

To transfer of bootlid fittings, attachments and  
perform water seepage test.

\$

170.00 *600*

To repair and realign rear exhaust pipe.

\$

170.00

To drop rear exhaust box, renew the same, to repair  
and realign centre exhaust pipe.

\$

170.00

*} 800*

**Trans-cab Auto Services Pte Ltd**

AAD1807-023

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5782H

|                                                                                              |    |        |        |
|----------------------------------------------------------------------------------------------|----|--------|--------|
| To transfer of rear end panel fittings, attachment and perform water seepage test.           | \$ | 170.00 | } 1001 |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | 170.00 |        |
| To supply and re-do rear luggage floor panel insulation padding.                             | \$ | 380.00 | 801    |
| To transfer of rear fender fittings, attachment and perform water seepage test.              | \$ | 380.00 | nn X   |
| To transfer of rear windscreen fittings and conduct water seepage test.                      | \$ | 170.00 | 1201   |
| To check steering geometry and computer wheel alignment                                      | \$ | 220.00 | 601    |
| To transfer of rear door fittings, attachment and perform water seepage test.                | \$ | 380.00 | nn X   |

**TOTAL \$ 12,540.00****Over All Total \$ 57,520.14****(LUMP SUM)****Repair Days****20 DAYS**

18 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: