

Trans-cab Auto Services Pte Ltd

AAD1807-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9618D*Not Notified
11/1/18*

Vehicle No.:

SHB 9618D

Chassis No.:

KL1LA69RJB122887

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

30.6.2018

Third Party Insurer :

AIG**PART****LIST**

1	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>N</i>	1,133.00	<i>X</i>
2	1	Rear door weatherstrip - Inner	\$	<i>Sn</i>	41.40	
3	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sn</i>	25.90	
4	1	Rear door top hinge	\$	<i>N</i>	35.00	
5	1	Rear door bottom hinge	\$	<i>N</i>	35.00	
6	1	Rear door inner lock	\$	<i>N</i>	425.00	
7	1	Rear door check / arrestor	\$	<i>Sn</i>	65.00	
8	1	Rear door lock striker / latch	\$	<i>N</i>	120.00	
9	1	Rear door outer weatherstrip moulding	\$	<i>Sn</i>	85.00	
10	1	Side Rocker Panel Garnish LH	\$	<i>Sn</i>	236.40	
11	1	Rear Fender LH	\$	<i>N</i>	1,145.00	
12	1	Rear Fender Inner Trim LH	\$	<i>Sn</i>	418.44	
13	1	Front Side Rocker Panel Garnish LH	\$	<i>Sn</i>	236.40	
14	1	Front Side Rocker Panel Outer LH	\$	<i>Sn</i>	600.00	
15	1	Front Side Rocker Panel Inner LH	\$	<i>N</i>	519.30	
16	1	Rear Bumper	\$	<i>N</i>	1,202.00	

TOTAL	\$	6,322.84
10%	\$	632.28
	\$	5,690.56

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>nn</i>	24.00	<i>X</i>
1 Set	Front licence plate with holder	\$	<i>Sn</i>	192.00	<i>X</i>
1 Set	Radiator Grille clip	\$	<i>nn</i>	35.00	<i>X</i>
1 Set	Front Fender Liner clip	\$	<i>nn</i>	30.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1807-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9618D

1	Front Fender RR Bracket LH	\$	7.10	}
1	Rear Wheel Rim Hub Cap LH	\$	166.30	
1	Rear Tyre LH	\$	180.00	
1	Rear Tyre Rim RLH	\$	126.00	
1Set	Rear Fender Inner Trim Clip LH	\$	30.00	
1	Rear door advertisement sticker	\$	330.00	
1	Rear fender advertisement sticker	\$	330.00	

TOTAL	\$	1,450.40
--------------	-----------	-----------------

TOTAL PARTS	\$	7,140.96
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	3000
Putty and spray painting of the affected portion.	\$	4,000.00	4000
Towing Fees.	\$	120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1807-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9618D

To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	69
To remove and fix rear door advertisement sticker	\$	~ 170.00	X
To remove and fix rear fender advertisement sticker	\$	~ 170.00	X

TOTAL	\$	10,800.00
--------------	-----------	------------------

Over All Total	\$	17,940.96
-----------------------	-----------	------------------

Repair Days (Lump Sum)**15 days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: