

ASS. REC. BY:

REF: CS/FCI18012275/R/sd3ⁿ² Special Instruction:

Surveyor

CWS

Rasul

ASSIGNMENT (Office)

From (Person):

Lurene juw

of

FCI

Date/Time:

11/7/18 @ 7:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 3173U

Insured:

SHA 9257S

at Workshop n/s:

Li Sheng Automobile

Tel:

8398 7169

of

Blk K # 01-18 punden kop

Policy No:

Claim No:

D18005199 MP5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

kup)

H.O.D. Endorsement:

Date/Time:

10:58am @ 5/7/18

Person Contacted:

Mr. Joh

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 3173U-X

SHA 9257S-CS/INC09011210/Ch

DOA: 19/05/2009

09/07/18 @ 15:24 p.m. revised PA to Lurene via email.

Surveyor: Pavan

REF:

7271W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: GBO 31734at Workshop m/s L1 S HONGof Pak #01-18 PimpulungInsured: FCI TP

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS D/S

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBO 31734 Yr Regn: 2014 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NV 350 Prime Mover 2488Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 200655 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ONI MC2E 2620062787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 02/07/18Survey held at L1 S HONG

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 05/07/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/02/19 Continued HS \$ 3,900/- @ 8 days with Resul.
(\$6,195.93 Red - 61%)

RECEIVED 28 FEB 2019

Date/Time, File Pass to?

26/02/19

1) Typist

Date/Time, File Return to?

2) _____



Preli. Report



Final Report

Days Of Repair: 8Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 3,900/- L/S)

170

50

39

259



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012275/R1sd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9257S	Veh. Inspected	GBD 3173U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005199MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	05/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/07/2018	Inspection Date	05/07/2018	
Survey held at	BLK K #01-18			
Repairer	LI SHENG AUTOMOBILE TRADING			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005199MFSH

Date: 09 July 2018

Our Ref: CS/FCI18012275/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBD 3173U .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/07/2018 at the premises of M/s Li Sheng Automobile Trading and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,095.93</u> .
Revised Estimate Amount	: S\$ <u>5,476.45</u> .
"Check" Items Amount	: S\$ <u>838.08</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 8 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-07-2018	Our Ref No. D18005199MFSH
Accident Date	02-07-2018	Claim Type. Third Party
Insured Vehicle	SHA9257S	Third Party Vehicle. GBD3173U
Survey Location	Blk K #01-18 Pandan Loop	
Contact Person.	TOH KHAR KIAN	
Contact No.	67746110/ 83987469	Fax No. 67744885
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LI SHENG AUTOMOBILE TRADING	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242076)



PRI Documents



Close



PRI Header Details

Claim No	D18005199MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & LI SHENG
Workshop Name	LI SHENG AUTOMOBILE TRADING (Contact Person : TOH KHAR KIAN)	Survey Location & Contact Details	Blk K #01-18 Pandan Loop Mobile: 83987469 , Phone: 67746110 , Fax: 6774488! EmailId: TOHKK_90@HOTMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9257S	TP Vehicle No	GBD3173U
PRI Recieved Date	04-07-2018 08:18:01 PM	Surveyor Appointed Date	04-07-2018 07:43:29 PM	Surveyor Accept Date	05-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shirley Hiew (LKK Auto)

From: Khar Kian Toh <tohkk_90@hotmail.com>
Sent: Tuesday, 26 February 2019 11:32 AM
To: Shirley Hiew (LKK Auto); SUR
Cc: lishengauto@yahoo.com.sg
Subject: Re: Accident involved with vehicle GBD3173U and SHA9257S (REF: D18005199MFSH) on 02/07/2018 along Sim Lim Square Car Park Exit.

Hi Shirley,

Confirm final fig as \$3900 (lump sum) @ 8 days of repairs.

Thanks.

Best Regards,
Toh Khar Kian



Li Sheng Automobile Trading
18 Pandan Loop #01-18 Singapore 128236 (Blk K)
Mobile: (65) 83987469 | Fax: 67744885
Email : tohkk_90@hotmail.com

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, February 25, 2019 3:19:20 PM
To: 'Khar Kian Toh'; SUR
Cc: lishengauto@yahoo.com.sg
Subject: RE: Accident involved with vehicle GBD3173U and SHA9257S (REF: D18005199MFSH) on 02/07/2018 along Sim Lim Square Car Park Exit.

Hi Kian Toh,

Please re-confirm final fig \$ 3,900.00 (lump sum) @ 8 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khar Kian Toh [mailto:tohkk_90@hotmail.com]
Sent: Friday, 11 January 2019 3:47 PM
To: SUR <sur@lkkauto.com>

Cc: lishengauto@yahoo.com.sg

Subject: Accident involved with vehicle GBD3173U and SHA9257S (REF: D18005199MFSH) on 02/07/2018 along Sim Lim Square Car Park Exit.

Dear All,

The above attachment is our LOD, Tax invoice, LOA , Merimen Search, and Rental Invoice.

Breakdown:

	<u>Amount(\$)</u>
1) Repair cost	\$4800.00
2) Loss of Rental (\$100 x 10 days) (8 Repairs days +1 Sunday+ 1 day waiting for survey)	\$1070.00
3) Miscellaneous (LTA Search and Merimen Search)	\$29.00
Total	\$5899.00

Please check and revert.

Best Regards,
Toh Khar Kian



Li Sheng Automobile Trading
18 Pandan Loop #01-18 Singapore 128236 (Blk K)
Mobile: (65) 83987469 | Fax: 67744885
Email : tohkk_90@hotmail.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 9 July 2018 3:24 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005199MFSH/1
Attachments: GBD 3173U - Preli Advise.pdf

Dear Lurene,

Enclosed preliminary revised for GBD 3173U.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 5 July 2018 11:00 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005199MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 4 July 2018 7:44 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005199MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the Insurance is terminated during its currency, the Certificate must be returned to the Insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory Insurance.
The Certificate must be returned if the Insurance is suspended during its currency.

Agency Code: **01204SE**
Comprehensive

Excess: \$750/-Sect. 1 & additional \$2500/- Sect. 1 for age <21 years
or > 65 years &/or S'pore D.L. < 2 years
Windscreen: S\$100.00/-

CERTIFICATE NO.

M492961

1. Index Mark and Registration
Number of Vehicle

GBD 3173 U

2. Name of Policy Holder

City Land Logistics

3. Effective date of the commencement of
Insurance for the purposes of the Act

01st September 2017

4. Date of Expiry of Insurance

31st August 2018

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

- (1) Use in connection with the Policyholder's business.
- (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- (3) Use for social, domestic and pleasure purposes.

The Policy does not cover

- (1) Use for hire or reward or for racing, pace-making, reliability trial, or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: **1y/04.08.2017**

for **India International Insurance Pte. Ltd.**
(APPROVED INSURERS)

M.Z. 300C (GOODS CARRYING)
PRIVATE TYPE

Authorized Signatory

IMPORTANT NOTICE

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agree to cover the new owner they will endorse the policy accordingly and will issue a new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE COMPANY. FAILURE TO DO SO WILL RESULT IN UNDERWRITERS DECLINING LIABILITY.

Agent/Broker Name: **Aetna**

Hire Purchase Company: **Abwin Pte Ltd**

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G7825066L**
 Name: **CHU TZE LIANG**

Birth Date: **14 Jun 1987**
 Issue Date: **21 Sep 2016**
 Valid Till: **16/10/2021**

002611928F



WORK PERMIT
 Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer: **CITY LAND LOGISTICS**

Sector: **SERVICE**

Name: **CHU TZE LIANG**
 Occupation: **LORRY/ TRUCK DRIVER**

Work Permit No.: **4 02126140**
 Date of Application: **25-10-2014**
 Date of Issue: **06-09-2017**
 Date of Expiry: **24-09-2019**



L8287555

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 2B Motorcycles $\leq$ 200 cc	17 Oct 2006
Class 2A Motorcycles between 201 cc and 400 cc	27 Nov 2013
Class 2 Motorcycles $>$ 400 cc	21 Sep 2016
Class 3 Motor cars with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq$ 2500kg	17 Oct 2006
Class 4 Motor vehicles which are constructed to carry load or passengers and the unladen weight $>$ 2500kg	21 Nov 2008
Motor vehicles which are not constructed to carry load or passengers and the unladen weight $\leq$ 7250kg	

NP 428A

Licence No: G7825066L



VISIT PASS
 Immigration Regulations

Name: **CHU TZE LIANG**

Date of Birth: **14-06-1987** Sex: **M** Nationality: **MALAYSIAN**

FIN: **G7825066L** Date of Issue: **06-09-2017** Date of Expiry: **24-09-2019**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



citylandlog@gmail.com

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

MS FIRST CAPITAL INSURANCE LTD

Your Ref Vehicle No:
SHA9257S(TP claim)

Date: 4/7/2018
Vehicle No: GBD3173U
Model: NISSAN NV350
Date of loss: 2/7/2018
Our ref: LSA261TJS
Year: 2014

Qty	Description	List Price	Remarks
1.00	REAR WINDSCREEN	\$ 837.00	X m
1.00	REAR TAIL GATE	\$ 1,742.00	Bul -
1.00	REAR BUMPER	\$ 690.60	De -
1.00	REAR END PANEL	\$ 246.20	Blue -
1.00	REAR STEP PANEL	\$ 162.40	X 2
6.00	REAR STEP PANEL CLIPS	\$ 36.00	X 3 m
1.00	TAILGATE CHROME GARNISH	\$ 511.40	? X
1.00	REAR EMBLEM	\$ 66.40	ne -
1.00	REAR LOGO - NV350	\$ 73.40	ne -
1.00	REAR LOGO - URVAN	\$ 56.20	ne -
1.00	TAILGATE LOCK	\$ 323.70	ne -
1.00	TAILGATE INNER TRIM BOARD	\$ 223.10	X 2 m
2.00	TAILLAMP	\$ 419.80	? X 2 m
2.00	REAR BUMPER RETAINER	\$ 37.00	ne -
10.00	REAR BUMPER CLIPS	\$ 55.00	ne -
1.00	END PANEL - INNER		REPAIR
1.00	FLOOR PANEL		REPAIR
1.00	REAR WEATHER STRIP	\$ 127.50	ne -

TOTAL: \$ 5,607.70
LESS 10%: \$ 560.77
30% \$ 5,046.93

3418
30%
2392.60

S/NET

Qty	Description	Unit Price	Remarks
1.00	END PANEL SEALANT	\$ 80.00	60 ne
1.00	REAR WINDSCREEN SEALANT	\$ 80.00	40 ne
1.00	SPEED LIMIT STICKER	\$ 15.00	ne / 10
1.00	REVERSE SENSOR SET	\$ 294.00	200 ne
1.00	COMPANY NAME STICKER	\$ 200.00	100 ne
1.00	REAR NUMBER PLATE	\$ 50.00	35 ne
TOTAL:		\$ 719.00	

445

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 4/7/2018
Vehicle No: GBD3173U
Model: NISSAN NV350
Date of loss: 2/7/2018
Our ref: LSA261TJS
Year: 2014

MS FIRST CAPITAL INSURANCE LTD

Your Ref Vehicle No:
SHA9257S(TP claim)

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 1,800.00	900
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 1,600.00	800
1.00	CHECK WIRING	\$ 50.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 100.00	60
1.00	REMOVE & REFIT AFFECTED TAILGATE TO FACILITATE REPAIR	\$ 250.00	80
1.00	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$ 250.00	X 11
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 80.00	60
1.00	TO REMOVE AND REFIT REAR WINDSCREEN	\$ 150.00	120
1.00	SUNDARIES	\$ 50.00	20 new

TOTAL: \$ 4,330.00

SUBTOTAL: \$ 10,095.93

Estimate prepared by: TOH KHAR KIAN

Telephone : 83987469

tohkk_90@hotmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before and after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL

Hp 90010068

8 days

4/5

05/07/18 @ 1555

Resurvey after repair

2392.60

445.00

2070.00

4907.60

20%

3926.08

4/5 - 3,900

8 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012275/R1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-02-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9257S	Veh. Inspected	GBD 3173U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005199MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350 PANEL VAN	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1MC2E26Z0002787	Colour	GREY	
Odometer	200659	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2018	Inspection Date	05/07/2018	
Survey held at	BLK K #01-18 PANDAN LOOP			
Repairer	LI SHENG AUTOMOBILE TRADING			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 3173U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	NOT NECESSARY	837.00	-
1	REAR TAIL GATE	BUCKLED	1,742.00	1,742.00
1	REAR BUMPER	DEFORMED	690.60	690.60
1	REAR END PANEL	BUCKLED	246.20	246.20
1	REAR STEP PANEL	NOT NECESSARY	162.40	-
6	REAR STEP PANEL CLIPS	NOT NECESSARY	36.00	-
1	TAILGATE CHROME GARNISH	NOT NECESSARY	511.40	-
1	REAR EMBLEM	NECESSARY	66.40	66.40
1	REAR LOGO-NV350	NECESSARY	73.40	73.40
1	REAR LOGO-URVAN	NECESSARY	56.20	56.20
1	TAILGATE LOCK	BENT	323.70	323.70
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	223.10	-
2	TAILLAMP	NOT NECESSARY	419.80	-
2	REAR BUMPER RETAINER	NECESSARY	37.00	37.00
10	REAR BUMPER CLIPS	NECESSARY	55.00	55.00
1	END PANEL-INNER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR WEATHERSTRIP	NECESSARY	127.50	127.50
	LESS 10% DISCOUNT		-560.77	-
	LESS 30% DISCOUNT		-	-1,025.40
			5,046.93	2,392.60
SPECIAL NETT ITEMS				
1	END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SPEED LIMIT STICKER (SN)	NECESSARY	15.00	10.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	294.00	200.00
1	COMPANY NAME STICKER (SN)	NECESSARY	200.00	100.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	35.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDARIES (SN)	NECESSARY	50.00	20.00
			769.00	465.00
	<u>LABOUR</u> LABOUR FOR REPAIR ON AFFECTED AREA.INCLUSIVE OF THE REPAIR OF END PANEL-INNER AND FLOOR PANEL. SPRAY PAINT ON AFFECTED AREA. CHECK WIRING. APPLY RUST PROOF ON AFFECTED PANEL. REMOVE & REFIT AFFECTED TAILGATE TO FACILIATE REPAIR. TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR. TO REMOVE AND REFIT REVERSE SENSOR. TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	1,800.00	900.00
			1,600.00	800.00
			50.00	30.00
			100.00	60.00
			250.00	80.00
			250.00	-
			80.00	60.00
			150.00	120.00
			4,280.00	2,050.00
			GRAND TOTAL	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00	

Report Ref No. CS/FCI18012275/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.