

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0762/2018/KS  
**Date** : 5-Jul-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle no : SKT 9934 K**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Le Tuan Quoc  
**Address** : 10 Margate Road  
#05-03  
Singapore 438061  
**Telephone** : (HP) +96179100  
**Type of Claim** : Third Party Claims  
**Policy No.** : 21004039252-03  
**Vehicle No** : **SKK 6658 A**  
**Model Code** : Audi A6 C7 AVANT 3.0 TFSI  
**Model / Year** : Feb-12  
**Engine No** : CGW 029401  
**Chassis No** : WAUZZZ4G1CN085671  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 29-Jun-18  
**Place of Accident** : EAST COAST ROAD IN FRONT OF 112 KATONG

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKK 6658 A

S/N	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 360.00	X
2	To renew rhs 1/4 glass to facillitate fender renewal	S/N	\$ 300.00	X
3	To remove and transfer rhs rear door's multil-lock system and power window devices.	S/N	\$ 280.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager , fuse and relays trays, electrical and audio equipment.	S/N	\$ 1,400.00	X
5	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain airbag and sill trims.	S/N	\$ 1,400.00	X 700
6	To dismantle rhs rear door, rhs side member trim and rear bumper. Cut out and reweld rhs rear fender. Renew rhs rear door and side member trim. Reinstall all parts removed.	<del>S/N</del>	\$ <del>5,950.00</del>	2000
<b>SUB - TOTAL LABOUR CHARGES</b>			<b>\$ 9,690.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SKK 6658 A.

S/N	Nature of Jobs	Estimated Charges
7	To respray rhs rear door, rhs side member trim, rhs rear fender, rhs sill panel, door entrance drain panel, roof channel and end panelling. To carry out join sealer works and stone chip treatment.	\$ <del>5,200.00</del> 2475_
8	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓
8	To carry out diagnostic check.	S/N \$ 192.00 ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 15,362.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKK 6658 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR RH <i>Dented</i>	\$ 3,211.00	✓
2	DOOR ATTACHMENT RHS ?	\$ 106.00	?
3	REAR DOOR OUTER SEAL RH <i>New</i>	\$ 202.00	✓
4	BONDING AGENT ?	\$ 43.00	?
5	CLEANING SOLUTION ?	\$ 64.00	?
6	REAR DOOR CATCH RH <i>New</i>	\$ 105.00	+
7	REAR DOOR SEAL RH ?	\$ 162.00	?
8	POWER WINDOW REGULATOR RR RH <i>New</i>	\$ 309.00	+
9	SIDE MEMBER TRIM RH <i>Repair</i>	\$ 752.00	+
10	SIDE MEMBER ATTACHMENTS PARTS <i>New</i>	\$ 91.00	✓
11	REAR FENDER RH <i>Dented</i>	\$ 3,038.00	✓
12	QUARTER GLASS	\$ 446.00	+
13	QUARTER GLASS PRIMER	\$ 19.00	+
14	QUARTER GLASS CHROME TRIM	\$ 222.00	+
15	ROOF MOLDING RH	\$ 440.00	
16	WHEEL HOUSING LINER RH <i>New</i>	\$ 246.00	+
17	WHEEL HOUSING LINER ATTACHMENT PARTS RH <i>New</i>	\$ 68.00	+
18	1/4 GLASS SEALANT <i>New</i>	S/N \$ 100.00	+
19	ACRYLIC SEALER <i>2m</i>	S/N \$ 180.00	✓
20	CAVITY WAX <i>2m</i>	S/N \$ 140.00	✓
<b>SUB-TOTAL SPARE PARTS</b>		<b>: \$ 9,944.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKK 6658 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	Wheel Rim <i>cut</i>	965	✓
21	STONE CHIP <i>3 New</i>	S/N \$ 180.00	✓
22	METAL FILLER POWDER	S/N \$ 280.00	✓
27	SUNDRIES ?	\$ 600.00	?
	<b>TOTAL SPARE PARTS</b>	<b>: \$ 11,004.00</b>	
	<b>TOTAL LABOUR CHARGES</b>	<b>: \$ 15,362.00</b>	
	<b>GRAND TOTAL</b>	<b>: \$ 26,366.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian King.  
Surveyed Date : 10/07/18. ✓  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 8 Days.

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant