

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

JOHN TAN KIT YONG
25 KAKI BUKIT ROAD4
06-51 SYNERGY @KB
Singapore 417800

TP111
Acher.

Accident date: 02th JULY 2018

Estimated repair cost for vehicle no: SJW3093Y TOYOTA COROLLA ALTIS 1.6 A

S/n	Qty	Items	U/price	Amount
				\$640.00 ✓
1	2	Rear tail lamp	\$320.00	\$51.60 X
2	4	Rear tail lamp clips	\$12.90	\$580.10 ✓
3	1	Rear bumper		\$110.40 ✓
4	2	Rear bumper side bracket outer	\$55.20	\$96.40 X
5	2	Rear bumper side bracket inner	\$48.20	\$40.00 30
6	8	Rear bumper clips	\$5.00	\$300.00 200 (SN)
7	1	Rear bumper reverse sensor		\$224.40 8560
8	2	Rear bumper bracket	\$112.20	\$350.00 X
9	1	Rear bumper reinforcement		\$180.00 ✓
10	1	Rear bumper inner sponge		\$655.00 X
11	1	Rear end panel		\$179.28 X
12	1	Rear End Panel Top Garnish		\$329.20 X
13	1	Rear spare tire panel top cover		\$250.00 X
14	1	Rear spare tire panel sealant		\$220.00 X
15	1	Rear spare tire panel lock		

Subtotal :- \$4,206.38

Labour charges

To remove & re-fix cushion

To remove & re-fix reverse sensor

To Check Wiring System

Tuff kote

Panel beating

Spray painting

\$120.00 50

\$120.00 50

\$60.00 30

\$120.00 50

\$600.00 300

\$600.00 400

Subtotal :- \$1,620.00

Total:- \$5,826.38

total: 1819.57.

4/c: 1.4K.

03 Days