

REF: ALH

W

2871F

ASSIGNMENT

From: _____ Date: 09/07/2018

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 169E

at Workshop m/s: Premium

of: 281 Alexander Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) **11am Owner waiting**

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLS 169E Yr Regn: 2016 OCT

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A8 L D4 3.0 TFSI Qu cc 2995

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 43758 T/Radio: Insured / Std / NI / NA

Eng/No: BLACK

C/No: WA4222 4H06N0 151 40

Gen. Cond: Good Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal. 6 mm		R/Bal. 6 mm	
L/Bal. 6 mm		L/Bal. 6 mm	

D.O.A. 23/06/18 D.O.I. 09/07/18

Survey held at: Premium Alexander

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/11/19	Confirm I.B.2 \$18172.28 with 4 working days.

(Red - \$6506.77
26%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1) S-PS: SI _____

2) Photos _____

3) Clean _____

4) _____

TOTAL _____

Add Fee: Site Insp (\$) _____

Interview (\$) _____

Tech. Invs (\$) _____

Weekend (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18012291/wb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-07-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 5928T	Veh. Inspected	SLS 169E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/06/2018	Inspection Date	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0759/2018/PH
Date : 4-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SLA 5928 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tan Yong Hong
Address : 16B Lornie Road

Singapore 298703

Telephone : HP +65 91523300
Type of Claim : THIRD PARTY CLAIM
Policy No. : GA261417/1
Vehicle No : **SLS 169 E**
Model Code : Audi A8L D4 3.0 TFSI QU
Model / Year : Oct-16
Engine No : CRE 003912
Chassis No : WAUZZZ4H0EN015140
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jun-18
Place of Accident : 587 BUKIT TIMAH ROAD CORONATION SHOPPING PLAZA

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 169 E.

FRONT

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	/
2	To dismantle and renew front bumper assy and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,600.00 1200	/
3	To respray front bumper and bonnet	\$ 1,900.00 1600	/
4	To carry out diagnostic check	S/N \$ 192.00	/
TOTAL LABOUR CHARGES - FRONT		: \$ 4,172.00	

Repair
HP 90010068
4 days
09/07/18 @ 1100
Resurvey & paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 169 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,902.00	DE ✓ 2321.60
2	FRONT BUMPER FIXING PART	\$ 422.00	Ne ✓ 314.80
3	FRONT NO. PLATE TRIM	\$ 616.00	SC ✓ → SU
4	RADIATOR GRILLE	\$ 3,080.00	SC ✓ 2464.00
5	FRONT BUMPER GUIDE - LH / RH	2 \$ 90.00	? SU
6	FRONT BUMPER FOAM	\$ 110.00	? CA ✓ 88.00
7	FRONT REINFORCEMENT BEAM	\$ 948.00	? SU
8	FRONT BUMPER TOP COVER	\$ 209.00	plut ✓ 166.00
9	SIGN "CAUTION" STICKER	\$ 12.00	X ne ✓ 9.28
10	AIR CONDITIONAL STICKER	\$ 17.00	X n
11	FRONT PARKING AID SENSOR	\$ 240.00	? SU
12	LED MATRIX HEADLIGHT - LH	\$ 11,536.00	SU ✓ 9228.80
12	FRONT NO. PLATE	S/N \$ 25.00	✓ SU ✓
13	SUNDRIES	net \$ 300.00	? 80.80 ✓
TOTAL SPARE PARTS CHARGES		\$ 20,507.00	
TOTAL LABOUR CHARGES		\$ 4,172.00	
GRAND TOTAL		\$ 24,679.00	

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0759/2018/PH
Date : 4-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.
Your insured vehicle : SLA 5928 T

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul,
4 working days - ok
Carrine 03 Sep 2018

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tan Yong Hong
Address : 16B Lornie Road
Singapore 298703
Telephone : HP +65 91523300
Type of Claim : THIRD PARTY CLAIM
Policy No. : GA261417/1
Vehicle No : **SLS 169 E**
Model Code : Audi A8L D4 3.0 TFSI QU
Model / Year : Oct-16
Engine No : CRE 003912
Chassis No : WAUZZZ4HOEN015140
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jun-18
Place of Accident : 587 BUKIT TIMAH ROAD CORONATION SHOPPING PLAZA

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 169 E .

FRONT

S/n	Nature of Jobs		Estimated Charges		Remarks
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$	480.00
2	To dismantle and renew front bumper assy and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$	1,600.00	\$	1,200.00
3	To respray front bumper and bonnet	\$	1,900.00	\$	1,600.00
4	To carry out diagnostic check	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES - FRONT		:	<u>\$ 4,172.00</u>	\$	<u>3,472.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 169 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,902.00	\$ 2,321.60
2	FRONT BUMPER FIXING PART	\$ 422.00	\$ 314.80
3	FRONT NO. PLATE TRIM	\$ 616.00	
4	RADIATOR GRILLE	\$ 3,080.00	\$ 2,464.00
5	FRONT BUMPER GUIDE - LH / RH	2 \$ 90.00	
6	FRONT BUMPER FOAM	\$ 110.00	\$ 88.00
7	FRONT REINFORCEMENT BEAM	\$ 948.00	
8	FRONT BUMPER TOP COVER	\$ 209.00	\$ 166.00
9	SIGN "CAUTION" STICKER	\$ 12.00	\$ 9.28
10	AIR CONDITIONAL STICKER	\$ 17.00	
11	FRONT PARKING AID SENSOR	\$ 240.00	
12	LED MATRIX HEADLIGHT - LH	\$ 11,536.00	\$ 9,228.80
12	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
13	SUNDRIES	\$ 300.00	\$ 82.80
	TOTAL SPARE PARTS CHARGES	\$ 20,507.00	\$ 14,700.28
	TOTAL LABOUR CHARGES	\$ 4,172.00	\$ 3,472.00
	GRAND TOTAL	\$ 24,679.00	\$ 18,172.28

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018 Edit Reg		09 Jul 2018 00:00 Edit Adj Rpt	S\$18,172.28 Edit Estimates	S\$18,172.28 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Mark Teoh Tsu Yang (Zhao Siyang, ID: S7342940D)		
Main Claimant:	TAN YONG HONG, ID: S0012871F		
Vehicle Reg. No.:	SLS169E	Date of Loss:	23/06/2018 11:00 - :59 [19 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7503247403SG	Policy/Cover Note No.:	2100455388 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA5928T	Policy No. (Claimant):	GA261417/1
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 16/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (08/02/2019): Alert - Adj Mandate Approved (S\$19846.34) - SLS169E - Claim Handler: MdNoor, Nor...
- AIG_SG_EXPRESS (10/12/2018): Alert - Adj Mandate Maintained - SLS169E - Claim Handler: MdNoor, Norsiah

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS169E (7503247403SG)**
[SLA5928T]
TP
TAN YONG HONG
Jun 23 2018 11:00AM
[Mark Teoh Tsu Yang (Zhao Siyang)]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▾
Letters/Correspondences			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On:	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
2	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
3	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
4	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
5	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
6	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
7	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
8	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
9	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
10	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
11	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
12	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
13	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
14	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
15	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
16	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
17	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
18	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
19	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
20	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
21	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
22	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
23	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
24	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
25	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
26	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
27	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
28	06/09/18 09:53	General View	1	Load JPG <input checked="" type="checkbox"/>
29	06/09/18 09:53	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
30	06/09/18 09:53	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
31	06/09/18 09:53	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>
32	06/09/18 09:53	Reinspection Photo	1	Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	06/09/18 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	06/09/18 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/18 16:48	TP GIA REPORT	Load PDF	
2	05/07/18 16:48	TP ESTIMATE	Load PDF	
3	12/07/18 17:36	TP ESTIMATE- MARKED	Load PDF	
4	01/11/18 16:14	GIA SEARCH	Load PDF	
5	01/11/18 16:14	LETTER TO OI	Load PDF	
6	01/11/18 17:13	Email to AIG to seek mandate 1.11.18	Load PDF	
7	23/04/19 10:08	AUTHORISATION TO ACT	Load PDF	
8	23/04/19 10:08	RELEASE VOUCHER	Load PDF	
9	23/04/19 10:08	WORKSHOP INVOICE	Load PDF	
10	23/04/19 10:08	APPROVAL	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/07/18 08:29	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLA5928T (Insd veh)	Model:	AUDI A8 L 3.0 (A)
	SLS169E (TP veh)		
Date of Accident:	23/06/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:		<input checked="" type="checkbox"/>	26,406.53
Final Repair Cost	:		<input checked="" type="checkbox"/>	19,444.34
Loss of Use	:		<input checked="" type="checkbox"/>	400.00
Rental (if any)	:		<input checked="" type="checkbox"/>	4.00 days at \$100.00 per day
LTA / GIA Search Fee	:		<input checked="" type="checkbox"/>	2.00
Others:	:		<input checked="" type="checkbox"/>	
	:		<input checked="" type="checkbox"/>	
Final Settlement Sum	:		<input checked="" type="checkbox"/>	19,846.34

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)			
B) For GIA Registered Workshop:	BOLA Applicable: Yes / No BOLA Scenario No: <u>NIL</u>			
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 19,446.34
2)	TAN YONG HONG	:	\$ 400.00
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

23 Apr
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18012291/R1WB3S2
Date: 23/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100455388
Claimant Vehicle No : SLS169E **Insured Vehicle No :** SLA5928T
 Date of Loss: 23/06/2018 Nature of Claim: TP Claim No: 7503247403SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS169E**
 Make & Model: AUDI A8 L, 3.0 (A) Engine No: CRE003912
 Reg. Date: 25/10/2016 (Man. Year: 2014) Chassis No: WAUZZZ4H0EN015140
 Colour: Black Odometer: 43758 km
 Engine Capacity: 2995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/40R19 Rear Tyre Size: 255/40R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,507.00	14,700.28	5,806.72	28.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,172.00	3,472.00	700.00	16.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,679.00	18,172.28	6,506.72	26.37
+ GST 7.00/7.00% (S\$)	1,727.53	1,272.06	455.47	26.37
Nett Amount (S\$)	26,406.53	19,444.34	6,962.19	26.37
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		19,846.34		

INSPECTION

Date of Assignment: 09/07/2018
 Date Inspected: 09/07/2018 Inspected At: 281 ALEXANDRA ROAD
 Estimated Period of Repair: 4.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: MOHD RASUL

Manager: VIVIAN LAU PEI FENG

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,902.00 FS	*2,321.60 FS
2	1		*FRONT BUMPER FIXING PART	Necessary	422.00 FS	*314.80 FS
3	1		*FRONT NO. PLATE TRIM	Serviceable	616.00 FS	*- FS
4	1		*RADIATOR GRILLE	Scratched	3,080.00 FS	*2,464.00 FS
5	2		*FRONT BUMPER GUIDE - LH/RH	Serviceable	90.00 FS	*- FS
6	1		*FRONT BUMPER FOAM	Cracked	110.00 FS	*88.00 FS
7	1		*FRONT REINFORCEMENT BEAM	Serviceable	948.00 FS	*- FS
8	1		*FRONT BUMPER TOP COVER	Cut	209.00 FS	*166.00 FS
9	1		*SIGN CAUTION STCKER	Necessary	12.00 FS	*9.28 FS
10	1		*AIR CONDITIONAL STICKER	Not Necessary	17.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR	Serviceable	240.00 FS	*- FS
12	1		*LED MAXTRIX HEADLIGHT -LH	Scratched	11,536.00 FS	*9,228.80 FS
13	1		*FRONT NO. PLATE	Scratched	25.00 FS	*25.00 FS
14	1		*SUNDRIES	Necessary	300.00 FS	*82.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	20,507.00	14,700.28
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY AND LHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,600.00	1,200.00
3	TO RESPRAY FRONT BUMPER AND BONNET.	New	1,900.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			4,172.00	3,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >