

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0759/2018/PH
Date : 4-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SLA 5928 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tan Yong Hong
Address : 16B Lornie Road

Singapore 298703
Telephone : HP +65 91523300
Type of Claim : THIRD PARTY CLAIM
Policy No. : GA261417/1
Vehicle No : **SLS 169 E**
Model Code : Audi A8L D4 3.0 TFSI QU
Model / Year : Oct-16
Engine No : CRE 003912
Chassis No : WAUZZZ4H0EN015140
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jun-18
Place of Accident : 587 BUKIT TIMAH ROAD CORONATION SHOPPING PLAZA

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 169 E .

FRONT

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer Assy and front parking aid.	S/N \$ 480.00	
2	To dismantle and renew front bumper Assy and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,600.00	
3	To respray front bumper and bonnet	\$ 1,900.00	
4	To carry out diagnostic check	S/N \$ 192.00	
TOTAL LABOUR CHARGES - FRONT		: \$ 4,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 169 E.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,902.00	
2	FRONT BUMPER FIXING PART	\$ 422.00	
3	FRONT NO. PLATE TRIM	\$ 616.00	
4	RADIATOR GRILLE	\$ 3,080.00	
5	FRONT BUMPER GUIDE - LH / RH	2 \$ 90.00	
6	FRONT BUMPER FOAM	\$ 110.00	
7	FRONT REINFORCEMENT BEAM	\$ 948.00	
8	FRONT BUMPER TOP COVER	\$ 209.00	
9	SIGN "CAUTION" STICKER	\$ 12.00	
10	AIR CONDITIONAL STICKER	\$ 17.00	
11	FRONT PARKING AID SENSOR	\$ 240.00	
12	LED MATRIX HEADLIGHT - LH	\$ 11,536.00	
12	FRONT NO. PLATE	S/N \$ 25.00	
13	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS CHARGES	: \$ 20,507.00	
	TOTAL LABOUR CHARGES	\$ 4,172.00	
	GRAND TOTAL	\$ 24,679.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant