

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 09 Jul 2018

Preliminary Advice

Insured Vehicle No : SLA8883T

TP Vehicle No : SKB6669R

Accident Date : 29/06/2018

Make : HONDA CIVIC

Assignment Date : 05/07/2018

Date of Inspection : 06/07/2018

Est. Duration of Repair : 8.00

Inspection At : ESTEEM PERFORMANCE PTE LTD - SIN MING (HQ)
385 SIN MING DRIVE
SINGAPORE 575718

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,311.12
Revised Amount	:S\$	9,783.20
Check Items (Estimated)	:S\$	12,168.72
Total	:S\$	21,951.92

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.