

ASS. REC. FY

REF: CS/FCI18012297/Kad3n2 Special Instructions

Surveyor
CWS

Kenneth
Lurene Jaw

ASSIGNMENT (Office)

FCI

Date/Time 5/7/18 @ 8:22pm

Estimated Cost:

Bill to

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

XD 3086C

Insured

SHC 722 6J

at Workshop n/e

Cheong Cheong

Tel

648 14152

of

BLK 5032 AMLC Ind. Park 2 # 01-293

Policy No

D-18088937MFSH

Claim No

D18005167MFSH

Sum Insured

Excess

Make of Veh

D.O.A

30/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (OS)

R.O.D. Endorsement

Date/Time 11:04am 05/7/18

Person Contacted

Angela

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XD 3086C-X

SHC 7226J-CC3/FCI13007798/Kyln

DoA 27/09/2012

06/7/18 @ 1:17pm revised to Lurene by email

28/8 11 Lurene @ 30,000 email to confirm (led to 9850, 29%)

26/9/18 re-open ref to amend report to property report.
as requested by insurance officer, Lurene that our inspection
report incomplete. Celine 26/9/18

ASS. REC. BY:

REF: FC21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

X0 3086C

Yr Regn:

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

C.C

Colour:

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/6/18

D.O.I.

5/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/7 File pass to Customer

RECEIVED 10 AUG 2018

Date/Time, File Pass to?

1) 30/8/18

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + P.S. \$

P.S. \$

Others

29x15=435

170.5 435

50

50

18

Report Format:

TP

Lump Sum / L.B.I. (\$

30000

30/8/18

723



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012297/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7226J	Veh. Inspected	XD 3086C
Policy No.		Coverage (\$)	0.00
Claim No.	D18005167MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/06/2018	Inspection Date	05/07/2018
Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Shiau Chan (LKKAUTO)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 25 September 2018 4:33 PM
To: 'Claim Workflow System'; SUR
Cc: assignments
Subject: RE: Request of Survey report-your ref no: 10525/ our Ref: D18005167MFSH;accident involving SHC7226J and XD3086C on 30-06-2018

Dear Sir / Madam,

Thank you for your email.

Dear Shiau Chan,

FYNA. Our Ref: CS/FCI18012297/Kqd3n2

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 25 September, 2018 4:25 PM
To: admin-d@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Cc: cwsmotorclaims@msfirstcapital.com.sg
Subject: Request of Survey report-your ref no: 10525/ our Ref: D18005167MFSH;accident involving SHC7226J and XD3086C on 30-06-2018

Dear Sir,

In submitted LKK inspection report 'Vehicle Particulars & Condition' details are incomplete

Please let us have amended inspection report on urgent basis.

Thanks & Regards,
Motor Claims Department
MS First Capital Insurance Ltd
cwsmotorclaims@msfirstcapital.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005167MFSH

Date: 06 July 2018

Our Ref: CS/FC118012297/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. XD 3086C.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/07/2018 at the premises of M/s CHEONG CHEONG. and have the following to report:-

Workshop Estimate Amount	: S\$ 39,850.00
Revised Estimate Amount	: S\$ 39,500.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-07-2018	Our Ref No. D18005167MFSH
Accident Date	30-06-2018	Claim Type. Third Party
Insured Vehicle	SHC7226J	Third Party Vehicle. XD3086C
Survey Location	BLK 5032 ANG MO KIO IND. PARK 2 #01-293	
Contact Person.	ANGELA NG	
Contact No.	64814152/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEONG CHEONG MOTOR SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242023)


PRI Documents

Close X

PRI Header Details

Claim No	D18005167MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHEONG
Workshop Name	CHEONG CHEONG MOTOR SERVICE PTE LTD (Contact Person : ANGELA NG)	Survey Location & Contact Details	BLK 5032 ANG MO KIO IND. PARK 2 #01-293 Mobile: 0 , Phone: 64814152 , Fax: 0 EmailId: C2MSVC@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7226J	TP Vehicle No	XD3086C
PRI Recieved Date	04-07-2018 05:41:49 PM	Surveyor Appointed Date	04-07-2018 08:21:33 PM	Surveyor Accept Date	05-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-07-2018	Upload Survey Report *:	Choose File
-----------------------------	---	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

63656101

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 July 2018 1:17 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005167MFSH/1
Attachments: CSFCI18012297Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of XD 3086C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 5 July 2018 11:08 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005167MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 July 2018 8:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005167MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7040E

Vehicle Details

Vehicle No.: XD3086C

Vehicle to be Exported: No

Intended De-registration Date: 06 Jul 2018

Vehicle Make: MITSUBISHI

Vehicle Model: FV51JJD4RDEA

Primary Colour: White

Manufacturing Year: 2008

Engine No.: 6M70421988

Chassis No.: FV51JJA00355

Maximum Power Output: -

Open Market Value: \$83,388.00

Original Registration Date: 19 Sep 2008

First Registration Date: 19 Sep 2008

Transfer Count: 2

Actual ARF Paid: \$4,170.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Jul 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$17,035.00

COE Rebate Amount: \$13,856.00

Total Rebate Amount: \$13,856.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Jul 2018

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	XD3086C
Vehicle Type:	B33 - Goods (Open) Tipper/Dumper Truck
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JJD4RDEA
Chassis No.:	FV51JJA00355
Propellant:	Diesel
Engine No.:	6M70421988
Engine Capacity:	12882 cc
Maximum Power Output:	-
Maximum Laden Weight:	28000 kg
Unladen Weight:	11060 kg
Year Of Manufacture:	2008
Original Registration Date:	19 Sep 2008
Lifespan Expiry Date:	18 Sep 2028
COE Category:	C - Goods Vehicle & Bus
PQP Paid:	\$17,035.00
COE Expiry Date:	31 Jul 2022
Road Tax Expiry Date:	24 Jul 2018
Inspection Due Date:	24 Jan 2019
Intended Transfer Date:	06 Jul 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 24 Jul 2018. You may renew the road tax from 25 Apr 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 25 Jul 2018 to 24 Jan 2019)

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	199.00	-	199.00
Total Amount Payable:			224.00

Amount Payable (From 25 Jul 2018 to 24 Jul 2019)

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	410.00	-	410.00
Total Amount Payable:			435.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

You may print this page for reference.

OK

Print

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 0592/07/2018

Page : 1

Date : 05/07/2018

M/S : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Not Notified
11 Pm @ 30,000
Survey After Paint

ACCIDENT REPAIR ON : XD 3086 C - MITSUBISHI FV51JJD4RDEA
CHASSIS NO
DATE OF ACCIDENT : 30/06/2018

7 days

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

- 1 ONE UNIT TRUCK-MOUNTED ATTENUATOR
- 2 ONE SET STICKER

Prt S/NETT
S/NETT

S\$ S\$
R 38,000.00
u 250.00
38,250.00

36000

LABOUR CHARGES :

- 3 STRIP / REFIT TMA & CRANE SERVICE & CHECKING WIRING
- 4 TOUCH-UP PAINT ON ACCIDENT AFFECTED AREAS

1,000.00 *800*
600.00 *450*
39,850.00



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012297/Kqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7226J	Veh. Inspected	XD 3086C
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18005167MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/06/2018	Inspection Date	05/07/2018
Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg No: 199607198R GST Reg No: 10-9607198-R

Page No: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 3086C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	ONE UNIT TRUCK-MOUNTED ATTENUATOR (SN)	BENT	38,000.00	36,000.00
1	ONE SET STICKER (SN)	NECESSARY	250.00	250.00
			38,250.00	36,250.00
	LABOUR			
	STRIP/REFIT TMA & CRANE SERVICE & CHECKING WIRING		1,000.00	800.00
	TOUCH-UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	450.00
			1,600.00	1,250.00
	GRAND TOTAL		39,850.00	37,500.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			30,000.00

Report Ref No. CS/FC118012297/Kqd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



Your Ref : D18005167MFSH

Date : 01st October 2018

Our Ref : CS/FCI18012297/Kqd3n2

M/s First Capital Insurance Ltd

36 ROBINSON ROAD

#16-01 CITY HOUSE

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

INSPECTION REPORT OF VEHICLE NO: XD 3086C

INSURED VEHICLE: SHC 7226J

ACCIDENT DATE: 30/06/2018

We submit herewith our recommendation below:

<u>Qty</u>	<u>Description of Parts</u>	<u>Estimate</u>	<u>Recommendation</u>
1	One unit Truck-Mounted Attenuator (SN)	\$38,000.00	\$36,000.00
2	One Set Sticker (SN)	\$ 250.00	\$ 250.00
<u>Labour Charges</u>			
	Strip/refit TMA & Crane Service & checking wiring.	\$1,000.00	\$ 800.00
	Touch-up Paint On Accident Affected Areas..	\$ 600.00	\$ 450.00
		<u>\$39,850.00</u>	<u>\$37,500.00</u>
	Recommended Cost of Lump Sum Repair (To Its Pre-Accident Condition)		<u>\$30,000.00</u>

(SIN DOLLARS: Thirty Thousand Only)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

We recommend that the repairs of the entire damage require about Seven working days to complete.

Vehicle Inspected By:

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.