

ASS. REC. BY:

REF: CS/FCI18012298 / R1d3 | n2
Special Instruction:

Surveyor:

RWS

Rasu

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

4/7/18 @ 7:27pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 5310T

Insured:

SHD 8579D

at Workshop in/s

Mura Automotive

Tel:

62723892

of Blk 1008, Bkt Meruh Lane 3 # 01-04

Policy No:

Claim No:

DIB 005200 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 01/07/2018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

10:56am 05/7/18

Person Contacted:

Nifha

Vehicle-IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKN 5310T-CC4/AXA17001334/T1p43q2 DOA: 19/01/2017
	SHD 8579D-X
	lump sum \$12507 (red: 741; 37%)

Signature: *[Signature]*

REF:


1035B

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *19K*
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SKN 5310T* Yr Regn: *2009 / MAR*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *TOYOTA CAMRY 2.0 A* c.c. *1998*
 Colour: *GOLD* A/C: Insured / Std / NI / NA
 Sp. Reading: *155395* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *MR053BK4107043316*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: *Order* / Jammed / Leaked / Burnt or
 Brake: *Order* / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____
 R: *215/60 R16*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *NEXEN*

Front	Rear
R/Bal. <i>6</i> mm	R/Bal. <i>6</i> mm
L/Bal. <i>6</i> mm	L/Bal. <i>6</i> mm
D.O.A. <i>01/07/18</i>	D.O.I. <i>12/07/18</i>

Survey held at *MOVA (Bm)*

Des. of Damages: Frt *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

refer to email furnished about counter

RECEIVED 18 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

18/7 Typist
 Date/Time, File Return to?

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: *TP*

Lump Sum / I.B.I: (\$ *1250/-*)

100
50
33

183

MOTOR SURVEY ASSIGNMENT

Date	04-07-2018	Our Ref No.	D18005200MFSH
Accident Date	01-07-2018	Claim Type.	Third Party
Insured Vehicle	SHD8579D	Third Party Vehicle.	SKN5310T
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08		
Contact Person.	NITHA		
Contact No.	62723892/ 0	Fax No.	62708314
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242080)



PRI Documents



Close



PRI Header Details

Claim No	D18005200MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & MOVA AU
Workshop Name	MOVA AUTOMOTIVE PTE LTD (Contact Person : NITHA)	Survey Location & Contact Details	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 Mobile: 0 , Phone: 62723892 , Fax: 62708314 EmailId: NITHA@MOVA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8579D	TP Vehicle No	SKN5310T
PRI Recieved Date	04-07-2018 08:45:12 PM	Surveyor Appointed Date	04-07-2018 07:26:16 PM	Surveyor Accept Date	05-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST STAR INSURANCE LTD

Ref : CS/FCI18012298/R1td3

36 ROBINSON ROAD

#16-01 CITY HOUSES SINGAPORE 068877

Date : 05-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

SHD 8579D	Veh. Inspected	SKN 5310T
	Coverage (\$)	0.00
D18005200MFSH	Excess (\$)	0.00
CWS (LURENE JAW)	Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Model	c.c	0
HIDDEN	Year of Reg.	
	Colour	
	Steering	
	Modification	

3. Conditions of Tyres

Size	Make	Balance
		mm
		mm
		mm
		mm

4. Description of Damages

--

5. General Information

01/07/2018	Inspection Date	12/07/2018
MOVA AUTOMOTIVE PTE LTD		
BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08		
SINGAPORE 159722		

6. Remarks

INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. AND TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Rasul (LKKAuto)

From: Jacelyn <jacelyn@movacom.sg>
Sent: Monday, 16 July, 2018 12:41 PM
To: Rasul (LKKAuto)
Subject: RE: SKN5310T - TP/FCI - TOYOTA CAMRY 2.0 A (DOA 01.07.2018)
Attachments: IMG20180714155444.jpg; IMG20180714155433.jpg; IMG20180714155438.jpg

Dear Rasul,

Finalize confirmed at \$1,250.00.

Best Regards,
Jacelyn Ooi
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, 16 July 2018 10:50 AM
To: Jacelyn
Subject: RE: SKN5310T - TP/FCI - TOYOTA CAMRY 2.0 A (DOA 01.07.2018)

Hi Jacelyn,

Refer to attachment
Finalise amount is \$ 1,250.00 / 3 days lump sum
Kindly confirm

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Jacelyn [<mailto:jacelyn@movacom.sg>]
Sent: Thursday, 12 July, 2018 11:09 AM
To: Rasul (LKKAuto)
Subject: SKN5310T - TP/FCI - TOYOTA CAMRY 2.0 A (DOA 01.07.2018)

Dear Rasul,

Please find the attached photograph for your reference.

Best Regards,
Jacelyn Ooi
Estimator
Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1035B
Vehicle Details	
Vehicle No.:	SKN5310T
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	1AZE131192
Chassis No.:	MR053BK4107043316
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$25,948.00
Original Registration Date:	30 Mar 2009
First Registration Date:	30 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$25,948.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2019
PARF Rebate Amount:	\$12,974.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$4,889.00
COE Rebate Amount:	\$343.00
Total Rebate Amount:	\$13,317.00

The information contained herein is correct as at 16 Jul 2018

OK

$$\begin{array}{r} 19,000 \\ 13,317 \\ \hline 5,683 \end{array}$$

(5k)

Driving License

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S76110358

NAME: TENG SIOU SONG (DENG SHAOXIONG)

DATE OF BIRTH: 12 MAY 1975

DATE OF ISSUE: 04 JAN 2000

CHINESE 100220



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S76110358

NAME: TENG SIOU SONG (DENG SHAOXIONG)

CHINESE 丁少雄

DATE OF BIRTH: 12-05-1975

DATE OF ISSUE: 04 JAN 2000



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class A Motor Cars and Motor Tractors, the weight of which exceeds that referred to in Class B

CLASS B

CLASS C

CLASS D

CLASS E

CLASS F

CLASS G

CLASS H

CLASS I

CLASS J

CLASS K

CLASS L

CLASS M

CLASS N

CLASS O

CLASS P

CLASS Q

CLASS R

CLASS S

CLASS T

CLASS U

CLASS V

CLASS W

CLASS X

CLASS Y

CLASS Z

CLASS AA

CLASS AB

CLASS AC

CLASS AD

CLASS AE

CLASS AF

CLASS AG

CLASS AH

CLASS AI

CLASS AJ

CLASS AK

CLASS AL

CLASS AM

CLASS AN

CLASS AO

CLASS AP

CLASS AQ

CLASS AR

CLASS AS

CLASS AT

CLASS AU

CLASS AV

CLASS AW

CLASS AX

CLASS AY

CLASS AZ

CLASS BA

CLASS BB

CLASS BC

CLASS BD

CLASS BE

CLASS BF

CLASS BG

CLASS BH

CLASS BI

CLASS BJ

CLASS BK

CLASS BL

CLASS BM

CLASS BN

CLASS BO

CLASS BP

CLASS BQ

CLASS BR

CLASS BS

CLASS BT

CLASS BU

CLASS BV

CLASS BV

CLASS BW

CLASS BX

CLASS BY

CLASS BZ

CLASS CA

CLASS CB

CLASS CC

CLASS CD

CLASS CE

CLASS CF

CLASS CG

CLASS CH

CLASS CI

CLASS CJ

CLASS CK

CLASS CL

CLASS CM

CLASS CN

CLASS CO

CLASS CP

CLASS CQ

CLASS CR

CLASS CS

CLASS CT

CLASS CU

CLASS CV

CLASS CW

CLASS CX

CLASS CY

CLASS CZ

CLASS DA

CLASS DB

CLASS DC

CLASS DD

CLASS DE

CLASS DF

CLASS DG

CLASS DH

CLASS DI

CLASS DJ

CLASS DK

CLASS DL

CLASS DM

CLASS DN

CLASS DO

CLASS DP

CLASS DQ

CLASS DR

CLASS DS

CLASS DT

CLASS DU

CLASS DV

CLASS DW

CLASS DX

CLASS DY

CLASS DZ

CLASS EA

CLASS EB

CLASS EC

CLASS ED

CLASS EE

CLASS EF

CLASS EG

CLASS EH

CLASS EI

CLASS EJ

CLASS EK

CLASS EL

CLASS EM

CLASS EN

CLASS EO

CLASS EP

CLASS EQ

CLASS ER

CLASS ES

CLASS ET

CLASS EU

CLASS EV

CLASS EW

CLASS EX

CLASS EY

CLASS EZ

CLASS FA

CLASS FB

CLASS FC

CLASS FD

CLASS FE

CLASS FF

CLASS FG

CLASS FH

CLASS FI

CLASS FJ

CLASS FK

CLASS FL

CLASS FM

CLASS FN

CLASS FO

CLASS FP

CLASS FQ

CLASS FR

CLASS FS

CLASS FT

CLASS FU

CLASS FV

CLASS FW

CLASS FX

CLASS FY

CLASS FZ

CLASS GA

CLASS GB

CLASS GC

CLASS GD

CLASS GE

CLASS GF

CLASS GG

CLASS GH

CLASS GI

CLASS GJ

CLASS GK

CLASS GL

CLASS GM

CLASS GN

CLASS GO

CLASS GP

CLASS GQ

CLASS GR

CLASS GS

CLASS GT

CLASS GU

CLASS GV

CLASS GW

CLASS GX

CLASS GY

CLASS GZ

CLASS HA

CLASS HB

CLASS HC

CLASS HD

CLASS HE

CLASS HF

CLASS HG

CLASS HH

CLASS HI

CLASS HJ

CLASS HK

CLASS HL

CLASS HM

CLASS HN

CLASS HO

CLASS HP

CLASS HQ

CLASS HR

CLASS HS

CLASS HT

CLASS HU

CLASS HV

CLASS HW

CLASS HX

CLASS HY

CLASS HZ

CLASS IA

CLASS IB

CLASS IC

CLASS ID

CLASS IE

CLASS IF

CLASS IG

CLASS IH

CLASS II

CLASS IJ

CLASS IK

CLASS IL

CLASS IM

CLASS IN

CLASS IO

CLASS IP

CLASS IQ

CLASS IR

CLASS IS

CLASS IT

CLASS IU

CLASS IV

CLASS IW

CLASS IX

CLASS IY

CLASS IZ

CLASS JA

CLASS JB

CLASS JC

CLASS JD

CLASS JE

CLASS JF

CLASS JG

CLASS JH

CLASS JI

CLASS JJ

CLASS JK

CLASS JL

CLASS JM

CLASS JN

CLASS JO

CLASS JP

CLASS JQ

CLASS JR

CLASS JS

CLASS JT

CLASS JU

CLASS JV

CLASS JW

CLASS JX

CLASS JY

CLASS JZ

CLASS KA

CLASS KB

CLASS KC

CLASS KD

CLASS KE

CLASS KF

CLASS KG

CLASS KH

CLASS KI

CLASS KJ

CLASS KK

CLASS KL

CLASS KM

CLASS KN

CLASS KO

CLASS KP

CLASS KQ

CLASS KR

CLASS KS

CLASS KT

CLASS KU

CLASS KV

CLASS KW

CLASS KX

CLASS KY

CLASS KZ

CLASS LA

CLASS LB

CLASS LC

CLASS LD

CLASS LE

CLASS LF

CLASS LG

CLASS LH

CLASS LI

CLASS LJ

CLASS LK

CLASS LL

CLASS LM

CLASS LN

CLASS LO

CLASS LP

CLASS LQ

CLASS LR

CLASS LS

CLASS LT

CLASS LU

CLASS LV

CLASS LW

CLASS LX

CLASS LY

CLASS LZ

CLASS MA

CLASS MB

CLASS MC

CLASS MD

CLASS ME

CLASS MF

CLASS MG

CLASS MH

CLASS MI

CLASS MJ

CLASS MK

CLASS ML

CLASS MM

CLASS MN

CLASS MO

CLASS MP

CLASS MQ

CLASS MR

CLASS MS

CLASS MT

CLASS MU

CLASS MV

CLASS MW

CLASS MX

CLASS MY

CLASS MZ

CLASS NA

CLASS NB

CLASS NC

CLASS ND

CLASS NE

CLASS NF

CLASS NG

CLASS NH

CLASS NI

CLASS NJ

CLASS NK

CLASS NL

CLASS NM

CLASS NN

CLASS NO

CLASS NP

CLASS NQ

CLASS NR

CLASS NS

CLASS NT

CLASS NU

CLASS NV

CLASS NW

CLASS NX

CLASS NY

CLASS NZ

CLASS OA

CLASS OB

CLASS OC

CLASS OD

CLASS OE

CLASS OF

CLASS OG

CLASS OH

CLASS OI

CLASS OJ

CLASS OK

CLASS OL

CLASS OM

CLASS ON

CLASS OO

CLASS OP

CLASS OQ

CLASS OR

CLASS OS

CLASS OT

CLASS OU

CLASS OV

CLASS OW

CLASS OX

CLASS OY

CLASS OZ

CLASS PA

CLASS PB

CLASS PC

CLASS PD

CLASS PE

CLASS PF

CLASS PG

CLASS PH

CLASS PI

CLASS PJ

CLASS PK

CLASS PL

CLASS PM

CLASS PN

CLASS PO

CLASS PP

CLASS PQ

CLASS PR

CLASS PS

CLASS PT

CLASS PU

CLASS PV

CLASS PW

CLASS PX

CLASS PY

CLASS PZ

CLASS QA

CLASS QB

CLASS QC

CLASS QD

CLASS QE

CLASS QF

CLASS QG

CLASS QH

CLASS QI

CLASS QJ

CLASS QK

CLASS QL

CLASS QM

CLASS QN

CLASS QO

CLASS QP

CLASS QQ

CLASS QR

CLASS QS

CLASS QT

CLASS QU

CLASS QV

CLASS QW

CLASS QX

CLASS QY

CLASS QZ

CLASS RA

CLASS RB

CLASS RC

CLASS RD

CLASS RE

CLASS RF

CLASS RG

CLASS RH

CLASS RI

CLASS RJ

CLASS RK

CLASS RL

CLASS RM

CLASS RN

CLASS RO

CLASS RP

CLASS RQ

CLASS RR

CLASS RS

CLASS RT

CLASS RU

CLASS RV

CLASS RW

CLASS RX

CLASS RY

CLASS RZ

CLASS SA

CLASS SB

CLASS SC

CLASS SD

CLASS SE

CLASS SF

CLASS SG

CLASS SH

CLASS SI

CLASS SJ

CLASS SK

CLASS SL

CLASS SM

CLASS SN

CLASS SO

CLASS SP

CLASS SQ

CLASS SR

CLASS SS

CLASS ST

CLASS SU

CLASS SV

CLASS SW

CLASS SX

CLASS SY

CLASS SZ

CLASS TA

CLASS TB

CLASS TC

CLASS TD

CLASS TE

CLASS TF

CLASS TG

CLASS TH

CLASS TI

CLASS TJ

CLASS TK

CLASS TL

CLASS TM

CLASS TN

CLASS TO

CLASS TP

CLASS TQ

CLASS TR

CLASS TS

CLASS TT

CLASS TU

CLASS TV

CLASS TW

CLASS TX

CLASS TY

CLASS TZ

CLASS UA

CLASS UB

CLASS UC

CLASS UD

CLASS UE

CLASS UF

CLASS UG

CLASS UH

CLASS UI

CLASS UJ

CLASS UK

CLASS UL

CLASS UM

CLASS UN

CLASS UO

CLASS UP

CLASS UQ

CLASS UR

CLASS US

CLASS UT

CLASS UY

CLASS UZ

CLASS VA

CLASS VB

CLASS VC

CLASS VD

CLASS VE

CLASS VF

CLASS VG

CLASS VH

CLASS VI

CLASS VJ

CLASS VK

CLASS VL

CLASS VM

CLASS VN

CLASS VO

CLASS VP

CLASS VQ

CLASS VR

CLASS VS

CLASS VT

CLASS VU

CLASS VV

CLASS VW

CLASS VX

CLASS VY

CLASS VZ

CLASS WA

CLASS WB

CLASS WC

CLASS WD

CLASS WE

CLASS WF

CLASS WG

CLASS WH

CLASS WI

CLASS WJ

CLASS WK

CLASS WL

CLASS WM

CLASS WN

CLASS WO

CLASS WP

CLASS WQ

CLASS WR

CLASS WS

CLASS WT

CLASS WU

CLASS WV

CLASS WW

CLASS WX

CLASS WY

CLASS WZ

CLASS XA

CLASS XB

CLASS XC

CLASS XD

CLASS XE

CLASS XF

CLASS XG

CLASS XH

CLASS XI

CLASS XJ

CLASS XK

CLASS XL

CLASS XM

CLASS XN

CLASS XO

CLASS XP

CLASS XQ

CLASS XR

CLASS XS

CLASS XT

CLASS XU

CLASS XV

CLASS XW

CLASS XX

CLASS XY

CLASS XZ

CLASS YA

CLASS YB

CLASS YC

CLASS YD

CLASS YE

CLASS YF

CLASS YG

CLASS YH

CLASS YI

CLASS YJ

CLASS YK

CLASS YL

CLASS YM

CLASS YN

CLASS YO

CLASS YP

CLASS YQ

CLASS YR

CLASS YS

CLASS YT

CLASS YU

CLASS YV

CLASS YW

CLASS YX

CLASS YY

CLASS YZ

CLASS ZA

CLASS ZB

CLASS ZC

CLASS ZD

CLASS ZE

CLASS ZF

CLASS ZG

CLASS ZH

CLASS ZI

CLASS ZJ

CLASS ZK

CLASS ZL

CLASS ZM

CLASS ZN

CLASS ZO

CLASS ZP

CLASS ZQ

CLASS ZR

CLASS ZS

CLASS ZT

CLASS ZU

CLASS ZV

CLASS ZW

CLASS ZX

CLASS ZY

CLASS ZZ

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S76110358

NAME: TENG SIOU SONG (DENG SHAOXIONG)

CHINESE 丁少雄

DATE OF BIRTH: 12-05-1975

DATE OF ISSUE: 04 JAN 2000



Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0068864-2

Estimate

04/07/2018

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01 City House

Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SKN5310T

Veh Model :- TOYOTA CAMRY

Estimate# :- CK417662

Claim # :- TP/132012

ACC. Date :- 01/07/18

Terms :- C.O.D Days

Remarks :- MFA 30 MAR 2019 (2019)

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BUMPER	1	PC	695.00	695.00
2.	REAR BUMPER REFLECTOR LH	1	PC	48.00	48.00
3.	REAR BUMPER REINFORCEMENT	1	PC	395.00	395.00
4.	REAR BUMPER CLIPS	10	PC	5.00	50.00
5.	END PANEL - REPAIR	1	PC		

LIST TOTAL S\$

25% DISCOUNT S\$

1,188.00

-297.00

891.00

SPECIAL NET ITEMS :

1.	REVERSE SENSOR	1	PC	220.00	220.00
----	----------------	---	----	--------	--------

SPECIAL NET TOTAL S\$

220.00

LABOUR :

TO REMOVE & REIT REVERSE SENSOR & DIAGNOSE
FUCNTION

TO KNOCK & STRAIGHTEN ON END PANEL. TO
REPLACE DAMAGED ITEMS. REALIGN CONNECTION

TO SPRAY PAINT ON REPAIRED AREAS

LABOUR TOTAL S\$

80.00

400.00

400.00

880.00

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp
Signature:
Date:

MOVA AUTOMOTIVE PTE LTD

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 1,991.00

GST @ 7 % 139.37

AMOUNT DUE S\$ 2,130.37

855

710

1565

2020

1252

45-1,250

3 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012298/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8579D	Veh. Inspected	SKN 5310T	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005200MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053BK4107043316	Colour	GOLD	
Odometer	155395	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	NEXEN	6 mm	
L/H Front Tyre	215/60 R16	NEXEN	6 mm	
R/H Rear Tyre	215/60 R16	NEXEN	6 mm	
L/H Rear Tyre	215/60 R16	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2018	Inspection Date	12/07/2018	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 5310T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	695.00	695.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	48.00	-
1	REAR BUMPER REINFORCEMENT	BENT	395.00	395.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-297.00	-285.00
			891.00	855.00
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-
	LABOUR			
	TO REMOVE & REFIT REVERSE SENSOR & DIAGNOSE FUNCTION.		80.00	60.00
	TO KNOCK & STRAIGHTEN ON END PANEL TO REPLACE DAMAGED ITEMS.REALIGN CONNECTION.INCLUSIVE OF THE REPAIR OF END PANEL.		400.00	300.00
	TO SPRAY PAINT ON REPAIRED AREAS.		400.00	350.00
			880.00	710.00
	GRAND TOTAL		1,991.00	1,565.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CS/FCI18012298/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.