

22/03/2010

SS. REC. BY:

REF: CS/FCI 18012299/71sd3/172

Special Instruction:

Surveyor
CWS

From (Person):

Tayyib
Lure juw

ASSIGNMENT (Office)

of FCI

Date/Time: 01/07/18 @ 7:04pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLQ 259SE

Insured:

SHA 9808C

at Workshop n/s:

Wealthes

Tel:

9129 4556

of

249 Alexandra Road

Policy No:

Claim No:

D18005136 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time: 10:34am 05/7/18

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 259SE -x
	SHA 9808C - 3/AIG 14009131 / Sun 3y2
23/07/18 @ 13:45 p.m	revised PA to Lure via email.

D.O.A: 10/05/2014

(08/11/13) wef

ASS. REC. BY: Tan

REF: FCI

ASSIGNMENT

From:

Date: 18/7/18

Estimated Cost:

On: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLQ 2595E

at Workshop m/s

Wearnes

of

249 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Before 2pm

Make of Veh:

Michelle

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 2595E

Yr Regn:

2017, June

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Megane

c.c.

1461

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 15K17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

Rear

R/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

18/7/18 & 1045

Survey held at

Wearnes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No Key

(\$ 5,092.29 Red - 57%)

RECEIVED 23 AUG 2018

Date/Time, File Pass to?

23/08/18

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ 3,899.81 p/p)

160
50
50
29
289



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005136MFSH

Date: 23 July 2018

Our Ref: CS/FCI18012299/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 2595E.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/07/2018 at the premises of M/s Wearnes Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 8,992.10 .
Revised Estimate Amount	: S\$ 3,970.90 .
"Check" Items Amount	: S\$.
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	02-07-2018	Our Ref No. D18005136MFSH
Accident Date	30-06-2018	Claim Type. Third Party
Insured Vehicle	SHA9808C	Third Party Vehicle. SLQ2595E
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	MICHELLE ONG	
Contact No.	0/ 91294556	Fax No. 62647137
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241981)



PRI Documents



Close



PRI Header Details

Claim No	D18005136MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : MICHELLE ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 91294556 , Phone: 0 , Fax: 62647137 EmailId: MICHELLE.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9808C	TP Vehicle No	SLQ2595E
PRI Recieved Date	04-07-2018 05:33:10 PM	Surveyor Appointed Date	04-07-2018 07:03:40 PM	Surveyor Accept Date	05-07-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012299/T1sd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9808C	Veh. Inspected	SLQ 2595E
Policy No.		Coverage (\$)	0.00
Claim No.	D18005136MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/06/2018	Inspection Date	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 23 July 2018 1:45 PM
To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'
Cc: 'SUR'; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18005136MFSH/1
Attachments: SLQ 2595E - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLQ 2595E.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 5 July 2018 10:36 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'SUR' <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005136MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 4 July 2018 7:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005136MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SERVICE ESTIMATE

90339 - C00001 SL: SERVICE SALES - PC
 Mr Fazrul Ismail Malsa Bin Abdul Malek
 Blk 426 Jurong West Avenue 1
 #03-334

Singapore 640426

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Fazrul Ismail Mal

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 03/07/2018
 WIP No. . : 14397
 Veh.In/Out:
 *Tel.No. . : Mobile: 96974519
 Reg.No. . : SLQ2595E
 Reg.date . : 30/06/2017
 Mileage .. : 0
 Chassis No: VF1RFB00957527713

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER,	0	1800.00	0	1,800.00	S	1350
REAR BUMPER,ETC							
800	TO PUTTY SPRAY PAINT ON REAR	0	1200.00	0	1,200.00	S	800
BUMPER,REAR LH FENDER,ETC							450
802	TO REMOVE & INSTALL INTERIOR P	0	900.00	0	900.00	S	✓
0031	TO REPLACE REAR LH RIM	0	50.00	0	50.00	S	✓
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0	280.00	S	✓
280	TO CHECK WIRING INCLUDE	0	330.00	0	330.00	S	✓
RESETTING OF ALL ELECTRICAL							
MODULES							
	ALLOY RIM 7 XJ 1 M4S	1.0 EA	591.80		591.80	S	cut ✓ 532.62
	TYRE PRESSURE SENSOR	1.0 EA	119.10		119.10	S	✓ 107.19
	FENDER REAR LH M4S	1.0 EA	1539.00		1,539.00	S	RY
	QTR GLASS LH	1.0 EA	269.40		269.40	S	X } X
	WINDSCREEN REAR	1.0 EA	633.20		633.20	S	X } nn
	PRIMER	1.0 EA	176.60		176.60	S	X
	WINDSCREEN SEALANT	2.0 EA	112.10		224.20	S	X

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Tanpin 97195744

WP

5 days

Sum @ lkkauto.com

18/7/18 @ 1045

Resurvey after repair

[Signature]
 23/7/18

SERVICE ESTIMATE

90339 - C00001 SL: SERVICE SALES - PC

Mr Fazrul Ismail Malsa Bin Abdul Malek
Blk 426 Jurong West Avenue 1
#03-334

Singapore 640426

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 03/07/2018

WIP No. . : 14397

Veh.In/Out:

*Tel.No. . : Mobile: 96974519

Reg.No. . : SLQ2595E

Reg.date. : 30/06/2017

Mileage . : 0

Chassis No: VF1RFB00957527713

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Fazrul Ismail Mal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	BODY PANEL SEALANT X	1.0 EA	878.80			878.80 S	X h7
--	----------------------	--------	--------	--	--	----------	------

Gross Total. 8,992.10

Labour Total 4,560.00
Parts Total 4,432.10
Package Total 0.00

Net..... 8,992.10
GST @ 7.0% 629.45
Total..... 9,621.55
Paid..... 0.00
Please Pay.. 9,621.55

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date. : 02/08/2018
 WIP No. : 14397
 Veh.In/Out: 23/07/2018 27/07/2018
 *Tel.No. :
 Reg.No. : SLQ2595E
 Reg.date : 30/06/2017
 Mileage : 15,271
 Chassis No: VF1RF800957527713

Closed by : Michelle Ong Siew Be
 Svc Consultant : ACC
 Remarks : Mr Fazrul Ismail Mal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER,	0	1350.00	0		1,350.00	S ✓
	REAR BUMPER,ETC						
800	TO PUTTY SPRAY PAINT ON REAR	0	800.00	0		800.00	S ✓
	BUMPER,REAR LH FENDER,ETC						
802	TO REMOVE & INSTALL INTERIOR P	0	450.00	0		450.00	S ✓
0031	TO REPLACE REAR LH RIM	0	50.00	0		50.00	S ✓
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S ✓
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S ✓
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	① ALLOY RIM 7 XJ 1 M4S	1.0 EA	591.80	10		532.62	S
	② TYRE PRESSURE SENSOR	1.0 EA	119.10	10		107.19	S

Gross Total. 3,899.81

Labour Total 3,260.00
 Parts Total 639.81
 Package Total 0.00

Net..... 3,899.81
 GST @ 7.0% 272.99
 Total..... 4,172.80
 Paid..... 0.00
 Please Pay.. 4,172.80

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Veron Chen (LKKAuto)

From: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Sent: Saturday, 4 August 2018 10:12 AM
To: Taufikh (LKKAuto); SUR
Subject: FINAL BILL for SLQ2595E
Attachments: SLQ2595E.pdf; HBPP4309.JPG; IMG_9203.JPG; IMG_9204.JPG; SHTE7273.JPG

Dear Taufikh,

Please refer to Final Bill as attached.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012299/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9808C	Veh. Inspected	SLQ 2595E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005136MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT MEGANE	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1RFB00957527713	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R15	MICHELIN	6 mm	
L/H Front Tyre	205/50 R15	MICHELIN	6 mm	
R/H Rear Tyre	205/50 R15	MICHELIN	6 mm	
L/H Rear Tyre	205/50 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/06/2018	Inspection Date	18/07/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2595E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	ALLOY RIM 7 XJ 1 M4S (SN)	CUT	591.80	532.62
1	TYRE PRESSURE SENSOR (SN)	NECESSARY	119.10	107.19
1	FENDER REAR LH M4S (SN)	TO REPAIR SEE LABOUR	1,539.00	-
1	QTR GLASS LH (SN)	NOT NECESSARY	269.40	-
1	WINDSCREEN REAR (SN)	NOT NECESSARY	633.20	-
1	PRIMER (SN)	NOT NECESSARY	176.60	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	224.20	-
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	878.80	-
			4,432.10	639.81
	LABOUR			
	TO REPLACE REAR LH FENDER, REAR BUMPER, ETC. INCLUSIVE OF THE REPAIR OF FENDER REAR LH M4S.		1,800.00	1,350.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER, REAR LH FENDER, ETC.		1,200.00	800.00
	TO REMOVE & INSTALL INTERIOR P.		900.00	450.00
	TO REPLACE REAR LH RIM.		50.00	50.00
	COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES.		330.00	330.00
			4,560.00	3,260.00
GRAND TOTAL			8,992.10	3,899.81
RECOMMENDED COST OF REPAIRS				3,899.81

Report Ref No. CS/FCI18012299/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.