

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 04 July 2018

Third Party Insurer: INDIA

Vehicle No: SLK3923S

Third Party Veh No: XE1986M

Model: TOYOTA AQUA HYBRID 1.5S A

Date of Accident: '03 JULY 2018

Chassis: NHP102573320

*Not Authorized
Runna Bepain
4 days*

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER		CR \$408.31
1	REAR BUMPER SIDE REATINER RH		DR \$68.28
8	REAR BUMPER CLIP	\$5.78	AN \$46.24
1	REAR BUMPER INNER SIDE SHIELD RH		\$124.00
1	REAR FENDER RH		R \$629.70
1	REAR FENDER AIR VENT RH		SN \$124.50
1	REAR TAILLAMP LOWER BRACKET RH		\$42.51
1	REAR WHEEL HUB CAP 15"		NE \$188.90
SUB TOTAL			\$1,632.44
Less 25%			-\$408.11
PARTS TOTAL			\$1,224.33

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TYRE RH - 175/65R15 84H		\$280.00
S/N TOTAL			\$280.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$1,200.00 *5000*

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$800.00 *4000*

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

\$250.00 *?*

LABOUR TOTAL \$2,250.00

WINSON

TOTAL \$3,754.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1

Acknowledged by Repairer
Signature:
Date: