



WEARNES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SERVICE ESTIMATE

72599 - C00001 SL: SERVICE SALES - PC

Mr Wang Wang Zeya
33 Lloyd Road
#01-05

Singapore 239106

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 18/09/2018

WIP No. : 14295

Veh.In/Out:

*Tel.No. : Mobile: 92315716

Reg.No. : SKK5678Z

Reg.date : 25/01/2013

Mileage : 0

Chassis No: SALLSAG5DA791391

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Wang Zeya

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT BUMPER, ETC	0	2400.00	0		2,400.00	\$ 1200
800	TO PUTTY SPRAYPAINT ON FRT BUMPER, ETC	0	2000.00	0		2,000.00	\$ 1000
R06	FRT NUMBER PLATE & HOLDER	0	60.00	0		60.00	\$ 30
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	\$ 243
	BUMPER FRT RRS2 5.0S	1.0 EA	2517.90			2,517.90	\$ DE
	BUMPER BRACKET FRT R	1.0 EA	47.60			47.60	\$?
	BUMPER BRACKET FRT L	1.0 EA	47.60			47.60	\$?
	BUMPER BARCKET RH CT	1.0 EA	184.20			184.20	\$?
	BUMPER BARCKET LH CT	1.0 EA	184.20			184.20	\$?
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	\$ ne

Paul
Hp 90010068

3 days

			Gross Total.			8,476.60	
Labour Total	4,946.00		Net.....			8,476.60	
Parts Total	3,530.60	<i>18/09/18</i>	GST @ 7.0%			593.36	
Package Total	0.00	<i>@1410</i>	Total.....			9,069.95	
			Paid.....			0.00	
			Please Pay..			9,069.95	

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

Resury b4 paint