

**SERVICE ESTIMATE**

72599 - C00001 SL: SERVICE SALES - PC

Mr Wang Wang Zeya  
33 Lloyd Road  
#01-05

Singapore 239106

Closed by .... : Paul Ong Qing Yong  
Svc Consultant :  
Remarks ..... : Mr Wang Zeya

GST Reg.No:M28920628X  
Inv.No. . . : B&P 0 Page 1  
Inv.date. . : 03/07/2018  
WIP No. . . : 14295  
Veh.In/Out:  
\*Tel.No. . . : Mobile: 92315716  
Reg.No. . . : SKK5678Z  
Reg.date . . : 25/01/2013  
Mileage . . : 0  
Chassis No: SALLSAG5DA791391

| Op.No | Description   | Mech Qty | Price   | Disc% | Pkg | Amount   | G |
|-------|---|----------|---------|-------|-----|----------|---|
| 802   | TO REPLACE FRT BUMPER, ETC  | 0        | 2400.00 | 0     |     | 2,400.00 | S |
| 800   | TO PUTTY SPRAYPAINT ON<br>FRT BUMPER, ETC                         | 0        | 2000.00 | 0     |     | 2,000.00 | S |
| R06   | FRT NUMBER PLATE & HOLDER   | 0        | 60.00   | 0     |     | 60.00    | S |
| 280   | TO CHECK WIRING INCLUDE<br>RESETTING OF ALL ELECTRICAL<br>MODULES | 0        | 486.00  | 0     |     | 486.00   | S |
|       | BUMPER FRT RRS2 5.0S  | 1.0 EA   | 2517.90 |       |     | 2,517.90 | S |
|       | BUMPER BRACKET FRT R  | 1.0 EA   | 47.40   |       |     | 47.40    | S |
|       | BUMPER BRACKET FRT L  | 1.0 EA   | 47.40   |       |     | 47.40    | S |
|       | BUMPER BARCKET RH CT  | 1.0 EA   | 183.30  |       |     | 183.30   | S |
|       | BUMPER BARCKET LH CT  | 1.0 EA   | 183.30  |       |     | 183.30   | S |
|       | ADHESIVE SEALER FL2   | 1.0 EA   | 425.40  |       |     | 425.40   | S |

Gross Total. 8,350.70

Labour Total 4,946.00  
Parts Total 3,404.70  
Package Total 0.00

Net..... 8,350.70  
GST @ 7.0% 584.55  
Total..... 8,935.25  
Paid..... 0.00  
Please Pay.. 8,935.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated