

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 09 Jul 2018

## Preliminary Advice

Insured Vehicle No	: SKV2617L		
TP Vehicle No	: SHD4879P	Accident Date	: 04/07/2018
Make	: HYUNDAI I40	Assignment Date	: 06/07/2018
Date of Inspection	: 06/07/2018	Est. Duration of Repair	: 3/Days
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...N/S Front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,325.28
Revised Amount	:S\$	1,395.20
Check Items (Estimated)	:S\$	170.24
Total	:S\$	1,565.44

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.