

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4879P

DATE 5/7/2018 12:45

U/Sum

MAKE :

U/S

Like

ECICS

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket (LH)			\$ 24.60
	Front Bumper Retainer Mounting			\$ 9.20
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH)			\$ 169.80
	Front Fender Retainer			\$ 9.20
	SUB TOTAL			\$ 1,394.10
	LESS 20% DISCOUNTED TOTAL			\$ 1,115.28
	Frt Fender Advertisement Logo (LH)			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,110.00
	ESTIMATE TOTAL			\$ 2,325.28

*XR
?
?
BT
?
?*

Nett / nec

*400
400
11*

*NAZ LK
L/S
6/7/18 1600
3 days
After repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.