

01/23/2012

REF: CS/CT18012335/Dt d3^{SP}

Special Instruction:

ASS. REC. BY:

Surveyor: Bryen
From (Person): Jaayn Tey

ASSIGNMENT (Office)

of CTI

Date/Time: 6/7/18 @ 9am

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: YP 7931L

Insured: PC 6010B

at Workshop m/s: Teamwork Garage

Tel: 6844 2475

of: 53 ubi Ave | #01-24

Policy No: DMBISN174586170B

Claim No: SNMI8D03286C02

Sum Insured:

Excess:

D.O.A. 30/06/2018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 10:30am 6/7/18

Person Contacted: Damen

Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/> Estimate
	<u>YP 7931L - X</u>
	<u>PC 6010B - X</u>
<u>2/10/18</u>	<u>Invoice 2/S 31,300/- with 21 days of inv.</u>
	<u>(Red: 40733.36, 56%)</u>

Survivor

REF:


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **YP 7931L** Yr Regn: **Nov / 2017**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Mitsubishi Canter FEB21 2998**
 Colour: **White** A/C: Insured / Std / NI / NA
 Sp. Reading: **36760** T/Radio: Insured / Std / NI / NA
 Eng/No: **4P20C69197**
 C/No: **FEB21EA21605**
 Gen. Cond: **6** / Good / Fair / Poor / Burnt
 Steering: In Order / Jammed / Leaked / Burnt or _____
 Brake: In Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **21** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: **195/85 R15**
 R: **— 11 — (double)**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Dunlop.**
 Front Rear
 R/Bal. **6** mm R/Bal. **6/6** mm
 L/Bal. **6** mm L/Bal. **6/6** mm
 D.O.A. **30/06/2018** D.O.I. **06/07/2018**
 Survey held at **Teamwork Paga ubi**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front y Rev
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Check Taping PC 6010B
	Extensive damage. Pending estimate by repairer. Repair cost exceed 40k.
	MV 75K LIA 33.6K HL 41.4K

RECEIVED 26 OCT 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair: **21**
 Resurvey No. of Trip: **2**

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	220
Transportation:	
S + RS:	
Photos:	
Others:	
TOTAL	

Report Format: **TP**
 Lump Sum / I.B.I: (\$) **31,300/-**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		06 Jul 2018 09:00 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main

Reference

Claim Details

Documents

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	BKK TRAVEL P/L, Co. Reg. No.: 201424387C		
Main Claimant:	MEI TONG CONSTRUCTION PTE LTD, Co. Reg. No.: NA		
Vehicle Reg. No.:	YP7931L	Date of Loss:	30/06/2018 17:00 - :59
Claim Type:	TP / SNM18D03286C02	Policy/Cover Note No.:	DMB1SN1745861700 (Comprehensive)
Vehicle Reg. No. (Insured):	PC6010B	Policy No. (Claimant):	DMCV17S021814
		Excess:	S\$0.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/07/2018]		
Driver/Custodian (Insured):	HUANG MAOYI (27 / Male), NRIC: G3098041M, Tel: +6581269631		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2018 11:02
Date Of Accident	30/06/2018 17:20
Exact Location Of Accident	ALONG RD 1 TAMPINES EXPRESSWAY PIE CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7931L
Insured/Policyholder	Company 9031H
Name Of Registered Owner	MEI TONG CONSTRUCTION PTE LTD
Co Reg No	NA
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82655644
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	FUSO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV17S021814
Cover Note Number	
Driver	
Name of Driver	SELLAMUTHU MATHAVAN
Passport No/FIN	G6504331U
Date Of Birth	09/05/1987
Occupation	OUTDOOR
Date Of Driving Pass	25/08/2011
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82655644
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 74 TANAH MERAH COAST ROAD #02-60 NORTH COAST LODGE
 Postcode 498753
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : CHENG JIANGUO
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name GEYLANG N.P.C
 Police Station Address ROAD: 132 PAYA LEBAR ROAD , POSTCODE: 409014 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC6010B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XE1795Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number XE2762K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SELLAMUTHU MATHAVAN
Approximate Age
Injuries Sustain NECK & BACK PAIN & LEG
Injured person in which vehicle? YP7931L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CHENG JIANGUO
Approximate Age
Injuries Sustain
Injured person in which vehicle? YP7931L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

Sketch Plan

3/7/18

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident or event in the claims process.
2. This Form must be completed for the policyholder and/or the authorised driver.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insured companies.
5. **Any false reporting may be referred to the relevant law enforcement.**
6. The report will be forwarded by the insurers of the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for providing roadside copies of this report with a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the discretion to register of the report being made available if feasible.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agencies/authorities (such as the police, for the purposes of:
 - (i) processing, handling or/else dealing with my claim including the verification of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) covering the cost of dealing with my claim/claims or responding to my enquiries by me;
 - (iv) administering my claims (including the making of my responses, statements, invoices, receipts or notes to me, which could involve disclosure of certain personal data about me, including about delivery of my claims as well as on the external cover of envelopes/mail packages) and/or;
 - (v) complying with applicable law in administering, processing, handling or/else dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name:
 ID No./EN No.:

3/7/18



**SINGAPORE
POLICE FORCE**



T/20180630/2154

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

2 of 3

Report No. T/20180630/2154

CONTINUATION OF REPORT

Brief Details.

On 30/06/2018 at about 1720hrs, I was driving my company vehicle YP7931L along TPE towards Changi on third lane. There is a tipper in front of my lorry when I was driving. I then managed to stop my lorry when the tipper in front of me stop as the traffic was heavy. There was a bus (PC6010B) that stopped behind my lorry. Out of sudden the bus that stop behind my lorry collided onto my rear lorry and cause my lorry to hit onto the front tipper XE2762K. I wish to state that another tipper XE1795Y had collided onto the bus (PC6010B) which causes the bus to collide onto my rear lorry.

My passenger who is my manager who was sitting beside me unable to come out as both his legs were stuck. Shortly SCDF officers came out to assist my passenger. He was then conveyed by ambulance. I am not injured.



**SINGAPORE
POLICE FORCE**



T/20180630/2154

3 of 3

Report No. T/20180630/2154

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G /  Sr Staff Sgt YAZID BIN AHMAD	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/06/2018 22:18
Officer In Charge Of Case:  TP / SINGAPORE POLICE FORCE Staff Sgt YAN MINGSHENG DANIEL Contact No.: 65476252	Classification Of Case:
Authentication Stamp NP158  SIGNATURE	



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475 68442474
 E-mail : claims@teamworkgarage.com

Register number : 201015366H
 3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd
 105 Cecil Street #19-00
 The Octagon
 Singapore 069534

Vehicle number	YP7931L
Make / Model	MITSUBISHI/FUSO
Chassis number	FEB21EA21605
Accident date	30 JUNE 2018
Reference	1807-04

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT WINDSCREEN broken	1041.18 ✓
1	FRONT WINDSCREEN WEATHERSTRIP deformed	477.20 ✓
1	FRONT WINDSCREEN WIPER ARM LHS broken	127.91 ✓
1	FRONT WINDSCREEN WIPER ARM RHS svc	127.19 ✗
1	FRONT WINDSCREEN WIPER BLADE LHS broken	51.36 ✓
1	FRONT WINDSCREEN WIPER BLADE RHS svc	51.36 ✗
2	FRONT WINDSCREEN WIPER ARM RIVOT CAP nec	13.98 ✓
1	FRONT WINDSCREEN WIPER LINKAGE bt	602.26 ✓
1	FRONT WINDSCREEN WASHER TUBE H/L	78.42 ✗
1	FRONT WINDSCREEN LOWER PANEL svc	1411.65 ✓
1	FRONT PANEL Bnc	2320.79 ✓
1	FRONT PANEL GARNISH Bnc	365.77 ✓
1	FUSO' MARK nec	147.63 ✓
1	FRONT PILLAR LHS Bnc	1289.49 ✓
1	FRONT PILLAR SEAL LHS nec	21.51 ✓
1	FRONT PILLAR TRIM LHS deformed	113.78 ✓
1	FRONT PILLAR RHS H/L	1289.49 ✗
1	FRONT PILLAR TRIM RHS H/L	113.78 ✗
1	FRONT PILLAR SEAL RHS H/L	21.51 ✗
1	RADIATOR GRILLE broken	1053.14 ✓
1	CANTER' MARK nec	74.70 ✓
1	THREE-DIA' MARK nec	78.66 ✓
1	RADIATOR GRILLE BRACKET broken	24.96 ✓
1	FRONT CORNER PANEL LHS broken	482.75 ✓
1	FRONT CORNER PANEL CAP LHS nec	38.61 ✓
1	FRONT CORNER PANEL RHS H/L	482.75 ✗
1	FRONT CORNER PANEL CAP RHS H/L	38.61 ✗
1	FRONT CORNER PANEL SEAL RH H/L	35.07 ✗
1	FRONT FLOOR END CROSS MEMBER Rental	1571.38 ✓
1	HEADLAMP LHS broken	461.45 ✓
1	HEADLAMP RHS H/L	461.45 ✗
1	TURN SIGNAL LAMP LHS broken	245.15 ✓
1	TURN SIGNAL LAMP RHS H/L	245.15 ✗
1	HEADLAMP GARNISH LHS deformed	211.96 ✓
1	HEADLAMP GARNISH RHS H/L	211.96 ✗
2	HEADLAMP LOWER BEZEL H/L nec o/s svc	11.75 23.50 ✓

12239.02

2	REAR VIEW MIRROR H/S broken o/s H/W	96.90	193.80	✓
1	REAR VIEW MIRROR STAY LHS bt		437.17	✓
1	REAR VIEW MIRROR STAY RHS N/W		418.19	X
1	FRONT UNDER VIEW MIRROR LHS dislodged		54.09	✓
2	REAR VIEW MIRROR STAY COVER H/S dislodged o/s H/W	15.05	30.10	✓
1	FRONT DOOR LHS Src		1906.41	✓
1	FRONT DOOR WEATHERSTRIP LHS deformed		424.99	✓
1	FRONT DOOR INNER WEATHERSTRIP LHS deformed		266.23	✓
1	FRONT DOOR LATCH & ACTUATOR LHS Down		639.41	✓
1	FRONT DOOR RHS r/w		1906.41	X
1	FRONT DOOR WEATHERSTRIP RHS Src		424.99	X
1	FRONT DOOR INNER WEATHERSTRIP RHS Src		266.23	X
1	FRONT DOOR LATCH AND ACTUATOR RHS H/W		639.41	X
1	HEATER ASSY broken		2337.68	✓
1	AIR INTAKE DUCT ASSY H/W		829.06	X
1	DASHBOARD ASSY broken		1601.57	✓
1	DASHBOARD FRAME LHS bt		290.52	✓
1	DASHBOARD FRAME RHS r/w		165.42	X
1	ROOF PANEL Src		1386.55	✓
1	REAR PILLAR LHS Dented		1103.81	✓
1	REAR PILLAR RHS H/W		1103.81	X
1	CAB TILT CAUTION LABEL H/W		46.48	✓
1	REAR END PANEL Dented Tailgate		4981.81	✓
1	REAR END PANEL REINFORCEMENT Dented H/W		612.49	X
1	REAR TAILLAMP LHS crack		178.84	✓
1	TAILLAMP BRACKET LHS bt		123.93	✓
1	REAR TAILLAMP RHS H/W		178.84	X
1	TAILLAMP BRACKET RHS # H/W		123.93	X
1	REAR NUMBER PLATE LAMP Src		102.35	X
1	FRONT WINDSCREEN MOTOR Down		730.67	✓
1	FRONT WINDSCREEN WASHER TANK Door deformed		182.68	✓
1	AIRCON CONDENSER H/W		1544.74	X
1	AIRCON CONDENSER FAN H/W		107.39	X
1	AIRCON CONDENSER FAN SHROUD H/W		71.84	X
1	AIRCON CONDENSER FAN MOTOR H/W		424.75	X
1	AIRCON CONDENSER REAR BRACKET H/W		889.70	X
1	AIRCON CONDENSER FRONT BRACKET H/W		35.14	X
1	AIRCON RECEIVER ASSY H/W		282.47	X
1	AIRCON PIPE H/W		219.83	X
1	AIRCON PIPE NO 2 H/W	16804.79	465.53	X
1	AIRCON PIPE NO 3 H/W		435.69	X
1	AIRCON COMPRESSOR DISCHARGE PIPE H/W		75.89	X
1	AIRCON COMPRESSOR DISCHARGE PIPE H/W		100.05	X
1	AIRCON COMPRESSOR SUCTION PIPE H/W		197.94	X
1	RADIATOR ASSY H/W		2491.92	X
1	RADIATOR FAN H/W		210.66	X

1	FRONT CABIN MOUNTING CROSS MEMBER HH	827.10	X
1	FRONT CABIN MOUNTING BRACKET LHS HH	879.38	X
1	FRONT CABIN MOUNTING BRACKET RHS HH	879.38	X
2	FRONT CABIN MOUNTING CUSHION LHS/RHS SVC	423.78	X
2	FRONT CABIN MOUNTING BUSHING LHS/RHS SVC	35.06	X
1	FRONT CABIN MOUNTING ANCHOR LEVER BT	238.20	✓
1	FRONT CABIN MOUNTING TILT TORSION BAR BT	571.71	✓
1	FRONT DOOR OUTER HANDLE SVC	260.00	X
1	FRONT DOOR INNER TRIM LH deformed	587.84	✓
1	FRONT WHEEL ARCH PANEL LH SVC	298.84	✓
1	FRONT SIDE FENDER LH SVC	63.59	✓
1	FRONT SIDE FENDER SEAL LH HLC	78.43	✓
1	FRONT STEP PANEL LH SVC	315.82	✓
1	FRONT STEP GARNISH LH broken	572.80	✓
1	FRONT SHOCK ABSORBER HH	345.31	X
1	FRONT LH LOWER ARM HH	1976.27	X
1	FRONT LH KNUCKLE HH	2227.01	X
1	STEERING SHAFT HH	1324.91	X
1	STEERING GEAR HH	1417.84	X
1	DRIVER SEAT HH	3511.28	X
1	PASSENGER SEAT HH	2926.26	X
1	POWER STEERING OIL RETURN TUBE HH	175.12	X
1	POWER STEERING OIL HOSE HH	15.49	X
1	POWER STEERING OIL RESERVOIR HH	530.80	X
		67131.14	
		16782.78	
	Subtotal	50348.36	
	Balance C/F	50348.36	
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	50348.36	
	REAR DECK TAILGATE I-STRIP SVC	200.00	X
	REAR DECK TAILGATE J-STRIP SVC	240.00	X
	23 PAX STICKER HLC	20.00 20/-	
	60KM/H STICKER HLC	20.00	✓
	REAR WOODEN STEP PANEL broken	550.00	✓
	REAR NUMBER PLATE BT	40.00 35/-	
	REAR DECK LOWER RAIL torn/shifted	700.00	✓
	REAR DECK WOODEN RAILING torn/shifted	850.00	✓
	REAR DECK FRONT LOWER RAIL torn/shifted	700.00	✓
	REAR DECK FLOOR PANEL torn/shifted	2550.00	✓
	REAR DECK LOWER VERTICAL WOOD torn/shifted	4000.00	✓
	U-BOLT BT	1200.00	✓
	BOLT AND NUT SET HH	280.00	X
	REAR BUMPER HS	900.00	X
	REAR BUMPER BRACKET HS	360.00	X
	POWER STEERING OIL HH	50.00	X
	Subtotal	12710.00	
	Balance C/F	63058.36	

2727.23

31771.04

25% 23828.28

10625.00

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	63058.36
1	TO CHECK WIRING AND LIGHTNING SYSTEM	80.00 30/-
2	TO REMOVE AND REPLACE CONDENSER AND TOP UP GAS	200.00 44
3	TO REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	200.00 44
4	TO REMOVE AND RENEW PASSENGER SEAT ASSY	300.00 150/-
5	TO REMOVE AND RENEW FRONT WINDSCREEN	150.00 120/-
6	REMOVE AND RENEW FRONT DASHBOARD	500.00 220/-
7	TRANSFER PARTS, ATTACHEMENT FROM FROM OLD DOOR TO	200.00 60/-
8	CHECK FRONT WHEEL ALIGNMENT	150.00 60/-
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 44
10	TO REPAIR AND STRAIGHTEN FRONT CHASSIS	400.00 180/-
11	TO REMOVE AND REPLACE REAR EXHAUST ASSY	150.00 44
12	TRANSFER PARTS, ATTACHEMENT FROM FROM OLD TAILGATE	200.00 50/-
13	PANEL BEATING ON AFFECTED AREAS	3500.00 2500/-
14	SPRAY PAINTING ON AFFECTED AREAS	2500.00 1000/-
15	APPLY ANTI RUST ON AFFECTED AREAS	250.00 80/-
	4750/-	1300/-
	Subtotal	8980.00
	Grand total	72038.36

39203.28

L/S 31300/-

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

06/07/2018 @ 1400hrs

hit Annual

2/3wks 21 days.



LKK Auto


Check MV

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jul 2018		06 Jul 2018 09:00 Edit Adj Rpt	S\$31,300.00 Edit Estimates	S\$31,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	BKK TRAVEL P/L , Co. Reg. No.: 201424387C								
Main Claimant:	MEI TONG CONSTRUCTION PTE LTD , Co. Reg. No.: NA								
Vehicle Reg. No.:	YP7931L	Date of Loss:	30/06/2018 17:00 - :59 [7 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03286C02	Policy/Cover Note No.:	DMB1SN1745861700 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC6010B	Policy No. (Claimant):	DMCV17S021814						
		Excess:	S\$0.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 17/07/2018]								
Driver/Custodian (Insured):	HUANG MAOYI (27 / Male), NRIC: G3098041M, Tel: +6581269631								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP7931L (SNM18D03286C02)**
[PC6010B]
TP
MEI TONG CONSTRUCTION PTE LTD
Jun 30 2018 5:00PM
[BKK TRAVEL P/L]
Teamwork Garage Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:57	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	03/07/18 11:48	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/10/18 14:22	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
2	20/10/18 14:22	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
3	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
18	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
19	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
20	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
21	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
22	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
23	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
24	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
25	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
26	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
27	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
28	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
29	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
30	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
31	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
32	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
33	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
34	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
35	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
36	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
37	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
38	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
39	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
40	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
41	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
42	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
43	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
44	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
45	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
46	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
47	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
48	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
49	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
50	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
51	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
52	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
53	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
54	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
55	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
56	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
57	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
58	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
59	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
60	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
61	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
62	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>
63	20/10/18 14:22	General View General View	Load JPG	<input checked="" type="checkbox"/>
64	20/10/18 14:22	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
65	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
66	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
67	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
68	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
69	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
70	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
71	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
72	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
73	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
74	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
75	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
76	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
77	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
78	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
79	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
80	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
81	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
82	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
83	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
84	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
85	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
86	20/10/18 14:22	General View	 Load JPG	<input checked="" type="checkbox"/>
87	20/10/18 14:22	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
88	20/10/18 14:22	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
89	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
113	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
161	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
162	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
163	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
164	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
165	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
166	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
167	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
168	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
169	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
170	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
171	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
172	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
173	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
174	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
175	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
176	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
177	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
178	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
179	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
180	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
181	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
182	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
183	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
184	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
185	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
186	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
187	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
188	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
189	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
190	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
191	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
192	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
193	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
194	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
195	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
196	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
197	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
198	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
199	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
200	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
201	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
202	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
203	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
204	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
205	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
206	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
207	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
208	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
209	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
231	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
233	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
247	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
248	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
249	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
250	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
251	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
252	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
253	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
254	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
255	20/10/18 14:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
256	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
257	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
258	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
259	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
260	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
261	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
262	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
263	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
264	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
265	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
266	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
267	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
268	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
269	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
270	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
271	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
272	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
273	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
274	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
275	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
276	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
277	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
278	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
279	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
280	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
281	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
282	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
283	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
284	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
285	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
286	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
287	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
288	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
289	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
290	20/10/18 14:23	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
291	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
292	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
293	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
294	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
295	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
296	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
297	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
298	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
299	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
300	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
301	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
302	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
303	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
304	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
305	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
306	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
307	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
308	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
309	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
310	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
311	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
312	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
313	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
314	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
315	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
316	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
317	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
318	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
319	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
320	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
321	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
322	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
323	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
324	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
325	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
326	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
327	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
328	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
329	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
330	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
331	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
332	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
333	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
334	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
335	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
336	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
337	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
338	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
339	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
340	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
341	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
342	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
343	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
344	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
345	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
346	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
347	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
348	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
349	20/10/18 14:24	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
350	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
351	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
352	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
353	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>
354	20/10/18 14:24	Finishing Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:49	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	03/07/18 11:49	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	03/07/18 11:50	Police report pg 1 [Linked Accident Report Documents]	Load TIF	
4	03/07/18 11:50	Police report pg 2 [Linked Accident Report Documents]	Load TIF	
5	03/07/18 11:50	Police report pg 3 [Linked Accident Report Documents]	Load TIF	
6	03/07/18 11:50	Driver IC & LIC [Linked Accident Report Documents]	Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/07/18 09:00	PRS	Load PDF	
2	06/07/18 09:00	OI GIA	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:57	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	03/07/18 11:48	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	03/07/18 11:49	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	03/07/18 11:49	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	03/07/18 11:50	Police report pg 1	Load TIF	
4	03/07/18 11:50	Police report pg 2	Load TIF	
5	03/07/18 11:50	Police report pg 3	Load TIF	
6	03/07/18 11:50	Driver IC & LIC	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012335/DTD3S2
Date: 29/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1745861700
Claimant Vehicle No : YP7931L **Insured Vehicle No :** PC6010B
 Date of Loss: 30/06/2018 Nature of Claim: TP Claim No: SNM18D03286C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP7931L**
 Make & Model: MITSUBISHI FUSO, 12.0 D FV51SS3VDEA (M) Engine No: 4P10C69197
 Reg. Date: 14/11/2017 (Man. Year: 2017) Chassis No: FEB21EA21605
 Colour: White Odometer: 36760 km
 Engine Capacity: 2998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85R15 Rear Tyre Size: 195/85R15(D)
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6/6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,058.35	34,453.28	28,605.07	45.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,980.00	4,750.00	4,230.00	47.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	72,038.35	39,203.28	32,835.07	45.58
Approved Total (Overridden) (S\$)		31,300.00		
(S\$)	72,038.35	31,300.00	40,738.35	56.55
+ GST 7.00/7.00% (S\$)	5,042.68	2,191.00	2,851.68	56.55
Nett Amount (S\$)	77,081.03	33,491.00	43,590.03	56.55

INSPECTION

Date of Assignment: 06/07/2018
 Date Inspected: 06/07/2018 Inspected At: Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 21.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2018)	
Parts:	N/A	MITSUBISHI FUSO 12.0 D FV51SS3VDEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7931L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Broken	1,041.18 FL	*1,041.18 FL
2	1		*FRONT WINDSCREEN WEATHERSTRIP	Deformed	477.20 FL	*477.20 FL
3	1		*FRONT WINDSCREEN WIPER ARM LHS	Broken	127.91 FL	*127.91 FL
4	1		*FRONT WINDSCREEN WIPER ARM RHS	Serviceable	127.19 FL	*- FL
5	1		*FRONT WINDSCREEN WIPER BLADE LHS	Broken	51.36 FL	*51.36 FL
6	1		*FRONT WINDSCREEN WIPER BLADE RHS	Serviceable	51.36 FL	*- FL
7	2		*FRONT WINDSCREEN WIPER ARM RIVOT CAP	Necessary	13.98 FL	*13.98 FL
8	1		*FRONT WINDSCREEN WIPER LINKAGE	Bent	602.26 FL	*602.26 FL
9	1		*FRONT WINDSCREEN WASHER TUBE	Not Necessary	78.42 FL	*- FL
10	1		*FRONT WINDSCREEN LOWER PANEL	Buckled	1,411.65 FL	*1,411.65 FL
11	1		*FRONT PANEL	Buckled	2,320.79 FL	*2,320.79 FL
12	1		*FRONT PANEL GARNISH	Buckled	365.77 FL	*365.77 FL
13	1		*FRONT PILLAR LHS	Buckled	1,289.49 FL	*1,289.49 FL
14	1		*FRONT PILLAR SEAL LHS	Necessary	21.51 FL	*21.51 FL
15	1		*FRONT PILLAR TRIM LHS	Deformed	113.78 FL	*113.78 FL
16	1		*FRONT PILLAR RHS	Not Necessary	1,289.49 FL	*- FL
17	1		*FRONT PILLAR TRIM RHS	Not Necessary	113.78 FL	*- FL
18	1		*FRONT PILLAR SEAL RHS	Not Necessary	21.51 FL	*- FL
19	1		*RADIATOR GRILLE	Broken	1,053.14 FL	*1,053.14 FL
20	1		*CANTER MARK	Necessary	74.70 FL	*74.70 FL
21	1		*THREE-DIA MARK	Necessary	78.66 FL	*78.66 FL
22	1		*RADIATOR GRILLE BRACKET	Broken	24.96 FL	*24.96 FL
23	1		*FRONT CORNER PANEL LHS	Broken	482.75 FL	*482.75 FL
24	1		*FRONT CORNER PANEL CAP LHS	Necessary	38.61 FL	*38.61 FL
25	1		*FRONT CORNER PANEL RHS	Not Necessary	482.75 FL	*- FL
26	1		*FRONT CORNER PANEL CAP RHS	Not Necessary	38.61 FL	*- FL
27	1		*FRONT CORNER PANEL SEAL RH	Not Necessary	35.07 FL	*- FL
28	1		*FRONT FLOOR END CROSS MEMBER	Dented	1,571.38 FL	*1,571.38 FL
29	1		*HEADLAMP LHS	Broken	461.45 FL	*461.45 FL
30	1		*HEADLAMP RHS	Not Necessary	461.45 FL	*- FL
31	1		*TURN SIGNAL LAMP LHS	Broken	245.15 FL	*245.15 FL
32	1		*TURN SIGNAL LAMP RHS	Not Necessary	245.15 FL	*- FL
33	1		*HEADLAMP GARNISH LHS	Deformed	211.96 FL	*211.96 FL
34	1		*HEADLAMP GARNISH RHS	Not Necessary	211.96 FL	*- FL
35	1		*HEADLAMP LOWER BEZEL	N/s Necessary/O/s Serviceable	23.50 FL	*11.75 FL
36	1		*REAR VIEW MIRROR	N/s Broken/O/s Not Necessary	193.80 FL	*96.90 FL
37	1		*REAR VIEW MIRROR STAY LHS	Bent	437.17 FL	*437.17 FL
38	1		*REAR VIEW MIRROR STAY RHS	Not Necessary	418.19 FL	*- FL
39	1		*FRONT UNDER VIEW MIRROR LHS	Dislodged	54.09 FL	*54.09 FL
40	1		*REAR VIEW MIRROR STAY COVER	Ns Dislodged/Os Not Necessary	30.10 FL	*15.05 FL
41	1		*FRONT DOOR LHS	Buckled	1,906.41 FL	*1,906.41 FL
42	1		*FRONT DOOR WEATHERSTRIP LHS	Deformed	424.99 FL	*424.99 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT DOOR INNER WEATHERSTRIP LHS	Deformed	266.23 FL	*266.23 FL
44	1		*FRONT DOOR RHS	Repair	1,906.41 FL	*- FL
45	1		*FRONT DOOR INNER WEATHERSTRIP RHS	Serviceable	266.23 FL	*- FL
46	1		*FRONT DOOR WEATHERSTRIP RHS	Serviceable	424.99 FL	*- FL
47	1		*FRONT DOOR LATCH & ACTUATOR RHS	Not Necessary	639.41 FL	*- FL
48	1		*FRONT DOOR LATCH & ACTUATOR LHS	Damaged	639.41 FL	*639.41 FL
49	1		*HEATER ASSY	Broken	2,337.68 FL	*2,337.68 FL
50	1		*AIR INTAKE DUCT ASSY	Not Necessary	829.06 FL	*- FL
51	1		*DASHBOARD ASSY	Broken	1,601.57 FL	*1,601.57 FL
52	1		*DASHBOARD FRAME LHS	Bent	290.52 FL	*290.52 FL
53	1		*DASHBOARD FRAME RHS	Repair	165.42 FL	*- FL
54	1		*ROOF PANEL	Buckled	1,386.55 FL	*1,386.55 FL
55	1		*REAR PILLAR LHS	Dented	1,103.81 FL	*1,103.81 FL
56	1		*REAR PILLAR RHS	Not Necessary	1,103.81 FL	*- FL
57	1		*CAB TILT CAUTIOUS LABEL	Necessary	46.48 FL	*46.48 FL
58	1		*REAR TAILGATE	Dented	4,981.81 FL	*4,981.81 FL
59	1		*REAR END PANEL REINFORCEMENT	Not Necessary	612.49 FL	*- FL
60	1		*REAR TAILLAMP LHS	Cracked	178.84 FL	*178.84 FL
61	1		*TAILLAMP BRACKET LHS	Bent	123.93 FL	*123.93 FL
62	1		*REAR TAILLAMP RHS	Not Necessary	178.84 FL	*- FL
63	1		*TAILLAMP BRACKET RHS	Not Necessary	123.93 FL	*- FL
64	1		*REAR NUMBER PLATE LAMP	Serviceable	102.35 FL	*- FL
65	1		*FRONT WINDSCREEN MOTOR	Damaged	730.67 FL	*730.67 FL
66	1		*FRONT WINDSCREEN WASHER TANK	Deformed	182.68 FL	*182.68 FL
67	1		*AIRCON CONDENSER	Not Necessary	1,544.74 FL	*- FL
68	1		*AIRCON CONDENSER FAN	Not Necessary	107.39 FL	*- FL
69	1		*AIRCON CONDENSER FAN SHROUD	Not Necessary	71.84 FL	*- FL
70	1		*AIRCON CONDENSER FAN MOTOR	Not Necessary	424.75 FL	*- FL
71	1		*AIRCON CONDENSER REAR BRACKET	Not Necessary	889.70 FL	*- FL
72	1		*AIRCON CONDENSER FRONT BRACKET	Not Necessary	35.14 FL	*- FL
73	1		*AIRCON RECEIVER ASSY	Not Necessary	282.47 FL	*- FL
74	1		*AIRCON PIPE	Not Necessary	219.83 FL	*- FL
75	1		*AIRCON PIPE NO 2	Not Necessary	465.53 FL	*- FL
76	1		*AIRCON PIPE NO 3	Not Necessary	435.69 FL	*- FL
77	1		*AIRCON COMPRESSOR DISCHARGE PIPE	Not Necessary	75.89 FL	*- FL
78	1		*AIRCON COMPRESSOR DISCHARGE PIPE	Not Necessary	100.05 FL	*- FL
79	1		*AIRCON COMPRESSOR SUCTION PIPE	Not Necessary	197.94 FL	*- FL
80	1		*RADIATOR ASSY	Not Necessary	2,491.92 FL	*- FL
81	1		*RADIATOR FAN	Not Necessary	210.66 FL	*- FL
82	1		*FUSO MARK	Necessary	147.63 FL	*147.63 FL
83	1		*FRONT CABIN MOUNTING CROSS MEMBER	Not Necessary	827.10 FL	*- FL
84	1		*FRONT CABIN MOUNTING BRACKET LHS	Not Necessary	879.38 FL	*- FL
85	1		*FRONT CABIN MOUNTING BRACKET RHS	Not Necessary	879.38 FL	*- FL
86	2		*FRONT CABIN MOUNTING CUSHION LHS/RHS	Serviceable	423.78 FL	*- FL
87	2		*FRONT CABIN MOUNTING BUSHING LHS/RHS	Serviceable	35.06 FL	*- FL
88	1		*FRONT CABIN MOUNTING ANCHOR LEVER	Bent	238.20 FL	*238.20 FL
89	1		*FRONT CABIN MOUNTING TILT TORSION BAR	Bent	571.71 FL	*571.71 FL
90	1		*FRONT DOOR OUTER HANDLE	Serviceable	260.00 FL	*- FL
91	1		*FRONT DOOR INNER TRIM LH	Deformed	587.84 FL	*587.84 FL
92	1		*FRONT WHEEL ARCH PANEL LH	Buckled	298.84 FL	*298.84 FL
93	1		*FRONT SIDE FENDER LH	Buckled	63.59 FL	*63.59 FL
94	1		*FRONT SIDE FENDER SEAL LH	Necessary	78.43 FL	*78.43 FL
95	1		*FRONT STEP PANEL LH	Buckled	315.82 FL	*315.82 FL
96	1		*FRONT STEP GARNISH LH	Broken	572.80 FL	*572.80 FL
97	1		*FRONT SHOCK ABSORBER	Not Necessary	345.31 FL	*- FL
98	1		*FRONT LH LOWER ARM	Not Necessary	1,976.27 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*FRONT LH KNUCKLE	Not Necessary	2,227.01 FL	*- FL
100	1		*STEERING SHAFT	Not Necessary	1,324.91 FL	*- FL
101	1		*STEERING GEAR	Not Necessary	1,417.84 FL	*- FL
102	1		*DRIVER SEAT	Not Necessary	3,511.28 FL	*- FL
103	1		*PASSENGER SEAT	Not Necessary	2,926.26 FL	*- FL
104	1		*POWER STEERING OIL RETURN TUBE	Not Necessary	175.12 FL	*- FL
105	1		*POWER STEERING OIL HOSE	Not Necessary	15.49 FL	*- FL
106	1		*POWER STEERING OIL RESERVOIR	Not Necessary	530.80 FL	*- FL
107	1		*REAR DECK TAILGATE I-STRIP	Serviceable	200.00 FS	*- FS
108	1		*REAR DECK TAILGATE J-STRIP	Serviceable	240.00 FS	*- FS
109	1		*23 PAX STICKER	Necessary	70.00 FS	*20.00 FS
110	1		*60KM/H STICKER	Necessary	20.00 FS	*20.00 FS
111	1		*REAR WOODEN STEP PANEL	Broken	550.00 FS	*550.00 FS
112	1		*REAR NUMBER PLATE	Bent	40.00 FS	*35.00 FS
113	1		*REAR DECK LOWER RAIL	Torn / Shifted	700.00 FS	*700.00 FS
114	1		*REAR DECK WOODEN RAILING	Torn / Shifted	850.00 FS	*850.00 FS
115	1		*REAR DECK FRONT LOWER RAIL	Torn / Shifted	700.00 FS	*700.00 FS
116	1		*REAR DECK FLOOR PANEL	Torn / Shifted	2,550.00 FS	*2,550.00 FS
117	1		*BOLT AND NUT SET	Not Necessary	280.00 FS	*- FS
118	1		*REAR DECK LOWER VERTICAL WOOD	Torn / Shifted	4,000.00 FS	*4,000.00 FS
119	1		*U-BOLT	Bent	1,200.00 FS	*1,200.00 FS
120	1		*REAR BUMPER	No such part	900.00 FS	*- FS
121	1		*REAR BUMPER BRACKET	No such part	360.00 FS	*- FS
122	1		*POWER STEERING OIL	Not Necessary	50.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	79,841.14	42,396.04
- List Item Discount on L Items 25.00/25.00% (S\$)	16,782.79	7,942.76
Total Parts (S\$)	63,058.35	34,453.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	TO REMOVE AND REPLACE CONDENSER AND TOP UP GAS	New	200.00	-
3	TO REMOVE AND REPLACE RADIATOR AND TOP UP COOLANT	New	200.00	-
4	TO REMOVE AND RENEW PASSENGER SEAT ASSY	New	300.00	150.00
5	TO REMOVE AND RENEW FRONT WINDSCREEN	New	150.00	120.00
6	REMOVE AND RENEW FRONT DASHBOARD	New	500.00	220.00
7	TRANSFER PARTS,ATTACHMENT FROM FROM OLD DOOR TO	New	200.00	60.00
8	CHECK FRONT WHEEL ALIGNMENT	New	150.00	60.00
9	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	200.00	-
10	TO REPAIR AND STRAIGHTEN FRONT CHASSIS	New	400.00	180.00
11	TO REMOVE AND REPLACE REAR EXHAUST ASSY	New	150.00	-
12	TRANSFER PARTS,ATTACHMENT FROM FROM OLD TAILGATE	New	200.00	50.00
13	PANEL BEATING ON AFFECTED AREAS	New	3,500.00	2,500.00
14	SPRAY PAINTING ON AFFECTED AREAS	New	2,500.00	1,300.00
15	APPLY ANTI RUST ON AFFECTED AREAS	New	250.00	80.00
Gross Labour Cost (\$\$)			8,980.00	4,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >