

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 JUL 2018

E S T I M A T E

Estimate No. : b1 47574
Date Estimated : 05/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ng Liang Hwi (Huang LiangHui)
5 Tampines St 86
#07-19, Q Bay Residence

SINGAPORE 528585

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG8384J	V458124	15/09/2015	218iA AT	0

DESCRIPTION

To replace rear bumper, tail panel, tailgate, attachments including knock out dent area cause by accident.

Painting front bumper, tailgate, tail panel and trunk floor.

To check electrical wiring systems and lightings at the rear section for proper function.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

2295 / 2550 5,100.00
? Change panel - 4250
2159.10 2399 3,197.00
? 2877 - panel 177.00
135 150
XAN 451? 531.00
90 / 100 118.00
XAN 451? 531.00
80 ? 150.00

Total Labour 1: 9,804.00

DESCRIPTION

RUBBER MOUNTING
REAR SILENCER
TRUNK LID
TAIL PANEL
REAR BUMPER PANEL PRIMED (PDC)
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE
RR BUMPER RH INNER SIDE GUIDE
SET MOUNTS PDC SENSOR REAR
REAR FLAP TOWING EYE PRIMED
REAR BUMPER HEAT INSULATOR
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	17.00	17.00
1	1,167.45	1,167.45
1	1,174.95	1,174.95
1	355.20	355.20
1	966.25	966.25
1	423.80	423.80
1	37.35	37.35
1	58.55	58.55
1	58.55	58.55
1	62.95	62.95
1	41.80	41.80
1	59.15	59.15
4	5.05	20.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47574
Date Estimated : 05/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJG8384J	V458124	15/09/2015	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
ULTRASONIC SENSOR ALPINWEISS (U300)	2	380.65	761.30
BLIND RIVET AVIBVLB	19	0.55	10.45
SCREW (SF PLUS M5X15)	5	0.55	2.75
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
(DG) CLEANER R1 (100ML)	1	23.85	23.85
PUNCH RIVET N4	19	0.55	10.45

Total Parts : 5,533.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 12/07/18 @ 1440 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEYED BY PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 6 days

X 10 days? pml

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	9,804.00
Parts	:	5,533.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,073.63
Grand Total	:	16,411.13

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47574
Date Estimated : 05/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Ng Liang Hwi (Huang LiangHui)
5 Tampines St 86
#07-19, Q Bay Residence

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

SINGAPORE 528585

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJG8384J	V458124	15/09/2015	218iA AT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	6.00	3.00	14.84
# EXPANDING NUT *	1.00	7.00	3.00	6.79
# EXPANDING NUT *	1.00	3.00	3.00	2.91
# LETTERING 218i *	62.55	1.00	3.00	60.67
# BUMP STOP *	3.25	10.00	3.00	31.52
# PLUG BLACK D=5MM *	0.90	10.00	3.00	8.73
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	3.00	255.21
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	3.00	27.01

Total Labour :
Total Parts : 407.68
Total Labour & Parts : 407.68