

**JKS MOTOR WORKS (ACCIDENT CLAIMS) PTE LTD**

8 KAKI BUKIT AVENUE 4, #03-46, Premier @ Kaki Bukit, Singapore, 415875

CO REG & GST No. : 201529104D

TEL: 67026828 FAX: 6702 6829

EMAIL: admin@jksmotorworks.com.sg

Motor Claims Department

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY, #24-01 AXA TOWER,
Singapore 068811

REF. NO :

VEH NO : SJD9500A

QUOTATION NO. : JKSQUOT035

DATE : 4-Jul-18

VEHICLE NO SLS1755G
MAKE/MODEL KIA CARENS
CHASSIS KNAHU815VJ7188292
ENGINE NO D4FDHH109191
REG. DATE 12 Sep 2017
CAPACITY 1685 cc
MILEAGE

Estimate for SLS1755G KIA CARENS

No	Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 10%)
SPARE PART ITEMS					
1	FRONT BUMPER / re	1	PC	750.00	675.00 /
2	FRONT BUMPER CENTER - UPPER * / CRA	1	PC	100.00	90.00 /
3	FRONT BUMPER GRILLE * / BR	1	PC	490.00	441.00 /
4	FRONT BUMPER CHROME GARNISH * / BR	1	PC	250.00	225.00 /
5	FRONT BUMPER "KIA" EMBLEM / SCR	1	PC	100.00	90.00 /
6	FRONT BUMPER GRILLE CLIPS / MC	1	SET	50.00	45.00 /
7	FRONT BUMPER LOWER GRILLE * / Cut	1	PC	180.00	162.00 /
8	FRONT BUMPER LOWER GARNISH SPOILER / re	1	PC	250.00	225.00 /
9	FRONT BUMPER LOWER GRILLE CLIPS / MC	1	SET	50.00	45.00 /
10	FRONT BUMPER FOG LAMP GARNISH LH & RH X NN	2	PCS	240.00	216.00 X
11	FRONT BUMPER FOGLAMP LH/RH * LH - BR. RH X NN	2	PCS	480.00	432.00 216
12	HEADLAMP LH & RH * LH - BR. RH X NN	2	PCS	3,400.00	3,060.00 1530
13	FRONT BUMPER REINFORCEMENT * / ST	1	PC	500.00	450.00 /
14	FRONT BUMPER SIDE RETAINER LH & RH * / BR	2	PCS	50.00	45.00 /
15	FRONT BUMPER CLIPS / MC	1	SET	50.00	45.00 /
16	AIRCON CONDENSER X NN	1	PC	900.00	810.00 X
17	RADIATOR X	1	PC	780.00	702.00 X
18	FRONT SUPPORT PANEL * / BR	1	PC	750.00	675.00 /
19	BONNET X NN	1	PC	920.00	828.00 X
20	REAR BUMPER / re	1	PC	650.00	585.00 /
21	REAR BUMPER CLIPS / MC	1	SET	50.00	45.00 /
22	REAR BUMPER LOWER GARNISH / re	1	PC	250.00	225.00 /
23	REAR BUMPER BOTTOM DIFFUSER / re	1	PC	500.00	450.00 /
24	REAR BUMPER REFLECTOR LH/RH * / CRA	2	PCS	320.00	288.00 /
25	REAR BUMPER FOG LAMP BULBS X NN	2	PCS	30.00	27.00 X

26	REAR BUMPER REINFORCEMENT	1	PC	500.00	450.00	✓
27	REAR BUMPER REINFORCEMENT BRACKET	2	PCS	360.00	324.00	✓
28	REAR BUMPER SIDE RETAINER LH/RH	2	PCS	160.00	144.00	✓
29	REAR BUMPER UPPER PROTECTOR	1	PC	50.00	45.00	X
30	TAILGATE	1	PC	1,500.00	1,350.00	✓
31	TAILGATE "KIA" EMBLEM	1	PC	100.00	90.00	✓
32	TAILGATE "CARENS" EMBLEM	1	PC	70.00	63.00	✓
33	TAILGATE "CRDI" EMBLEM	1	PC	70.00	63.00	✓
34	TAILGATE RUBBER	1	PC	125.00	112.50	X
35	TAILGATE "C&C" LOGO	1	PC	100.00	90.00	✓
36	TAIL LIGHT LH & RH	2	PCS	760.00	684.00	X
37	TAILGATE REFLECTOR LH & RH	2	PCS	600.00	540.00	X
38	TAILGATE INNER TRIM	1	PC	260.00	234.00	X
39	TAILGATE INNER TRIM CLIPS	1	SET	50.00	45.00	✓
40	TAILGATE LOCK	1	PC	150.00	135.00	✓
41	TAILGATE WINDSCREEN MOULDING	1	PC	180.00	162.00	✓
42	TAILGATE WEATHER STRIP	1	PC	160.00	144.00	✓
43	REAR TAILGATE LOCK CATCH	1	PC	30.00	27.00	X
44	REAR END PANEL	1	PC	600.00	540.00	✓
45	REAR END PANEL TOP GARNISH	1	PC	85.00	76.50	✓
46	REAR END PANEL TOP GARNISH CLIPS	1	SET	50.00	45.00	X
47	SPARE TYRE PANEL	1	PC	150.00	135.00	X
48	SPARE TYRE PANEL TOP TRIM	1	PC	360.00	324.00	X
49	REAR EXHAUST MUFFLER AND MOUNTING	1	PC	800.00	720.00	X
					0.00	10228.5

SPECIAL NETT

50	FRONT NUMBER PLATE W/ HOLDER	1	SET	50.00	50.00	40
51	REAR NUMBER PLATE W/ HOLDER	1	SET	50.00	50.00	X
52	REAR BUMPER REVERSE SENSOR	4	PCS	1,000.00	1,000.00	7250

LABOUR

53	LABOUR TO REMOVE/REPLACE, CUT/WELD INCLUSIVE OF PANEL BEATING ON AFFECTED/NECESSARY PARTS AFFECTED BY THE ACCIDENT (FRONT)	1	SRV	800.00	800.00	600
54	TO PUTTY AND SPRAY PAINT ON ACCIDENT AFFECTED PORTION (FRONT)	1	SRV	700.00	700.00	200
55	LABOUR TO REMOVE/REPLACE, CUT/WELD INCLUSIVE OF PANEL BEATING ON AFFECTED / NECESSARY PARTS AFFECTED BY THE ACCIDENT (REAR)	1	SRV	1,100.00	1,100.00	600
56	TO PUTTY AND SPRAY PAINT ON ACCIDENT AFFECTED PORTION (REAR)	1	SRV	1,400.00	1,400.00	700
57	TO APPLY ANTI RUST COATING ON REPAIRED/REPLACE PANELS	1	SRV	180.00	180.00	60
58	TO CHECK/RECONNECT WIRING AND ENSURE PROPER FUNCTION INCLUSIVE OF HEADLAMP ALIGNMENT	1	SRV	100.00	100.00	X NN

59	TO REMOVE AND TRANSFER SERVICEABLE TAILGATE COMPARTMENTS TO NEW TAILGATE	1	SRV	200.00	200.00	60
60	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE AND CONDUCT WATER LEAKAGE TEST	1	SRV	180.00	180.00	100
61	TO REMOVE AND REPLACE / REINSTALL AIRCON CONDENSER INCLUDING TOP UP GAS	1	SRV	180.00	180.00	100
62	TO REMOVE AND REINSTALL LUGGAGE COMPARTMENT TRIMMINGS AND FITTINGS TO FACILITATE REPAIRS	1	SRV	250.00	250.00	60
63	TO RESET AND REPROGRAM ECU AFTER REPAIRS	1	SRV	350.00	350.00	X
64	COMPUTERIZED ALIGNMENT	1	SRV	100.00	100.00	X

2480

8 Days.

part by part

before paint photos.

Gino Giamp - 82880282

06/7/18.

12998.5

☆ subject to parts price correct.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



J.K.S.
MOTORWORKS

JKS MOTOR WORKS (ACCIDENT CLAIMS) PTE LTD

8 KAKI BUKIT AVENUE 4, #03-46, Premier @ Kaki Bukit, Singapore, 415875

CO REG & GST No. : 201529104D

TEL: 67026828 FAX: 6702 6829

EMAIL: admin@jksmotorworks.com.sg

Motor Claims Department

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY, #24-01 AXA TOWER,

Singapore 068811

REF. NO :

VEH NO : SJD9500A

QUOTATION NO. : JKSQUOT035

DATE : 9-Jul-18

VEHICLE NO SLS1755G
MAKE/MODEL KIA CARENS
CHASSIS KNAHU815VJ7188292
ENGINE NO D4FDHH109191
REG. DATE 12 Sep 2017
CAPACITY 1685 cc
MILEAGE

Estimate for SLS1755G KIA CARENS

No	Description	Qty	UOM	Repairer's Estimate	Revised Amount (Less 10%)
SUPPLEMENTARY					
1	TAIL GATE GARNISH / PR	1	PC	280.00	252.00
2	BOOT INNER TOOL BOX CONTAINER REAR / ee	1	PC	400.00	360.00
3	TOWING COVER REAR / ee	1	PC	30.00	27.00
4	BUMPER BRACKET FRONT / PR. x 2	1	PC	80.00	72.00
5	BUMPER INNER SPONGE FRONT / CHA.	1	PC	120.00	108.00
6	BRACKET REINFORCEMENT FRONT / CRA.	1	PC	180.00	162.00

7. Antenna Sensor. / DM

1 PC 150 135

Gene Ong.
09/7/18.

accidentclaims@jksmotorworks.com