

Surveyor
menmen

Marcus

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

6/7/18 01:14pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 67664

Insured:

SJH 8778B

at Workshop m/s

Specialist Motor

Tel:

6747 2112

of

Blk 3018A Ubi Road 1 # 01-24

Policy No:

DMHCSN1639881701

Claim No:

SNM18D03340C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/07/2018

CA / REV / REP. / REV 24 HRS

cup)

H.O.D. Endorsement:

Date/Time:

3:08pm 6/7/18

Person Contacted:

Irene-fing

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 67664-CC61A1918009532/Ae93

D.O.A.: 23/05/2015

SJH 8778B -x

(08/11/13) wef

REF:

ASS. REC. BY: *Moraw***ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKP 67664*at Workshop m/s *split.*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PB Seen: *2* Consistent? : Yes or NoEst. Repairs: *2* days Res.: Yes or NoLum Sum: *30* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKP 67664* Yr Regn: *7, 14*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *Lexus ES300h c.c. 2494*Colour: *white* A/C: Insured / Std / NI / NASp. Reading: *99299* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JTHBW/66X02059897*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: *2.5/55-R17*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / *YOKO* or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *0* mm L/Bal. *6* mmD.O.A. *4/7/18* D.O.I. *6/7/18*

Survey held at _____

Des. of Damages: *Front* / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/9/18 confirmed d/s \$1000 with incase. Upd 5834.70, 45%

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report1) *1/1/19* *typist*☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *2*

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)) \$ + RS, \$☐ : Interview (\$ _____)) Photos☐ : Tech. Invs (\$ _____)) Others☐ : Weekend (\$ _____))

TOTAL

Report Format : *MER-TP*Lump Sum / I.B.I: (\$ *1000*)*220*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 13:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	NG LUNG KHENG
Vehicle Reg. No.:	SKP6766U
Claim Type:	TP / SNM18D03340C02
Vehicle Reg. No. (Insured):	SJH8778B
Date of Loss:	04/07/2018 00:00 - :59
Policy/Cover Note No.:	DMHCSN1639881701
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/07/2018]
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2364F
Vehicle Details	
Vehicle No.:	SKP6766U
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H LUXURY CVT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	2AR1063001
Chassis No.:	JTHBW1GGX02059897
Maximum Power Output:	151.0 kW (202 bhp)
Open Market Value:	\$45,066.00
Original Registration Date:	22 Jul 2014
First Registration Date:	22 Jul 2014
Transfer Count:	1
Actual ARF Paid:	\$45,093.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jul 2024
PARF Rebate Amount:	\$33,819.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,889.00
COE Rebate Amount:	\$39,142.00
Total Rebate Amount:	\$72,961.00

The information contained herein is correct as at 09 Jul 2018

OK

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SKP6766U/1807107

06th July 2018

The Manager
Motor Claim Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NOT Affected
LKK
Zhiguo Attorney
2dy
6/7/18
4/5 = 1000/

Date of Accident : 04th July 2018
Location : Holland Ave Holland Village Open Carpark
Third Party Claim Vehicle No : SJH 8778 B
Repair Cost For Vehicle No : SKP 6766 U Lexus ES300H

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia	Deepcut 1	935.10	\$ 935.10 ✓
2	Front bumper clips	Net 1set	38.00	\$ 38.00 ✓
3	Front bumper side retainer LH&RH	11 2	65.80	\$ 131.60 X
				\$ 1,104.70

Labour Charges :-

	Amounts
Cut out, renew, knocking & welding front bumper, remove & install all damage parts, & re-align body	\$ 280.00 150
Spray painting on damage parts (pearl white)	\$ 300.00 250
Paint coating	\$ 150.00 X

Labour Charge

\$ 730.00

Total Amount

\$ 1,834.70

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012346/UQD3N2

Date: 14/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1639881701
Claimant Vehicle No :	SKP6766U	Insured Vehicle No :	SJH8778B
Date of Loss:	04/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03340C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6766U	Engine No:	2AR1063001
Make & Model:	LEXUS ES300H, 2.5 Executive (A)	Chassis No:	JTHBW1GGX02059897
Reg. Date:	22/07/2014 (Man. Year: 2014)	Odometer:	99299 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,104.70	875.79	228.91	20.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	400.00	330.00	45.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,834.70	1,275.79	558.91	30.46
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	1,834.70	1,000.00	834.70	45.50
+ GST 7.00/7.00% (\$\$)	128.43	70.00	58.43	45.50
Nett Amount (\$\$)	1,963.13	1,070.00	893.13	45.50

INSPECTION

Date of Assignment:	06/07/2018	
Date Inspected:	06/07/2018	Inspected At: Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
Parts: 143	LEXUS ES300H 2.5 Executive (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP6766U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Deep Cut	935.10 F	*935.10 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	38.00 F	*38.00 FL
3	2		*FRONT BUMPER SIDE RETAINER LH & RH	Not Necessary	131.60 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,104.70 973.10
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 97.31
					Total Parts (\$\$)	1,104.70 875.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT,RENEW,KNOCKING & WELDING FRONT BUMPER,REMOVE & INSTALL ALL DAMAGE PARTS,& RE-ALIGN BODY	New	280.00	150.00
2	SPRAY PAINTING ON DAMAGE PARTS (PEARL WHITE)	New	300.00	250.00
3	PAINT COATING	New	150.00	-
Gross Labour Cost (\$\$)			730.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >