

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0779/2018/GW
Date : 07-Jul-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Low Wai Mung
Address : 23 Jalan Rajah
#08-02
Singapore 329138
Telephone : HP +65 97641499
Type of Claim : Third Party Claims
Policy No. : 1800015962
Vehicle No : **SLW 5337 H**
Model Code : Audi T T coupe 1.8 TFSI S
Model / Year : Feb-18
Engine No : CJS 228096
Chassis No : TRUZZZFV4J1005045
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 06-Jul-18
Place of Accident : PIE Twds Tuas at Clementi Rd Exit 26 A

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 5337 H.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$ 900.00 500	
3	To respray rear bumper.		\$ 900.00 550	
4	To remove and renew rear exhaust silencer. Align to position.	S/N	\$ 480.00	?
5	To carry out diagnostic checks.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 5337 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rebond</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS <i>Rebond</i>	\$ 234.00	X
3	REAR BUMPER SPOILER <i>cut</i>	\$ 246.00	✓
4	REAR BUMPER COVER TRIM-LH/RH <i>Rebond</i>	2 \$ 44.00	X
5	REAR BUMPER CLOSING ELEMENT <i>Rebond</i>	\$ 124.00	X
6	REAR BUMPER CENTRE PLATE MOUNT KIT <i>Rebond</i>	\$ 51.00	X
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>Rebond</i>	2 \$ 108.00	X
8	REAR BUMPER GUIDE SECTION-LH/RH <i>Rebond</i>	2 \$ 64.00	+
9	REAR BUMPER LOW GUIDE SECTION-LH/RH <i>Rebond</i>	2 \$ 96.00	+
10	REAR BUMPER SIDE REINFORCEMENT-LH/RH ?	2 \$ 786.00	?
11	REAR BUMPER HOLDING STRAP-LH/RH <i>Rebond</i>	2 \$ 108.00	X
12	REAR SENSOR <i>Rebond</i>	2 \$ 421.00	+
13	REAR SENSOR SEAL RING <i>Rebond</i>	4 \$ 14.00	+
14	TAIL LIGHT-LH ?	\$ 1,293.00	?
15	TAIL LIGHT TRIM-LH <i>Rebond</i>	\$ 26.00	X
16	REAR SILENCER ?	\$ 982.00	?
17	REAR SILENCER DUAL CLIP ?	\$ 50.00	?
18	REAR SILENCER TRIM-LH ?	\$ 117.00	?
19	SUNDRIES ?	\$ 400.00	?
20	REAR CAR PLATE NO. <i>Rebond</i>	S/N \$ 25.00	X
TOTAL SPARE PARTS CHARGES		\$ 7,096.00	
TOTAL LABOUR CHARGES		\$ 2,752.00	
GRAND TOTAL		\$ 9,848.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 11/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant