



AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

AIG Building

#07-16

Singapore (079120)

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 6/7/2018

Vehicle Num : SKR8555M

Make/Model : AUDI A7 3.0

Chassis No : WAUZZZ4GXB011499

Accident Date : 4/7/2018

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR FENDER LH	1 pc	\$ 1,900.00	\$ Ry 1,900.00
2	REAR BUMPER LH	1 pc	\$ 2,000.00	\$ Rx 2,000.00
3	WHEELHOUSING LINER LH	1 pc	\$ 170.00	\$ x 170.00
4	REAR DOOR LH	1 pc	\$ 2,500.00	\$ bt 2,500.00
5	REAR DOOR INNER SEAL LH	1 pc	\$ 360.00	\$ uc 360.00
6	ROCKER PANEL LH	1 pc	\$ 575.00	\$ de 575.00
7	RIM	1 pc	\$ 2,300.00	\$ cut 2,300.00
8	TYRE	1 pc	\$ 600.00	\$? 600.00
9	REAR DRIVESHAFT LH	1 pc	\$ 1,580.00	\$? 1,580.00
10	REAR WHEELBEARING HOUSING LH	1 pc	\$ 930.00	\$? 930.00
11	TIE ROD LH	1 pc	\$ 95.00	\$? 95.00
12	CONTROL ARM UPPER LH	1 pc	\$ 450.00	\$? 450.00
13	TRAILING ARM LH	1 pc	\$ 720.00	\$? 720.00
TOTAL PARTS				\$ 14,180.00
LABOUR				
1	To remove/ replace/ refit & panel beat of rear bumper, rear fender LH, rear door LH, rocker panel LH & other affected area			\$ 800 1,300.00
2	To putty & respray rear bumper, rear fender LH, rear door LH, rocker panel LH & other affected accident area.			\$ 900 1,500.00
3	To check accident affected wiring system & recover.			\$ 30 50.00
4	To remove & refit door/window wiring mechanism.			\$ ✓ 50.00
5	To recode & decode engine management system & fault code clearing after repair works.			\$ ✓ 100.00
6	To send for wheel alignment.			\$ 80 100.00
7	To remove/replace & refit under carriage.		photo.	\$ 150? 300.00
TOTAL				\$ 17,580.00
GST 7%				\$ 1,230.60
GRAND TOTAL				\$ 18,810.60

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1

Tanjin 27495749
WP
11/7/18 @ 1730
6 days
Lumpsum
Ready after repair
suu@lkkauto.com