



AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 AIG Building
 #07-16
 Singapore (079120)

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East
 #05-155, Enterprise Hub
 Singapore 608586

Repair Estimate

Tel: 6267 9916
 Fax: 6267 9313
 www.carcrafters.sg

Date : 6/7/2018

Vehicle Num : SKR8555M

Make/Model : AUDI A7 3.0

Chassis No : WAUZZZ4GXB011499

Accident Date : 4/7/2018

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR FENDER LH	1 pc	\$ 1,900.00	\$ 1,900.00
2	REAR BUMPER LH	1 pc	\$ 2,000.00	\$ 2,000.00
3	WHEELHOUSING LINER LH	1 pc	\$ 170.00	\$ 170.00
4	REAR DOOR LH	1 pc	\$ 2,500.00	\$ 2,500.00
5	REAR DOOR INNER SEAL LH	1 pc	\$ 360.00	\$ 360.00
6	ROCKER PANEL LH	1 pc	\$ 575.00	\$ 575.00
7	RIM	1 pc	\$ 2,300.00	\$ 2,300.00
8	TYRE	1 pc	\$ 600.00	\$ 600.00
9	REAR DRIVESHAFT LH	1 pc	\$ 1,580.00	\$ 1,580.00
10	REAR WHEELBEARING HOUSING LH	1 pc	\$ 930.00	\$ 930.00
11	TIE ROD LH	1 pc	\$ 95.00	\$ 95.00
12	CONTROL ARM UPPER LH	1 pc	\$ 450.00	\$ 450.00
13	TRAILING ARM LH	1 pc	\$ 720.00	\$ 720.00
	TOTAL PARTS			\$ 14,180.00
	LABOUR			
1	To remove/ replace/ refit & panel beat of rear bumper, rear fender LH, rear door LH, rocker panel LH & other affected area			\$ 1,300.00
2	To putty & respray rear bumper, rear fender LH, rear door LH, rocker panel LH & other affected accident area.			\$ 1,500.00
3	To check accident affected wiring system & recover.			\$ 50.00
4	To remove & refit door/window wiring mechanism.			\$ 50.00
5	To recode & decode engine management system & fault code clearing after repair works.			\$ 100.00
6	To send for wheel alignment.			\$ 100.00
7	To remove/replace & refit under carriage.			\$ 300.00
	TOTAL			\$ 17,580.00
	GST 7%			\$ 1,230.60
	GRAND TOTAL			\$ 18,810.60