

(KND010)

INS. CASE OWNER:

CC 6/EQ1801 2354, A 4679

LKK:

IDAC:

Surveyor:

A/Min

DOI:

ASSIGNMENT

5/3/18

Date / Time:

6/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

4m 808TH

Name of Insured:

MYRAA LOGISTICS P/L

Insured Tel No.:

HP:

Claim No.:

0MCH417-000760

Excess Sec II :SS

D.O.A:

5/3/18

Policy No.:

Make / Model:

MITSUBISHI

Place of Accident:

67 MYRAA PARADE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD SHAMBER BIN MOHD

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability:

Final ? Yes / No

SDX 61A

INSRS:
WSP:
Tel:
Liability:
RMKS:Premium
CarzINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

6/7/18
11H

29-11-18

TRANSFER - THIN? TO JOY

17-12-18

01144M called 012A - no ans.

6 1154 called 2x - no answer

10 284 called - no answer

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

20/12/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 2-10-18

Confirm with:

Confirm by:

Repair Cost:

SS 3600

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 11-12-18

Confirm with:

Email

Call

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

SS 3600

Loss of Rental (LOR):

SS 450

(4 days) 120

Loss of Use (LOU):

SS 15

(x days)

Loss of Income (LOI):

SS 15

(x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 745

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 4,087.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4,087.45

Name 1:

PREMIUM CARE SERVICES P/L LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

011
19/11
011

ASS. REC. BY: Adrian King

REF:

u

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDX61A. Yr Regn: 206, Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier. CC 1986.

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 67539 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU600063728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18.

R: 235/55R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 05/07/13.

Survey held at: Premium Carz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP EQ.

\$3,600

R (\$3,715.71/517)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS (\$

Phone:

Other:

TOTAL

Report Format:

Lump Sum / L.B.L. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118012354/ub3

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 06-07-2018



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 8087H	Veh. Inspected	SDX 61A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/07/2018	Inspection Date
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Date : 05/07/2018

TO: EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Our Customer: Lee Kok Leong

Vehicle No: SDX61A

Model: Toyota Harrier Elegance 2.0A

Manufacture Year: 2015

Date of Accident: 05/07/2018

Total Estimate Repair Days: 6

Total Pages: 1

254600063728

Attn: Motor Claim Department
Fax: 6224 3903

Re: Repair Estimate For Third Party Claim against YM8087H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Replaced</i>	1	\$1,381.20	\$1,381.20	✓
2	Rear bumper clip <i>me</i>	10	\$5.78	\$57.80	✓ 30
3	Rear bumper side retainer RH <i>for</i>	1	\$68.30	\$68.30	✓
4	Rear bumper side retainer LH	1	\$68.30	\$68.30	✓
5	Rear bumper lower protector garnish <i>cut</i>	1	\$865.70	\$865.70	✓ 369.10
6	Tail gate <i>Replaced</i>	1	\$2,379.00	\$2,379.00	✓ 1680
7	Tail gate lock <i>Replaced</i>	1	\$590.00	\$590.00	✓ 418.60
8	Tail gate weatherstrip <i>new</i>	1	\$442.00	\$442.00	+
9	Tail gate "Harrier" emblem <i>me</i>	1	\$60.00	\$60.00	✓
10	Tail gate insulator board <i>for new</i>	1	\$578.00	\$578.00	✓
11	Tail gate insulator clip	1	\$5.78	\$5.78	✓
12	Rear end panel <i>Replaced</i>	1	repair	repair	+
	Sub Total			\$6,496.08	
	Less 25%			\$1,624.02	
	Sub-Total 1			\$4,872.06	
A.	Spare parts (S/Nett)				
1	Sealant <i>new</i>	1	\$60.00	\$60.00	✓
2	Reverse sensor (Set) <i>new</i>	1	\$250.00	\$250.00	✓ 200
3	Rear number plate <i>for new Best</i>	1	\$ 40.00	\$40.00	✓ 30
4	Rear number plate casing	1	\$ 60.00	\$60.00	✓ 30
	Sub-Total 2			\$410.00	
	Total Spare Parts			\$5,282.06	
B.	Labour				
1	To check wiring.			\$60.00	✓ 30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	✓ 450 1030
3	Spray painting all affected parts & areas. <i>including number plate garnish</i>			\$800.00	✓ 450
4	To spray anti-rust undercoat.			\$60.00	+
5	To remove and refit rear windscreen glass.			\$120.00	✓ 100
	Total Labour			\$1,840.00	
	Total Repair Cost			\$7,122.06	

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Adnan Lij
2/5 05/07/18
04 days

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

supplementary 135.15

total: 448177
4/5: 3.6k

36k

Date: 06/07/2018

TO: EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

Our Customer: Lee Kok Leong
Vehicle No: SDX61A
Model: Toyota Harrier Elegance 2.0A
Manufacture Year: 2015
Date of Accident: 05/07/2018
Total Estimate Repair Days: 6
Total Pages: 1

Attn: Motor Claim Department
Fax: 6224 3903

Re: Supplementary Repair Estimate For Third Party Claim against YM8087H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	"Toyota" logo <i>new</i>	1	\$78.00	\$78.00	<i>✓</i>
2	Rear bumper foam <i>del</i>	1	\$180.20	\$180.20	<i>✓</i>
	Sub Total			\$258.20	
	Less 25%			\$64.55	
	Supplementary Total Repair Cost			\$193.65	

180.20
135.15

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Lee Kok Leong
 Period of Insurance : 02 Feb 2018 To 01 Feb 2019
 Engine No. : 3ZRB676349
 Chassis No. : ZSU800093728

Vehicle No. : SDX61A
 Policy No. : 2100450839-02
 Endorsement No. :
 Issued Date : 08 Jan 2018

ABOUT THE COVER

Make/Model : TOYOTA HARRIER 2.0 PREMIUM
 Engine Capacity/Tonnage : 1,986.00 CC Sum Insured : Market Value First Year of Registration : 2016
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 *You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDP") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, rally, taxi or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1800cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 183) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lee Kok Leong - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
 Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sale Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 183), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1950 (Malaysia).

05/14/15000

LEE KOK LEONG

BLK 112 WHAMPOA ROAD #06-77
 SINGAPORE 321112 SP-BRIANTAN

Underwritten by AIO Asia Pacific Insurance Pte. Ltd.

M. N. L.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

05/14/15000



Co. Reg. No.: 201416720G
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

INVOICE NO: PC8914

Date : 17/12/2018

Your Ref.: CC6/EQI18012354/ub3
Our Ref.: 0322/SDX61A/TP/PC/0718

Bill To :

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

Our Customer : Lee Kok Leong
IC No : S7238468G
Address : Blk 112 Whampoa Road
#06-77
Singapore 321112

Vehicle No : SDX61A
Date of Accident : 05/07/2018
Model : Toyota Harrier Elegance 2.0A

Re: Third Party Claim Against YM8087H

No.	Item Descriptions	Amount
1	FINALIZED SETTLEMENT SUM	
	COR	\$ 3,600.00
	Rental Fee (4 days @ \$120/day)	\$ 480.00
	LTA Search Fee	\$ 7.45
TOTAL AMOUNT DUE		\$ 4,087.45

(Singapore Dollars Four Thousand Eighty Seven and Cents Forty Five only)

Yours faithfully



Premium Carz Services Pte Ltd

* All cheque should be crossed and make payable to "Premium Carz Services Pte Ltd"



YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg	06 Jul 1997

NP 428A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7238468G



LEE KOK LEONG
(LI GUOLIANG)
李国良
Race
CHINESE
Date of Birth
14-10-1972
Country of Birth
SINGAPORE
Sex
M

107532



NRIC No. S7238468G



Issue Date
01-06-1993
Date of Expiry
25-06-1993

APT BLK 112 WHAMPOA ROAD #08-77
SINGAPORE 321112
NRIC No. S7238468G Date: 09/08/2018



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 03/10/2018

Your Ref : CC6/EQ118012354/ub3

Our Ref : 0322/SDX61A/TP/PC/0718

EQ INSURANCE COMPANY LTD
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110
Attn : Motor Claims Dept.

Dear Sir/Madam

ACCIDENT INVOLVING SDX61A & YM8087H ON 05/07/2018 ALONG IN FRONT OF BLK 71 MARINE DRIVE

We refer to the above accident.

The accident was caused solely by the negligence of your insured and as a result, we had incurred the following Costs and Losses: -

Costs of Repair (Lump Sum)	\$ 3,600.00
Rental Fee (4 days at \$120/day)	\$ 480.00
LTA TP Search Fee	\$ 7.45
Claimed Amount	<u>\$ 4,087.45</u>

Enclosed are the supporting documents for your perusal:

1. Invoice SDX61A
2. Rental Agreement/Receipt
3. LTA Tax Invoice/Receipt
4. GIA Report for SDX61A
5. Certificate of Insurance
6. Satisfaction Voucher
7. Letter of Authority and Indemnity

Please let us hear from you within the next 14 days.

Yours faithfully



PREMIUM CARZ SERVICES PTE LTD

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 17 December 2018 3:05 PM
To: 'antaralogistics@yahoo.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING YM 8087H AND SDX 61A ON 05/07/2018

Our ref: CC6/EQI18012354/Ajb3

ANTARA LOGISTICS PTE LTD

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING YM 8087H AND SDX 61A ON 05/07/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417583
Tel: 6636 9100 Fax: 6636 9113

LETTER OF AUTHORITY AND INDEMNITY

ACCIDENT INVOLVING VEHICLE NO. SDX61A AND YM8087H
AT/ALONG IN FRONT OF BLK 71 MARINE DRIVE
ON 5 DAY JULY MONTH 2018 YEAR

- a) I/We, the owner of vehicle no. SDX61A hereby instruct and authorize you to commence repair to the said vehicles.
- b) You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment are given by me/us with respect to the conduct of my/our claims against third party driver and/or his insurers including if necessary, to commence legal proceedings in Court in my/our name against the third party.
- c) You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit. Upon settlement of my claim, you are authorized to sign any Discharge Voucher or any document to confirm my acceptance of the settlement as full and final discharge of my claim, on my behalf.
- d) Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional cost and disbursements for acting for me/us and to relieve payment of the balance of the settlement sum on my/our behalf directly into your account.
- e) In the event that, I/we am/are required to attend at my/our solicitors' office or to attend court in connection to my/our claim, I/we shall render full co-operation.
- f) In the event that my/our claim against the third party and/or his insurers is Not successful or cannot be proceeded with, I/we authorized you to make a claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respects, I/we understand and accept that the excess amount applicable under the policy of insurance shall be borne by me/us. I/we shall also be personally liable to bear all legal cost incurred by you in claiming back for the repair cost by your Solicitors.
- g) If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any losses recoverable under the policy of insurance or make any offer to pay less than the amount claimed by you, I/we agree to undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
- h) I/we have read and understand the above statement and agreed.

Dated this 5 day July month 2018 year

Signature


Name

NRIC/ROC No.

Address


: Lee Kok Leong
: S7238468G
: Blk 112 Whampoa Road
: #06-77
: Singapore 32112

Company Stamp





Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

SATISFACTION VOUCHER

Our ref.: 0322/SDX61A/TP/PC/0718
To : AE Insurance Company Ltd

ACCIDENT INVOLVING SDX61A AND YM8087H ON 5/7/2018
ALONG IN FRONT OF BLK 71 MARINE DRIVE

I/We hereby acknowledge having received from Premium Carz Services Pte Ltd, 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883, my/our vehicle number SDX61A which has been repaired to my/our satisfaction and acceptance. I/We admit that the payment of *SGD _____ account for such repairs is in full discharge of my/our claim.

Dated : 9 day of July 2018

Signature : 

Owners' name: Lee Kok Leong

NRIC/Co. Reg.: S72 38468G

Address : Blk 112 Whampoa Road
#06-77
Singapore 321112

(*Based on final settlement from insurance)



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417853
Tel : 6836 9100 Fax : 6636 9113

INVOICE: 0322

Date : 3/10/2018

Bill To :

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block, MND Complex
Singapore 069110

Our Customer

Name : Lee Kok Leong
IC No. : S7238468G
Address : Blk 112 Whampoa Road
#06-77
Singapore 321112

Vehicle No : SDX61A
Date of Accident : 05/07/2018
Model : Toyota Harrier

No.		Qty	Unit Price	Amount
1	To supply labour and materials to repair the above-mentioned vehicle to its pre-accident condition (Lump Sum)	1	-	\$3,600.00
TOTAL				\$3,600.00

For Premium Carz Services Pte Ltd



* All cheque should be crossed and make payable to "Premium Carz Services Pte Ltd"



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

No. 19428

Date. 9/7/18

OFFICIAL RECEIPT

Received from Lee Kok Leong
the sum of Dollars Four hundred eighty only

being Payment Of S\$ 517 L (5/7/18 - 9/7/18)

DAWN ENTERPRISES

\$

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Premium Carz

SDX61A

Nº 35852

RENTAL AGREEMENT

DATE 5/7/18

HIRER'S PARTICULARS

Name Lee Kok Leong
Address Blk 112 Whampoa Road
#06-77
Singapore 321112
I/C or Passport No. S72384686 Country _____
Occupation _____
Date of Birth 14/10/1972 Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 9368 8223 (Residence) 8171997

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

- 1 No insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
- 2 This vehicle is licensed to carry 8 passengers only.
- 3 Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- 4 For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate.
- 5 Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- 6 No refund will be given for vehicle returns early.
- 7 No refund will be given for petrol left in vehicle.
- 8 Hirer is liable to pay all parking fine and traffic summonses.
- 9 Vehicles to be return during office hour only.
- 10 No Service on Public Holiday and Sunday.

CHARGES

4 Day at \$ <u>120.00</u> per days	\$ <u>480.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	
TOTAL AMOUNT	\$ <u>480.00</u>
AMOUNT PAID	\$ <u>480.00</u>
BALANCE DUE	
Days Extension From _____ To _____	
Amount Deposit (refundable) \$	

SCHEDULE

SKF 547L T/A/H

Date	Time	Mileage
5/7/18	4.30pm	
9/7/18	5.15pm	

FROM

5/7/18

TO

9/7/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Land Transport Authority

GST Registration No. : M4-0006529-2

Receipt Date/Time : 05 Jul 2018 / 16:42:47

Receipt No. : ITNET-00000-180705-001687

Previous Receipt No. :

S/N	Item Description/
-----	-------------------

Business Transaction Reference
No.

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - YM8087H

As at 05 Jul 2018/13:40:00

Insurance Co: EQ INSURANCE COMPANY LTD

1 Insurance Enquiry - YM8087H

Enquiry Fee

20180705164159372044

7.00	0.49	7.49
------	------	------

Sub-Total	7.00	0.49	7.49
-----------	------	------	------

Total Before Rounding	7.00	0.49	7.49
-----------------------	------	------	------

Rounding Difference	0.04
---------------------	------

Total Amount Payable	7.45
----------------------	------

Paid By

20180705164212949	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total	7.45
-------	------

Cash Change	0.00
-------------	------

Tendered Amount	7.45
-----------------	------

Excess Refundable Amount	0.00
--------------------------	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 31/12/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YM 8087H (Insd Veh)	Your Ref. No. : DMCHHQ17-000230
	SDX 61A (TP Veh)	Our Ref. No. : CC6/EQI18012354/Ajb3q2
Date of Accident	5/7/2018	

Liability	100%	
Final Repair Cost	: \$ 3,600.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 480.00	4 days
Others:	: \$ 7.45	
	: \$	
	4,087.45	
Final Settlement Sum	: \$ 4,087.45	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	PREMIUM CARZ SERVICES PTE LTD	: \$ 4,087.45
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ18012354/Ajb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 31-12-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 8087H	Veh. Inspected	SDX 61A
Policy No.	DMCHHQ17-000230	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600063728	Colour	SILVER
Odometer	67539	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/07/2018	Inspection Date	05/07/2018
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 61A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,381.20	1,381.20
10	REAR BUMPER CLIP @\$5.78	NECESSARY	57.80	30.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	68.30	68.30
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	68.30	68.30
1	REAR BUMPER LOWER PROTECTOR GARNISH	CUT	865.70	369.10
1	TAIL GATE	DENTED	2,379.00	1,680.00
1	TAIL GATE LOCK	DAMAGED	590.00	418.60
1	TAIL GATE WEATHERSTRIP	NOT NECESSARY	442.00	-
1	TAIL GATE 'HARRIER' EMBLEM	NECESSARY	60.00	60.00
1	TAIL GATE INSULATOR BOARD	NOT NECESSARY	578.00	-
1	TAIL GATE INSULATOR CLIP	NOT NECESSARY	5.78	-
1	REAR END PANEL (NPA)	NOT NECESSARY	-	-
1	'TOYOTA' LOGO (ADDITIONAL)	NOT NECESSARY	78.00	-
1	REAR BUMPER FOAM (ADDITIONAL)	DEFORMED	180.20	180.20
	LESS 25% DISCOUNT		-1,688.57	-1,063.93
			5,065.71	3,191.77
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT (SN)	NECESSARY	60.00	60.00
1	SET REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	40.00	30.00
1	REAR NUMBER PLATE CASING (SN)	BENT	60.00	30.00
			410.00	320.00
<u>LABOUR</u>				
	TO CHECK WIRING.		60.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLAC ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		800.00	450.00
	TO SPRAY ANTI-RUST UNDERCOAT.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	100.00

Report Ref No. CC6/EQI18012354/Ajb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS . (MOULDING NUMBER PLATE GARNISH).		800.00	450.00
			1,840.00	1,030.00
GRAND TOTAL			7,315.71	4,541.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC6/EQ118012354/Ajb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.