

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



⊗ 14/8/2018
any & repi
Dw 18/7
⊗ 20/8/2018
any & repi

GST REG. NO : M2 - 0020081 - X

06 JUL 2018

E S T I M A T E

Estimate No. : **b1 47594**
Date Estimated : **06/07/2018**
Prepared By : **Chua Kee Sin**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Yoon Chee Hung
22A Berwick Drive

Singapore 519255

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD420U	C867185	25/10/2011	523iA	0

DESCRIPTIONVALUE

Replace rear boot lid, rear bumper and remove attachment
etc include knock on accident dent

1700 2,550.00

Spreya rear bumper, tail panel and rear boot lid

1868 2,819.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

? 150.00

Total Labour 1: **5,967.00**DESCRIPTIONQTY PRICVALUE

BOOTLID
SET MOUNTS PDC SENSOR REAR (PDC)
RR BUMPER BOTTOM CENTRE GUIDE
RR BUMPER CTR GUIDE
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
RR BUMPER CARRIER
RR BUMPER PANEL PRIMED (PDC)
RR BUMPER TOW HOOK COVER PRIMED
PROTECTION FOIL L=55MM
RR BUMPER ADAPTER
EMBLEM GROMMET
BMW EMBLEM
MODEL LETTERING 523I
STRIKER BOOT LID
SPINDLE DRIVE RH
TRUNK LID LOCK TOP
TRUNK LID POWER LOCK DRIVE
TRIGGER CONTACT
REAR LH REFLECTOR

1 1,602.40
1 62.95
1 58.95
1 67.35
1 142.55
1 142.55
1 714.25
1 1,467.20
1 46.45
2 4.75
1 48.00
2 0.80
1 69.50
1 62.55
1 52.25
1 522.65
1 425.35
1 586.65
1 131.95
1 35.20

bt 1,602.40
? 62.95
? 58.95
? 67.35
? 142.55
? 142.55
? 714.25
de 1,467.20
de 46.45
nei 9.50
? 48.00
nei 1.60
nei 69.50
nei 62.55
? 52.25
? 522.65
? 425.35
? 586.65
? 131.95
K 35.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47594
Date Estimated : 06/07/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD420U	C867185	25/10/2011	523iA	0

DESCRIPTION

REAR RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (A89 IMPERIALBLAU)

QTY	PRIC	VALUE
1	35.20	35.20
4	5.05	20.20
4	368.80	1,475.20
Total Parts :		7,780.45

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display parts during resurvey
- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 20/8/18 @ 1pm Excess S\$ _____

Surveyor's Name Tan Jia Sign Tan Jia

Surveyor's Tel 92495744 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes ☒ No ☐ PML Yes / No _____

Surveyor's E-mail tanjia@lkk.com

No. of Working Days Recommend 05 days

Labour 1	:	5,967.00
Parts	:	7,780.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	962.32
Grand Total	:	14,709.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **