

Surveyor

REF:


CC3/MSG18012407/NSB02

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **SLK 4271H**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMB 1543 D** Yr Regn: **Dec / 2014**
 Type: M.Car / M.Cycle **(Bus)** / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Man** C.C. **10518**
 Colour **Multicolour** A/C: Insured / Std / NI / NA
 Sp.Reading **336000.7** T/Radio: Insured / Std / NI / NA
 Eng/No: **50338902813893**
 C/No: **WMAA22ZZ3F7002484**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **275 / 70 R22.5**
 R: **275 / 70 R22.5**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Firenza**
 Front _____ Rear _____
 R/Bal. **6** mm R/Bal. **6/6** mm
 L/Bal. **6** mm L/Bal. **6/6** mm
 D.O.A. **13/3/2018** D.O.I. **5/7/2018**
 Survey held at **SMRT**
 Des. of Damages: Frt / **Rear** / **O/S** N/S / U/C / Rooftop or
O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB 1543D - X
	SLK 4271H - CC6 / LCR17019539 / WMAA302
10/07/18	@14:16 p.m. received ZA to Eliza Ho Tung Boon via messenger.
29/10/18	@16:27 p.m. spoken with Catherine (repairer), vehicle has not send in to repair.
RECEIVED 30 OCT 2018	

Date/Time, File Pass to?

☒ Preli. Report
☐ Final Report

Days Of Repair: **2**

1) _____
 Date/Time, File Return to?

Resurvey No. of Trip: **1**

2) _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS: \$ _____
 Photos _____
 Others _____

Report Format: **Prel. Report**
 Lump Sum / I.B.I: (\$ _____)

TOTAL

150
10
160

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SMB1543D		
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	OmniBus (SMRT - ARF-exempted)		
Vehicle Make :	MAN		
Vehicle Model :	NL 320F (A22) 11L AUTO ABS TURBO		
Chassis No. :	WMAA22ZZ3F7002484		
Propellant :	Diesel		
Engine No. :	50338902813893		
Engine Capacity :	10518 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	18000 kg		
Unladen Weight :	11280 kg		
Year Of Manufacture :	2014		
Original Registration Date :	12 Dec 2014		
Lifespan Expiry Date :	11 Dec 2031		
Road Tax Expiry Date :	11 Dec 2018		
Inspection Due Date :	11 Dec 2018		
Intended Transfer Date :	09 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

Shirley Hiew (LKK Auto)

From: Iryani Amin <iryani_amin@sg.msig-asia.com>
Sent: Tuesday, 10 July 2018 8:56 AM
To: Shirley Hiew (LKK Auto)
Cc: Eliza Ho
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 13/03/2018 , SMB 1543D (TP VEHICLE), SLK 4271H (OI VEHICLE)

Importance: High

Dear Shirley ,

This is our claim refer number : M552381

Have a nice day

Iryani Binte Amin
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2555 | Direct fax +65 6225 7402 | iryani_amin@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



A member of **MS&AD** INSURANCE GROUP

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 9 July, 2018 2:37 PM
To: Lionel Tan <lionel_tan@sg.msig-asia.com>; Iryani Amin <iryani_amin@sg.msig-asia.com>
Cc: 'KKLau' <kklau@lkkauto.com>; 'SUR' <sur@lkkauto.com>; 'Accounts (LKKAuto)' <account@lkkauto.com>
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 13/03/2018 , SMB 1543D (TP VEHICLE), SLK 4271H (OI VEHICLE)

Dear Lionel/Iryani,

Please be informed that we had inspected the vehicle SMB 1543D M/s: SMRT AUTOMOTIVE SERVICE PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 on 05/07/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 9 July 2018 2:37 PM
To: 'Lionel Tan'; iryani_amin@sg.msig-asia.com
Cc: 'KKLau'; 'SUR'; 'Accounts (LKKAuto)'
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 13/03/2018 , SMB 1543D (TP VEHICLE), SLK 4271H (OI VEHICLE)
Attachments: TP GIA REPORT.pdf

Dear Lionel/Iryani,

Please be informed that we had inspected the vehicle SMB 1543D M/s: SMRT AUTOMOTIVE SERVICE PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 on 05/07/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 10 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLK4271H	Accident Date	: 13/03/2018
TP Vehicle No	: SMB1543D	Assignment Date	: 10/07/2018
Make	: MAN NL320F (A22)	Est. Duration of Repair	: 2 days
Date of Inspection	: 05/07/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,428.00
Revised Amount	:S\$	1,845.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,845.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/03/2018 17:09
Date Of Accident	13/03/2018 10:50
Exact Location Of Accident	JALAN BUKIT MERAH AFTER BUS STOP NO: 10501 (BLK 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMB1543D
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	MAN
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	DII027592MFBP
Cover Note Number	
Driver	
Name of Driver	LI XUAN
Passport No/FIN	G2988346M
Date Of Birth	21/10/1988
Occupation	OUTDOOR
Date Of Driving Pass	07/08/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 ANG MO KIO ST 62
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TREVELLING ON THE LEFT MOST LANE OF JALAN BUKIT MERAH ON THE ABOVE STATED DATE & TIME. WHEN SUDDENLY ONE PRIVATE VEHICLE, SLK4271H CUT INTO MY LANE FROM THE RIGHT AND THE LEFT FRONT PORTION GRAZED AGAINST MY BUS RIGHT REAR PORTION. MY BUS SUSTAINED RIGHT REAR BODY SCRATHES. THIRD PARTY REFUSED TO EXCHANGE PARTICULARS & LEFT THE SCENE AFTER TAKING SOME PHOTOS. NO INJURY REPORTED. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK4271H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/03/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

AS Attached —

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to A111 report -

DECLARATION

I/We declare that foregoing particulars are true in every respect.



Policyholder's signature

Date & Time: 13/03/18


Driver's signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:


Sketch Plan Pg. 3



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1543D
Ref. No : BUS/03/18/1022
Reg. Date : 01/01/1900
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Li Xuan
Type of Accident : SIDE SWIPE
Date / Time of Accident : 13/03/2018 10:50:00 AM
Accident Reported Date / Time : 13/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : MSIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
scratches on the right rear portion.
TP: SLK4271H (MSIG)
Prepared Date : 14/03/2018 03:19:03 PM



Sathya Sai
5/7/2018

- ~~Est~~ Lump Sum Repair
- Photo after paint

2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 1,218.00	0.00
Total Material Charges	: 0.00	0.00
Other Charges	: 150.00	0.00
TOTAL	: 2,428.00	0.00
Lum Sum Total	: 2,450.00	0.00
No. of Repair Days	: 3.00	0.00 2 days
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	: 05/07/2018 10:20:10 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/07/2018 10:20:10 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,060.00	0.00 795
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,218.00	0.00 900
Total Spray Painting & Panel Beating	1,218.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL RHS REAR	150.00	0.00 ✓
Total Other Costs	150.00	0.00

2428

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)										
									0.00	0.00

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

795
+ 1050
1845

L/S: \$ 1850 @ 2 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018		10 Jul 2018 08:56 Edit Adj Rpt	S\$1,845.00 Edit Estimates	S\$1,845.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Main Claimant:	SMRT BUSES LTD , Co. Reg. No.: 198202292D								
Vehicle Reg. No.:	SMB1543D	Date of Loss:	13/03/2018 10:00 - :59 [39 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552381	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLK4271H	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 09/08/2018]								
Driver/Custodian (Insured):	TAN TECK HAI, CHRISTOPHER (59 / Male), NRIC: S1304481C, Tel: +6598209860								
Adj Asg. Remarks:	DIRECT SURVEY DONE BY LKK AUTO CONSULTANTS ON 05/07/2018								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB1543D (552381)**
[SLK4271H]
TP
SMRT BUSES LTD
Mar 13 2018 10:00AM
[GRAB RENTALS PTE LTD]
SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/07/18 08:53	Accident Statement From: SC - Reg. No: SLK4271H, Claimant: GRAB RENTALS PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/07/18 14:16	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
3	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/07/18 14:17	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
16	10/07/18 14:17	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
17	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
18	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>
19	10/07/18 14:17	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/07/18 08:55	TPD SMB1543D GIA REPORT		Load PDF	
2	10/07/18 08:55	DIRECT SURVEY DONE BY LKK AUTO		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18012407/NSBE2

Date: 30/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069766MKF

Claimant Vehicle No : SMB1543D

Insured Vehicle No : SLK4271H

Date of Loss: 13/03/2018

Nature of Claim: TP

Claim No: 552381

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB1543D

Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A)

Engine No: 50338902813893

Reg. Date: 12/12/2014 (Man. Year: 2014)

Chassis No: WMAA22ZZ3F7002484

Colour: Multi-colour

Odometer: 336000 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6/6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,428.00	1,845.00	583.00	24.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	2,428.00	1,845.00	583.00	24.01

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 05/07/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Oct 2018)

Parts: N/A MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB1543D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR RH REAR PORTION	New	1,060.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,218.00	900.00
3	PIXEL STENCIL RHS REAR	New	150.00	150.00
Gross Labour Cost (\$\$)			2,428.00	1,845.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >