

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 10 Jul 2018

Preliminary Advice

Vehicle No	: SKW629K	Accident Date	: 30/06/2018
Make	: HONDA ODYSSEY	Policy No.	: DMPCSN1669891701
Assignment Date	: 06/07/2018	Excess	: S\$0.00
Date of Inspection	: 10/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,801.82
Revised Amount	:S\$	7,165.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,165.43

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	64,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,306.00

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 6/6 mm
Tyre Condition (Rear) : 6/6 mm

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle was involved in an accident on 18/2/2018. The damage area is at the same area as this current accident on 30/6/2018. Furthermore , current accident is reported to hit and run.

We suggest to carry out interview/ investigation.