

ASSIGNED BY:

REF

CS/CT1180124181 R1-1039

Date of Instruction:

Surveyor's
Name:

From (Person):

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

at Workshop no/:

of

Policy No:

Sum Insured:

Make of Veh:

(Client's Record):

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Claim No:

Excess:

D.O.A.

Insp: 255 Alexandra Rd.

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 1900 H-X
	SKM 4283 A-X
13/8/18 -	called Mr Ng Vehicle is still not in the office.
	Part by Part \$3193.95 (Red: 7863.89; 71%)

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 03 SEP 2018

Date/Time, File Pass to?



: Preli. Report

1) SKA Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / V.B.I. (\$ 3193.95)

TP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 13:40 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	QUEK JIAN WEN GEORGE (GUO JIANWEN), ID: S9004558Z		
Main Claimant:	HAMZAH BIN MOHAMED, ID: S7801221H		
Vehicle Reg. No.:	SLW1900H	Date of Loss:	05/07/2018 06:00 - :59
Claim Type:	TP / SNM18D03335C02	Policy/Cover Note No.:	DMPCSN3029791700 (Comprehensive)
Vehicle Reg. No. (Insured):	SKM4283A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/07/2018]		
Driver/Custodian (Insured):	QUEK JIAN WEN GEORGE (GUO JIANWEN) (28 / Male), NRIC: S9004558Z		
Adj Asg. Remarks:	EST \$11,831.89, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18012418/R1td3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 4283A	Veh. Inspected	SLW 1900H
Policy No.	DMPCSN3029791700	Coverage (\$)	0.00
Claim No.	SNM18D03335C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/07/2018	Inspection Date	27/08/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 3 September 2018 12:03 PM
To: 'Ng Sin Hai'; Rasul (LKKAuto); SUR
Subject: RE: Submission Pre-Invoice for vehicle SLW1900H

Dear Sin Hai,

Hereby we confirm the following finalization
Cost of repair : \$3,193.95 (before GST)
No of working days : 05 days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Thursday, 30 August 2018 4:41 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Submission Pre-Invoice for vehicle SLW1900H

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : \$3,193.95 (before GST)
No of working days : 05 days. (LOR)

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2018 20:42
Date Of Accident	05/07/2018 06:50
Exact Location Of Accident	TAMPINES AVE 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW1900H
Insured/Policyholder	
Name Of Registered Owner	HAMZAH BIN MOHAMED
NRIC No	S7801221H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92983515
Alternative Phone No	OFFICE-92983515

Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	HAMZAH BIN MOHAMED
NRIC No	S7801221H
Date Of Birth	10/01/1978
Occupation	INDOOR
Date Of Driving Pass	28/03/2000
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92983515
Fax Number	
Contact Number	OFFICE-92983515
Email Address	NOEMAIL

Sketch Plan

Vehicle No. _____

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to remediate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue in Annex E



Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MT000587 (Private Car (2 Years))

1. Index Mark and Registration Number of Vehicle

Chassis No.: JHMRU1810GX203749

2. Name of Policyholder

HAMZAH BIN MOHAMED HUSSEIN

3. Effective date of the Commencement of Insurance for the purposes of the Act

19/01/2018 (17:30:30)

4. Date of Expiry of Insurance

18/01/2020

5. Persons or Class of Persons entitled to drive*

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 56 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account No: E2316DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess : SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
Financial Interest:	OCBC BANK LIMITED		

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorized Signature

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLW1900H

Chassis No : JHMRU1810GX203749

Model : HRV DX-SIN CVT YM 2016

Owner's Name : HAMZAH BIN MOHAMED HUSSEIN

Ins Policy No. :

Date of Accident : 5/7/2018

Document No. : SQT18002766

Date : 6. Jul 2018

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : L15B4533751

Date | Time : 6. Jul 2018 8:29:58 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: HAMZAH BIN MOHAMED HUSSEIN OWNER INSURER: TOKIO MARINE ACC DATE: 05/07/2018 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH: SKM4283A						
BOSUN	SUNDRIES	1	100.00 30 30		100.00	7.00	✓ 107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	✓ 192.60
BKBU01R	REMOVE AND RENEW LHF WHEEL/RIM/TYRE	1	50.00		50.00	3.50	✓ 53.50
BKFE11R	REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS	1	2500.00 1120		2500.00	175.00	✓ 2675.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2000.00 900		2000.00	140.00	✓ 2140.00
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)	1	1680.00 1120? X		1680.00	117.60	✓ 1797.60
	Sum Labor				<u>6510.00</u>	<u>455.70</u>	<u>6.965.70</u>
42700-T7A-J91	DISKALUMINIUM WHEEL	1	765.80	25	574.35	40.20	✓ 614.55
44300-T6A-J51	BEARING ASSYFR.HUB	1	135.50	25	101.62	7.11	✓ 108.73
44600-T0B-A00	HUB ASSYFR.	1	183.50	25	137.62	9.63	✓ 147.25
60260-T7A-010ZZ	PANEL COMPL.FR.FENDER	1	387.20	25	290.40	20.33	✓ 310.73
74150-T7A-N00	FENDER ASSYL.FR INNER	1	88.20	25	66.15	4.63	✓ 70.78
74155-T7A-000	ENCLOSUREL.FR.FENDER	1	9.70	25	7.27	0.51	✓ 7.78
74157-T7B-003	PROTECTOR,LFR.WHEEL ARCH	1	150.60	25	112.95	7.91	✓ 120.86
91501-TR0-003	CLIPINNER FENDER	22	2.30	25	37.95	2.66	✓ 40.61
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	✓ 22.47
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	✓ 48.15
33150-T7S-E11	HEAD LIGHT ASSY,L	1	1479.70	25	1109.77	77.68	✓ 1187.45



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLW1900H
Chassis No : JHMRU1810GX203749
Model : HRV DX-SIN CVT YM 2016
Owner's Name : HAMZAH BIN MOHAMED HUSSEIN
Ins Policy No. :
Date of Accident : 5/7/2018

Document No. : SQT18002766
Date : 6. Jul 2018
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : L15B4533751
Date | Time : 6. Jul 2018 8:29:58 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33900-SLE-J51	LIGHT ASSYR.FR.FOG	1	237.90	25	178.42	12.49	190.91
33950-SLE-J51	LIGHT ASSYL.FR.FOGLIGHT	1	235.00	25	176.25	12.34	188.59
91501-SWA-003	CLIPINSULATOR	8	2.10	25	12.60	0.88	13.48
71126-T7B-Z01	SET.FR.GRILLE ASSY	1	265.50	25	199.12	13.94	213.06
71122-T7A-901	MOLDINGFR.GRILLE UPPER	1	186.10	25	139.57	9.77	149.34
71123-T7A-901	MOLDINGFR.GRILLE	1	42.80	25	32.10	2.25	34.35
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER	1	38.70	25	29.02	2.03	31.05
71151-T7A-000	BEAMR.FR.GRILLE SIDE UPPER	1	17.20	25	12.90	0.90	13.80
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER	1	4.50	25	3.37	0.24	3.61
75700-TA0-A00	EMBLEMFR.	1	25.90	25	19.42	1.36	20.78
90675-SA5-003	NUT,CLIP 6MM	2	2.80	25	4.20	0.29	4.49
91505-TM8-003	CLIPBUMPER	12	2.00	25	18.00	1.26	19.26
04711-T7A-N00ZZ	FACE,FR.BUMPER	1	466.20	25	349.65	24.48	374.13
71102-T7B-000	FACE FR. BUMPER LOWER	1	344.20	25	258.15	18.07	276.22
71103-T7A-000	GRILLEFR.BUMPER	1	77.50	25	58.12	4.07	62.19
71105-T7A-000	GARNISHR.FR.FOG LIGHT	1	21.10	25	15.82	1.11	16.93
71106-T7A-000	GARNISHL.FR.FOG LIGHT	1	21.10	25	15.82	1.11	16.93
71110-T7A-000	SPOILERFR.BUMPER AIR	1	50.00	25	37.50	2.63	40.13
71111-T7A-000	GUIDER.FR.BUMPER AIR	1	27.90	25	20.92	1.46	22.38
71116-T7A-000	GUIDEL.FR.BUMPER AIR	1	27.90	25	20.92	1.46	22.38
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	23.90	25	17.92	1.25	19.17
71193-T7A-000	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-T7A-000	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	22	2.00	25	33.00	2.31	35.31
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER	1	236.60	25	177.45	12.42	189.87
Sum Item					4367.84	305.75	4,673.59
BO-WHEEL ALIGN X4 WHEEL ALIGNMENT					180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Printed on 6/7/2018 8:43:44 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLW1900H

Chassis No : JHMRU1810GX203749

Model : HRV DX-SIN CVT YM 2016

Owner's Name : HAMZAH BIN MOHAMED HUSSEIN

Ins Policy No. :

Date of Accident : 5/7/2018

Document No. : SQT18002766 Page 3

Date : 6. Jul 2018

Customer No. : WZC008

Svc Advisor : NG SIN HAI


Engine No : L15B4533751

Date | Time : 6. Jul 2018 8:29:58 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	RASUL - Hp 90010068						
Date & Time	27/08/18 @ 1220						
Excess							
Status							
Signature							

Total Amount 11,057.84 774.05 11,831.89

Total (Inclusive of GST) 11,831.89

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 6/7/2018 8:43:44 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRU1810GX203749
License No: SLW1900H
Mileage: 931
Engine No: L15B4533751

Document No: SVO18044746
Printed By: SHNG
Order Date: 31. July 2018
Order Time: 7:00:39 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:HAMZAH BIN MOHAMED HUSSEIN OWNER INSURER:TOKIO MARINE ACC DATE:05/07/2018 SURVEYED BY:RASUL DATE:27/08/2018 REF NO: TP INSURER:CHINA TAIPING INSURANCE (S'PORE) PTE LT TP VEH:SKM4283A						
42700-T7A-J93	DISK,ALUMINIUM WHEEL	1	721.60	25	541.20	37.88	579.08
74157-T7M-H01	PROTECTORL.FR.WHEEL ARCH	1	150.60	25	112.95	7.91	120.86
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
91505-TM8-003	CLIPBUMPER	12	2.00	25	16.00	1.26	19.26
71198-T7A-000	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	22	2.00	25	33.00	2.31	35.31
	SUM PARTS:				733.95	51.38	785.33
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BML01I	1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	180.00		180.00	12.60	192.60
BKBU01R	1438 REMOVE AND RENEW LHF WHEEL/RIM/TYRE	1	50.00		50.00	3.50	53.50
BKFE11R	1466 REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS	1	1,120.00		1,120.00	78.40	1,198.40
BP05R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				2,280.00	159.60	2,439.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				3,193.95	223.58	3,417.53
	Total Payable (SGD)						3,417.53

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018		06 Jul 2018 13:40 Edit Adj Rpt	\$43,193.95 Edit Estimates	\$43,193.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	QUEK JIAN WEN GEORGE (GUO JIANWEN), ID: S9004558Z								
Main Claimant:	HAMZAH BIN MOHAMED, ID: S7801221H								
Vehicle Reg. No.:	SLW1900H	Date of Loss:	05/07/2018 06:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03335C02	Policy/Cover Note No.:	DMPCSN3029791700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKM4283A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/07/2018]								
Driver/Custodian (Insured):	QUEK JIAN WEN GEORGE (GUO JIANWEN) (28 / Female), NRIC: S9004558Z								
Adj Asg. Remarks:	EST \$11,831.89, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW1900H (SNM18D03335C02)
[SKM4283A]
TP
HAMZAH BIN MOHAMED
Jul 5 2018 6:00AM
[QUEK JIAN WEN GEORGE (GUO JIANWEN)]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail	Print	
1	05/07/18 20:48	Video - Accident [Linked Accident Report Documents]							Load AVI		
2	05/07/18 20:48	Video - Accident [Linked Accident Report Documents]							Load AVI		
3	05/07/18 20:49	Video - Accident [Linked Accident Report Documents]							Load AVI		
4	05/07/18 20:49	Video - Accident [Linked Accident Report Documents]							Load AVI		
5	05/07/18 20:49	Video - Accident [Linked Accident Report Documents]							Load AVI		
Assessment Reports									1 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail	Print	
1	05/07/18 20:51	Accident Statement							Load HTM		
Photos/Images									3 per page		☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail	Print	
1	05/07/18 20:50	Accident Photo [Linked Accident Report Documents]							Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/09/18 11:38	General View							Load JPG	☒	
2	03/09/18 11:38	General View							Load JPG	☒	
3	03/09/18 11:38	General View							Load JPG	☒	
4	03/09/18 11:38	General View							Load JPG	☒	
5	03/09/18 11:38	General View							Load JPG	☒	
6	03/09/18 11:38	General View							Load JPG	☒	
7	03/09/18 11:38	General View							Load JPG	☒	
8	03/09/18 11:38	General View							Load JPG	☒	
9	03/09/18 11:38	General View							Load JPG	☒	
10	03/09/18 11:38	General View							Load JPG	☒	
11	03/09/18 11:38	General View							Load JPG	☒	
12	03/09/18 11:38	General View							Load JPG	☒	
13	03/09/18 11:38	General View							Load JPG	☒	
14	03/09/18 11:38	General View							Load JPG	☒	
15	03/09/18 11:38	General View							Load JPG	☒	
16	03/09/18 11:38	General View							Load JPG	☒	
17	03/09/18 11:38	General View							Load JPG	☒	
18	03/09/18 11:38	General View							Load JPG	☒	
19	03/09/18 11:38	General View							Load JPG	☒	
20	03/09/18 11:38	General View							Load JPG	☒	
21	03/09/18 11:38	General View							Load JPG	☒	
22	03/09/18 11:38	General View							Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
23	03/09/18 11:38	General View	Load JPG	☒
24	03/09/18 11:38	General View	Load JPG	☒
25	03/09/18 11:38	General View	Load JPG	☒
26	03/09/18 11:38	General View	Load JPG	☒
27	03/09/18 11:38	General View	Load JPG	☒
28	03/09/18 11:38	General View	Load JPG	☒
29	03/09/18 11:38	General View	Load JPG	☒
30	03/09/18 11:38	General View	Load JPG	☒
31	03/09/18 11:38	General View	Load JPG	☒
32	03/09/18 11:38	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/07/18 13:40	REPAIR EST WITH TP GIA	Load PDF	
2	06/07/18 13:40	OI GIA	Load PDF	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 20:51	Sketch Plan [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 20:48	Video - Accident	Load AVI	
2	05/07/18 20:48	Video - Accident	Load AVI	
3	05/07/18 20:49	Video - Accident	Load AVI	
4	05/07/18 20:49	Video - Accident	Load AVI	
5	05/07/18 20:49	Video - Accident	Load AVI	
Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 20:51	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 20:50	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	05/07/18 20:51	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012418/TD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3029791700

Claimant Vehicle No: SLW1900H

Insured Vehicle No: SKM4283A

Date of Loss: 05/07/2018

Nature of Claim: TP

Claim No: SNM18D03335C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW1900H

Make & Model: HONDA HR-V, 1.5 (A)

Reg. Date: 31/01/2018 (Man. Year: 2017)

Colour: Red

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L15B4533751

Chassis No: JHMRU1810GX203749

Odometer: 13526 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Tyre Size: 215/60 R16

Rear Left Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,647.84	943.95	3,703.89	79.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,410.00	2,250.00	4,160.00	64.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,057.84	3,193.95	7,863.89	71.12
+ GST 7.00/7.00% (S\$)	774.05	223.58	550.47	71.12
Nett Amount (S\$)	11,831.89	3,417.53	8,414.36	71.12

INSPECTION

Date of Assignment: 06/07/2018

Date Inspected: 27/08/2018 Inspected At:

NO. 255 ALEXANDRA ROAD
SINGAPORE 159937
Repairer: Kah Motor Co Sdn Bhd (Ubi)

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)	
Parts: M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLW1900H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*DISKALUMINIUM WHEEL	Scratched	574.35 FS	*541.20 FS
3	1		*BEARING ASSYFR.HUB	Serviceable	101.62 FS	*- FS
4	1		*HUB ASSYFR	Serviceable	137.62 FS	*- FS
5	1		*PANEL COMPL.FR.FENDER	Repair	290.40 FS	*- FS
6	1		*FENDER ASSYL.FR.INNER	Serviceable	66.15 FS	*- FS
7	1		*ENCLOSUREL.FR.FENDER	Serviceable	7.27 FS	*- FS
8	1		*PROTECTOR ,L.FR.WHEEL ARCH	Scratched	112.95 FS	*112.95 FS
9	1		*CLIPINNER FENDER (22 PCS)	Not Necessary	37.95 FS	*- FS
10	14		*CLIPBUMPER	Necessary	21.00 FS	*21.00 FS
11	1		*NUMBER PLATE WITH CASING -S	Serviceable	45.00 FS	*- FS
12	1		*HEAD LIGHT ASSY ,L	Serviceable	1,109.77 FS	*- FS
13	1		*LIGHT ASSYR.FR.FOG	Serviceable	178.42 FS	*- FS
14	1		*LIGHT ASSYL.FR.FOGLIGHT	Serviceable	176.25 FS	*- FS
15	8		*CLIPINSULATOR	Serviceable	12.60 FS	*- FS
16	1		*SET ,FR.GRILLE ASSY	Serviceable	199.12 FS	*- FS
17	1		*MOLDINGFR.GRILLE UPPER	Serviceable	139.57 FS	*- FS
18	1		*MOLDINGFR.GRILLE	Serviceable	32.10 FS	*- FS
19	1		*BEAMR,FR,GRILLE SIDE UPPER	Serviceable	29.02 FS	*- FS
20	1		*BEAMR,FR,GRILLE SIDE UPPER	Serviceable	12.90 FS	*- FS
21	1		*BEAML,FR,GRILLE SIDE UPPER	Serviceable	3.37 FS	*- FS
22	1		*EMBLEMFR	Serviceable	19.42 FS	*- FS
23	2		*NUT ,CLIP 6MM	Serviceable	4.20 FS	*- FS
24	12		*CLIPBUMPER	Necessary	18.00 FS	*18.00 FS
25	1		*FACE,FR.BUMPER	Repair	349.65 FS	*- FS
26	1		*FACE,FR.BUMPER LOWER	Serviceable	258.15 FS	*- FS
27	1		*GRILLEFR.BUMPER	Serviceable	58.12 FS	*- FS
28	1		*GARNISHR,FR.FOG LIGHT	Serviceable	15.82 FS	*- FS
29	1		*GARNISHL,FR.FOG LIGHT	Serviceable	15.82 FS	*- FS
30	1		*SPOILERFR.BUMPER AIR	Serviceable	37.50 FS	*- FS
31	1		*GUIDER.FR.BUMPER AIR	Serviceable	20.92 FS	*- FS
32	1		*GUIDEL.FR.BUMPER AIR	Serviceable	20.92 FS	*- FS
33	1		*BEAMR.FR.BUMPER UPPER	Serviceable	17.92 FS	*- FS
34	1		*BEAML.FR.BUMPER UPPER	Serviceable	17.92 FS	*- FS
35	1		*SPACERR.FR.BUMPER SIDE	Serviceable	7.80 FS	*- FS
36	1		*SPACERL.FR.BUMPER SIDE	Necessary	7.80 FS	*7.80 FS
37	1		*CLIPBUMPER (22 PCS)	Necessary	33.00 FS	*33.00 FS
38	1		*BEAM COMP ,FR.BUMPER	Not Necessary	177.45 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*WHEEL ALIGNMENT	Necessary	180.00 FS	*180.00 FS
F=Franchise part, S=SpcNett.						
Total Parts (S\$)					4,647.84	943.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT FR LIGHTING MECHANISMS	New	180.00	180.00
2	REMOVE AND RENEW LHF WHEEL/RIM/TYRE	New	50.00	50.00
3	REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS	New	2,500.00	1,120.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,000.00	900.00
5	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS	New	1,680.00	0.00
Gross Labour Cost (S\$)			6,410.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >