

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIG

Date/Time:

9/7/18 @ 10:13am

Estimated Cost:

Bill to:

OD / (ID) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

ET 5558K

Insured:

GBG83A

at Workshop in/:

Preerse Auto

Tel:

6745 7367

of

No. 1 Kaki Bukit Ave 6 # 02-34 / 36

Policy No:

29030264 MKC

Claim No:

56 3096

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/07/2018

CA / REV / REP. / REV 24 HRS

lup

11-07-2018

H.O.D. Endorsement:

Date/Time:

11:22am @ 9/7/18

Person Contacted:

pei ying

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

ET 5558K - NA / III 08022889 / r

D.O.A: 13/08/2018

GBG83A - X

12/7/18

Informed Katherine Wong pending workshop est via merimen

29/10/18

Send preli revised via merimen

(08/11/13) wef

ASS. REC. BY:

REF:

MSIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 11/07/18

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: ET 5558 K

at Workshop m/s

Precise Autoof No. 1 Kerki Bukit Ave 6 # 02-34/36

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 20k.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp18/6/2018

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: ET5558KYr Regn: 6.06Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda CivicIMA: 1339Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 35/405

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMFD 362065201756Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or hankook

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 2/7/18D.O.I. 11/7/18

Survey held at \_\_\_\_\_

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop orRear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/10/18 LTA / 3639 2yrs 11mths. net 6361

2/5 #4300 confirmed with yachery. (Red 5362.88, 559)

RECEIVED 30 OCT 2018

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 29/10 - typistReport Format: merimenLump Sum / I.B.I: (\$) 4300/2Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

20010210

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 29 Oct 2018

**Preliminary Advice**

|                    |                                                                                     |                         |              |
|--------------------|-------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBG83A                                                                            | Accident Date           | : 02/07/2018 |
| TP Vehicle No      | : ET5558K                                                                           | Assignment Date         | : 09/07/2018 |
| Make               | : HONDA CIVIC                                                                       | Est. Duration of Repair | : 6.00       |
| Date of Inspection | : 11/07/2018                                                                        |                         |              |
| Inspection At      | : PRECISE AUTO SERVICE (HQ)<br>NO 1 KAKI BUKIT AVE 6, #02-34/36<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

|                             |      |                     |
|-----------------------------|------|---------------------|
| Repairer's Estimate (Gross) | :S\$ | 9,662.88            |
| Revised Amount              | :S\$ | 4,300.00 (LUMP SUM) |
| Check Items (Estimated)     | :S\$ | 0.00                |
| Total                       | :S\$ | 4,300.00            |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 03 Jul 2018 |               | 09 Jul 2018<br>10:13<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |                                                                                                                       |  |  |                        |                                                                               |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------|--|--|------------------------|-------------------------------------------------------------------------------|
| Insured:                    | BUDGETCARS PTE LTD, Co. Reg. No.: 201618239Z                                                                          |  |  | Date of Loss:          | 02/07/2018 02:00 - :59<br>[144 Months and 13 Days From LTA Reg Date (Man Yr)] |
| Main Claimant:              | LIM CHIN HEE, ID: S1693050D                                                                                           |  |  | Policy/Cover Note No.: | 29030264MKC<br>Coverage: 29/09/2017 - 28/09/2018                              |
| Vehicle Reg. No.:           | ET5558K                                                                                                               |  |  | Policy No. (Claimant): |                                                                               |
| Claim Type:                 | TP / 563096                                                                                                           |  |  | Excess:                |                                                                               |
| Vehicle Reg. No. (Insured): | GBG83A                                                                                                                |  |  |                        |                                                                               |
| Repairer:                   | Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367                         |  |  |                        |                                                                               |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544] |  |  |                        |                                                                               |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 10/07/2018]                                    |  |  |                        |                                                                               |
| Adj Asg. Remarks:           | liability: 100%, TP reject SJE - assign LKK Auto consultants Pte Ltd.                                                 |  |  |                        |                                                                               |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## Cheapest Hyundai Avante 1.6A



Cheapest Hyundai Avante 1.6A.  
Sporty Look. Flexible Loan Can  
Be Arranged.  
Direct Owner StarAd.

**AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Browse by Category

« Back ( 1 2 3 4 5 6 ) Next »

Sort by Date Posted

20 results/page

107 vehicles

Honda Civic

Advanced Search



Submit

|                                                                                                                                                                                                                                                                                                                                       | Make        | Model                                      | Price    | Depreciation | Reg Date         | Eng Cap  | Mileage    | Veh Type | Status    |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|--------------------------------------------|----------|--------------|------------------|----------|------------|----------|-----------|
| <b>Search Selection</b>                                                                                                                                                                                                                                                                                                               | Honda Civic |                                            | Any      | Any          | > 10 year(s) old | Any      | Any        | Any      | Available |
|                                                                                                                                                                                                                                                       | Honda Civic | Honda Civic Hybrid 1.3A (COE till 06/2021) | \$22,800 | \$7,670 /yr  | 08-Aug-2006      | 1,339 cc | 140,000 km | Sedan    | Available |
| <b>Fuel Type:</b> Petrol-Electric<br>Healthy Hybrid Battery. New Full Leather Seat And New Roof Lining With Receipts To Prove. Car Interior Looks Nice And Smells Good. Car Comes With New Tyre And 16" Sports Rims. Well Maintained By Owner...<br>Posted: 11-Jul-2018 Tags: 2006 Honda Civic, Honda Civic, Honda, Civic, Used Honda |             |                                            |          |              |                  |          |            |          |           |
|                                                                                                                                                                                                                                                     | Honda Civic | Honda Civic 1.8A (COE till 05/2021)        | \$25,800 | \$9,110 /yr  | 11-May-2006      | 1,799 cc | 143,000 km | Sedan    | Available |
| One Year In House Warranty, New "SMA" Plate, From \$4000 Onwards Drive Away, Purchase With Official Warranty Certificate With A Peace Of Mind, Our Company Renew Cars Based On Conditions, Fully Refurbis...<br>Carway<br>Posted: 11-Jul-2018 Tags: 2006 Honda Civic, Honda Civic, Honda, Civic, Used Honda                           |             |                                            |          |              |                  |          |            |          |           |
|                                                                                                                                                                                                                                                     | Honda Civic | Honda Civic 1.8A G (New 5-yr COE)          | \$33,800 | \$6,760 /yr  | 02-Jul-2008      | 1,799 cc | 146,788 km | Sedan    | Available |
| \$3k Down Payment, In House Loan Available, At Low Monthly Installment, Flexible Loan Available. 100% Accident Free. Trade In Are Welcome, View To Believe Before It's Gone. Please! Call For Appointment!<br>Posted: 11-Jul-2018 Tags: 2008 Honda Civic, Honda Civic, Honda, Civic, Used Honda                                       |             |                                            |          |              |                  |          |            |          |           |
|                                                                                                                                                                                                                                                     | Honda Civic | Honda Civic 1.6A VTI (New 5-yr COE)        | \$37,800 | \$7,560 /yr  | 17-Jun-2008      | 1,595 cc | -          | Sedan    | Available |
| Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...<br>Posted: 10-Jul-2018 Tags: 2008 Honda Civic, Honda Civic, Honda, Civic, Used Honda                                      |             |                                            |          |              |                  |          |            |          |           |
| <div> <div>Car Buying</div> <div>Car Aftermarket</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Ownership</div> <div>Lifestyle</div> </div> <div> <div>Buy Tyres Online!</div> <div>Latest Special Offers from Tyrepac!</div> </div>                                                          |             |                                            |          |              |                  |          |            |          |           |
|                                                                                                                                                                                                                                                     | Honda Civic | Honda Civic 1.6A VTI (COE till 11/2027)    | \$52,000 | \$5,570 /yr  | 12-Nov-2007      | 1,595 cc | 120,000 km | Sedan    | Available |
| Excellent And Original Condition, Well Maintained Interior And Exterior, New Tyres, New Shock Absorber, New Interior Roof, Call Now For Viewing.<br>Posted: 10-Jul-2018 Tags: 2007 Honda Civic, Honda Civic, Honda, Civic, Used Honda                                                                                                 |             |                                            |          |              |                  |          |            |          |           |
|                                                                                                                                                                                                                                                     | Honda Civic | Honda Civic 1.8A VTI-S (New 5-yr COE)      | \$37,800 | \$7,560 /yr  | 24-May-2008      | 1,799 cc | -          | Sedan    | Available |
| Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...<br>Posted: 10-Jul-2018 Tags: 2008 Honda Civic, Honda Civic, Honda, Civic, Used Honda                                      |             |                                            |          |              |                  |          |            |          |           |

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

|                |                |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID:      | 3050D          |

**Vehicle Details**

|                                |                   |
|--------------------------------|-------------------|
| Vehicle No.:                   | ET5558K           |
| Vehicle to be Exported:        | No                |
| Intended De-registration Date: | 11 Jul 2018       |
| Vehicle Make:                  | HONDA             |
| Vehicle Model:                 | CIVIC IMA A       |
| Primary Colour:                | Black             |
| Manufacturing Year:            | 2006              |
| Engine No.:                    | LDA21018762       |
| Chassis No.:                   | JHMFD36206S201756 |
| Maximum Power Output:          | 70.0 kW (93 bhp)  |
| Open Market Value:             | \$26,900.00       |
| Original Registration Date:    | 19 Jun 2006       |
| First Registration Date:       | 19 Jun 2006       |
| Transfer Count:                | 0                 |
| Actual ARF Paid:               | \$18,830.00       |

**Intended PARF Rebate Details**

|                               |           |
|-------------------------------|-----------|
| PARF Eligibility:             | Forfeited |
| PARF Eligibility Expiry Date: | -         |
| PARF Rebate Amount:           | \$0.00    |

**Intended COE Rebate Details**

|                             |                          |
|-----------------------------|--------------------------|
| COE Expiry Date:            | 18 Jun 2021              |
| COE Category:               | A - Car (1600cc & below) |
| COE Period(Years):          | 5                        |
| PQP Paid:                   | \$23,227.00              |
| COE Rebate Amount:          | \$13,639.00              |
| <b>Total Rebate Amount:</b> | <b>\$13,639.00</b>       |

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2018

**OK**

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO.: 35766600C

GST REG. NO.: 35766600C

19-10-18

Date Of Accident : 02-07-18

OUR REF : ET 5558K/T/18

Lim Chin Hee  
Blk 551 Woodlands Dr 44  
#12-58  
Singapore 730550

marcus.  
F: 62564315  
Date in/out : 10/07/18 to 19/07/18  
11/7/18

not Alford  
d/s \$4300/  
6dy.

**ESTIMATE BILL ON VEH. NO. : ET 5558K**

**VEH. MODEL : HONDA CIVIC**

**CHASSIS NO : JHMFD36206S201756**

## LIST ITEM

|                                |               |        |     |
|--------------------------------|---------------|--------|-----|
| Boot Lid                       |               | 610.70 | ✓   |
| Boot Lid Hinge                 | 2pcs @ 48.60  | 97.20  | X   |
| Boot Lid Stopper               | 2pcs @ 7.00   | 14.00  | X   |
| Boot Lid Lock                  |               | 194.50 | ✓   |
| Boot Lid Lock Washer           | 2pcs @ 3.80   | 7.60   | X   |
| Boot Lid Lock Snap             |               | 4.00   | X   |
| Boot Lid Lock Silencer         |               | 3.80   | X   |
| Boot Lid Lock Cable            |               | 87.60  | X   |
| Boot Lid Lock Striker          |               | 15.00  | X   |
| Boot Lid Weather Stripe        |               | 97.60  | ✓   |
| Boot Lid Reflector reflector   | 2pcs @ 145.90 | 291.80 | 1pc |
| Boot Lid Reflector Sealant     | 2pcs @ 14.00  | 28.00  | X   |
| Boot Lid Badge                 |               | 26.70  | ✓   |
| Boot Lid Emlum "Hybrid"        |               | 34.00  | ✓   |
| Boot Lid Emlum "Civic"         |               | 29.00  | ✓   |
| Rear Number Plate Lamp         | 2pcs @ 38.00  | 76.00  | X   |
| Rear Number Plate Lamp Garnish |               | 121.60 | X   |
| Tail Lamp Assy                 | 2pcs @ 226.20 | 452.40 | 4pc |
| Tail Lamp Sealant              | 2pcs @ 14.60  | 29.20  | X   |
| Tail Lamp Base Panel           | 2pcs @ 65.70  | 131.40 | 1pc |

|                                    |              |                    |          |
|------------------------------------|--------------|--------------------|----------|
| Rear Bumper Fascia                 | 7.5          | 638.00             | ✓        |
| Rear Bumper Side Retainer          | 2pcs @ 14.60 | 29.20              | ✓        |
| Rear Bumper Bracket                | 2pcs @ 13.90 | 27.80              | ✓        |
| Rear Bumper Clips                  | 10pcs @ 3.90 | 39.00              | ✓        |
| Rear Bumper Exhaust Garnish        | CM           | 17.00              | ✓        |
| Rear Bumper Exhaust Garnish Clips  | 2pcs @ 3.90  | 7.80               | ✓        |
| Rear End Panel                     | 20           | 300.50             | ✓        |
| Rear End Panel Inner Side Bracket  | 2pcs @ 19.80 | 39.60              | ✓        |
| Rear End Panel Top Trim            | 400          | 60.80              | ✓        |
| Rear End Panel Top Trim Clips      | 4pcs @ 4.50  | 18.00              | ✓        |
| Rear Floor Panel Board             | 11           | 297.80             | ✓        |
| Rear Floor Panel Insulator Cloth   | 11           | 155.00             | ✓        |
| Exhaust Silencer                   | 11           | 535.10             | ✓        |
| Exhaust Silencer Gasket            | 2pcs @ 12.50 | 25.00              | ✓        |
| Exhaust Silencer Hook              | 3pcs @ 19.00 | 57.00              | ✓        |
| Rear Fender Inner Trim Board RH    | 241.20       | 472.40             | ✓        |
| Rear Fender Inner Trim Board Clips | 3000         | 44.00              | ✓        |
|                                    |              | 5,116.10           |          |
|                                    |              | Less Discount 20%: | 1,023.22 |
|                                    |              |                    | 4,092.88 |

### SPECIAL NETT ITEM

Reverse Sensor

Boot Lid Spoiler

### LABOUR CHARGE

Towing

To check & reconnect snap wiring

To remove & refix interior upholstery

To remove & refix exhaust silencer

To tuff coat affected areas

To adjust chassis alignment on car O liner

shock  
washed

380.00 200

580.00 500

80.00 X

250.00 30

200.00 80

280.00 60

300.00 80

380.00 X

To reset electrical module system

17 120.00 X

To respray affected areas

1,500.00 1100

To renew damaged parts, straighten & repair rear fender, rear floor panel  
rear chassis member & aligned all parts

1,500.00 1100

GST 7% :  
**AMOUNT DUE:**

9,662.88  
676.40  
**10,339.28**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012419/UVD3N2

Date: 31/10/2018

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 29030264MKC |
| Claimant Vehicle No : | ET5558K                              | Insured Vehicle No : | GBG83A      |
| Date of Loss:         | 02/07/2018                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | 563096      |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                  |
|-----------------------------|------------------------------|-------------|------------------|
| Reg No:                     | ET5558K                      | Engine No:  | LDA21018762      |
| Make & Model:               | HONDA CIVIC, 1.3 IMA (A)     | Chassis No: | JHMF36206S201756 |
| Reg. Date:                  | 19/06/2006 (Man. Year: 2006) | Odometer:   | 351405 km        |
| Colour:                     | Black                        |             |                  |
| Engine Capacity:            | 1339 cc                      |             |                  |
| Market Value/New Car Price: | N/A                          |             |                  |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                  |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 195/65R15    | Rear Tyre Size:  | 195/65R15    |
| Front Left Side:  | Hankook 6 mm | Rear Left Side:  | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                          | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 5,052.88         | 2,928.80        | 2,124.08        | 42.04        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 4,610.00         | 2,450.00        | 2,160.00        | 46.85        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>9,662.88</b>  | <b>5,378.80</b> | <b>4,284.08</b> | <b>44.34</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>4,300.00</b> |                 |              |
| (S\$)                                    | 9,662.88         | 4,300.00        | 5,362.88        | 55.50        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>676.40</b>    | <b>301.00</b>   | <b>375.40</b>   | <b>55.50</b> |
| <b>Nett Amount (S\$)</b>                 | <b>10,339.28</b> | <b>4,601.00</b> | <b>5,738.28</b> | <b>55.50</b> |

## INSPECTION

Date of Assignment: 09/07/2018

Date Inspected: 11/07/2018 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

|                                                             |                                                                                                                                                                              |
|-------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                  | Version: 1.0 (Last Synchronised: 31 Oct 2018)                                                                                                                                |
| <b>Parts:</b> 143                                           | HONDA CIVIC 1.3 IMA (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                    |
| <b>Labour:</b> Repairer's                                   | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for ET5558K) |                                                                                                                                                                              |
| <b>Validity:</b>                                            | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                        | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

## Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition       | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|-----------------|------------|------------|
| 1   | 1   |          | *BOOT LID                           | Bent/Buckled    | 610.70 FL  | *610.70 FL |
| 2   | 2   |          | *BOOT LID HINGE                     | Repair          | 97.20 FL   | *- FL      |
| 3   | 2   |          | *BOOT LID STOPPER                   | Not Necessary   | 14.00 FL   | *- FL      |
| 4   | 1   |          | *BOOT LID LOCK                      | Twisted/Shorted | 194.50 FL  | *194.50 FL |
| 5   | 2   |          | *BOOT LID LOCK WASHER               | Not Necessary   | 7.60 FL    | *- FL      |
| 6   | 1   |          | *BOOT LID LOCK SNAP                 | Not Necessary   | 4.00 FL    | *- FL      |
| 7   | 1   |          | *BOOT LID LOCK SILENCER             | Not Necessary   | 3.80 FL    | *- FL      |
| 8   | 1   |          | *BOOT LID LOCK CABLE                | Not Necessary   | 87.60 FL   | *- FL      |
| 9   | 1   |          | *BOOT LID LOCK STRIKER              | Not Necessary   | 15.00 FL   | *- FL      |
| 10  | 1   |          | *BOOT LID WEATHER STRIPE            | Twisted         | 97.60 FL   | *97.60 FL  |
| 11  | 1   |          | *BOOT LID REFLECTOR                 | O/s Cracked     | 291.80 FL  | *145.90 FL |
| 12  | 2   |          | *BOOT LID REFLECTOR SEALANT         | Not Necessary   | 28.00 FL   | *- FL      |
| 13  | 1   |          | *BOOT LID BADGE                     | Necessary       | 26.70 FL   | *26.70 FL  |
| 14  | 1   |          | *BOOT LID EMBLEM HYBRID             | Necessary       | 34.00 FL   | *34.00 FL  |
| 15  | 1   |          | *BOOT LID EMBLEM CIVIC              | Necessary       | 29.00 FL   | *29.00 FL  |
| 16  | 2   |          | *REAR NUMBER PLATE LAMP             | Not Necessary   | 76.00 FL   | *- FL      |
| 17  | 1   |          | *REAR NUMBER PLATE LAMP GARNISH     | Not Necessary   | 121.60 FL  | *- FL      |
| 18  | 1   |          | *TAIL LAMP ASSY                     | O/s Broken      | 452.40 FL  | *226.20 FL |
| 19  | 2   |          | *TAIL LAMP SEALANT                  | Not Necessary   | 29.20 FL   | *- FL      |
| 20  | 1   |          | *TAIL LAMP BASE PANEL               | O/s Dented      | 131.40 FL  | *65.70 FL  |
| 21  | 1   |          | *REAR BUMPER FASCIA                 | Distorted       | 638.00 FL  | *638.00 FL |
| 22  | 2   |          | *REAR BUMPER SIDE RETAINER          | Bent            | 29.20 FL   | *29.20 FL  |
| 23  | 2   |          | *REAR BUMPER BRACKET                | Not Necessary   | 27.80 FL   | *- FL      |
| 24  | 10  |          | *REAR BUMPER CLIPS                  | Necessary       | 39.00 FL   | *39.00 FL  |
| 25  | 1   |          | *REAR BUMPER EXHAUST GARNISH        | Cracked         | 17.00 FL   | *17.00 FL  |
| 26  | 2   |          | *REAR BUMPER EXHAUST GARNISH CLIPS  | Not Necessary   | 7.80 FL    | *- FL      |
| 27  | 1   |          | *REAR END PANEL                     | Dented          | 300.50 FL  | *300.50 FL |
| 28  | 2   |          | *REAR END PANEL INNER SIDE BRACKET  | No such part    | 39.60 FL   | *- FL      |
| 29  | 1   |          | *REAR END PANEL TOP TRIM            | Twisted         | 60.80 FL   | *60.80 FL  |
| 30  | 4   |          | *REAR END PANEL TOP TRIM CLIPS      | Not Necessary   | 18.00 FL   | *- FL      |
| 31  | 1   |          | *REAR FLOOR PANEL BOARD             | Not Necessary   | 297.80 FL  | *- FL      |
| 32  | 1   |          | *REAR FLOOR PANEL INSULATOR CLOTH   | Not Necessary   | 155.00 FL  | *- FL      |
| 33  | 1   |          | *EXHAUST SILENCER                   | Repair          | 535.10 FL  | *- FL      |
| 34  | 2   |          | *EXHAUST SILENCER GASKET            | Not Necessary   | 25.00 FL   | *- FL      |
| 35  | 3   |          | *EXHAUST SILENCER HOOK              | Not Necessary   | 57.00 FL   | *- FL      |
| 36  | 1   |          | *REAR FENDER INNER TRIM BOARD RH    | Deformed/Torn   | 472.40 FL  | *241.20 FL |
| 37  | 8   |          | *REAR FENDER INNER TRIM BOARD CLIPS | Necessary       | 44.00 FL   | *30.00 FL  |
| 38  | 1   |          | *SET REVERSES ENSOR                 | Shorted         | 380.00 FS  | *200.00 FS |
| 39  | 1   |          | *BOOT LID SPOILER                   | Warped          | 580.00 FS  | *500.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,076.10</b> | <b>3,486.00</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>1,023.22</b> | <b>557.20</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>5,052.88</b> | <b>2,928.80</b> |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. |     |          |             |           |            |        |

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                           | Lab.Type | Repairer's | Amount   |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                                                                                                       |          |            |          |
| 1                       | TOWING                                                                                                                | New      | 80.00      | -        |
| 2                       | TO CHECK & RECONNECT SNAP WIRING                                                                                      | New      | 250.00     | 30.00    |
| 3                       | TO REMOVE & REFIX INTERIOR UPHOLSTERY                                                                                 | New      | 200.00     | 80.00    |
| 4                       | TO REMOVE & REFIX EXHAUST SILENCER                                                                                    | New      | 280.00     | 60.00    |
| 5                       | TO TUFF COAT AFFECTED AREAS                                                                                           | New      | 300.00     | 80.00    |
| 6                       | TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER                                                                            | New      | 380.00     | -        |
| 7                       | TO RESET ELECTRICAL MODULE SYSTEM                                                                                     | New      | 120.00     | -        |
| 8                       | TO RESPRAY AFFECTED AREAS                                                                                             | New      | 1,500.00   | 1,100.00 |
| 9                       | TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR<br>REAR FENDER,REAR FLOOR PANEL,REAR CHASSIS<br>MEMBER & ALIGNED ALL PARTS | New      | 1,500.00   | 1,100.00 |
| Gross Labour Cost (S\$) |                                                                                                                       |          | 4,610.00   | 2,450.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;