

## CHUNNI MOTOR WORK PTE LTD

## REPAIR ESTIMATE

INDIA

LKK

VEHICLE NO: SHD 360SU

DATE : 4.07.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

| PARTS DESCRIPTION                                            | QTY | UNIT PRICE | AMOUNT      |
|--------------------------------------------------------------|-----|------------|-------------|
| BONNET <i>gnc</i>                                            |     |            | \$ 938.40   |
| INSULATOR, HOOD <i>vt</i>                                    |     |            | \$ 398.10   |
| INSULATOR CLIPS <i>huc</i>                                   |     |            | \$ 3.60     |
| BONNET RUBBER <i>hnd</i>                                     |     |            | \$ 35.50    |
| BONNET HINGE (RH) <i>vt</i>                                  |     |            | \$ 56.40    |
| BONNET HINGE (LH) <i>vt</i>                                  |     |            | \$ 56.40    |
| BONNET LOCK <i>vt</i>                                        |     |            | \$ 128.90   |
| RADIATOR GRILLE <i>broken</i>                                |     |            | \$ 438.00   |
| RADIATOR GRILLE EMBLEM <i>broken</i>                         |     |            | \$ 88.00    |
| LAMP ASSY, FOG, RH <i>broken</i>                             |     |            | \$ 920.00   |
| LAMP ASSY, FOG, LH <i>broken mounty broken</i>               |     |            | \$ 920.00   |
| FRONT BUMPER COVER <i>broken</i>                             |     |            | \$ 499.90   |
| FRONT BUMPER REINFORCEMENT <i>gnc</i>                        |     |            | \$ 696.40   |
| FRONT BUMPER REINFORCEMENT ABSORBER <i>deformed hnd</i>      |     |            | \$ 115.70   |
| FRONT BUMPER SPONGE <i>form</i>                              |     |            | \$ 78.80    |
| FRONT BUMPER CENTRE GRILLE <i>broken</i>                     |     |            | \$ 301.90   |
| FRONT BUMPER SIDE RETAINER <i>broken</i>                     |     | \$ 77.00   | \$ 154.00   |
| FRONT LOWER CROSSMEMBER <i>vt</i>                            |     |            | \$ 357.70   |
| FRONT UNDER COVER <i>deformed</i>                            |     |            | \$ 180.80   |
| FRONT BUMPER TOP GARNISH <i>broken</i>                       |     |            | \$ 225.40   |
| COVER, FRONT BUMPER HOLE, RH <i>cut</i>                      |     |            | \$ 28.38    |
| COVER, FRONT BUMPER HOLE, LH <i>dislodged</i>                |     |            | \$ 28.38    |
| REINFORCEMENT SUB-ASSY, FRONT BUMPER LOWER <i>vt</i>         |     |            | \$ 236.10   |
| SUPPORT FR BUMPER, RH <i>hnd</i>                             |     |            | \$ 81.70    |
| SUPPORT FR BUMPER, LH <i>hnd</i>                             |     |            | \$ 81.70    |
| FRONT BUMPER CENTRE FRAME <i>hnd</i>                         |     |            | \$ 236.90   |
| BRACKET, FRONT BUMPER SIDE, RH <i>hnd</i>                    |     |            | \$ 77.00    |
| BRACKET, FRONT BUMPER SIDE, LH <i>hnd</i>                    |     |            | \$ 77.00    |
| ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>deformed</i> |     |            | \$ 127.70   |
| UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>                  |     |            | \$ 3,413.40 |
| UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>                  |     |            | \$ 3,413.40 |
| HEAD LAMP PANEL (RH) <i>Deformed</i>                         |     |            | \$ 213.50   |
| HEAD LAMP PANEL (LH) <i>Deformed</i>                         |     |            | \$ 213.50   |
| TOP PANEL CENTRE <i>Deformed</i>                             |     |            | \$ 364.90   |
| TOP PANEL SIDE, LH <i>Deformed</i>                           |     |            | \$ 69.20    |
| TOP PANEL SIDE, RH <i>Deformed</i>                           |     |            | \$ 69.20    |
| BRACE PANEL <i>gnc</i>                                       |     |            | \$ 75.20    |
| BRACKET, HEADLAMP MOUNTING, RH <i>hnd</i>                    |     |            | \$ 25.50    |
| BRACKET, HEADLAMP MOUNTING, LH <i>hnd</i>                    |     |            | \$ 25.50    |
| HEADLAMP BULB <i>hnd</i>                                     |     | \$ 34.30   | \$ 68.60    |
| RADIATOR ASSY <i>vt</i>                                      |     |            | \$ 1,841.80 |
| RADIATOR FAN COWLING ASSY <i>broken</i>                      |     |            | \$ 661.30   |
| RADIATOR TOP HOSE, LH <i>deformed</i>                        |     |            | \$ 43.03    |
| RADIATOR TOP HOSE, RH <i>deformed</i>                        |     |            | \$ 42.60    |
| RADIATOR BOTTOM MOUNTING <i>hnd</i>                          |     |            | \$ 27.50    |
| STAY, RADIATOR SUPPORT, RH <i>hnd</i>                        |     |            | \$ 65.70    |
| STAY, RADIATOR SUPPORT, LH <i>hnd</i>                        |     |            | \$ 65.70    |


SHD 3605U

| PARTS DESCRIPTION                                          | QTY | UNIT PRICE  | AMOUNT      |             |
|------------------------------------------------------------|-----|-------------|-------------|-------------|
| RADIATOR FAN BLADE (RH) <i>2 defined</i>                   |     |             | \$ 233.10   | <i>2 ✓</i>  |
| RADIATOR FAN BLADE (LH) <i>2 defined</i>                   |     |             | \$ 233.10   | <i>2 ✓</i>  |
| RADIATOR FAN MOTOR (RH) <i>2 Dem</i>                       |     |             | \$ 543.70   | <i>2 ✓</i>  |
| RADIATOR FAN MOTOR (LH) <i>2 Dem</i>                       |     |             | \$ 543.70   | <i>2 ✓</i>  |
| DEFLECTOR, RADIATOR SIDE, RH <i>torn</i>                   |     |             | \$ 83.50    | <i>✓</i>    |
| DEFLECTOR, RADIATOR SIDE, LH <i>2 torn</i>                 |     |             | \$ 77.00    | <i>2 ✓</i>  |
| RESERVE TANK ASSY, RADIATOR W/O CAP <i>2 broken</i>        |     |             | \$ 395.30   | <i>2 ✓</i>  |
| BUTTON ASSY, HORN <i>NN</i>                                |     |             | \$ 2,377.30 | <i>X</i>    |
| HORN (1 PC) <i>Dem</i>                                     |     |             | \$ 112.71   | <i>✓</i>    |
| CLEANER ASSY, AIR <i>broken</i>                            |     |             | \$ 970.30   | <i>✓</i>    |
| AIR CLEANER TOP COVER <i>broken</i>                        |     |             | \$ 446.50   | <i>✓</i>    |
| AIR CLEANER BOTTOM COVER <i>defined</i>                    |     |             | \$ 947.80   | <i>✓</i>    |
| AIR CLEANER HOSE <i>defined</i>                            |     |             | \$ 62.12    | <i>✓</i>    |
| AIR DUCT <i>defined</i>                                    |     |             | \$ 129.40   | <i>✓</i>    |
| INLET ASSY, AIR CLEANER <i>defined</i>                     |     |             | \$ 199.20   | <i>✓</i>    |
| AIR DUCT CENTRE <i>defined</i>                             |     |             | \$ 94.03    | <i>✓</i>    |
| COMPRESSOR ASSY, W/MOTOR <i>2 Dem</i>                      |     |             | \$ 4,623.48 | <i>2 ✓</i>  |
| CONDENSER ASSY, W/RECEIVER <i>2 BT</i>                     |     |             | \$ 1,336.60 | <i>2 ✓</i>  |
| AIRCON DISCHARGE HOSE <i>2 BT</i>                          |     |             | \$ 386.90   | <i>2 ✓</i>  |
| AIRCON LIQUID HOSE & PIPE <i>2 BT</i>                      |     |             | \$ 580.45   | <i>2 ✓</i>  |
| AIRCON HOSE SUCTION <i>2 defined</i>                       |     |             | \$ 541.87   | <i>2 ✓</i>  |
| FENDER SUB-ASSY, FRONT LH <i>SLC</i>                       |     |             | \$ 950.50   | <i>✓</i>    |
| FENDER SUB-ASSY, FRONT RH <i>Revised</i>                   |     |             | \$ 950.50   | <i>✓</i>    |
| FRONT HOUSING ASSY, LH <i>2 Revised</i>                    |     |             | \$ 958.30   | <i>2 ✓</i>  |
| FRONT HOUSING ASSY, RH <i>2 Revised</i>                    |     |             | \$ 958.30   | <i>2 ✓</i>  |
| FRONT FENDER SHIELD, LH <i>SLC defined</i>                 |     |             | \$ 198.50   | <i>✓</i>    |
| FRONT FENDER SHIELD, RH <i>SLC</i>                         |     |             | \$ 198.50   | <i>X</i>    |
| FRONT FENDER SHIELD CLIP <i>SLC</i>                        |     | \$ 14.90    | \$ 29.80    | <i>X</i>    |
| FRONT FENDER HYBRID EMBLEM, LH <i>SLC</i>                  |     |             | \$ 86.50    | <i>✓</i>    |
| FRONT FENDER HYBRID EMBLEM, RH <i>SLC</i>                  |     |             | \$ 86.50    | <i>✓</i>    |
| PROTECTOR, FRONT FENDER, UPPER, LH <i>discontinued</i>     |     |             | \$ 46.10    | <i>✓</i>    |
| PROTECTOR, FRONT FENDER SIDE PANEL, RH <i>NN</i>           |     |             | \$ 113.90   | <i>X</i>    |
| GUSSET, FRONT FENDER APRON, LOWER RH <i>NN</i>             |     |             | \$ 34.90    | <i>X</i>    |
| GUSSET, FRONT FENDER APRON, LOWER LH <i>NN</i>             |     |             | \$ 34.90    | <i>X</i>    |
| MEMBER, FRONT APRON TO COWL SIDE, UPPER RH <i>NN</i>       |     |             | \$ 138.40   | <i>X</i>    |
| MEMBER, FRONT APRON TO COWL SIDE, UPPER LH <i>NN</i>       |     |             | \$ 138.40   | <i>X</i>    |
| MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH <i>NN</i> |     |             | \$ 82.30    | <i>X</i>    |
| MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT LH <i>NN</i> |     |             | \$ 82.30    | <i>X</i>    |
| TRAY, BATTERY <i>2 NN</i>                                  |     |             | \$ 42.80    | <i>2 X</i>  |
| FRONT SAFETY BELT (LH/RH) <i>jam</i>                       |     | \$ 838.00   | \$ 1,676.00 | <i>✓</i>    |
| REAR SAFETY BELT (LH/RH) <i>NN Sam</i>                     |     | \$ 838.00   | \$ 1,676.00 | <i>2 ✓</i>  |
| FRONT CUSHION SEAT (LH/RH) <i>Dem</i>                      |     | \$ 1,180.00 | \$ 2,360.00 | <i>✓</i>    |
| FRONT CUSHION SEAT ADJUSTER (LH) <i>NN</i>                 |     |             | \$ 1,450.40 | <i>X</i>    |
| FRONT CUSHION SEAT ADJUSTER (RH) <i>NN</i>                 |     |             | \$ 1,530.80 | <i>X</i>    |
| FRONT CUSHION SEAT CUSHION PAD (RH) <i>NN</i>              |     |             | \$ 526.80   | <i>X</i>    |
| FRONT CUSHION SEAT CUSHION PAD (LH) <i>NN</i>              |     |             | \$ 850.40   | <i>X</i>    |
| FRONT CUSHION SEAT CUSHION COVER (LH/RH) <i>NN</i>         |     | \$ 1,580.00 | \$ 3,160.00 | <i>X</i>    |
| FRONT CUSHION SEAT BACK PAD (LH/RH) <i>NN</i>              |     | \$ 520.30   | \$ 1,040.60 | <i>X</i>    |
| FRONT CUSHION SEAT BACK COVER (LH/RH) <i>NN</i>            |     | \$ 2,940.20 | \$ 5,880.40 | <i>X</i>    |
| FRONT CUSHION SEAT BACK FRAME (LH/RH) <i>NN</i>            |     | \$ 780.80   | \$ 1,561.60 | <i>X</i>    |
| FRONT PILLAR UPPER COVER, LH <i>discontinued NN</i>        |     |             | \$ 96.00    | <i>NN X</i> |

SHD 3605U

| PARTS DESCRIPTION                                                  | QTY | UNIT PRICE | AMOUNT        |        |
|--------------------------------------------------------------------|-----|------------|---------------|--------|
| WIPER TOP GARNISH <i>Nhl</i>                                       |     |            | \$ 668.32     | X      |
| WIPER SPARE TANK <i>broken</i>                                     |     |            | \$ 183.75     | ✓      |
| WIPER SPARE TANK MOTOR <i>Dem</i>                                  |     |            | \$ 242.70     | ✓      |
| WIPER SPARE TANK FLOAT (NECK) <i>deformed</i>                      |     |            | \$ 55.50      | ✓      |
| ENGINE UNDER COVER <i>2 torn</i>                                   |     |            | \$ 457.20     | ✓      |
| ENGINE CROSS MEMBER <i>2 Hnl</i>                                   |     |            | \$ 2,504.40   | 2 X    |
| FRONT CHASSIS MEMBER <i>2 o/s 3t</i>                               |     |            | \$ 2,010.80   | 2 ✓    |
| ENGINE MOUNTING (LH/RH) <i>2 Dem</i>                               |     | \$ 382.70  | \$ 765.40     | 2 ✓    |
| ENGINE MTG (FRONT) <i>2 Dem</i>                                    |     |            | \$ 174.63     | 2 ✓    |
| ENGINE MTG (REAR) <i>2 Hnl</i>                                     |     |            | \$ 172.90     | 2 X    |
| ENGINE TOP COVER <i>Nhl</i>                                        |     |            | \$ 260.00     | X      |
| FAN BELT <i>Nhl</i>                                                |     |            | \$ 155.00     | X      |
| SIDE AIRBAG, LH <i>activated</i>                                   |     |            | \$ 1,479.00   | ✓      |
| SIDE AIRBAG, RH <i>activated</i>                                   |     |            | \$ 1,479.00   | ✓      |
| AIR BAG ASSY, DRIVER SIDE LOWER, RH <i>activated</i>               |     |            | \$ 1,615.10   | ✓      |
| AIR BAG ASSY, FRONT SEAT, RH <i>activated</i>                      |     |            | \$ 857.90     | ✓      |
| AIR BAG ASSY, FRONT SEAT, LH <i>activated</i>                      |     |            | \$ 857.90     | ✓      |
| AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR, LH <i>2 Hnl</i> |     |            | \$ 3,277.50   | 2 X    |
| DASHBOARD ASSY <i>Dem</i>                                          |     |            | \$ 5,480.90   | ✓      |
| COMPUTER ASSY, AIR BAG ECU <i>activated</i>                        |     |            | \$ 2,402.00   | ✓      |
| SENSOR, AIR BAG, FRONT RH <i>activated</i>                         |     |            | \$ 313.50     | ✓      |
| SENSOR, SPEED, FRONT RH <i>Nhl</i>                                 |     |            | \$ 455.10     | X      |
| SENSOR, SPEED, FRONT LH <i>Nhl</i>                                 |     |            | \$ 455.10     | X      |
| COMPUTER, ENGINE CONTROL <i>Nhl</i>                                |     |            | \$ 2,636.10   | X      |
| SENSOR ASSY, SIDE AIR BAG, RH <i>activated</i>                     |     |            | \$ 709.30     | ✓      |
| SENSOR, AIR BAG, REAR RH <i>2 Hnl</i>                              |     |            | \$ 567.80     | X      |
| ENGINE MAIN WIRE <i>Nhl</i>                                        |     |            | \$ 6,138.00   | X      |
| WIRING FRONT <i>total minority cable</i>                           |     |            | \$ 8,450.50   | 2 X ✓  |
| HYBRID INVERTER SPARE TANK <i>deformed</i>                         |     |            | \$ 371.30     | 2 ✓    |
| HYBRID INVERTER BYPASS HOSE (INLET) <i>deformed</i>                |     |            | \$ 42.60      | 2 ✓    |
| HYBRID INVERTER BYPASS HOSE (OUTLET) <i>deformed</i>               |     |            | \$ 29.30      | 2 ✓    |
| HYBRID COOLING PUMP MOTOR <i>Nhl</i>                               |     |            | \$ 432.20     | X      |
| SUB TOTAL                                                          |     |            | \$ 105,827.45 |        |
| LESS 20% <i>25%</i>                                                |     |            | \$ 21,165.49  |        |
| DISCOUNTED TOTAL                                                   |     |            | \$ 84,661.96  |        |
| FRONT NO. PLATE <i>Painted</i>                                     |     |            | \$ 25.00      | NETT ✓ |
| FRONT NO PLATE TRIM COVER <i>Dem</i>                               |     |            | \$ 30.00      | NETT ✓ |
| FRONT NO. PLATE GARNISH <i>Dem</i>                                 |     |            | \$ 99.00      | NETT ✓ |
|                                                                    |     |            | \$ 154.00     |        |

SHD 3605U

| PARTS DESCRIPTION                                                                                                                                                                                                                                                                           | QTY | UNIT PRICE | AMOUNT             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------------------|
| <b>LABOUR CHARGE</b>                                                                                                                                                                                                                                                                        |     |            |                    |
| Panel Beating                                                                                                                                                                                                                                                                               |     |            | \$ 2,400.00 1200/- |
| Spray Painting Charge                                                                                                                                                                                                                                                                       |     |            | \$ 1,600.00 1000/- |
| Wiring Charge                                                                                                                                                                                                                                                                               |     |            | \$ 100.00 30/-     |
| Tuff Kote                                                                                                                                                                                                                                                                                   |     |            | \$ 150.00 60/-     |
| Towing Charge                                                                                                                                                                                                                                                                               |     |            | \$ 60.00 NW        |
| Front Chassis Alignment Charge                                                                                                                                                                                                                                                              |     |            | \$ 400.00 150/-    |
| Remove/Refix Undercarriage (FRT)                                                                                                                                                                                                                                                            |     |            | \$ 200.00 NW       |
| FRT Wheel Alignment                                                                                                                                                                                                                                                                         |     |            | \$ 120.00 NW       |
| Remove/Refix Aircon & Refill Gas                                                                                                                                                                                                                                                            |     |            | \$ 150.00 80/-     |
| Remove/Refix Engine /Gearbox                                                                                                                                                                                                                                                                |     |            | \$ 650.00 150/-    |
| Remove/Refix Dashboard                                                                                                                                                                                                                                                                      |     |            | \$ 400.00 180/-    |
| Remove/Refix Fuse Box                                                                                                                                                                                                                                                                       |     |            | \$ 120.00 NW       |
| R/Refix Air Bag/Steering Wheel/Dashboard/Seat                                                                                                                                                                                                                                               |     |            | \$ 120.00 80/-     |
| Diagnosis Check                                                                                                                                                                                                                                                                             |     |            | \$ 550.00 150/-    |
| <b>TOTAL LABOUR</b>                                                                                                                                                                                                                                                                         |     |            | \$ 7,020.00        |
| <b>ESTIMATE TOTAL</b>                                                                                                                                                                                                                                                                       |     |            | \$ 91,835.96       |
| <p>09/07/2018 @ 1400h</p> <p>NAT Andrew</p> <p>L/sum 21 dgs.</p> <p> Ryan</p> <p>LKK Auto</p> <p></p> <p>Check SV</p> |     |            |                    |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHD 3605U (Supplementary)

MAKE :

MODEL : TOYOTA PRIUS

DATE : 30.07.2018

TEL NO : 6542 5119

FAX NO : 6542 6039

| PARTS DESCRIPTION                           | QTY | UNIT PRICE | AMOUNT      |
|---------------------------------------------|-----|------------|-------------|
| ROOF LINING <i>crumpled</i>                 |     |            | \$ 2,082.10 |
| AIR BAG ASSY-DASHBOARD LOWER, RH <i>Dem</i> |     |            | \$ 1,800.00 |
| AIR BAG ASSY-DASHBOARD UPPER, LH <i>Dem</i> |     |            | \$ 2,500.00 |
| STEERING AIR BAG ANGLE <i>Dem</i>           |     |            | \$ 981.80   |
| HOSE THROTTLE BODY EGR VALVE <i>cut</i>     |     |            | \$ 58.00    |
| SUB TOTAL                                   |     |            | \$ 7,421.90 |
| LESS 20%                                    |     |            | \$ 1,484.38 |
| DISCOUNTED TOTAL                            |     |            | \$ 5,937.52 |

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.