

(A5/2018)

INS. CASE OWNER:

CDB UP
AIG1801 W472, A W B3

LKK:

IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

5/7/18

Date / Time:

5/7/18

Registered in Merimen:

11/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC 3197M

Name of Insured:

W472

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

05/07/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN HEE BENH.

Driver Tel No.:

(V/L-YES / NO)

Claim No.:

3006A447266

Policy No.:

9999999999

Make / Model:

HONDA

Place of Accident:

VISHNU ME 7

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLC 3197M

GT 37070

SLC 3197M



INSRS:

WSP:

Tel:

Liability:

RMKS:

01




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/7/18

vinan

12/7/18

Email letter to 02

29/8/18

File pass to typist type report

17/9/18

Email to AIG to get mandate

17/9/18

mandate approve via merimen

RECEIVED 18 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

12/7/18 Email.

Divion

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

SS

9500.00

Loss of Rental (LOR):

SS

days

Loss of Use (LOU):

SS

960.00

x 12 days

Loss of Income (LOI):

SS

(S

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

10467.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

10467.45

Name 1:

NEW Hock Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

REQ. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 627707D

Yr Regn: 2001

Jne

Type: M.Car / M.Cycle / Bus / Van Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar

c.c 3153.

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 563992

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN13F4F23 Z0844152

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14C

R: 155 R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06

mm

R/Bal: 06

mm

L/Bal: 06

mm

L/Bal: 06

mm

D.O.A.

D.O.I.

05/07/18

Survey held at

NHT

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/07/18

TP ALG

Confirm US \$4500.00 with 10 working days.

COE Expiry: 11/06/21

MV: 2012 23K

PV: 131K

Nett: 9.9K

(Ref: \$27917.30
75%)

Date/Time, File Pass (17)

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return (17)

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + PSL 58

Prelim:

Others:

TOTAL

Report Format :

Lump Sum / L.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|--|----------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CC6/LCR18012432/Awb3 | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120 | | Date : 09-07-2018 |  |
| | | Code : LCR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLC 3197M | Veh. Inspected | GZ 7707D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 09/07/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 05/07/2018 | Inspection Date | 05/07/2018 |
| Survey held at | NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |



新福德車廠私人有限公司 *Adnan-LKR #16*

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

UNITED WORKS PTE LTD

06/07/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP HCR

Vivian

JN1SF4F23Z0844152

Accident date: 05/07/2018

Estimated repair cost for vehicle no: GZ7707D NISSAN CABSTAR '01

CHASSIS: JN1SF4F23Z0844152

| S/n | Qty | Items / Nett | U/price | Amount |
|-----|-----|---|----------|-----------------------------------|
| 1 | 1 | Rear Tail Gate <i>Dented</i> | | \$1,399.70 ✓ |
| 2 | 1 | Rear Tail Gate Nissan Logo Sticker <i>given</i> | | \$99.10 ✓ |
| 3 | 1 | Rear Tail Gate Lower Nissan Cabstar Sticker | | \$28.10 ✓ |
| 4 | 2 | Rear Tail Gate Top Side Handle <i>Not new</i> | \$185.10 | \$370.20 x |
| 5 | 2 | Rear Tail Gate Lower Side Lock <i>RH Best</i> | \$48.20 | \$96.40 <i>48.20</i> |
| 6 | 2 | Rear Tail Gate Lower Side Hinges <i>Not new</i> | \$147.30 | \$294.60 x |
| 7 | 2 | Rear Tail Gate Lower Side Bracket <i>RH Best</i> | \$125.50 | \$251.00 <i>125.50</i> |
| 8 | 4 | Rear Tail Gate Lower Side Bracket Stopper Rubber <i>Not new</i> | \$12.10 | \$48.40 <i>12.10</i> |
| 9 | 2 | Rear Tail Lamp <i>Cracked</i> | \$248.60 | \$497.20 ✓ |
| 10 | 2 | Rear Tail Lamp Bracket <i>RH Best</i> | \$111.20 | \$222.40 <i>111.20</i> |
| 11 | 1 | Rear Number Lamp <i>Not new</i> | | \$67.50 x |
| 12 | 1 | Rear Number Bracket <i>Best</i> | | \$175.50 ✓ |
| 13 | 1 | Rear Spare Tyre Lock <i>Dented</i> | | \$238.30 ✓ |
| 14 | 2 | Rear Exhaust Mounting <i>new</i> | \$33.50 | \$67.00 x |
| 15 | 1 | Rear Tailgate Aluminium Cover <i>Not new</i> | | \$278.20 x |
| 16 | 100 | Rear Tailgate & Floor Panel Aluminium Rivert <i>new</i> | \$1.50 | \$150.00 <i>50</i> |
| 17 | 1 | Rear Floor Panel Aluminium Cover <i>Not new</i> | | \$455.10 x |
| 18 | 1 | Rear Tailgate Lower Member <i>Repair</i> | | \$418.80 x |
| 19 | 1 | Rear Floor Panel <i>Repair</i> | | \$8,000.00 x |
| 20 | 1 | Brake Booster Pump <i>3000</i> | | \$346.10 x |
| 21 | 1 | Brake Booster Bracket <i>new</i> | | \$135.50 x |
| 22 | 1 | Front Windscreen Rubber <i>new</i> | | \$160.40 ✓ |
| 23 | 1 | Front RH Wiper Nozzle <i>Cracked</i> | | \$28.80 ✓ |
| 24 | 1 | Front Nissan Panel (Black Color) <i>Cracked</i> | | \$544.10 ✓ |
| 25 | 1 | Front Panel <i>Cracked</i> | | \$1,554.00 ✓ |
| 26 | 1 | Front Grille <i>Cracked</i> | | \$355.60 ✓ |
| 27 | 1 | Front Grille Emblem Logo <i>new</i> | | \$66.40 ✓ |
| 28 | 2 | Front Head Lamp <i>Cracked</i> | \$348.20 | \$696.40 ✓ |

| | | | | | |
|----|---|----------------------------------|----------|------------|--------|
| 29 | 2 | Front Side Lamp RH cracked | \$184.50 | \$369.00 | 184.50 |
| 30 | 1 | Front Bumper Deformed | | \$706.90 | ✓ |
| 31 | 2 | Front Bumper Bracket 3 new | \$704.60 | \$1,409.20 | x |
| 32 | 1 | Front Bumper Center Member 3 new | | \$353.80 | x |
| 33 | 1 | Front Dashboard not new | | \$994.70 | ✓ |
| 34 | 1 | Front RH Door Pillar 2 new | | \$1,135.50 | x |
| 35 | 1 | Front RH Door Inner Lock 2 new | | \$167.60 | x |

7082
6373.80

Subtotal :- \$22,181.50

| S/n | Qty | Items / Special Nett | U/price | Amount | |
|-----|-----|---|---------|------------|-----|
| 1 | 1 | Rear Tail Gate 70 Km/h Sticker 3 new | | \$20.00 | 15 |
| 2 | 1 | Rear Tail Gate 13 Pax Sticker | | \$20.00 | 15 |
| 3 | 1 | Rear Reverse Sensor not new | | \$294.00 | x |
| 4 | 1 | Rear Number Plate Bent | | \$50.00 | 30 |
| 5 | 1 | Rear Step Panel Bracket Bent | | \$750.00 | 550 |
| 6 | 1 | Rear Chassis Center Member Bent | | \$680.00 | 280 |
| 7 | 1 | Rear Exhaust 3 new | | \$545.50 | x |
| 8 | 1 | Rear Center Exhaust | | \$423.40 | x |
| 9 | 1 | Brake Booster not new | | \$1,147.90 | ✓ |
| 10 | 1 | Front Bumper Number Plate Bent | | \$50.00 | 30 |
| 11 | 1 | Front Air Con Cooling Coil Blower Assy cracked | | \$787.10 | ✓ |
| 12 | 1 | Front Air Con Cooling Coil Discharge Pipe 3 new | | \$166.10 | x |
| 13 | 1 | Front Air Con Cooling Coil Suction Pipe 3 new | | \$125.20 | + |
| 14 | 1 | Front Steering Box not new | | \$1,536.60 | x |

170710

Subtotal :- \$6,595.80

Labour charges

| | | |
|--|----------|-----|
| To remove & refit front dashboard | \$380.00 | 220 |
| To remove & refit air con blower pipe & top up gas | \$450.00 | 150 |
| To remove & refit front windscreen | \$100.00 | ✓ |
| Gum | \$50.00 | ✓ |
| To remove & refit rear reverse sensor | \$100.00 | x |
| To remove & refit rear & center exhaust | \$380.00 | x |

80

| | |
|---|--------------------------------|
| To remove & refit rear body & repair chassis member | \$1,200.00 X |
| To remove & refit rear aluminium box | \$450.00 X. |
| To remove & refit brake booster & steering box | \$380.00 200 |
| To Check Wiring | \$100.00 30 |
| Tuff kote | \$150.00 X |
| Towing Fees | \$100.00 60 |
| Panel beating | 370 \$2,800.00 1600 |
| Spray painting | \$2,000.00 1300 |

Subtotal :- \$8,640.00

Total:- \$37,417.30

total 1187090
H/S 9.51C

10 Days

9.51C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged panel during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary damage must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 6702D

Vehicle Details

Vehicle No.: GZ7707D
Vehicle to be Exported: No
Intended De-registration Date: 06 Jul 2018
Vehicle Make: NISSAN
Vehicle Model: CABSTAR
Primary Colour: Silver
Manufacturing Year: 2001
Engine No.: QD32152716
Chassis No.: JN15F4F23Z0844152
Maximum Power Output: -
Open Market Value: \$19,159.00
Original Registration Date: 12 Jun 2001
First Registration Date: 12 Jun 2001
Transfer Count: 3
Actual ARF Paid: \$958.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Jun 2021
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$22,326.00
COE Rebate Amount: \$13,085.00
Total Rebate Amount: \$13,085.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Jul 2018.

OK

MV 20K
PV 13.11K
Nett 6.9K



SELL YOUR CAR BY BIDDING

HIGHEST SELLING PRICE GUARANTEED!

OR GET \$100 CASH!



SEARCH
 Price Range
 Depreciation
 > 10 year(s)
 Vehicle Type
 Search View All Advanced Search

Used Car Comparison

Comparing 3 Vehicles

Nissan Cabstar (COE till 12/2020)



Add to Shortlist

Nissan Cabstar (COE till 03/2022)



Add to Shortlist

Nissan Cabstar (COE till 03/2022)



Add to Shortlist



NO IMAGE AV

Use search bar above to see 30 compares.

Clear All

Add all to Shortlist

Back to search result

| CAR DETAILS | | | | |
|-------------------|--|---|--|---|
| Price | \$25,500 | \$26,800 | \$28,800 | - |
| Instalment | N.A. | N.A. | N.A. | - |
| Registration Date | 02-Feb-2001 | 23-Feb-2001 | 02-Apr-2003 | - |
| Manufactured | 2000 | 2000 | 2003 | - |
| Mileage | - | - | - | - |
| Transmission | Manual | Manual | Manual | - |
| Engine Cap | 3,153 cc | 3,153 cc | 3,153 cc | - |
| Road Tax | - | - | - | - |
| Power | - | - | - | - |
| Curb Weight | 1,500 kg | 1,680 kg | 1,740 kg | - |
| Features | - | The Most Trusted 10 Feet Commercial Lorry In Singapore! Fuel Efficient Engine And Reliable Machine! | Cheapest In The Market! Best Deal! Uses Timing Chain So No Worries About Timing Belt Breaking! | - |
| Accessories | - | Full Checkered Plated Deck. | Power Window, Music Player, New Paint, Compressor Changed, Servicing Just Done And Many More On The List To Go! | - |
| Description: | Please Call In Advance Before Viewing. Thanks. | Looking For Value For Money 10 Feet Lorry? This Nissan Cabstar Definitely Is The One You Looking For! Eligible For PARF Of \$4,800! Until Last Day Of Driving! Low Depreciation And Monthly! Highest Trade-In For Your Current Vehicle! High And Fast Approve Loan! Immediate Insurance Quotation! No Repairs Needed! Call Now For More Details On How Much You Can Take Back Until The Last Day! Call Now! | PQP Paid \$24,394. High Scrap Value! Owner Use For Transport To Site And Back Only. Must Sell Great Condition Cabstar! No Repairs Needed At All! Call Our Friendly Salesperson To View Now | - |
| COE | \$31,269 | \$24,394 | - | - |
| OMV | \$23,464 | \$21,194 | \$19,912 | - |
| ARF | \$1,174 | \$1,060 | \$996 | - |
| Depreciation | \$10,240 /yr | \$7,170 /yr | \$7,710 /yr | - |
| No. of Owners | 4 | 3 | 3 | - |
| Type of Vehicle | Truck | Truck | Truck | - |
| Category | COE Car | COE Car | COE Car | - |
| Availability | Available | Available | Available | - |
| Remarks | Fuel type Diesel | Fuel type Diesel | Fuel type Diesel | - |

WORTH \$16,000
Cars & Prizes EACH WEEK

SNAP & WIN

Snap a shot of yourself and a car you love! Simply tag @SGCARMART #SGCMLoveCars to participate! Find out more >

1st - 31st July 2018

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

2011 Mazda 3, Under Utilized!

55k Km Mileage, Agent Unit.
Selling Cheap!
Diesel, Clean, StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Save Search

Print

< Back (1 2) Next >

Sort by Date Posted

20 results/page

| | | | | | | | | |
|------------------|----------------|-------|-----------------|------------------|---------|----------|----------|-----------|
| 40 vehicles | Search Cabstar | | Advanced Search | | Search | View All | | |
| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
| Search Selection | Cabstar | Any | Any | > 10 year(s) old | Any | Any | Any | Available |



☐ Nissan Cabstar (COE till 05/2019)

\$6,500

\$7,210 /yr

27-Jun-2000

3,153 cc

350,000 km

Truck

Available

Fuel Type: Diesel

Good Running Condition, One Owner Since New. Sell It Due To Upgrade. Sms Or WhatsApp Are Welcome.

Posted: 30-Jun-2018 Tags: 2001 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☒ Nissan Cabstar (COE till 12/2020)

\$25,500

\$10,240 /yr

02-Feb-2001

3,153 cc

-

Truck

Available

Fuel Type: Diesel

Please Call In Advance Before Viewing. Thanks.

Posted: 30-Jun-2018 Tags: 2001 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☒ Nissan Cabstar (COE till 03/2022)

\$26,800

\$7,170 /yr

23-Feb-2001

3,153 cc

-

Truck

Available

Fuel Type: Diesel

Looking For Value For Money 10 Feet Lorry? This Nissan Cabstar Definitely Is The One You Looking For! Eligible For PARF Of \$4.8K! Until Last Day Of Driving! Low Depreciation And Monthly! Highest Trade...

Net Link Partners Pte Ltd

Posted: 28-May-2018 Tags: 2001 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☐ Nissan Cabstar (COE till 07/2022)

\$24,800

\$6,090 /yr

10-Aug-2002

3,153 cc

-

Truck

Available

Fuel Type: Diesel

Excellent Condition, No Repair Needed, Price Negotiable, Easy Loan, Low Interest, Call To Make Appointment Before Drop By.

Posted: 04-Jul-2018 Tags: 2002 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle



☒ Nissan Cabstar (COE till 03/2022)

\$28,800

\$7,710 /yr

02-Apr-2003

3,153 cc

-

Truck

Available

Fuel Type: Diesel

PCP Paid: \$24,394, High Scrap Value! Owner Use For Transport To Site And Back Only. Must Sell Great Condition Cabstar! No Repairs Needed At All! Call Our Friendly Salesperson To View Now

Net Link Partners Pte Ltd

Posted: 02-Jul-2018 Tags: 2003 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☐ Nissan Cabstar (New 5-yr COE)

\$22,800

\$4,560 /yr

10-Jun-2003

3,153 cc

-

Truck

Available

Fuel Type: Diesel

Best Deal! Super Low Depreciation, 1 Owner, No Repair Needed, Well Maintenance By Previous Owner, Price Still Can Nego, High Loan With Lowest Interest Rate Available, Super High Trade In, Call Now!

ABWIN Bus Pte Ltd

Posted: 02-Jul-2018 Tags: 2003 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan

Compare [3]

Compare [3]

Nissan Cabstar (COE till

\$23,800

\$4,850 /yr

12-Jun-2003

3,153 cc

-

Truck

Available

View Received Message

This mail is associated with :

***GZ7707D (3006944712SG)**
[SLC3197M]
TP
UNITED WORKS PTE LTD
Jul 5 2018 6:00PM
[LCRF PTE LTD]
New Hock Teck Motor Pte Ltd

- Reply
- Reply All
- Mark as Unread
- Print Message
- Delete Message
- Forward

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 17/09/2018 16:58 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10707.45) - GZ7707D - Claim Handler: Tan, Wilson-KL

Approved:10707.45.

DOCUMENTS SUMMARY
There are no documents.

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1807-0142 / GZ7707D
Your Ref : SLC3197M
Date : 25th July 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

AIG ASIA Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building, #09-16
Singapore 079120

WITHOUT PREJUDICE

Dear Sirs,

**RE: ACCIDENT INVOLVING GZ7707D & SLC3197M AT YISHUN AVE 7 LAMP POST 42 ON
05.07.2018, 18:07HRS**

We are instructed by **UNITED WORKS PTE LTD** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **GZ7707D** was damaged by vehicle **SLC3197M** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

| | |
|--|---------------------|
| 1) Repair Costs | \$ 9,500.00 |
| 2) Loss of Use for 12 days (10 + 2 Weekends) | \$ 1,200.00 |
| 3) LTA Search Fees | \$ 7.45 |
| | <u>\$ 10,707.45</u> |

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$10,707.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

NEW HOCK TECK MOTOR PTE LTD



Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 12 July, 2018 2:29 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLC 3197M AND GZ 7707D ON 05/07/2018

Our Ref: CC6/LCR18012432/Awb3

12 July 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLC 3197M AND GZ 7707D ON 05/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd
Kaki Bukit Avenue 6
Blk 1 #01-43
Singapore 417883

Dear Sir,

Accident on

05/07/18, 1807

Involving Vehicles

GZ7707D, SLC3197M

Along

Yishun Ave 7 LP 42

I/We, the registered owner/driver of vehicle registration no: _____
have involved in the above accident.

GZ7707D

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature
(Company's stamp if applicable)

Name: _____

NRIC No.: _____

Date: _____

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. GZ7707D and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 05 day of 07 20 13.

| | | | |
|-------------------|---|---|---|
| Signature | : |  |  |
| Name | : | <u>United Works Pte Ltd</u> | |
| ID No. | : | <u>200716702D</u> | |
| Address | : | <u></u> | |
| Witness Signature | : |  | |
| Witness Name | : | <u>Chow Yue Yin</u> | |
| Witness ID | : | <u>S8126618H</u> | |
| Witness Address | : | <u>1 Kaki Bukit Avenue 6 #01-43</u> <u>Singapore 417883</u> | |

WITHOUT PREJUDICE

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, NEW HOCK TECK MOTOR PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 9,500.00 (repair cost), S\$ 960.00 (loss of ^{all} ~~car~~ use), S\$7.45 (disbursement), for vehicle no. GZ 7707D that was damaged pursuant to the accident which occurred on 05/07/2018 (date) along YISHUN AVE 7 (location) involving vehicle no/s SLC 3197M.

This is pursuant to the inspection conducted on 05/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner UNITED WORKS PTE LTD (the third party claimant") of vehicle no. GZ 7707D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GZ 7707D (vehicle no.) as a result of the accident.



We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of 09 (month) 2018 (year)



Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

AIG ASIA Pacific Insurance Pte Ltd

78 Shenton Way,
AIG Building, #09-16
Singapore 079120

Invoice No : NPL1807-0142

Date : 25-Jul-18

Date of Accident : 05-Jul-18

Vehicle No. : G27707D

Model Type : Nissan Cabstar

Client: UNITED WORKS PTE LTD

| Descriptions | | Amount |
|----------------------|--|----------|
| Lump Sum Repair Cost | | 9,500.00 |
| Total | | 9,500.00 |

SIN DOLLARS: NINE THOUSAND AND FIVE HUNDRED ONLY



[> Back to OneMotoring](#)

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Jul 2018 / 10:22:52

Receipt Date/Time : 06 Jul 2018 / 10:22:52

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180706-000475

Previous Receipt No. :

| S/N | Item Description/ Business Transaction Reference No. | Amount Before GST (S\$) | GST Amount (S\$) | Amount After GST (S\$) |
|-----|--|-------------------------------|------------------------|------------------------------|
|-----|--|-------------------------------|------------------------|------------------------------|

Result of Insurance Enquiry - SLC3197M

As at 05 Jul 2018/18:07:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLC3197M

Enquiry Fee

20180706102157713154

7.00 0.49 7.49

Sub-Total 7.00 0.49 7.49

Total Before Rounding 7.00 0.49 7.49

Rounding Difference 0.04

Total Amount Payable 7.45

Paid By

20180706102204963 Direct Debit: eNETS Debit
(Internet Banking) 7.45

Total 7.45

Cash Change 0.00

Tendered Amount 7.45

Excess Refundable Amount 0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|--|--|--|------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 07 Jul 2018 Edit Reg | | 05 Jul 2018 00:00 Edit Adj Rpt | S\$9,500.00 Edit Estimates | S\$9,500.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | LCRF PTE LTD, Co. Reg. No.: 201624597K | | | | | | | | |
| Main Claimant: | UNITED WORKS PTE LTD, Co. Reg. No.: 200716702D | | | | | | | | |
| Vehicle Reg. No.: | GZ7707D | Date of Loss: | 05/07/2018 18:00 - :59 [204 Months and 23 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / 3006944712SG | Policy/Cover Note No.: | 0999994815 (Comprehensive) | | | | | | |
| Vehicle Reg. No. (Insured): | SLC3197M | Policy No. (Claimant): | DMCPHQ18-003230 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241 | | | | | | | | |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL] | | | | | | | | |
| Claimant's Insurer: | EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/07/2018] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> AIG_SG_EXPRESS (17/09/2018): Alert - Adj Mandate Approved (S\$10707.45) - GZ7707D - Claim Handler: Tan, Wilson... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*GZ7707D (3006944712SG)
[SLC3197M]

TP



















































UNITED WORKS PTE LTD


















































Jul 5 2018 6:00PM

[LCRF PTE LTD]

New Hock Teck Motor Pte Ltd

| | | | | | | | | | | | | | | | | | | | | |
|-------------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|----------|-------------------------------------|-----------------|--|--|
| Upload Documents | | | Upload Photos | | | Compose New Letter | | | Upload Video | | | Upload Audio | | | View | | | View in Browser | | |
| Letters/Correspondences | | | | | | | | | | | | | | | 1 per page | | <input type="checkbox"/> | | | |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | (Draft) | Third Party Express Settlement – Payment Breakdown | | | | | | | | | | | | | 1 | Edit | | | | |
| Assessment Reports | | | | | | | | | | | | | | | 1 per page | | <input type="checkbox"/> | | | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | | | | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | 10/07/18 13:14 | Accident Statement From:OD - Reg. No: SLC3197M, Claimant: LCRF PTE LTD | | | | | | | | | | | | | 1 | Load HTM | | | | |
| Photos/Images | | | | | | | | | | | | | | | 3 per page | | <input type="checkbox"/> | | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | | | | | | | | | | Thumbnail | | Print | | | |
| 1 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 2 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 3 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 4 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 5 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 6 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 7 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 8 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 9 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 10 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 11 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 12 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 13 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 14 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 15 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 16 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 17 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 18 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 19 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 20 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 21 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 22 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 23 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 24 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 25 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 26 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 27 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 28 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 29 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |
| 30 | 29/08/18 12:53 | General View | | | | | | | | | | | | | 1 | Load JPG | <input checked="" type="checkbox"/> | | | |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 31 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 29/08/18 12:53 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-----------------------------------|--|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 81 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 84 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 29/08/18 12:53 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 126 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 127 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 128 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 129 | 29/08/18 12:54 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences | | | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|--|------------|-------------------------------------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 09/07/18 15:22 | TP GIA REPORT. | Load PDF | |
| 2 | 12/07/18 14:30 | Email letter to OI ACCIDENT INVOLVING SLC 3197M AND GZ 7707D ON 05.07.2018 | Load PDF | |
| 3 | 14/09/18 16:58 | LTA SEARCH | Load PDF | |
| 4 | 17/09/18 11:04 | Email to AIG to seek mandate 17.9.18 | Load PDF | |
| 5 | 19/09/18 09:00 | WORKSHOP INVOICE | Load PDF | |
| 6 | 19/09/18 09:00 | AUTHORISATION TO ACT FORM | Load PDF | |
| 7 | 19/09/18 09:00 | Release Voucher | Load PDF | |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail | Print |
| 1 | 11/07/18 18:38 | E-filed GIA report | Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |

| |
|--|
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|---------------------|--------|------------------------|
| Vehicle No: | SLC3197M (Insd veh) | Model: | NISSAN CABSTAR 3.0 (M) |
| | GZ7707D (TP veh) | | |
| Date of Accident: | 05/07/2018 | | |

| | | | | |
|-----------------------|---|------------------------------|--|-------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | |
| Repair Estimate | : | \$ | 37,417.30 | |
| Final Repair Cost | : | \$ | 9,500.00 | |
| Loss of Use | : | \$ | 960.00 | 12.00 days at \$80.00 per day |
| Rental (if any) | : | \$ | 0.00 | days |
| LTA / GIA Search Fee | : | \$ | 7.45 | |
| Others: | : | \$ | 0.00 | |
| | : | \$ | | |
| Final Settlement Sum | : | \$ | 10,467.45 | |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 100 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|-----------------------------|------|-----------|
| 1) | New Hock Teck Motor Pte Ltd | : \$ | 10,467.45 |
| 2) | | : \$ | |
| 3) | | : \$ | |
| 4) | | : \$ | |

JOANNE LEE KHANG MIN

19 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18012432/AWB3Q2

Date: 19/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994815
Claimant Vehicle No : GZ7707D **Insured Vehicle No :** SLC3197M
Date of Loss: 05/07/2018 **Nature of Claim:** TP **Claim No:** 3006944712SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ7707D**
 Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: QD32152716
 Reg. Date: 12/06/2001 (Man. Year: 2001) Chassis No: JN1SF4F23Z0844152
 Colour: Silver Odometer: 563992 km
 Engine Capacity: 3153 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C Rear Tyre Size: 155 R12C
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|------------------|------------------|--------------|
| Parts | 28,777.30 | 8,080.90 | 20,696.40 | 71.92 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 8,640.00 | 3,790.00 | 4,850.00 | 56.13 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 37,417.30 | 11,870.90 | 25,546.40 | 68.27 |
| Approved Total (Overridden) (\$\$) | | 9,500.00 | | |
| Nett Amount (\$\$) | 37,417.30 | 9,500.00 | 27,917.30 | 74.61 |
| + Loss of Use (12.0 x S\$80.00/day) (\$\$) | | 960.00 | | |
| + Doc/Search Fee (\$\$) | | 7.45 | | |
| Nett Liability (\$\$) | | 10,467.45 | | |

INSPECTION

Date of Assignment: 05/07/2018
 Date Inspected: 05/07/2018 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|------------|--------------|
| 1 | 1 | | *REAR TAIL GATE | Dented | 1,399.70 F | *1,399.70 FL |
| 2 | 1 | | *REAR TAIL GATE NISSAN LOGO STICKER | Necessary | 99.10 F | *99.10 FL |
| 3 | 1 | | *REAR TAIL GATE LOWER NISSAN CABSTAR STICKER | Necessary | 28.10 F | *28.10 FL |
| 4 | 2 | | *REAR TAIL GATE TOP SIDE HANDLE | Not Necessary | 370.20 F | *- FL |
| 5 | 1 | | *REAR TAIL GATE LOWER SIDE LOCK | O/S Bent | 96.40 F | *48.20 FL |
| 6 | 2 | | *REAR TAIL GATE LOWER SIDE HINGES | Not Necessary | 294.60 F | *- FL |
| 7 | 1 | | *REAR TAIL GATE LOWER SIDE BRACKET | O/S Bent | 251.00 F | *125.50 FL |
| 8 | 1 | | *REAR TAIL GATE LOWER SIDE BRACKET STOPPER RUBBER | O/S Cut | 48.40 F | *12.10 FL |
| 9 | 2 | | *REAR TAIL LAMP | Cracked | 497.20 F | *497.20 FL |
| 10 | 1 | | *REAR TAIL LAMP BRACKET | O/S Bent | 222.40 F | *111.20 FL |
| 11 | 1 | | *REAR NUMBER LAMP | Not Necessary | 67.50 F | *- FL |
| 12 | 1 | | *REAR NUMBER BRACKET | Bent | 175.50 F | *175.50 FL |
| 13 | 1 | | *REAR SPARE TYRE LOCK | Damaged | 238.30 F | *238.30 FL |
| 14 | 2 | | *REAR EXHAUST MOUNTING | Not Necessary | 67.00 F | *- FL |
| 15 | 1 | | *REAR TAILGATE ALUMINIUM COVER | Not Necessary | 278.20 F | *- FL |
| 16 | 10 | | *REAR TAILGATE & FLOOR PANEL ALUMINIUM RIVERT | Necessary | 150.00 F | *50.00 FL |
| 17 | 1 | | *REAR FLOOR PANEL ALUMINIUM COVER | Not Necessary | 455.10 F | *- FL |
| 18 | 1 | | *REAR TAILGATE LOWER MEMBER | Repair | 418.80 F | *- FL |
| 19 | 1 | | *REAR FLOOR PANEL | Repair | 8,000.00 F | *- FL |
| 20 | 1 | | *BRAKE BOOSTER PUMP | Not Necessary | 346.10 F | *- FL |
| 21 | 1 | | *BRAKE BOOSTER BRACKET | Not Necessary | 135.50 F | *- FL |
| 22 | 1 | | *FRONT WINDSCREEN RUBBER | Necessary | 160.40 F | *160.40 FL |
| 23 | 1 | | *FRONT RH WIPER NOZZLE | Cracked | 28.80 F | *28.80 FL |
| 24 | 1 | | *FRONT NISSAN PANEL (BLACK COLOR) | Cracked | 544.10 F | *544.10 FL |
| 25 | 1 | | *FRONT PANEL | Distorted | 1,554.00 F | *1,554.00 FL |
| 26 | 1 | | *FRONT GRILLE | Cracked | 355.60 F | *355.60 FL |
| 27 | 1 | | *FRONT GRILLE EMBLEM LOGO | Necessary | 66.40 F | *66.40 FL |
| 28 | 2 | | *FRONT HEAD LAMP | Cracked | 696.40 F | *696.40 FL |
| 29 | 1 | | *FRONT SIDE LAMP | O/S Cracked | 369.00 F | *184.50 FL |
| 30 | 1 | | *FRONT BUMPER | Deformed | 706.90 F | *706.90 FL |
| 31 | 2 | | *FRONT BUMPER BRACKET | Not Necessary | 1,409.20 F | *- FL |
| 32 | 1 | | *FRONT BUMPER CENTER MEMBER | Not Necessary | 353.80 F | *- FL |
| 33 | 1 | | *FRONT DASHBOARD | Not Necessary | 994.70 F | *- FL |
| 34 | 1 | | *FRONT RH DOOR PILLAR | Repair | 1,135.50 F | *- FL |
| 35 | 1 | | *FRONT RH DOOR INNER LOCK | Not Necessary | 167.60 F | *- FL |
| 36 | 1 | | *REAR TAIL GATE 70KM/H STICKER | Necessary | 20.00 FS | *15.00 FS |
| 37 | 1 | | *REAR TAIL GATE 13 PAX STICKER | Necessary | 20.00 FS | *15.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|------------|
| 38 | 1 | | *REAR REVERSE SENSOR | Not Necessary | 294.00 FS | *- FS |
| 39 | 1 | | *REAR NUMBER PLATE | Bent | 50.00 FS | *30.00 FS |
| 40 | 1 | | *REAR STEP PANEL BRACKET | Bent | 750.00 FS | *550.00 FS |
| 41 | 1 | | *REAR CHASSIS CENTER MEMBER | Bent | 680.00 FS | *280.00 FS |
| 42 | 1 | | *REAR EXHAUST | Not Necessary | 545.50 FS | *- FS |
| 43 | 1 | | *REAR CENTER EXHAUST | Not Necessary | 423.40 FS | *- FS |
| 44 | 1 | | *BRAKE BOOSTER | Not Necessary | 1,147.90 FS | *- FS |
| 45 | 1 | | *FRONT BUMPER NUMBER PLATE | Bent | 50.00 FS | *30.00 FS |
| 46 | 1 | | *FRONT AIR CON COOLING COIL BLOWER ASSY | Cracked | 787.10 FS | *787.10 FS |
| 47 | 1 | | *FRONT AIR CON COOLING COIL DISCHARGE PIPE | Not Necessary | 166.10 FS | *- FS |
| 48 | 1 | | *FRONT AIR CON COOLING COIL SUCTION PIPE | Not Necessary | 125.20 FS | *- FS |
| 49 | 1 | | *FRONT STEERING BOX | Not Necessary | 1,536.60 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 28,777.30 | 8,789.10 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00 | 708.20 |
| Total Parts (\$\$) | 28,777.30 | 8,080.90 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REFIT FRONT DASHBOARD | New | 380.00 | 220.00 |
| 2 | TO REMOVE & REFIT AIR CON BLOWER PIPE & TOP UP GAS | New | 450.00 | 150.00 |
| 3 | TO REMOVE & REFIT FRONT WINDSCREEN | New | 100.00 | 100.00 |
| 4 | GUM | New | 50.00 | 50.00 |
| 5 | TO REMOVE & REFIT REAR REVERSE SENSOR | New | 100.00 | 0.00 |
| 6 | TO REMOVE & REFIT REAR & CENTER EXHAUST | New | 380.00 | 80.00 |
| 7 | TO REMOVE & REFIT REAR BODY & REPAIR CHASSIS MEMBER | New | 1,200.00 | 0.00 |
| 8 | TO REMOVE & REFIT REAR ALUMINIUM BOX | New | 450.00 | 0.00 |
| 9 | TO REMOVE & REFIT BRAKE BOOSTER & STEERING BOX | New | 380.00 | 200.00 |
| 10 | TO CHECK WIRING | New | 100.00 | 30.00 |
| 11 | TUFF KOTE | New | 150.00 | 0.00 |
| 12 | TOWING FEES | New | 100.00 | 60.00 |
| 13 | PANEL BEATING | New | 2,800.00 | 1,600.00 |
| 14 | SPRAY PAINTING | New | 2,000.00 | 1,300.00 |
| Gross Labour Cost (S\$) | | | 8,640.00 | 3,790.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >