

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1225A
 Ref. No : BUS/06/18/5054
 Reg. Date : 03/07/2018
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Sun Yanchun
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 30/06/2018 05:15:00 PM
 Accident Reported Date / Time : 02/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SG1225A - REAR PORTION
 SLZ6022T (TP) - FRONT PORTION
 Prepared Date : 03/07/2018 09:43:54 AM



Sathya Sai
 5/7/2018

5 days

- Part by Part

- Photo before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 3,180.00	0.00
Total Spray Painting Charges	: 616.00	0.00
Total Material Charges	: 9,589.58	9,589.58
Other Charges	: 0.00	0.00
TOTAL	: 13,385.58	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 04/07/2018 05:44:25 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/07/2018 03:48:20 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	3,180.00	0.00 2120
Total Labour	3,180.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00 500
Total Spray Painting & Panel Beating	616.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
MA62864 02114			CROSS BAR REAR BUMPER (SBS VERSION) ✓DT	1	2,700.00	10.00	2,430.00	Replace	Replace	No
	REAR	6009907	REAR BUMPER CENTER ✓DMG	1	1,791.33	10.00	1,612.20	Replace	Replace	No
	REAR	6009909	REAR BUMPER RH ✓CHK	1	837.84	10.00	754.06	Replace	Replace	No
MA62868 34508			COVER UNDER RH (SBS VERSION) ✓CHK	1	1,750.00	10.00	1,575.00	Replace	Replace	No
MQ62850 0348901			PIPE COPPER (SBS VERSION) ✓DT	1	850.00	10.00	765.00	Replace	Replace	No
62875029 74	REAR	6010113	FLAP ENGINE :FOR MB CITARO O530 R	1	5,573.10	100.00	0.00	Repair	Repair	No
38204056		6010008	LAMP,LICENSE PLATE:FOR MB CITARO O530 ✓CRK	2	97.68	10.00	175.82	Replace	Replace	No
62888500 05	REAR	6009908	REAR BUMPER LH R	1	837.84	10.00	0.00	Repair	Replace	No
			COOLANT:ANTIFREEZE ✓NEL	1	524.00	10.00	471.60	Replace	Replace	No
A000683 2308			COVER UNDER LH (SBS VERSION) ✓CHK	1	1,931.00	10.00	1,737.90	Replace	Replace	No
	REAR		NUMBER PLATE ✓DT	1	68.00	0.00	68.00	Replace	Replace	No
TOTAL MATERIALS							9,589.58	9,589.58		
TOTAL MATERIALS(Discounted)							9,589.58	9,589.58		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									