

Trans-cab Auto Services Pte Ltd

AAD1807-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

Not Authorised
LI Sing &

Vehicle No.:

SHC 5542J

Chassis No.:

VF1ABL15AUC278894

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

5.7.2018

Third Party Insurer :

EQ

PART		LIST	
1	FENDER PANEL FRT RH	\$	783.83 ✓
1	WHEELARCH FRT RH	\$	278.84 X
1	FENDER BRACKET LOWER RH	\$	15.79 X
1	FENDER INSULATOR RH	\$	130.84 ✓
1	DOOR PANEL FRT RH	\$	2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	261.28
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK FRT RH	\$	194.77
1	DOOR LOCK FRT RH	\$	908.75
1	DOOR CATCH FRT RH	\$	131.23
1	DOOR HANDLE OUTER FRT RH	\$	477.76
1	DOOR HANDLE COVER FRT RH	\$	13.22
1	DOOR HANDLE MODULE FRT RH	\$	133.60
1	DOOR REGULATOR FRT RH	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	120.97
1	DOOR PANEL REAR RH	\$	2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	176.82
1	DOOR HINGE UPPER RH	\$	274.50
1	DOOR HINGE LOWER RH	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR LOCK REAR RH	\$	908.75
1	DOOR HANDLE OUTER REAR RH	\$	126.49
1	DOOR HANDLE CAP REAR RH	\$	35.52
1	DOOR HANDLE SEAL REAR RH	\$	7.89
1	DOOR HANDLE COVER REAR RH	\$	13.22
1	DOOR HANDLE MODULE REAR RH	\$	133.60
1	DOOR REGULATOR REAR RH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43

Trans-cab Auto Services Pte Ltd

AAD1807-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	Su 6.31	}
1	DOOR FINISHER REAR RH	\$	Su 423.10	
1	DOOR MOULDING REAR RH	\$	Su 176.82	
1	DOOR MOULDING CLIP L70Y	\$	Su 5.92	
1	DOOR MOULDING SCREW L70Y	\$	Su 6.91	
1	DOOR CASING REAR RH	\$	Su 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	Su 30.39	
1	DOOR CASING CLIP	\$	nn 12.63	
1	DOOR CASING LIGHT L70Y	\$	Su 48.74	
1	DOOR FINISHER INNER REAR RH	\$	Su 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	Su 210.96	
1	DOOR BLIND REAR RH	\$	Su 741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	Su 410.66	
1	DOOR SEAL REAR RH	\$	Su 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Su 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	Su 334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	Su 115.64	
1	FENDER PANEL REAR RH	\$	n 3,299.13	}
1	FENDER PANEL INNER TRIM REAR	\$	Su 671.45	
1	WHEELARCH REAR RH	\$	Su 543.47	
1	DOOR MIRROR ASSY RH	\$	Su 1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	Su 466.51	
1	ROCKER PANEL INNER RH	\$	n 1,024.79	}
1	ROCKER PANEL CENTER RH	\$	n 990.25	
1	BUMPER COVER REAR	\$	n 1,108.46	

\$	29,407.90
----	------------------

10% \$	2,940.79
--------	-----------------

\$	26,467.11
----	------------------

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	X

Trans-cab Auto Services Pte Ltd

AAD1807-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	— 6000
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	— 1500
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	— 6000
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	26,929.24
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	800
Putty and spray painting of the affected portion.	\$	4,200.00	1320
To rust-proofing of the affected areas.	\$	170.00	120
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	80
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	20
To Check Electrical Lighting Concerned.	\$	170.00	20

Trans-cab Auto Services Pte Ltd

AAD1807-039

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60%
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60%
Towing Fees.	\$	120.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X

TOTAL	\$	11,830.00
--------------	-----------	------------------

Over All Total	\$	38,759.24
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: