

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6829X

DATE 6/7/2018 9:48

MAKE :

MODEL : HYUNDAI i40

LKK/Nag

PbyP

PH

Lke

ALG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket Top (RH)			\$ 22.40
	Front Bumper Retainer Mounting			\$ 9.20
	Frnt Wheel Hub Cap, RH			\$ 150.70
	SUB TOTAL			\$ 744.60
	LESS 20%			\$ 148.92
	DISCOUNTED TOTAL			\$ 595.68
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	Frnt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 980.00
	ESTIMATE TOTAL			\$ 1,575.68

XR
?
?
Lesh

200
400
i
XAN

NA 2 LKK
6/7/18 1545
P/P
2 days
After repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.