

15/5/2019

INS. CASE OWNER:

Lunthia

CCV / AXA180

12445, R2u63^{SW}LKK:
IDAC:

Surveyor:

R4sni

DOI:

ASSIGNMENT

01/10/18

Date / Time:

01/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGA 5096C

Claim No.:

S8m00Npx/56027

Name of Insured:

VEE km let

Policy No.:

GA085615

Insured Tel No.:

HP:

Make / Model:

M450W

Excess Sec II : \$

D.O.A.:

2/2/18

Place of Accident:

BET upp BT Timan RD - 11
old market

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

9/11/2018

INSRS:
WSP:
Tel:
Liability:
RMKS:Ding
AutoINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

01/10/18

TH

SGA 5096C-X

SGA 5096C-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7/11/18
BT 11

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOB

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

10/10/18 Confirm with Michelle

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.: 5

If NO or B 28, Ass. Lia:

Repair Cost:

\$

15144.45

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

1140.00 (560 x 19 days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$

2.00

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

16286.45

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

16286.45

Name 1:

DING AUTO PTE LTD

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
10/10/18

RECEIVED 23 OCT 2018

* Gmmt/dnm.
- OIRK, sent out 21 LETTER.

31/10/18

OID making right turn and collided
with TP which was driving straight from
opposite direction.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012445/R1ub3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 09-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGA 5096C	Veh. Inspected	SLH 5205J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	09/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/07/2018	Inspection Date		
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/07/2018 9.36

JOB-NO: 85008431

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 4

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH5205J

TRANS: AUTO

CHASSIS: MR053REH104559106

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335956

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,400.00	0.00	2,400.00		Y	1400
2 RUSH PROOFING	1.00	250.00	0.00	250.00		Y	150
3 TO ADJUST HEAD LAMP & CHECK WIRING	1.00	120.00	0.00	120.00		Y	30
4 REMOVE & REPLACE FRONT ENGINE	1.00	400.00	0.00	400.00		Y	200
5 REMOVE & REFIT FRONT WINDSCREEN	1.00	130.00	0.00	130.00		Y	120
6 REMOVE & REFIT FRONT DASH BOARD	1.00	200.00	0.00	200.00		Y	150
7 REMOVE & REFIT FRONT SEAT RHS	1.00	150.00	0.00	150.00		Y	60
8 REMOVE & REFIT FRONT CARPET RHS	1.00	120.00	0.00	120.00		Y	60
9 R & R ROOF LINING	1.00	260.00	0.00	260.00		Y	200
10 MOUNT WORK BENCH	1.00	350.00	0.00	350.00		Y	200
11 TO REMOVE & REPLACED RHF DOOR & RHR DOOR TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	200.00	0.00	200.00		Y	120
12 R & R REAR SPORT RIM & FRONT SPORT RIM & TRANSFER BOTH TYRE TO THE NEW RIM	1.00	150.00	0.00	150.00		Y	80
13 WHEEL ALIGNMENT	1.00	150.00	0.00	150.00		Y	60
14 REMOVE & REFIT UNDER CARRIAGE	1.00	300.00	0.00	300.00		Y	180
15 ALIGNMENT FRONT SUPPORT PANEL WHEEL HOUSE PANEL	1.00	120.00	0.00	120.00		Y	80
16 REFILL AIR CON GAS	1.00	100.00	0.00	100.00		Y	80
17 TO SPRAY PAINT ON THE AFFECTED AREAS FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
18 TO SPRAY PAINT ON THE AFFECTED AREAS BONNET	1.00	250.00	0.00	250.00		Y	150
19 TO SPRAY PAINT ON THE AFFECTED AREAS FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00		Y	200
20 TO SPRAY PAINT ON THE AFFECTED AREAS FRONT REINFORCEMENT	1.00	250.00	0.00	250.00		Y	200
21 TO SPRAY PAINT ON THE AFFECTED AREAS FRONT FENDER RHS	1.00	250.00	0.00	250.00		Y	200
22 TO SPRAY PAINT ON THE AFFECTED AREAS FRONT DOOR RHS	1.00	250.00	0.00	250.00		Y	200
23 TO SPRAY PAINT ON THE AFFECTED AREAS REAR DOOR RHS	1.00	250.00	0.00	250.00		Y	200
24 TO SPRAY PAINT ON THE AFFECTED AREAS REAR FENDER RHS	1.00	250.00	0.00	250.00		Y	200

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR DISP	REV PRICE
25 TO SPRAY PAINT ON THE AFFECTED AREAS,ROCKER PANEL	1.00	250.00	0.00	250.00		Y	100
26 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT A PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
27 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT B PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
28 R & R CONDENSOR & RADIATOR	1.00	120.00	0.00	120.00		Y	60 X 14
29 R & R LHS,RHS DOOR COMPONENTS	1.00	150.00	0.00	150.00		Y	X 17
30 R & R B PILLAR GARNISH	1.00	120.00	0.00	120.00		Y	60
31 R & R SEAT BELT RHS	1.00	120.00	0.00	120.00		Y	60
32 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
33 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,ROOF LINING	1.00	250.00	0.00	250.00		Y	X 17
34 ALIGNMENT FRONT CHASSIS	1.00	200.00	0.00	200.00		Y	X 17
TOTAL		9,360.00	0.00	9,360.00			

MATERIALS

1 FRONT BUMPER	1.00	511.22	127.81	383.41	X L	Y	30
2 FRONT BUMPER FOG LAMP COVER RHS	1.00	121.75	30.44	91.31	X SU	Y	50
3 FRONT BUMPER LOWER GRILLE	1.00	138.71	34.68	104.03	X SU	Y	
4 FRONT BUMPER SIDE RETAINER RHS	1.00	58.17	14.54	43.63	X L	Y	
5 FRONT BUMPER SIDE RETAINER LHS	1.00	58.17	14.54	43.63	X SU	Y	
6 FRONT BUMPER BRACKET RHS	1.00	135.70	33.93	101.77	X L	Y	
7 FRONT BUMPER BRACKET LHS	1.00	135.70	33.93	101.77	X L	Y	
8 FRONT REINFORCEMENT	1.00	386.60	96.65	289.95	X L	Y	
9 FRONT REINFORCEMENT ARM LHS	1.00	135.70	33.93	101.77	X L	Y	
10 FRONT REINFORCEMENT ARM RHS	1.00	135.70	33.93	101.77	X L	Y	
11 FRONT BUMPER SPONGE	1.00	102.38	25.60	76.78	X L	Y	
12 FRONT BUMPER LOWER CENTRE COVER	1.00	211.67	52.92	158.75	X L	Y	
13 BONNET	1.00	1,140.40	285.10	855.30	X L	Y	50
14 BONNET INSULATOR	1.00	301.36	75.34	226.02	X L	Y	
15 BONNET HINGE LHS	1.00	76.60	19.15	57.45	X L	Y	
16 BONNET HINGE RHS	1.00	76.60	19.15	57.45	X L	Y	
17 BONNET HINGE BOLT	1.00	38.25	9.56	28.69	X L	Y	
18 HEAD LAMP RHS	1.00	794.10	198.53	595.57	X L	Y	
19 HEAD LAMP PANEL RHS	1.00	564.00	141.00	423.00	X SU	Y	
20 FRONT SUPPORT PANEL	1.00	1,074.60	268.65	805.95	X SU	Y	
21 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	X L	Y	
22 FRONT RADIATOR GRILLE	1.00	565.00	141.25	423.75	X L	Y	
23 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	48.00	12.00	36.00	X L	Y	
24 FRONT RADIATOR GRILLE TOP GARNISH	1.00	125.00	31.25	93.75	X SU	Y	
25 FRONT FENDER RHS	1.00	859.00	214.75	644.25	X L	Y	
26 FRONT FENDER "VVTI" EMBLEM RHS	1.00	46.00	11.50	34.50	X L	Y	
27 FRONT FENDER INNER SHIELD RHS	1.00	182.00	45.50	136.50	X L	Y	
28 FRONT FENDER WHEEL HOUSE PANEL RHS	1.00	557.00	139.25	417.75	X SU	Y	
29 FRONT FENDER QUARTER GARNISH RHS	1.00	65.00	16.25	48.75	X L	Y	
30 FRONT WASHER TANK MOTOR	1.00	196.00	49.00	147.00	X SU	Y	
31 FRONT WASHER TANK	1.00	167.00	41.75	125.25	X L	Y	
32 FRONT DRIVER SHAFT RHS	1.00	1,441.60	360.40	1,081.20	X L	Y	
33 FRONT LOWER ARM RHS	1.00	265.07	66.27	198.80	X L	Y	
34 FRONT LOWER ARM BALL JOINT RHS	1.00	270.00	67.50	202.50	X L	Y	
35 FRONT KNUCLE ARM RHS	1.00	521.50	130.38	391.12	X L	Y	
36 FRONT KNUCLE ARM BEARING RHS	1.00	132.67	33.17	99.50	X L	Y	
37 FRONT KNUCLE ARM BOLT WITH NUT RHS	1.00	15.00	3.75	11.25	X L	Y	
38 FRONT SHOCK ABSORBER RHS	1.00	316.97	79.24	237.73	X L	Y	
39 FRONT SHOCK ABSORBER TOP MOULDING RHS	1.00	161.89	40.47	121.42	X L	Y	
40 FRONT SHOCK ABSORBER NUT SET	1.00	12.60	3.15	9.45	X L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
41 FRONT SHOCK ABSORBER DUST COVER	1.00	48.95	12.24	36.71	?	L	Y
RHS					?		
42 FRONT SHOCK ABSORBER BUSH RHS	1.00	27.85	6.96	20.89	?	L	Y
43 FRONT SHOCK ABSORBER SPRING RHS	1.00	122.60	30.65	91.95	?	L	Y
44 FRONT SHOCK ABSORBER SPRING SEAT	1.00	56.75	14.19	42.56	?	L	Y
UPPER RHS					?		
45 FRONT SHOCK ABSORBER SPRING SEAT	1.00	69.85	17.46	52.39	?	L	Y
LOWER RHS					?		
46 FRONT STABILIZER LINK RHS	1.00	190.70	47.68	143.02	?	L	Y
47 FRONT STABILIZER LINK NUT RHS	1.00	7.85	1.96	5.89	?	L	Y
48 FRONT STABILIZER BAR RHS	1.00	369.75	92.44	277.31	?	L	Y
49 FRONT STABILIZER BAR BRACKET RHS	1.00	29.75	7.44	22.31	?	L	Y
50 FRONT STABILIZER BAR BUSH RHS	1.00	37.85	9.46	28.39	?	L	Y
51 FRONT STEERING RAIL AND PINION ASSY	1.00	1,720.70	430.18	1,290.52	?	L	Y
52 FRONT WHEEL BEARING RHS	1.00	147.80	36.95	110.85	?	L	Y
53 FRONT WHEEL HUB RHS	1.00	266.40	67.10	201.30	?	L	Y
54 FRONT WHEEL HUB NUT	1.00	27.60	6.90	20.70	?	L	Y
55 FRONT BRAKE DISC RHS	1.00	221.70	55.43	166.27	?	L	Y
56 FRONT DOOR RHS	1.00	1,138.00	284.50	853.50	?	L	Y
57 FRONT DOOR WINDOW FRAME STICKER	1.00	68.00	17.00	51.00	?	L	Y
RHS					?		
58 FRONT DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	?	L	Y
59 FRONT DOOR RUBBER BEADING RHS	1.00	183.60	45.90	137.70	?	L	Y
60 FRONT DOOR BODY RUBBER RHS	1.00	313.67	78.42	235.25	?	L	Y
61 FRONT DOOR GLASS RHS	1.00	442.50	110.63	331.87	?	L	Y
62 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	?	L	Y
63 REAR FENDER INNER SHIELD RHS	1.00	67.75	16.94	50.81	?	L	Y
64 FRONT DOOR CHECKER RHS	1.00	151.20	37.80	113.40	?	L	Y
65 FRONT DOOR HINGE UPPER RHS	1.00	78.34	19.59	58.75	?	L	Y
66 FRONT DOOR HINGE BOTTOM RHS	1.00	78.34	19.59	58.75	?	L	Y
67 FRONT DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L	Y
68 FRONT DOOR LOCK CATCH RHS	1.00	45.67	11.42	34.25	?	L	Y
69 FRONT DOOR WINDOW REGULATOR RHS	1.00	177.60	44.40	133.20	?	L	Y
70 FRONT DOOR WINDOW REGULATOR	1.00	566.72	141.68	425.04	?	L	Y
MOTOR RHS					?		
71 FRONT B PILLAR RHS	1.00	375.60	93.90	281.70	?	L	Y
72 FRONT A PILLAR RHS	1.00	478.90	119.73	359.17	?	L	Y
73 REAR DOOR RHS	1.00	1,198.50	299.63	898.87	?	L	Y
74 REAR DOOR WINDOW FRAME STICKER RHS	1.00	67.84	16.96	50.88	?	L	Y
75 REAR DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	?	L	Y
76 REAR DOOR BODY RUBBER RHS	1.00	160.55	40.14	120.41	?	L	Y
77 REAR DOOR GLASS RHS	1.00	412.40	103.10	309.30	?	L	Y
78 REAR DOOR QUARTER GLASS RHS	1.00	86.40	21.60	64.80	?	L	Y
79 REAR DOOR QUARTER GLASS RHS	1.00	80.24	20.06	60.18	?	L	Y
RUBBER					?		
80 REAR DOOR CHECKER RHS	1.00	165.00	41.25	123.75	?	L	Y
81 REAR DOOR HINGE UPPER RHS	1.00	79.00	19.75	59.25	?	L	Y
82 REAR DOOR HINGE BOTTOM RHS	1.00	79.00	19.75	59.25	?	L	Y
83 REAR DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L	Y
84 REAR DOOR WINDOW REGULATOR RHS	1.00	170.00	42.50	127.50	?	L	Y
85 REAR DOOR WINDOW REGULATOR MOTOR	1.00	564.00	141.00	423.00	?	L	Y
RHS					?		
86 ROCKER PANEL RHS	1.00	628.00	157.00	471.00	?	L	Y
87 SIDE MIRROR RHS	1.00	1,129.00	282.25	846.75	?	L	Y
88 SIDE MIRROR COVER RHS	1.00	81.50	20.38	61.12	?	L	Y
89 FRONT RADIATOR	1.00	1,510.50	377.63	1,132.87	?	L	Y
90 CONDENSOR	1.00	1,289.24	322.31	966.93	?	L	Y
91 FRONT ABS SENSOR RHS	1.00	420.00	105.00	315.00	?	L	Y
92 FRONT DISC ROTOR RHS	1.00	298.00	74.50	223.50	?	L	Y
93 FRONT DISC ROTOR DUST COVER RH	1.00	100.41	25.10	75.31	?	L	Y

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR DISP	REV PRICE
94 BRAKE CALIPER RHS	1.00	700.76	175.19	525.57	X	L	Y
95 FRONT BRAKE HOSE RHS	1.00	120.00	30.00	90.00	X	L	Y
96 CROSSMEMBER ASSY	1.00	1,812.60	453.15	1,359.45	X	L	Y
97 FRONT DOOR RUN CHANNEL	1.00	143.00	35.75	107.25	X	L	Y
98 REAR BUMPER	1.00	487.00	121.75	365.25	repair	L	Y
99 REAR SHOCK ABSORBER RHS	1.00	317.00	79.25	237.75	X	L	Y
10 FRONT BUMPER CLIP	1.00	35.00	0.00	35.00	X	S	Y
10 FRONT NUMBER PLATE & CASING	1.00	80.00	0.00	80.00	X	S	Y
10 BONNET INSULATOR CLIP	1.00	35.00	0.00	35.00	X	S	Y
10 HEAD LAMP CLIP	1.00	35.00	0.00	35.00	X	S	Y
10 FRONT RADIATOR GRILLE TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	X	S	Y
10 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	X	S	Y
10 REAR FENDER INNER SHIELD RHS CLIP	1.00	35.00	0.00	35.00	X	S	Y
10 FRONT DOOR TRIM BOARD RHS CLIP	1.00	35.00	0.00	35.00	X	S	Y
10 REAR DOOR TRIM BOARD CLIP RHS	1.00	35.00	0.00	35.00	X	S	Y
10 FRONT SPORT RIM RHS	1.00	600.00	0.00	600.00	X	S	Y
11 FRONT TYRE RHS	1.00	450.00	0.00	450.00	X	S	Y
11 REAR SPORT RIM RHS	1.00	600.00	0.00	600.00	X	S	Y
11 REAR TYRE RHS	1.00	450.00	0.00	450.00	X	S	Y
11 WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	X	S	Y
11 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	X	S	Y
TOTAL:		38,604.11	007.39	29,596.72			
TOTAL PARTS & LABOUR		47,964.11	9,007.39	38,956.83			

EXCESS/LOADING \$\$ 0.00

No. Of Day:

15 days

RE-SURVEY BEFORE/ AFTER PAINTING

PART-BY PART OR LUMP SUM: \$\$

DATE OF SURVEY: 09 / 07 / 18 @ 1600

SURVEYED BY:

RASUL

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

NOTE: TO CHECK PART PRICES

P - 8554.82
 Suppl - 88.87
 L - 4420.00
 S/N - 1090.00
 T - 14,153.69

SUPPLEMENTRY ITEM

DINGAUTO

BLK 10, #01-20

Sin Ming Industrial Est, Sec C

Singapore 575645

Tel: 6457 5884

Fax: 6453 4227

VEHICLE NO:	SLH5205J
MODEL:	TOYOTA ALTIS
CHASSIS NO:	MR053REH104554106
INSURANCE:	
DATE SURVEY:	

[illegible]

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

09/07/2018 9:36

JOB-NO: 85008431

Page 1 of 4

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

ADDRESS: 50 UBI AVENUE 3

#01-12

SINGAPORE 408866

0

NIL

VEHICLE DETAILS

LICENSE NO: SLH5205J

TRANS: AUTO

CHASSIS: MR053REH104559106

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335956

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

\$4420

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,400.00	0.00	2,400.00			Y 1400
2 RUSH PROOFING	1.00	250.00	0.00	250.00			Y 150
3 TO ADJUST HEAD LAMP & CHECK WIRING	1.00	120.00	0.00	120.00			Y 30
4 REMOVE & REPLACE FRONT ENGINE	1.00	400.00	0.00	400.00			X photo 200? X 200 photo?
5 REMOVE & REFIT FRONT WINDCREEN	1.00	130.00	0.00	130.00			X photo 120? Y 150
6 REMOVE & REFIT FRONT DASH BOARD	1.00	200.00	0.00	200.00			Y 60
7 REMOVE & REFIT FRONT SEAT RHS	1.00	150.00	0.00	150.00			Y 60
8 REMOVE & REFIT FRONT CARPET RHS	1.00	120.00	0.00	120.00			Y X
9 R & R ROOF LINING	1.00	260.00	0.00	260.00			Y 200 photo?
10 MOUNT WORK BENCH	1.00	350.00	0.00	350.00			Y 120
11 TO REMOVE & REPLACED RHF DOOR & RHR DOOR,TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	200.00	0.00	200.00			Y 80
12 R & R REAR SPORT RIM & FRONT SPORT RIM & TRANSFER BOTH TYRE TO THE NEW RIM	1.00	150.00	0.00	150.00			Y 60
13 WHEEL ALIGNMENT	1.00	150.00	0.00	150.00			Y 180
14 REMOVE & REFIT UNDER CARRIAGE	1.00	300.00	0.00	300.00			Y 80
15 ALIGNMENT FRONT SUPPORT PANEL,WHEEL HOUSE PANEL	1.00	120.00	0.00	120.00			Y 80
16 REFILL AIR CON GAS	1.00	100.00	0.00	100.00			Y 200
17 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT BUMPER.	1.00	250.00	0.00	250.00			Y X
18 TO SPRAY PAINT ON THE AFFECTED AREAS,BONNET	1.00	250.00	0.00	250.00			Y 150
19 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00			Y X
20 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT REINFORCEMENT	1.00	250.00	0.00	250.00			Y 200
21 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT FENDER RHS	1.00	250.00	0.00	250.00			Y 200
22 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT DOOR RHS	1.00	250.00	0.00	250.00			Y 200
23 TO SPRAY PAINT ON THE AFFECTED AREAS,REAR DOOR RHS	1.00	250.00	0.00	250.00			Y 200
24 TO SPRAY PAINT ON THE AFFECTED AREAS,REAR FENDER RHS	1.00	250.00	0.00	250.00			Y 200

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
25 TO SPRAY PAINT ON THE AFFECTED AREAS,ROCKER PANEL	1.00	250.00	0.00	250.00		Y	100
26 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT A PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
27 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT B PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
28 R & R CONDENSOR & RADIATOR	1.00	120.00	0.00	120.00		Y	60 X
29 R & R LHS,RHS DOOR COMPONENTS	1.00	150.00	0.00	150.00		Y	X
30 R & R B PILLAR GARNISH	1.00	120.00	0.00	120.00		Y	60
31 R & R SEAT BELT RHS	1.00	120.00	0.00	120.00		Y	60
32 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
33 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,ROOF LINING	1.00	250.00	0.00	250.00		Y	X
34 ALIGNMENT FRONT CHASSIS	1.00	200.00	0.00	200.00		Y	X
TOTAL:		9,360.00	0.00	9,360.00			

MATERIALS

1 FRONT BUMPER	1.00	511.22	127.81	383.41	X	L	Y	200
2 FRONT BUMPER FOG LAMP COVER RHS	1.00	121.75	30.44	91.31	X	L	Y	50
3 FRONT BUMPER LOWER GRILLE	1.00	138.71	34.68	104.03	X	L	Y	
4 FRONT BUMPER SIDE RETAINER RHS	1.00	58.17	14.54	43.63	X	L	Y	
5 FRONT BUMPER SIDE RETAINER LHS	1.00	58.17	14.54	43.63	X	L	Y	
6 FRONT BUMPER BRACKET RHS	1.00	135.70	33.93	101.77	X	L	Y	
7 FRONT BUMPER BRACKET LHS	1.00	135.70	33.93	101.77	X	L	Y	
8 FRONT REINFORCEMENT	1.00	386.60	96.65	289.95	X	L	Y	
9 FRONT REINFORCEMENT ARM LHS	1.00	135.70	33.93	101.77	X	L	Y	
10 FRONT REINFORCEMENT ARM RHS	1.00	135.70	33.93	101.77	X	L	Y	
11 FRONT BUMPER SPONGE	1.00	102.38	25.60	76.78	X	L	Y	
12 FRONT BUMPER LOWER CENTRE COVER	1.00	211.67	52.92	158.75	X	L	Y	
13 BONNET	1.00	1,140.40	285.10	855.30	X	L	Y	
14 BONNET INSULATOR	1.00	301.36	75.34	226.02	X	L	Y	
15 BONNET HINGE LHS	1.00	76.60	19.15	57.45	X	L	Y	
16 BONNET HINGE RHS	1.00	76.60	19.15	57.45	X	L	Y	
17 BONNET HINGE BOLT	1.00	38.25	9.56	28.69	X	L	Y	
18 HEAD LAMP RHS	1.00	794.10	198.53	595.57	X	L	Y	
19 HEAD LAMP PANEL RHS	1.00	564.00	141.00	423.00	X	L	Y	
20 FRONT SUPPORT PANEL	1.00	1,074.60	268.65	805.95	X	L	Y	
21 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	X	L	Y	
22 FRONT RADIATOR GRILLE	1.00	565.00	141.25	423.75	X	L	Y	
23 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	48.00	12.00	36.00	X	L	Y	
24 FRONT RADIATOR GRILLE TOP GARNISH	1.00	125.00	31.25	93.75	X	L	Y	
25 FRONT FENDER RHS	1.00	859.00	214.75	644.25	X	L	Y	
26 FRONT FENDER "VVTI" EMBLEM RHS	1.00	46.00	11.50	34.50	X	L	Y	
27 FRONT FENDER INNER SHIELD RHS	1.00	182.00	45.50	136.50	X	L	Y	
28 FRONT FENDER WHEEL HOUSE PANEL RHS	1.00	557.00	139.25	417.75	X	L	Y	
29 FRONT FENDER QUARTER GARNISH RHS	1.00	65.00	16.25	48.75	X	L	Y	
30 FRONT WASHER TANK MOTOR	1.00	196.00	49.00	147.00	X	L	Y	
31 FRONT WASHER TANK	1.00	167.00	41.75	125.25	X	L	Y	
32 FRONT DRIVER SHAFT RHS	1.00	1,441.60	360.40	1,081.20	X	L	Y	
33 FRONT LOWER ARM RHS	1.00	265.07	66.27	198.80	X	L	Y	
34 FRONT LOWER ARM BALL JOINT RHS	1.00	270.00	67.50	202.50	X	L	Y	
35 FRONT KNUCLE ARM RHS	1.00	521.50	130.38	391.12	X	L	Y	
36 FRONT KNUCLE ARM BEARING RHS	1.00	132.67	33.17	99.50	X	L	Y	
37 FRONT KNUCLE ARM BOLT WITH NUT RHS	1.00	15.00	3.75	11.25	X	L	Y	
38 FRONT SHOCK ABSORBER RHS	1.00	316.97	79.24	237.73	X	L	Y	
39 FRONT SHOCK ABSORBER TOP MOULDING RHS	1.00	161.89	40.47	121.42	X	L	Y	
40 FRONT SHOCK ABSORBER NUT SET	1.00	12.60	3.15	9.45	X	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
41 FRONT SHOCK ABSORBER DUST COVER ¹ RHS	1.00	48.95	12.24	36.71	?	L Y	
42 FRONT SHOCK ABSORBER BUSH RHS	1.00	27.85	6.96	20.89	?	L Y	
43 FRONT SHOCK ABSORBER SPRING RHS ¹	1.00	122.60	30.65	91.95	?	L Y	
44 FRONT SHOCK ABSORBER SPRING SEAT ¹ UPPER RHS	1.00	56.75	14.19	42.56	?	L Y	
45 FRONT SHOCK ABSORBER SPRING SEAT ¹ LOWER RHS	1.00	69.85	17.46	52.39	?	L Y	
46 FRONT STABILIZER LINK RHS PA ✓	1.00	190.70	47.68	143.02	?	L Y	
47 FRONT STABILIZER LINK NUT RHS	1.00	7.85	1.96	5.89	?	L Y	
48 FRONT STABILIZER BAR RHS	1.00	369.75	92.44	277.31	?	L Y	
49 FRONT STABILIZER BAR BRACKET RHS ¹	1.00	29.75	7.44	22.31	?	L Y	
50 FRONT STABILIZER BAR BUSH RHS ¹	1.00	37.85	9.46	28.39	?	L Y	
51 FRONT STEERING RAIL AND PINION ASSY ¹	1.00	1,720.70	430.18	1,290.52	?	L Y	
52 FRONT WHEEL BEARING RHS	1.00	147.80	36.95	110.85	?	L Y	
53 FRONT WHEEL HUB RHS ¹	1.00	268.40	67.10	201.30	?	L Y	
54 FRONT WHEEL HUB NUT ¹	1.00	27.60	6.90	20.70	?	L Y	
55 FRONT BRAKE DISC RHS ¹	1.00	221.70	55.43	166.27	?	L Y	
56 FRONT DOOR RHS	1.00	1,138.00	284.50	853.50	new	L Y	
57 FRONT DOOR WINDOW FRAME STICKER RHS	1.00	68.00	17.00	51.00	new	L Y	
58 FRONT DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	repair	L Y	
59 FRONT DOOR RUBBER BEADING RHS	1.00	183.60	45.90	137.70	new	L Y	
60 FRONT DOOR BODY RUBBER RHS	1.00	313.67	78.42	235.25	new	L Y	
61 FRONT DOOR GLASS RHS	1.00	442.50	110.63	331.87	X	L Y	
62 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	repair	L Y	
63 REAR FENDER INNER SHIELD RHS	1.00	67.75	16.94	50.81	X	L Y	
64 FRONT DOOR CHECKER RHS	1.00	151.20	37.80	113.40	X	L Y	
65 FRONT DOOR HINGE UPPER RHS PA ✓	1.00	78.34	19.59	58.75	?	L Y	
66 FRONT DOOR HINGE BOTTOM RHS PA ✓	1.00	78.34	19.59	58.75	?	L Y	
67 FRONT DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L Y	
68 FRONT DOOR LOCK CATCH RHS	1.00	45.67	11.42	34.25	X	L Y	
69 FRONT DOOR WINDOW REGULATOR RHS PA ✓	1.00	177.60	44.40	133.20	?	L Y	
70 FRONT DOOR WINDOW REGULATOR MOTOR RHS	1.00	566.72	141.68	425.04	?	L Y	
71 FRONT B PILLAR RHS	1.00	375.60	93.90	281.70	repair	L Y	
72 FRONT A PILLAR RHS ¹	1.00	478.90	119.73	359.17	repair	L Y	
73 REAR DOOR RHS	1.00	1,198.50	299.63	898.87	PA	L Y	
74 REAR DOOR WINDOW FRAME STICKER RHS	1.00	67.84	16.96	50.88	new	L Y	
75 REAR DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	X	L Y	
76 REAR DOOR BODY RUBBER RHS	1.00	160.55	40.14	120.41	new	L Y	
77 REAR DOOR GLASS RHS	1.00	412.40	103.10	309.30	X	L Y	
78 REAR DOOR QUARTER GLASS RHS	1.00	86.40	21.60	64.80	X	L Y	
79 REAR DOOR QUARTER GLASS RHS ¹ RUBBER	1.00	80.24	20.06	60.18	X	L Y	
80 REAR DOOR CHECKER RHS	1.00	165.00	41.25	123.75	X	L Y	
81 REAR DOOR HINGE UPPER RHS	1.00	79.00	19.75	59.25	X	L Y	
82 REAR DOOR HINGE BOTTOM RHS PA ✓	1.00	79.00	19.75	59.25	?	L Y	
83 REAR DOOR TRIM BOARD RHS ¹	1.00	1,333.60	333.40	1,000.20	?	L Y	
84 REAR DOOR WINDOW REGULATOR RHS	1.00	170.00	42.50	127.50	X	L Y	
85 REAR DOOR WINDOW REGULATOR MOTOR RHS	1.00	564.00	141.00	423.00	X	L Y	
86 ROCKER PANEL RHS	1.00	628.00	157.00	471.00	PA	L Y	
87 SIDE MIRROR RHS	1.00	1,128.00	282.25	846.75	new	L Y	
88 SIDE MIRROR COVER RHS	1.00	81.50	20.38	61.12	repair	L Y	
89 FRONT RADIATOR	1.00	1,510.50	377.63	1,132.87	X	L Y	
90 CONDENSOR	1.00	1,289.24	322.31	966.93	X	L Y	
91 FRONT ABS SENSOR RHS	1.00	420.00	105.00	315.00	X	L Y	
92 FRONT DISC ROTOR RHS	1.00	298.00	74.50	223.50	X	L Y	
93 FRONT DISC ROTOR DUST COVER RH	1.00	100.41	25.10	75.31	X	L Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
94 BRAKE CALIPER RHS	1.00	700.76	175.19	525.57	X L	Y	
95 FRONT BRAKE HOSE RHS	1.00	120.00	30.00	90.00	X L	Y	
96 CROSSMEMBER ASSY	1.00	1,812.60	453.15	1,359.45	X L	Y	
97 FRONT DOOR RUN CHANNEL	1.00	143.00	35.75	107.25	X L	Y	
98 REAR BUMPER	1.00	487.00	121.75	365.25	repair	Y	
99 REAR SHOCK ABSORBER RHS	1.00	317.00	79.25	237.75	X L	Y	
10 FRONT BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT NUMBER PLATE & CASING	1.00	80.00	0.00	80.00	X S	Y	
10 BONNET INSULATOR CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 HEAD LAMP CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT RADIATOR GRILLE TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	X S	Y	
10 REAR FENDER INNER SHIELD RHS CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT DOOR TRIM BOARD RHS CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 REAR DOOR TRIM BOARD CLIP RHS	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT SPORT RIM RHS	1.00	600.00	0.00	600.00	X S	Y	
11 FRONT TYRE RHS	1.00	450.00	0.00	450.00	X S	Y	
11 REAR SPORT RIM RHS	1.00	600.00	0.00	600.00	X S	Y	
11 REAR TYRE RHS	1.00	450.00	0.00	450.00	X S	Y	
11 WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	X S	Y	
11 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
TOTAL:		38,604.11	9,007.39	29,596.72			

TOTAL PARTS & LABOUR :

47,964.11

9,007.39

38,956.72

EXCESS/LOADING: \$\$ 0.00

No. Of Day:

15 days

RE-SURVEY (BEFORE/AFTER PAINTING)

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY:

01 / 07 / 18 @ 1600

SURVEYED BY:

RASHU

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

NOTE: TO CHECK PART PRICES

parts : \$8676.24

S/N : \$1090

Total amount : \$14186.24

SUPPLEMENTRY ITEM

DINGAUTO

BLK 10, #01-20

Sin Ming Industrial Est, Sec C

Singapore 575645

Tel: 6457 5884

Fax: 6453 4227

VEHICLE NO:	SLH 5205 J
MODEL:	TOYOTA ALTIS
CHASSIS NO:	MR053REH 104559106
INSURANCE:	-
DATE SURVEY:	

[illegible]

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/07/2018 9:36

JOB-NO: 85008431

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD.

CONTACT: 0

Page 1 of 4

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH5205J

TRANS: AUTO

CHASSIS: MR053REH104559106

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335956

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,400.00	0.00	2,400.00	Y		1400
2 RUSH PROOFING	1.00	250.00	0.00	250.00	Y		150
3 TO ADJUST HEAD LAMP & CHECK WIRING	1.00	120.00	0.00	120.00	Y		30
4 REMOVE & REPLACE FRONT ENGINE	1.00	400.00	0.00	400.00	Y		200
5 REMOVE & REFIT FRONT WINDSCREEN	1.00	130.00	0.00	130.00	Y		120
6 REMOVE & REFIT FRONT DASH BOARD	1.00	200.00	0.00	200.00	Y		150
7 REMOVE & REFIT FRONT SEAT RHS	1.00	150.00	0.00	150.00	Y		60
8 REMOVE & REFIT FRONT CARPET RHS	1.00	120.00	0.00	120.00	Y		60
9 R & R ROOF LINING	1.00	260.00	0.00	260.00	Y		X
10 MOUNT WORK BENCH	1.00	350.00	0.00	350.00	Y		200
11 TO REMOVE & REPLACED RHF DOOR & RHR DOOR TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	200.00	0.00	200.00	Y		120
12 R & R REAR SPORT RIM & FRONT SPORT RIM & TRANSFER BOTH TYRE TO THE NEW RIM	1.00	150.00	0.00	150.00	Y		80
13 WHEEL ALIGNMENT	1.00	150.00	0.00	150.00	Y		60
14 REMOVE & REFIT UNDER CARRIAGE	1.00	300.00	0.00	300.00	Y		180
15 ALIGNMENT FRONT SUPPORT PANEL, WHEEL HOUSE PANEL	1.00	120.00	0.00	120.00	Y		80
16 REFILL AIR CON GAS	1.00	100.00	0.00	100.00	Y		80
17 TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT BUMPER.	1.00	250.00	0.00	250.00	Y		200
18 TO SPRAY PAINT ON THE AFFECTED AREAS, BONNET	1.00	250.00	0.00	250.00	Y		X
19 TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00	Y		150
20 TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT REINFORCEMENT	1.00	250.00	0.00	250.00	Y		X
21 TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT FENDER RHS	1.00	250.00	0.00	250.00	Y		200
22 TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT DOOR RHS	1.00	250.00	0.00	250.00	Y		200
23 TO SPRAY PAINT ON THE AFFECTED AREAS, REAR DOOR RHS	1.00	250.00	0.00	250.00	Y		200
24 TO SPRAY PAINT ON THE AFFECTED AREAS, REAR FENDER RHS	1.00	250.00	0.00	250.00	Y		200

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
25 TO SPRAY PAINT ON THE AFFECTED AREAS,ROCKER PANEL	1.00	250.00	0.00	250.00		Y	100
26 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT A PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
27 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT B PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
28 R & R CONDENSOR & RADIATOR	1.00	120.00	0.00	120.00		Y	60 X
29 R & R LHS,RHS DOOR COMPONENTS	1.00	150.00	0.00	150.00		Y	X
30 R & R B PILLAR GARNISH	1.00	120.00	0.00	120.00		Y	60
31 R & R SEAT BELT RHS	1.00	120.00	0.00	120.00		Y	60
32 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
33 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,ROOF LINING	1.00	250.00	0.00	250.00		Y	X
34 ALIGNMENT FRONT CHASSIS	1.00	200.00	0.00	200.00		Y	X
TOTAL:		9,360.00	0.00	9,360.00			

MATERIALS

1 FRONT BUMPER	1.00	511.22	127.81	383.41	DE L	Y	200
2 FRONT BUMPER FOG LAMP COVER RHS	1.00	121.75	30.44	91.31	DE L	Y	50
3 FRONT BUMPER LOWER GRILLE	1.00	138.71	34.68	104.03	X L	Y	
4 FRONT BUMPER SIDE RETAINER RHS	1.00	58.17	14.54	43.63	DE L	Y	
5 FRONT BUMPER SIDE RETAINER LHS	1.00	58.17	14.54	43.63	X L	Y	
6 FRONT BUMPER BRACKET RHS	1.00	135.70	33.93	101.77	DE L	Y	
7 FRONT BUMPER BRACKET LHS	1.00	135.70	33.93	101.77	X L	Y	
8 FRONT REINFORCEMENT	1.00	386.60	96.85	289.75	X L	Y	
9 FRONT REINFORCEMENT ARM LHS	1.00	135.70	33.93	101.77	X L	Y	
10 FRONT REINFORCEMENT ARM RHS	1.00	135.70	33.93	101.77	X L	Y	
11 FRONT BUMPER SPONGE	1.00	102.38	25.60	76.78	X L	Y	
12 FRONT BUMPER LOWER CENTRE COVER	1.00	211.67	52.92	158.75	X L	Y	
13 BONNET	1.00	1,140.40	285.10	855.30	X L	Y	
14 BONNET INSULATOR	1.00	301.36	75.34	226.02	X L	Y	
15 BONNET HINGE LHS	1.00	76.60	19.15	57.45	X L	Y	
16 BONNET HINGE RHS	1.00	76.60	19.15	57.45	X L	Y	
17 BONNET HINGE BOLT	1.00	38.25	9.56	28.69	X L	Y	
18 HEAD LAMP RHS	1.00	794.10	198.53	595.57	DE L	Y	
19 HEAD LAMP PANEL RHS	1.00	564.00	141.00	423.00	? L	Y	
20 FRONT SUPPORT PANEL	1.00	1,074.60	268.65	805.95	repair L	Y	
21 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	X L	Y	
22 FRONT RADIATOR GRILLE	1.00	565.00	141.25	423.75	? L	Y	
23 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	48.00	12.00	36.00	? L	Y	
24 FRONT RADIATOR GRILLE TOP GARNISH	1.00	125.00	31.25	93.75	X L	Y	
25 FRONT FENDER RHS	1.00	859.00	214.75	644.25	DE L	Y	
26 FRONT FENDER "VTI" EMBLEM RHS	1.00	46.00	11.50	34.50	DE L	Y	
27 FRONT FENDER INNER SHIELD RHS	1.00	182.00	45.50	136.50	DE L	Y	
28 FRONT FENDER WHEEL HOUSE PANEL RHS	1.00	557.00	139.25	417.75	repair L	Y	
29 FRONT FENDER QUARTER GARNISH RHS	1.00	65.00	16.25	48.75	DE L	Y	
30 FRONT WASHER TANK MOTOR	1.00	196.00	49.00	147.00	X L	Y	
31 FRONT WASHER TANK	1.00	167.00	41.75	125.25	DE L	Y	
32 FRONT DRIVER SHAFT RHS	1.00	1,441.60	360.40	1,081.20	? L	Y	
33 FRONT LOWER ARM RHS	1.00	265.07	66.27	198.80	? L	Y	
34 FRONT LOWER ARM BALL JOINT RHS	1.00	270.00	67.50	202.50	? L	Y	
35 FRONT KNUCLE ARM RHS	1.00	521.50	130.38	391.12	? L	Y	
36 FRONT KNUCLE ARM BEARING RHS	1.00	132.67	33.17	99.50	? L	Y	
37 FRONT KNUCLE ARM BOLT WITH NUT RHS	1.00	15.00	3.75	11.25	DE L	Y	
38 FRONT SHOCK ABSORBER RHS	1.00	316.97	79.24	237.73	? L	Y	
39 FRONT SHOCK ABSORBER TOP MOULDING RHS	1.00	161.89	40.47	121.42	? L	Y	
40 FRONT SHOCK ABSORBER NUT SET	1.00	12.60	3.15	9.45	DE L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
41 FRONT SHOCK ABSORBER DUST COVER RHS	1.00	48.95	12.24	36.71	?	L Y	
42 FRONT SHOCK ABSORBER BUSH RHS	1.00	27.85	6.96	20.89	?	L Y	
43 FRONT SHOCK ABSORBER SPRING RHS	1.00	122.60	30.65	91.95	?	L Y	
44 FRONT SHOCK ABSORBER SPRING SEAT UPPER RHS	1.00	56.75	14.19	42.56	?	L Y	
45 FRONT SHOCK ABSORBER SPRING SEAT LOWER RHS	1.00	69.85	17.46	52.39	?	L Y	
46 FRONT STABILIZER LINK RHS	1.00	190.70	47.68	143.02	?	L Y	
47 FRONT STABILIZER LINK NUT RHS	1.00	7.85	1.96	5.89	?	L Y	
48 FRONT STABILIZER BAR RHS	1.00	369.75	92.44	277.31	?	L Y	
49 FRONT STABILIZER BAR BRACKET RHS	1.00	29.75	7.44	22.31	?	L Y	
50 FRONT STABILIZER BAR BUSH RHS	1.00	37.85	9.46	28.39	?	L Y	
51 FRONT STEERING RAIL AND PINION ASSY	1.00	1,720.70	430.18	1,290.52	?	L Y	
52 FRONT WHEEL BEARING RHS	1.00	147.80	36.95	110.85	?	L Y	
53 FRONT WHEEL HUB RHS	1.00	268.40	67.10	201.30	?	L Y	
54 FRONT WHEEL HUB NUT	1.00	27.60	6.90	20.70	?	L Y	
55 FRONT BRAKE DISC RHS	1.00	221.70	55.43	166.27	?	L Y	
56 FRONT DOOR RHS	1.00	1,138.00	284.50	853.50	Phu	L Y	
57 FRONT DOOR WINDOW FRAME STICKER RHS	1.00	68.00	17.00	51.00	new	L Y	
58 FRONT DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	repair	L Y	
59 FRONT DOOR RUBBER BEADING RHS	1.00	183.60	45.90	137.70	new	L Y	
60 FRONT DOOR BODY RUBBER RHS	1.00	313.67	78.42	235.25	new	L Y	
61 FRONT DOOR GLASS RHS	1.00	442.50	110.63	331.87	X	L Y	
62 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	repair	L Y	
63 REAR FENDER INNER SHIELD RHS	1.00	67.75	16.94	50.81	X	L Y	
64 FRONT DOOR CHECKER RHS	1.00	151.20	37.80	113.40	X	L Y	
65 FRONT DOOR HINGE UPPER RHS	1.00	78.34	19.59	58.75	?	L Y	
66 FRONT DOOR HINGE BOTTOM RHS	1.00	78.34	19.59	58.75	?	L Y	
67 FRONT DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	X	L Y	
68 FRONT DOOR LOCK CATCH RHS	1.00	45.67	11.42	34.25	X	L Y	
69 FRONT DOOR WINDOW REGULATOR RHS	1.00	177.60	44.40	133.20	?	L Y	
70 FRONT DOOR WINDOW REGULATOR MOTOR RHS	1.00	566.72	141.68	425.04	?	L Y	
71 FRONT B PILLAR RHS	1.00	375.60	93.90	281.70	repair	L Y	
72 FRONT A PILLAR RHS	1.00	478.90	119.73	359.17	repair	L Y	
73 REAR DOOR RHS	1.00	1,198.50	299.63	898.87	Phu	L Y	
74 REAR DOOR WINDOW FRAME STICKER RHS	1.00	67.84	16.96	50.88	new	L Y	
75 REAR DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	X	L Y	
76 REAR DOOR BODY RUBBER RHS	1.00	160.55	40.14	120.41	new	L Y	
77 REAR DOOR GLASS RHS	1.00	412.40	103.10	309.30	X	L Y	
78 REAR DOOR QUARTER GLASS RHS	1.00	86.40	21.60	64.80	Phu	L Y	
79 REAR DOOR QUARTER GLASS RHS RUBBER	1.00	80.24	20.06	60.18	Phu	L Y	
80 REAR DOOR CHECKER RHS	1.00	165.00	41.25	123.75	X	L Y	
81 REAR DOOR HINGE UPPER RHS	1.00	79.00	19.75	59.25	X	L Y	
82 REAR DOOR HINGE BOTTOM RHS	1.00	79.00	19.75	59.25	?	L Y	
83 REAR DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L Y	
84 REAR DOOR WINDOW REGULATOR RHS	1.00	170.00	42.50	127.50	X	L Y	
85 REAR DOOR WINDOW REGULATOR MOTOR RHS	1.00	564.00	141.00	423.00	X	L Y	
86 ROCKER PANEL RHS	1.00	628.00	157.00	471.00	Phu	L Y	
87 SIDE MIRROR RHS	1.00	1,129.00	282.25	846.75	Phu	L Y	
88 SIDE MIRROR COVER RHS	1.00	81.50	20.38	61.12	repair	L Y	
89 FRONT RADIATOR	1.00	1,510.50	377.63	1,132.87	X	L Y	
90 CONDENSOR	1.00	1,289.24	322.31	966.93	X	L Y	
91 FRONT ABS SENSOR RHS	1.00	420.00	105.00	315.00	X	L Y	
92 FRONT DISC ROTOR RHS	1.00	298.00	74.50	223.50	X	L Y	
93 FRONT DISC ROTOR DUST COVER RH	1.00	100.41	25.10	75.31	X	L Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
94 BRAKE CALIPER RHS	1.00	700.76	175.19	525.57	X L	Y	
95 FRONT BRAKE HOSE RHS	1.00	120.00	30.00	90.00	X L	Y	
96 CROSSMEMBER ASSY	1.00	1,812.60	453.15	1,359.45	X L	Y	
97 FRONT DOOR RUN CHANNEL	1.00	143.00	35.75	107.25	X L	Y	
98 REAR BUMPER	1.00	487.00	121.75	365.25	X repair L	Y	
99 REAR SHOCK ABSORBER RHS	1.00	317.00	79.25	237.75	X L	Y	
100 FRONT BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
101 FRONT NUMBER PLATE & CASING	1.00	80.00	0.00	80.00	X S	Y	
102 BONNET INSULATOR CLIP	1.00	35.00	0.00	35.00	X S	Y	
103 HEAD LAMP CLIP	1.00	35.00	0.00	35.00	X S	Y	
104 FRONT RADIATOR GRILLE TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	X S	Y	
105 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	X S	Y	
106 REAR FENDER INNER SHIELD RHS CLIP	1.00	35.00	0.00	35.00	X repeated S	Y	
107 FRONT DOOR TRIM BOARD RHS CLIP	1.00	35.00	0.00	35.00	X S	Y	
108 REAR DOOR TRIM BOARD CLIP RHS	1.00	35.00	0.00	35.00	X S	Y	
109 FRONT SPORT RIM RHS	1.00	600.00	0.00	600.00	X 300 S	Y	
110 FRONT TYRE RHS	1.00	450.00	0.00	450.00	X 70% punctured S	Y	
111 REAR SPORT RIM RHS	1.00	600.00	0.00	600.00	X 300 S	Y	
112 REAR TYRE RHS	1.00	450.00	0.00	450.00	X S	Y	
113 WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	X S	Y	
114 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
TOTAL:		38,604.11	9,007.39	29,596.72			
TOTAL PARTS & LABOUR:		47,964.11	9,007.39	38,956.72			

EXCESS/LOADING:SS 0.00

No. Of Day:

15 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY PART OR LUMP SUM: SS

DATE OF SURVEY: 09 / 07 / 18 @ 1600

SURVEYED BY:

RASHU

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

NOTE: TO CHECK PART PRICES



Service Request Details

Claim

S8M00NP7

Reference

None 

Loss Date

July 7, 2018

Request Date

July 9, 2018

Due Date

July 16, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

09072018 @ 10:49am
Michelle veh in
Rasul

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLH5205J

Make

TPVD TOYOTA

Model

COROLLA ALTIS-1.6 CLASSIC CVT (A)

Service Address

...

Primary Contact/Insured

LEE KIM LEI

408 FAJAR ROAD, #10-349, 670408, Singapore

KIMLEILEE@GMAIL.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

NON REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

10 JULY 2018

LEE KIM LEI
408 FAJAR ROAD, #10-349
Singapore 670408

Dear Sir,

OUR REF : CC4/ASM18012445/R1ub3
YOUR REF : SGA 5096C

**ACCIDENT INVOLVING SGA 5096C & SLH 5205J ALONG ROAD 1 UPPER
BUKIT TIMAH ROAD ON 07/07/2018**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to thinthin@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/ commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 2360 if you have any further enquiries.

Yours sincerely,
Claim department

This is a computer generated letter and no signature is required.

CC: AXA INSURANCE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2018 09:40
Date Of Accident	07/07/2018 04:30
Exact Location Of Accident	JUNCTION BET UPPER BT TIMAH RD TO OLD JURONG RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGA5096C
Insured/Policyholder	
Name Of Registered Owner	LEE KIM LEI
NRIC No	S2591224A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96674037
Alternative Phone No	HOME-96674037

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO 1.5LSR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA075615
Cover Note Number	

Driver

Name of Driver	LEE KIM LEI
NRIC No	S2591224A
Date Of Birth	16/07/1963
Occupation	INDOOR
Date Of Driving Pass	31/07/1990
Driving Experience	27 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96674037
Fax Number	
Contact Number	HOME-96674037
Email Address	NOEMAIL

Address	408 FAJAR RD #10-349 SINGAPORE 670408
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WORKER GENDER: : FEMALE
Passenger 2	NAME: : WORKER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH5205J
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	TEO WEE LENG
NRIC/Passport Number	S7721356B
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage
No. Of Passenger (Including Driver)



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Re:Reminder : Request for Mandate approval S8M00NP7

Type

Question

Message

Mandate approved \$17046.45, breakdown : (1) COR \$15144.45 (2) LOU+LOI \$1900 (19days) (3) LTA fee \$2

[Reply](#)

<< Re:Reminder : Request for Mandate approval S8M00NP7

Type

Question

Message

Mandate approved \$17046.45, breakdown : (1) COR \$15144.45 (2) LOU+LOI \$1900 (19days) (3) LTA fee \$2

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGA 5096C (Insd veh)	Model:	TOYOTA
	SLH 5205J (TP veh)		COROLLA ALTIS 1.6
Date of Accident:	07/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	41,778.91
Final Repair Cost	:	\$	15,144.45
Loss of Use	:	\$	1,140.00
Rental (if any)	:	\$	19 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	16,286.45

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	DING AUTO PTE LTD	:	\$ 16,286.45

NUR SHAQILAH BTE ABDOL
WAHAB

08/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012445/R1ub3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 08-11-2018



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGA 5096C	Veh. Inspected	SLH 5205J
Policy No.	GA075615	Coverage (\$)	0.00
Claim No.	S8M00NP7	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104559106	Colour	GREY
Odometer	89595	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R15	DUNLOP	6 mm
L/H Front Tyre	205/55R15	DUNLOP	6 mm
R/H Rear Tyre	205/55R15	DUNLOP	6 mm
L/H Rear Tyre	205/55R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/07/2018	Inspection Date	09/07/2018
Survey held at	249, JLN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5205J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	511.22	511.22
1	FRONT BUMPER FOG LAMP COVER RHS (CONSISTENT)	SCRATCHED	121.75	121.75
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	138.71	-
1	FRONT BUMPER SIDE RETAINER RHS (CONSISTENT)	NECESSARY	58.17	58.17
1	FRONT BUMPER SIDE RETAINER LHS (CONSISTENT)	SERVICEABLE	58.17	-
1	FRONT BUMPER BRACKET RHS (CONSISTENT)	NECESSARY	135.70	135.70
1	FRONT BUMPER BRACKET LHS (CONSISTENT)	SERVICEABLE	135.70	-
1	FRONT REINFORCEMENT (CONSISTENT)	SERVICEABLE	386.60	-
1	FRONT REINFORCEMENT ARM LHS (CONSISTENT)	SERVICEABLE	135.70	-
1	FRONT REINFORCEMENT ARM RHS (CONSISTENT)	SERVICEABLE	135.70	-
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	102.38	-
1	FRONT BUMPER LOWER CENTRE COVER (CONSISTENT)	SERVICEABLE	211.67	-
1	BONNET (CONSISTENT)	SERVICEABLE	1,140.40	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	301.36	-
1	BONNET HINGE LHS (CONSISTENT)	SERVICEABLE	76.60	-
1	BONNET HINGE RHS (CONSISTENT)	SERVICEABLE	76.60	-
1	BONNET HINGE BOLT (CONSISTENT)	SERVICEABLE	38.25	-
1	HEAD LAMP RHS (CONSISTENT)	CRACKED	794.10	794.10
1	HEAD LAMP PANEL RHS (CONSISTENT)	SERVICEABLE	564.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,074.60	-
1	FRONT BRACE PANEL (CONSISTENT)	SERVICEABLE	115.70	-
1	FRONT RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	565.00	-
1	FRONT RADIATOR GRILLE "TOYOTA" EMBLEM (CONSISTENT)	SERVICEABLE	48.00	-
1	FRONT RADIATOR GRILLE TOP GARNISH (CONSISTENT)	SERVICEABLE	125.00	-
1	FRONT FENDER RHS (CONSISTENT)	BUCKLED	859.00	859.00
1	FRONT FENDER "VVTI" EMBLEM RHS (CONSISTENT)	NECESSARY	46.00	46.00
1	FRONT FENDER INNER SHIELD RHS (CONSISTENT)	DEFORMED	182.00	182.00
1	FRONT FENDER WHEEL HOUSE PANEL RHS (CONSISTENT)	TO REPAIR SEE LABOUR	557.00	-

Report Ref No. CC4/ASM18012445/R1ub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER QUARTER GARNISH RHS (CONSISTENT)	DEFORMED	65.00	65.00
1	FRONT WASHER TANK MOTOR (CONSISTENT)	SERVICEABLE	196.00	-
1	FRONT WASHER TANK (CONSISTENT)	DEFORMED	167.00	167.00
1	FRONT DRIVER SHAFT RHS (CONSISTENT)	BENT	1,441.60	1,441.00
1	FRONT LOWER ARM RHS (CONSISTENT)	BENT	265.07	265.07
1	FRONT LOWER ARM BALL JOINT RHS (CONSISTENT)	BENT	270.00	270.00
1	FRONT KNUCKLE ARM RHS (CONSISTENT)	BENT	521.50	521.50
1	FRONT KNUCKLE ARM BEARING RHS (CONSISTENT)	BENT	132.67	132.67
1	FRONT KNUCKLE ARM BOLT WITH NUT RHS (CONSISTENT)	NECESSARY	15.00	15.00
1	FRONT SHOCK ABSORBER RHS (CONSISTENT)	BENT	316.97	316.97
1	FRONT SHOCK ABSORBER TOP MOULDING RHS (CONSISTENT)	NOT NECESSARY	161.89	-
1	SET FRONT SHOCK ABSORBER NUT (CONSISTENT)	NECESSARY	12.60	12.60
1	FRONT SHOCK ABSORBER DUST COVER RHS (CONSISTENT)	SERVICEABLE	48.95	-
1	FRONT SHOCK ABSORBER BUSH RHS (CONSISTENT)	SERVICEABLE	27.85	-
1	FRONT SHOCK ABSORBER SPRING RHS (CONSISTENT)	SERVICEABLE	122.60	-
1	FRONT SHOCK ABSORBER SPRING SEAT UPPER RHS (CONSISTENT)	SERVICEABLE	56.75	-
1	FRONT SHOCK ABSORBER SPRING SEAT LOWER RHS (CONSISTENT)	SERVICEABLE	69.85	-
1	FRONT STABILIZER LINK RHS (CONSISTENT)	BENT	190.70	190.70
1	FRONT STABILIZER LINK NUT RHS (CONSISTENT)	SERVICEABLE	7.85	-
1	FRONT STABILIZER BAR RHS (CONSISTENT)	SERVICEABLE	369.75	-
1	FRONT STABILIZER BAR BRACKET RHS (CONSISTENT)	SERVICEABLE	29.75	-
1	FRONT STABILIZER BAR BUSH RHS (CONSISTENT)	SERVICEABLE	37.85	-
1	FRONT STEERING RAIL AND PINION ASSY (CONSISTENT)	SERVICEABLE	1,720.70	-
1	FRONT WHEEL BEARING RHS (CONSISTENT)	SERVICEABLE	147.80	-
1	FRONT WHEEL HUB RHS (CONSISTENT)	SERVICEABLE	268.40	-
1	FRONT WHEEL HUB NUT (CONSISTENT)	SERVICEABLE	27.60	-
1	FRONT BRAKE DISC RHS (CONSISTENT)	SERVICEABLE	221.70	-
1	FRONT DOOR RHS (CONSISTENT)	BUCKLED	1,138.00	1,138.00

Report Ref No. CC4/ASM18012445/R1ub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR WINDOW FRAME STICKER RHS (CONSISTENT)	NECESSARY	68.00	68.00
1	FRONT DOOR OUTER HANDLE RHS (CONSISTENT)	TO REPAIR SEE LABOUR	201.30	-
1	FRONT DOOR RUBBER BEADING RHS (CONSISTENT)	NECESSARY	183.60	183.60
1	FRONT DOOR BODY RUBBER RHS (CONSISTENT)	NECESSARY	313.67	313.67
1	FRONT DOOR GLASS RHS (CONSISTENT)	SERVICEABLE	442.50	-
1	REAR FENDER RHS (CONSISTENT)	TO REPAIR SEE LABOUR	1,085.00	-
1	REAR FENDER INNER SHIELD RHS (CONSISTENT)	SERVICEABLE	67.75	-
1	FRONT DOOR CHECKER RHS (CONSISTENT)	SERVICEABLE	151.20	-
1	FRONT DOOR HINGE UPPER RHS (CONSISTENT)	BENT	78.34	78.34
1	FRONT DOOR HINGE BOTTOM RHS (CONSISTENT)	BENT	78.34	78.34
1	FRONT DOOR TRIM BOARD RHS (CONSISTENT)	SERVICEABLE	1,333.60	-
1	FRONT DOOR LOCK CATCH RHS (CONSISTENT)	SERVICEABLE	45.67	-
1	FRONT DOOR WINDOW REGULATOR RHS (CONSISTENT)	BENT	177.60	177.60
1	FRONT DOOR WINDOW REGULATOR MOTOR RHS (CONSISTENT)	SERVICEABLE	566.72	-
1	FRONT B PILLAR RHS (CONSISTENT)	TO REPAIR SEE LABOUR	375.60	-
1	FRONT A PILLAR RHS (CONSISTENT)	TO REPAIR SEE LABOUR	478.90	-
1	REAR DOOR RHS (CONSISTENT)	BENT	1,198.50	1,198.50
1	REAR DOOR WINDOW FRAME STICKER RHS (CONSISTENT)	NECESSARY	67.84	67.84
1	REAR DOOR OUTER HANDLE RHS (CONSISTENT)	SERVICEABLE	201.30	-
1	REAR DOOR BODY RUBBER RHS (CONSISTENT)	NECESSARY	160.55	160.55
1	REAR DOOR GLASS RHS (CONSISTENT)	SERVICEABLE	412.40	-
1	REAR DOOR QUARTER GLASS RHS (CONSISTENT)	SERVICEABLE	86.40	-
1	REAR DOOR QUARTER GLASS RHS RUBBER (CONSISTENT)	SERVICEABLE	80.24	-
1	REAR DOOR CHECKER RHS (CONSISTENT)	SERVICEABLE	165.00	-
1	REAR DOOR HINGE UPPER RHS (CONSISTENT)	SERVICEABLE	79.00	-
1	REAR DOOR HINGE BOTTOM RHS (CONSISTENT)	BENT	79.00	79.00
1	REAR DOOR TRIM BOARD RHS (CONSISTENT)	SERVICEABLE	1,333.60	-

Report Ref No. CC4/ASM18012445/R1ub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR WINDOW REGULATOR RHS (CONSISTENT)	SERVICEABLE	170.00	-
1	REAR DOOR WINDOW REGULATOR MOTOR RHS (CONSISTENT)	SERVICEABLE	564.00	-
1	ROCKER PANEL RHS (CONSISTENT)	BENT	628.00	628.00
1	SIDE MIRROR RHS (CONSISTENT)	BROKEN	1,129.00	1,129.00
1	SIDE MIRROR COVER RHS (CONSISTENT)	TO REPAIR SEE LABOUR	81.50	-
1	FRONT RADIATOR (CONSISTENT)	NOT NECESSARY	1,510.50	-
1	CONDENSOR (CONSISTENT)	NOT NECESSARY	1,289.24	-
1	FRONT ABS SENSOR RHS (CONSISTENT)	NOT NECESSARY	420.00	-
1	FRONT DISC ROTOR RHS (CONSISTENT)	NOT NECESSARY	298.00	-
1	FRONT DISC ROTOR DUST COVER RH (CONSISTENT)	NOT NECESSARY	100.41	-
1	BRAKE CALIPER RHS (CONSISTENT)	NOT NECESSARY	700.76	-
1	FRONT BRAKE HOSE RHS (CONSISTENT)	NOT NECESSARY	120.00	-
1	CROSSMEMBER ASSY (CONSISTENT)	NOT NECESSARY	1,812.60	-
1	FRONT DOOR RUN CHANNEL (CONSISTENT)	NOT NECESSARY	143.00	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	487.00	-
1	REAR SHOCK ABSORBER RHS (CONSISTENT)	NOT NECESSARY	317.00	-
1	FRONT FENDER REAR STAND GARNISH (CONSISTENT) (ADDITIONAL)	DEFORMED	118.50	118.50
	LESS 25% DISCOUNT		-9,036.90	-2,880.70
			27,110.71	8,643.69
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT NUMBER PLATE & CASING (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	BONNET INSULATOR CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	HEAD LAMP CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT RADIATOR GRILLE TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT FENDER INNER SHIELD CLIP RHS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR FENDER INNER SHIELD RHS CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-

Report Ref No. CC4/ASM18012445/R1ub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR TRIM BOARD RHS CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR DOOR TRIM BOARD CLIP RHS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT SPORT RIM RHS (SN) (CONSISTENT)	SCRATCHED	600.00	300.00
1	FRONT TYRE RHS (70%) (SN) (CONSISTENT)	PUNCTURE	450.00	315.00
1	REAR SPORT RIM RHS (SN) (CONSISTENT)	SCRATCHED	600.00	300.00
1	REAR TYRE RHS (SN) (CONSISTENT)	NOT NECESSARY	450.00	-
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
			2,575.00	1,090.00
	LABOUR			
	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL, FRONT FENDER WHEEL HOUSE PANEL RHS, FRONT DOOR OUTER HANDLE RHS, REAR FENDER RHS, FRONT B PILLAR RHS, FRONT A PILLAR RHS, SIDE MIRROR COVER RHS AND REAR BUMPER.		2,400.00	1,400.00
	RUSH PROOFING.		250.00	150.00
	TO ADJUST HEAD LAMP & CHECK WIRING.		120.00	30.00
	REMOVE & REPLACE FRONT ENGINE.	NOT NECESSARY	400.00	-
	REMOVE & REFIT FRONT WINDSCREEN.	NOT NECESSARY	130.00	-
	REMOVE & REFIT FRONT DASH BOARD.		200.00	150.00
	REMOVE & REFIT FRONT SEAT RHS.		150.00	60.00
	REMOVE & REFIT FRONT CARPET RHS.		120.00	60.00
	R&R ROOF LINING.	NOT NECESSARY	260.00	-
	MOUNT WORK BENCH.		350.00	200.00
	TO REMOVE & REPLACED RHS DOOR & RHR DOOR. TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR.		200.00	120.00
	R&R SEAT SPORT RIM & FRONT SPORT RIM & TRANSFER BOTH TYRE TO THE NEW RIM.		150.00	80.00
	WHEEL ALIGNMENT.		150.00	60.00
	REMOVE & REFIT UNDER CARRIAGE.		300.00	180.00
	ALIGNMENT FRONT SUPPORT PANEL, WHEEL HOUSE PANEL.		120.00	80.00

Report Ref No. CC4/ASM18012445/R1ub3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REFILL AIR CON GAS.		100.00	80.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT BUMPER.		250.00	200.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, BONNET.	NOT NECESSARY	250.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT SUPPORT PANEL.		250.00	150.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT REINFORCEMENT.	NOT NECESSARY	250.00	-
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT FENDER RHS.		250.00	200.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT DOOR RHS.		250.00	200.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, REAR DOOR RHS.		250.00	200.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, REAR FENDER RHS.		250.00	200.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, ROCKER PANEL.		250.00	100.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT A PILLAR RHS.		250.00	100.00
	TO SPRAY PAINT ON THE AFFECTED AREAS, FRONT B PILLAR RHS.		250.00	100.00
	R&R CONDENSOR & RADIATOR.	NOT NECESSARY	120.00	-
	R&R LHS, RHS DOOR COMPONENTS.	NOT NECESSARY	150.00	-
	R&R B PILLAR GARNISH.		120.00	60.00
	R&R SEAT BELT RHS.		120.00	60.00
	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS, REAR BUMPER.		250.00	200.00
	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS, ROOF LINING.	NOT NECESSARY	250.00	-
	ALIGNMENT FRONT CHASSIS.	NOT NECESSARY	200.00	-
			-	-
			-	-
			-	-
			9,360.00	4,420.00
GRAND TOTAL			39,045.71	14,153.69

Report Ref No. CC4/ASM18012445/R1ub3s2



RECOMMENDED COST OF REPAIRS			14,153.69
-----------------------------	--	--	-----------

Report Ref No. CC4/ASM18012445/R1ub3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.